

ESTIMATE TO REPAIR

VEHICLE NO. : SKZ 6189 H
 MAKE : TOYOTA
 MODEL : HARRIER PREMIUM 2.0 CVT
 YEAR : 2015
 CHASSIS NO : ZSU600068347

SURVEYOR NAME :
 DATE OF SURVEY :
 TIME OF SURVEY :
 DATE : 31-Jan-18
 DATE OF ACCIDENT : 29-Jan-18
 THIRD PARTY REF : GW 5596 K / EQ INSURANCE

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 1,897.80
1 pc	Rear Bumper Sponge				\$ 165.80
2 pcs	Rear Bumper Sensor		\$ 398.80		\$ 797.60
2 pcs	Rear Bumper Retainer		\$ 78.87		\$ 157.74
1 pc	Rear End Panel				\$ 887.80
1 pc	Rear End Panel Garnsih				\$ 687.80
1 pc	Tailgate				\$ 2,580.80
1 pc	Tailgate Top Lock				\$ 789.80
1 pc	Tailgate Bottom Lock				\$ 66.90
1 pc	Tailgate Rubber				\$ 587.80
1 pc	Tailgate Top Outer Garnish c/w Lamp				\$ 1,870.77
1 pc	Tailgate Emblem				\$ 89.80
1 pc	Rear Windscreen Sealant				\$ 125.70
					\$ 10,706.11
	Less 25%				\$ 2,676.53
					\$ 8,029.58
1 tube	Rear Windscreen Sealant	S.Nett			\$ 40.00
1 pc	Rear Number Plate	S.Nett			\$ 40.00
	To putty & spray painting.				\$ 950.00
	To remove and refix rear windscreen glass.				\$ 120.00
	To transfer tailgate fittings.				\$ 120.00
	To anti-rust.				\$ 80.00
	Signature Protection Treatment at accident affected panel.				\$ 450.00
	Labour Charges.				\$ 800.00
TG-RA/-					\$ 10,629.58

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0