

22/03/2002

ASS. REC. BY:

REF: CS/40118001987/R1vd302 Special Instruction:

Surveyor: Rasu ASSIGNMENT (Office)From (Person): Jenny Lew of UOI Date/Time: 1/2/18 @ 9:35am

Estimated Cost: _____ Bill to: _____

☒ OD ☐ H ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CSTo Inspect Vehicle No: SKD 2688B Insured: _____at Workshop m/s Performance Tel: 81214600of 303 Alexandra RdPolicy No: _____ Claim No: M12D07211802Sum Insured: _____ Excess: \$750.00Make of Veh: _____ D.O.A. 27/01/2018

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS H.O.D. Endorsement: _____Date/Time: 9:42am 1/2/18 Person Contacted: Inthiran Vehicle ☒ IN ☐ OUT

Date/Time Action/Instruction (✓) Estimate

SKD 2688B - x2/2/18 Revert to Jenny by email3/2/18 Rece authorise repair from Jenny by email4/2/18 Informed Inthiran c/a ex \$750 by email8/3/18 @ 251pm Inthiran said will email us finalise

Form

REF:

CS40118001987/R/vd3


2293F

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 () TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKD 2688B
 at Workshop m/s PERFORMANCE
 of _____
 Insured: NO
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 750
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 128K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / (REV) / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKD 2688B Yr Regn: 2014 / SEP
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: P.M.W 520 I C/C 1997
 Colour: BLUE A/C: Insured / Std / NI / NA
 Sp. Reading: 79611 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBA SA 32090D335166
 Gen. Cond: Good / () Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / () S/Rim / STD A/Rim or
 Tyre Size: F: 235/45R18
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or CONTINENTAL
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 27/01/18 D.O.I. 01/02/18
 Survey held at PERFORMANCE
 Des. of Damages: () Front / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/9/18 final fig \$ 28,463.50 confirmed by email (Ref 3995.25, 12/9)

[Signature]

20/9/2018

RECEIVED 21 SEP 2018.

Date/Time. File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time. File Return to?

21/9- typist

Report Format : OD

Lump Sum / I.B.I: (\$) 28,463.50

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

Survey Fee

Transportation

\$ + RS \$

Photos

Others

TOTAL

23X15

1704 305

50

50

124

739

Survey Department Check List (Case Handler)

Reference No.: CS/4011800/1987/R1vd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

Case Handler

20/6/18

Date

*C: Critical *N: Non-Critical

21/05/2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI18001987/R1vd3

3 ANSON ROAD #28-01

SPRINGLEAF TOWER SINGAPORE 079909

Date : 01-02-2018



Code : UOI2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKD 2688B
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	750.00
Assign From JENNY LEW	Assign Date	01/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/01/2018	Inspection Date	01/02/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 20 September 2018 5:17 PM
To: 'LEW JENNY'
Cc: LEE KATIE; SUR
Subject: RE: SKD2688B DOA 27.01.18

Dear Jenny,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Thursday, 20 September 2018 4:59 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: SKD2688B DOA 27.01.18

Dear Veron,

Please proceed up to S\$28,463.50 incl Supp.items.
Excess: S\$750.00

Claim no. M12D07211802

Warmest Regards

Jenny Lew

Claims Department

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, 20 September, 2018 11:20 AM
To: LEW JENNY <jennylew@uoi.com.sg>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: SKD2688B DOA 27.01.18

Dear Jenny,

Enclosed with revised (incl.supplementary).

For your approval please.

Please provide us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LEW JENNY <jennylew@uoi.com.sg>

Sent: Friday, 2 February 2018 3:59 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: LEE KATIE <katielee@uoi.com.sg>

Subject: RE: SKD2688B DOA 27.01.18

Dear Veron,

Please proceed with the repair authorisation up to S\$28,385.30

Excess: S\$750.00

Warmest Regards

Jenny Lew

Claims Department

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Friday, 2 February, 2018 2:10 PM

To: LEW JENNY <jennylew@uoi.com.sg>; SUR <sur@lkkauto.com>

Cc: LEE KATIE <katielee@uoi.com.sg>

Subject: RE: SKD2688B DOA 27.01.18

Dear Jenny,

Enclosed preliminary revised of vehicle SKD 2688B

Date of survey: 1/2/2018

Number of days: 10-12 days

We have Not authorise repair.

Kindly let us have your approval and provides us the claim number please.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: LEW JENNY [mailto:jennylew@uoi.com.sg]
Sent: Thursday, 1 February 2018 9:35 AM
To: inthiran.thurasamy@simedarby.com.sg; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: SKD2688B DOA 27.01.18

Dear Inthiran,

We will appoint LKK to conduct the survey.

Dear Shiau Chan,

Please arrange to survey the vehicle at Performance Motors Limited.
Excess: S\$750.00

Thank You.

Warmest Regards
Jenny Lew
Claims Department
United Overseas Insurance Limited
3 Anson Road, #28-01 Springleaf Tower, Singapore 079909 Main . (65) 6222 7733 | DID . (65) 6490 9329 | Fax . (65) 6327 3869 | Email . jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

-----Original Message-----

From: Inthiran Thurasamy [mailto:inthiran.thurasamy@simedarby.com.sg]
Sent: Wednesday, 31 January, 2018 6:20 PM
To: LEE KATIE <katielee@uoi.com.sg>
Subject: SKD2688B DOA 27.01.18

Dear Sir/Madam,

Please see attached for the OD claim and arrange for survey.
The vehicle in workshop, please arrange survey asap.

Thank you.

Warm regards

Inthiran

Customer Service Advisor

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Body & Paint Department

H/P : 81214600

This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent t

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 20 September 2018 11:20 AM
To: 'LEW JENNY'
Cc: LEE KATIE
Subject: RE: SKD2688B DOA 27.01.18
Attachments: PRELI REVISED (WITH SUPPLEMENTARY).pdf; SUPPLEMENTARY.pdf

Dear Jenny,

Enclosed with revised (incl.supplementary).

For your approval please.

Please provide us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Friday, 2 February 2018 3:59 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: SKD2688B DOA 27.01.18

Dear Veron,

Please proceed with the repair authorisation up to S\$28,385.30
Excess: S\$750.00

Warmest Regards

Jenny Lew

Claims Department

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Friday, 2 February, 2018 2:10 PM
To: LEW JENNY <jennylew@uoi.com.sg>; SUR <sur@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: SKD2688B DOA 27.01.18

Dear Jenny,

Enclosed preliminary revised of vehicle SKD 2688B
Date of survey: 1/2/2018
Number of days: 10-12 days

We have Not authorise repair.

Kindly let us have your approval and provides us the claim number please.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: LEW JENNY [mailto:jennylew@uoi.com.sg]
Sent: Thursday, 1 February 2018 9:35 AM
To: inthiran.thurasamy@simedarby.com.sg; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: SKD2688B DOA 27.01.18

Dear Inthiran,

We will appoint LKK to conduct the survey.

Dear Shiau Chan,

Please arrange to survey the vehicle at Performance Motors Limited.
Excess: S\$750.00

Thank You.

Warmest Regards
Jenny Lew
Claims Department
United Overseas Insurance Limited
3 Anson Road, #28-01 Springleaf Tower, Singapore 079909 Main . (65) 6222 7733 | DID . (65) 6490 9329 | Fax . (65) 6327 3869 | Email . jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the

contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

-----Original Message-----

From: Inthiran Thurasamy [mailto:inthiran.thurasamy@simedarby.com.sg]
Sent: Wednesday, 31 January, 2018 6:20 PM
To: LEE KATIE <katielee@uoi.com.sg>
Subject: SKD2688B DOA 27.01.18

Dear Sir/Madam,

Please see attached for the OD claim and arrange for survey.
The vehicle in workshop, please arrange survey asap.

Thank you.

Warm regards
Inthiran
Customer Service Advisor
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Body & Paint Department
H/P : 81214600

This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent t



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED
Our ref: CS/UOI18001987/R1vd3

Date: 20/9/2018

The Motor Claims Department
M/s UNITED OVERSEAS INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKD 2688B


We thank you for your instruction on 1/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 1/2/2018 at the premises of M/s PERFORMANCE MOTORS LTD and have the following to report:-

Workshop Estimate Amount	: S\$32,458.75 (incl.supplementary \$1247)
Revised Estimate Amount	: S\$28,463.50 (incl.supplementary \$1247.00)
"Check" Items Amount	: S\$
Market Value	: S\$128,000.00
LTA Reimbursement Value	: S\$87,643.00
Nett Value	: S\$40,357.00

Description of Damage:

The vehicle sustained damages at the front portion



Comments/Present Status:

Damages Consistent
Repair Cost Economical

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 2 February 2018 4:08 PM
To: Inthiran Thurasamy
Cc: PBSP; SUR
Subject: SKD 2688B-DOA: 27/1/2018 (UOI OD)

Dear Inthiran,

As instructed by our client UOI , please proceed to repair the insured vehicle **SKD 2688B (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Friday, 2 February 2018 3:59 PM
To: Veron Chen (LKKAUTO); SUR
Cc: LEE KATIE
Subject: RE: SKD2688B DOA 27.01.18

Dear Veron,

Please proceed with the repair authorisation up to S\$28,385.30
Excess: S\$750.00

Warmest Regards

Jenny Lew

Claims Department

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Friday, 2 February, 2018 2:10 PM
To: LEW JENNY <jennylew@uoi.com.sg>; SUR <sur@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: SKD2688B DOA 27.01.18

Dear Jenny,

Enclosed preliminary revised of vehicle SKD 2688B

Date of survey: 1/2/2018

Number of days: 10-12 days

We have Not authorise repair.

Kindly let us have your approval and provides us the claim number please.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: LEW JENNY [mailto:jennylew@uoi.com.sg]
Sent: Thursday, 1 February 2018 9:35 AM

To: inthiran.thurasamy@sime-darby.com.sg; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: SKD2688B DOA 27.01.18

Dear Inthiran,

We will appoint LKK to conduct the survey.

Dear Shiau Chan,

Please arrange to survey the vehicle at Performance Motors Limited.
Excess: S\$750.00

Thank You.

Warmest Regards
Jenny Lew
Claims Department
United Overseas Insurance Limited
3 Anson Road, #28-01 Springleaf Tower, Singapore 079909 Main . (65) 6222 7733 | DID . (65) 6490 9329 | Fax . (65) 6327 3869 | Email . jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

-----Original Message-----

From: Inthiran Thurasamy [<mailto:inthiran.thurasamy@sime-darby.com.sg>]
Sent: Wednesday, 31 January, 2018 6:20 PM
To: LEE KATIE <katielee@uoi.com.sg>
Subject: SKD2688B DOA 27.01.18

Dear Sir/Madam,

Please see attached for the OD claim and arrange for survey.
The vehicle in workshop, please arrange survey asap.

Thank you.

Warm regards
Inthiran
Customer Service Advisor
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Body & Paint Department
H/P : 81214600

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 2 February 2018 2:10 PM
To: 'LEW JENNY'; SUR
Cc: LEE KATIE
Subject: RE: SKD2688B DOA 27.01.18
Attachments: SKD 2688B PRELI REVISED.pdf

Dear Jenny,

Enclosed preliminary revised of vehicle SKD 2688B
Date of survey: 1/2/2018
Number of days: 10-12 days

We have Not authorise repair.

Kindly let us have your approval and provides us the claim number please.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: LEW JENNY [mailto:jennylew@uoi.com.sg]
Sent: Thursday, 1 February 2018 9:35 AM
To: inthiran.thurasamy@simedarby.com.sg; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: SKD2688B DOA 27.01.18

Dear Inthiran,

We will appoint LKK to conduct the survey.

Dear Shiau Chan,

Please arrange to survey the vehicle at Performance Motors Limited.
Excess: S\$750.00

Thank You.

Warmest Regards
Jenny Lew
Claims Department
United Overseas Insurance Limited
3-Anson Road, #28-01 Springleaf Tower, Singapore 079909 Main . (65) 6222 7733 | DID . (65) 6490 9329 | Fax . (65) 6327 3869 | Email . jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

-----Original Message-----

From: Inthiran Thurasamy [mailto:inthiran.thurasamy@sime-darby.com.sg]

Sent: Wednesday, 31 January, 2018 6:20 PM

To: LEE KATIE <katielee@uoi.com.sg>

Subject: SKD2688B DOA 27.01.18

Dear Sir/Madam,

Please see attached for the OD claim and arrange for survey.
The vehicle in workshop, please arrange survey asap.

Thank you.

Warm regards

Inthiran

Customer Service Advisor

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Body & Paint Department

H/P : 81214600

This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent t



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED
Our ref: CS/UOI18001987/R1vd3

Date: 2/2/2018

The Motor Claims Department
M/s UNITED OVERSEAS INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKD 2688B


We thank you for your instruction on 1/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 1/2/2018 at the premises of M/s PERFORMANCE MOTORS LTD and have the following to report:-

Workshop Estimate Amount	: S\$	30,947.00
Revised Estimate Amount	: S\$	21,145.80
"Check" Items Amount	: S\$	7,239.50
Market Value	: S\$	128,000.00
LTA Reimbursement Value	: S\$	87,643.00
Nett Value	: S\$	40,357.00

Description of Damage:

The vehicle sustained damages at the front portion



Comments/Present Status:

Damages Consistent
Repair Cost Economical

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Thursday, 1 February 2018 9:35 AM
To: inthiran.thurasamy@simedarby.com.sg; SUR; assignments
Cc: LEE KATIE
Subject: RE: SKD2688B DOA 27.01.18
Attachments: img-131181820-0001.zip

Dear Inthiran,

We will appoint LKK to conduct the survey.

Dear Shiau Chan,

Please arrange to survey the vehicle at Performance Motors Limited.
Excess: S\$750.00

Thank You.

Warmest Regards
Jenny Lew
Claims Department
United Overseas Insurance Limited
3 Anson Road, #28-01 Springleaf Tower, Singapore 079909 Main . (65) 6222 7733 | DID . (65) 6490 9329 | Fax . (65) 6327 3869 | Email . jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

-----Original Message-----

From: Inthiran Thurasamy [mailto:inthiran.thurasamy@simedarby.com.sg]
Sent: Wednesday, 31 January, 2018 6:20 PM
To: LEE KATIE <katielee@uoi.com.sg>
Subject: SKD2688B DOA 27.01.18

Dear Sir/Madam,

Please see attached for the OD claim and arrange for survey.
The vehicle in workshop, please arrange survey asap.

Thank you.

Warm regards
Inthiran
Customer Service Advisor

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Body & Paint Department
H/P : 81214600

This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent t

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2293F
Vehicle Details	
Vehicle No.:	SKD2688B
Vehicle to be Exported:	No
Intended De-registration Date:	02 Feb 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520I AT D/AB 2WD 4DR LED NAV
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	B1380673N20B20B
Chassis No.:	WBA5A32090D335166
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$46,806.00
Original Registration Date:	12 Sep 2014
First Registration Date:	12 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$52,529.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2024
PARF Rebate Amount:	\$39,396.00
Intended COE Rebate Details	
COE Expiry Date:	11 Sep 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):	10
QP Paid:	\$73,010.00
COE Rebate Amount:	\$48,247.00
Total Rebate Amount:	\$87,643.00

The information contained herein is correct as at 02 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/01/2018 21:04
Date Of Accident	27/01/2018 15:15
Exact Location Of Accident	ALONG YIO CHU KANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD2688B
Insured/Policyholder	
Name Of Registered Owner	NG YIAK MENG
NRIC No	S1422293F
Email Address	YMNG2008@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97571727
Alternative Phone No	OFFICE-97571727

Vehicle Particulars

Manufacturer	BMW
Model	520I
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM120024121600
Cover Note Number	NA

Driver

Name of Driver	NG YIAK MENG
NRIC No	S1422293F
Date Of Birth	09/06/1960
Occupation	INDOOR
Date Of Driving Pass	01/12/1978
Driving Experience	39 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97571727
Fax Number	
Contact Number	OFFICE-97571727
Email Address	YMNG2008@YAHOO.COM.SG

Address	FLORIDA PARK, 26 SUNRISE AVENUE
Postcode	806684
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was traveling along Yio Chu Kang Road and it was a slow traffic as there was a congestion ahead. We were waiting for the traffic light to turn green. As the traffic lights turn green, I thought the driver in front of me moved, so I moved forward not realising that the vehicle was stationary. I accidentally hit the front vehicle rear. We exchange particulars. No injury involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDZ1128A
Vehicle Make/Model/Colour	BMW / 740LI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DICKIE CHEW EN LAI
NRIC/Passport Number	S0020558C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

VERIFIED BY AJAX MARS
REPORTING OFFICER
Mohammad Azaly Bin Abdullah
Witnessed by Reporting Centre
Personnel

Sketch Plan



Common Statement

ACCIDENT STATEMENT (2000 characters)

I was traveling along Yio Chu Kang Road and it was a slow traffic as there was a congestion ahead. We we're waiting for the traffic light to turn green. As the traffic lights turn green, I thought the driver in front of me moved, so I moved forward not realising that the vehicle was stationary. I accidentally hit the front vehicle rear.

We exchange particulars.

No injury involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD AZALY BIN ABDULLAH



MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

27 January 2018 at 6:44 PM

27 January 2018 at 6:44 PM

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438160

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45727
Date Estimated : 31/01/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ng Yiak Meng
26 Sunrise Avenue

Singapore 806684

- ACCOUNT - 115

United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower

Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD2688B	D335166	12/09/2014	520iA	0

DESCRIPTION

to replace front bumper, air duct (inner support), headlamp support lh&rh, bonnet and attachments including knock out dent area cause by accident.

Painting front bumper and bonnet.

To supply front emboss number plate.

To replace radiator assembly, fan housing with fan including pressure test, bleed cooling system and conduct checks for leak. (For all models except 7 series).

To replace charge air cooler including conduct checks for leak and proper function.

To replace air con condenser and air con hose including to vacuum system, top up freon gas and check for leak. (For all models except for 7 series).

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To replace both left and right headlights including program and conduct tests for proper function.

To carry out body cavity preservation. (Per panel).

Sundries.

5555 4675 5,850.00

3695 2102 2,336.00

✓ 83.00

~ x ? 702 826.00

~ x 451? 531.00

✓ 852 1,003.00

✓ 150 177.00

✓ 902 1,062.00

✓ 100 118.00

✓ 150.00

Total Labour 1: 12,236.00

DESCRIPTION

CHARGE AIR COOLER
MODULE MOUNT LH

QTY	PRIC
1	609.75
1	73.85

5555 4675 5,850.00
✓ 83.00
~ x ? 702 826.00
~ x 451? 531.00
✓ 852 1,003.00
✓ 150 177.00
✓ 902 1,062.00
✓ 100 118.00
✓ 150.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190128 (AfterSales)
63190130 (AfterSales)
Fax. 64796601 (AfterSales)
64796624 (AfterSales)

Claim No.

Excess S\$ 750

Sign

Authorised

Yes / No

Time

Surveyor's Tel

Authorised Date

SURVEYOR PHOTO BY SURVEYOR Yes / No

P.M.L. Yes / No

Surveyor's E-mail

No. of Working Days Recommend Page No. : 2 of 210-12

Estimate No. : b1 45727
Date Estimated : 31/01/2018
Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD2688B	D335166	12/09/2014	520iA	0

DESCRIPTION	QTY	PRIC	VALUE
MODULE MOUNT RH	1	73.85	73.85
COVER	1	51.05	51.05
RADIATOR	1	967.35	967.35
BONNET	1	2,170.40	2,170.40
SET MOUNTS PDC SENSOR FRT (PDC)	1	31.95	31.95
FRT BUMPER CARRIER	1	668.10	668.10
GRILLE AIR INLET MIDDLE	1	80.65	80.65
GRILLE AIR INLET OPEN LH (LINES)	1	80.00	80.00
GRILLE AIR INLET OPEN LH (LINES)	1	80.00	80.00
FRT SHOCK ABSORBER	1	46.80	46.80
FRT BUMPER LH PROTECTIVE RUBBER STR	1	40.15	40.15
FRT BUMPER RH PROTECTIVE RUBBER STR	1	40.15	40.15
FRT BUMPER PANEL PRIMED (PDC)	1	1,246.40	1,246.40
FRT TOWING LUG COVER PRIMED	1	38.70	38.70
FRT LH GRILLE (BASIS)	1	117.50	117.50
FRT RH GRILLE (BASIS)	1	117.50	117.50
BMW EMBLEM	1	67.80	67.80
RH LOCK BONNET PASSIVE	1	222.60	222.60
BONNET CATCH OPERATOR	1	38.65	38.65
LH LOCK BONNET PASSIVE	1	222.60	222.60
LEVER	1	36.10	36.10
BRACKET	1	18.40	18.40
SUPPORT LH	1	17.95	17.95
SUPPORT RH	1	17.95	17.95
CONNECTION TOP FRT	1	151.55	151.55
CONNECTION TOP REAR	1	151.55	151.55
LH HEADLAMP SUPPORT	1	123.05	123.05
RH HEADLAMP SUPPORT	1	125.35	125.35
AIR DUCT	1	286.35	286.35
LH HEADLIGHT LED TECHNOLOGY	1	4,099.10	4,099.10
RH HEADLIGHT LED TECHNOLOGY	1	4,099.10	4,099.10
CONDENSER AIR CONDITIONING	1	1,003.35	1,003.35
DECOUPLING RING PDC TORQUE CONVERTE	2	5.05	10.10
BUMPER PDC SENSOR (A89 IMPERIALBLAU)	2	368.80	737.60

Total Parts : 18,711.00

18,389.75

33,458.75

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Labour 1	:	12,236.00
Parts	:	18,711.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,166.29
Grand Total	:	33,113.29

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45727
Date Estimated : 31/01/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Ng Yiak Meng
26 Sunrise Avenue

- ACCOUNT - 115
United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower

Singapore 079909

Singapore 806684

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE
SKD2688B	D335166	12/09/2014	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.25	4.00		5.00 <i>ne</i>
# UNION *	21.70	1.00		21.70 <i>ne</i>
# AIR CHANNEL (5-8) *	34.40	1.00		34.40 <i>cut</i>
# PLUG *	5.10	2.00		10.20 <i>ne</i>
# CLIP *	2.15	2.00		4.30 <i>ne</i>
# FRT BUMPER LH CONNECTOR *	5.00	1.00		5.00 <i>car</i>
# FRT BUMPER RH CONNECTOR *	21.70	1.00		21.70 <i>car</i>
# SUPPORT *	5.00	1.00		5.00 <i>ne</i>
# GRILLE AIR INLET OPEN RH (LINES) *	68.30	1.00		68.30 <i>car</i>
# LEVER LH *	7.20	1.00		7.20 <i>ne</i>
# LH UPPER LOCK SECTION *	66.90	1.00		66.90 <i>ne</i>
# RH UPPER LOCK SECTION *	66.90	1.00		66.90 <i>ne</i>
# COVER RIGHT *	10.95	1.00		10.95 <i>car</i>
# FRT RH LOCATOR SEAL *	56.80	1.00		56.80 <i>ne</i>
# WIRING SET PDC FRT *	105.25	1.00		105.25 <i>ne</i>
# LH HIGH PRESSURE NOZZLE *	179.30	1.00		179.30 <i>car</i>
# GASKET SET *	43.95	2.00		87.90 <i>ne</i>
# BUMPER PDC SENSOR (A89 IMPERIABLAU) *	368.80	1.00		368.80 <i>Rept X</i>
# NOTICE SAFETY CATCH *	23.80	1.00		23.80 <i>ne</i>

Total Labour :	
Total Parts :	1,149.40
Total Labour & Parts :	1,149.40

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020061-X



FINAL REPORT

# SUPPORT *	16.60	1.00	16.60	(A) nec
GRILLE AIR INLET MIDDLE	80.65	1.00	80.65	
GRILLE AIR INLET OPEN LH (LINES)	80.00	1.00	80.00	
# GRILLE AIR INLET OPEN RH (LINES) *	68.30	1.00	68.30	(A) CQ
FRT SHOCK ABSORBER	48.00	1.00	48.00	
# LEVER LH *	7.20	1.00	7.20	(A) BT
FRT BUMPER LH PROTECTIVE RUBBER STR	41.15	1.00	41.15	
FRT BUMPER RH PROTECTIVE RUBBER STR	41.15	1.00	41.15	
FRT BUMPER PANEL PRIMED (PDC)	1,277.55	1.00	1,277.55	
FRT LH GRILLE (BASIS)	120.50	1.00	120.50	
FRT RH GRILLE (BASIS)	120.50	1.00	120.50	
BMW EMBLEM	69.50	1.00	69.50	
RH LOCK BONNET PASSIVE	184.00	1.00	184.00	
# LH UPPER LOCK SECTION *	66.90	1.00	66.90	{CA} BT
# RH UPPER LOCK SECTION *	66.90	1.00	66.90	{CA} BT
LH LOCK BONNET PASSIVE	184.00	1.00	184.00	
SUPPORT LH	18.40	1.00	18.40	
SUPPORT RH	18.40	1.00	18.40	
CONNECTION TOP FRT	155.35	1.00	155.35	
LH HEADLAMP SUPPORT	126.10	1.00	126.10	
RH HEADLAMP SUPPORT	128.45	1.00	128.45	
# COVER RIGHT *	10.95	1.00	10.95	(A) CQ
AIR DUCT	293.50	1.00	293.50	
# FRT RH LOCATOR SEAL *	56.80	1.00	56.80	
# WIRING SET PDC FRT *	105.25	1.00	105.25	{nec nec(A) CQ nec}
# LH HIGH PRESSURE NOZZLE *	179.30	1.00	179.30	
# GASKET SET *	43.95	2.00	87.90	
LH HEADLIGHT LED TECHNOLOGY	4,201.60	1.00	4,201.60	
RH HEADLIGHT LED TECHNOLOGY	4,201.60	1.00	4,201.60	
CONDENSER AIR CONDITIONING	1,028.45	1.00	1,028.45	
DECOUPLING RING PDC TORQUE CONVERTE	5.05	2.00	10.10	
BUMPER PDC SENSOR (A89 IMPERIABLAU)	368.80	1.00	368.80	
# BUMPER PDC SENSOR (A89 IMPERIABLAU) *	368.80	1.00	368.80	
# NOTICE SAFETY CATCH *	23.80	1.00	23.80	(A) BT

SUPPLEMENTARY ITEMS

Total Labour :	11,457.00
Total Parts :	17,006.50
Total Labour & Parts :	28,463.50
Deduction for Excess :	750.00
Total Repair Costs less Excess:	27,713.50
GST @7%:	1,939.95
Grand Total :	29,653.45

8-18-20

Performance Motors Limited

A member of the Sirra Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45727
Date Estimated : 31/01/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Ng Yiak Meng
26 Sunrise Avenue

- ACCOUNT - 115
United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower

Singapore 079909

Singapore 806684

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKD2688B	D335166	12/09/2014	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.25	4.00		5.00 ncl
# UNION *	21.70	1.00		21.70 ncl
# AIR CHANNEL (5-8) *	34.40	1.00		34.40 cut
# PLUG *	5.10	2.00		10.20 ncl
# CLIP *	2.15	2.00		4.30 ncl
# FRT BUMPER LH CONNECTOR *	57.95	1.00		57.95 csa
# FRT BUMPER RH CONNECTOR *	54.75	1.00		54.75 csa
# SUPPORT *	16.60	1.00		16.60 ncl
# GRILLE AIR INLET OPEN RH (LINES) *	68.30	1.00		68.30 csa
# LEVER LH *	7.20	1.00		7.20 bt
# LH UPPER LOCK SECTION *	66.90	1.00		66.90 bt
# RH UPPER LOCK SECTION *	66.90	1.00		66.90 bt
# COVER RIGHT *	10.95	1.00		10.95 csa
# FRT RH LOCATOR SEAL *	56.80	1.00		56.80 ncl
# WIRING SET PDC FRT *	105.25	1.00		105.25 ncl
# LH HIGH PRESSURE NOZZLE *	179.30	1.00		179.30 csa
# GASKET SET *	43.95	2.00		87.90 ncl
# BUMPER PDC SENSOR (A89 IMPERIABLAU) *	368.80	1.00		368.80 rept x
# NOTICE SAFETY CATCH *	23.80	1.00		23.80 bt

Total Labour :	
Total Parts :	1,247.00
Total Labour & Parts :	1,247.00

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 20 September 2018 5:36 PM
To: 'PBSP'; SUR
Subject: RE: REVISED SUPPLEMENTARY / SKD2688B

Dear Caroline,

Confirmed amount \$ 28,463.50 before excess \$750 and GST

No of days: 10 days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Wednesday, 19 September 2018 4:16 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: REVISED SUPPLEMENTARY / SKD2688B

Dear Veron

We refer to the above and attached revised Supplementary.

Please confirm COR as follows:

Total Labour : 11,457.00
Total Parts : 17,006.50
Total Labour & Parts : 28,463.50

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI18001987/R1vd3e2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date : 18-10-2018	
			Code : UOI2	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.			Veh. Inspected	SKD 2688B
Policy No.	DHOM120024121600		Coverage (\$)	0.00
Claim No.	M12D07211802		Excess (\$)	750.00
Assign From	JENNY LEW		Assign Date	01/02/2018
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 520i		c.c	1997
Engine No.	HIDDEN		Year of Reg.	2014
Chassis No.	WBA5A32090D335166		Colour	BLUE
Odometer	79611		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45 R18	CONTINENTAL	6 mm	
L/H Front Tyre	235/45 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	235/45 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	235/45 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/01/2018		Inspection Date	01/02/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE MARKET VALUE IS S\$128,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 2688B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT EMBOSS NUMBER PLATE (SN)	BENT	83.00	83.00
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	MODULE MOUNT RH (SN)	SERVICEABLE	73.85	-
1	COVER (SN)	CRACKED	52.30	52.30
1	RADIATOR (SN)	SERVICEABLE	967.35	-
1	BONNET (SN)	BUCKLED	2,224.70	2,224.70
1	SET MOUNTS PDC SENSOR FRT (PDC) (SN)	NOT NECESSARY	31.95	-
1	FRT BUMPER CARRIER (SN)	BENT	684.75	684.75
1	GRILLE AIR INLET MIDDLE (SN)	CRACKED	80.65	80.65
1	GRILLE AIR INLET OPEN LH (LINES) (SN)	CRACKED	80.00	80.00
1	GRILLE AIR INLET OPEN LH (LINES) (SN)	SERVICEABLE	80.00	-
1	FRT SHOCK ABSORBER (SN)	CRACKED	48.00	48.00
1	FRT BUMPER LH PROTECTIVE RUBBER STR (SN)	NECESSARY	41.15	41.15
1	FRT BUMPER RH PROTECTIVE RUBBER STR (SN)	NECESSARY	41.15	41.15
1	FRT BUMPER PANEL PRIMED (PDC) (SN)	DEFORMED	1,277.55	1,277.55
1	FRT TOWING LUG COVER PRIMED (SN)	SERVICEABLE	38.70	-
1	FRT LH GRILLE (BASIS) (SN)	CRACKED	120.50	120.50
1	FRT RH GRILLE (BASIS) (SN)	CRACKED	120.50	120.50
1	BMW EMBLEM (SN)	NECESSARY	69.50	69.50
1	RH LOCK BONNET PASSIVE (SN)	BENT	222.60	184.00
1	BONNET CATCH OPERATOR (SN)	SERVICEABLE	38.65	-
1	LH LOCK BONNET PASSIVE (SN)	BENT	222.60	184.00
1	LEVER (SN)	SERVICEABLE	36.10	-
1	BRACKET (SN)	SERVICEABLE	18.40	-
1	SUPPORT LH (SN)	CRACKED	18.40	18.40
1	SUPPORT RH (SN)	CRACKED	18.40	18.40
1	CONNECTION TOP FRT (SN)	CRACKED	155.35	155.35
1	CONNECTION TOP REAR (SN)	SERVICEABLE	151.55	-
1	LH HEADLAMP SUPPORT (SN)	BENT	126.10	126.10
1	RH HEADLAMP SUPPORT (SN)	BENT	128.45	128.45
1	AIR DUCT (SN)	CRACKED	293.50	293.50
1	LH HEADLIGHT LED TECHNOLOGY (SN)	BROKEN	4,201.60	4,201.60
1	RH HEADLIGHT LED TECHNOLOGY (SN)	BROKEN	4,201.60	4,201.60
1	CONDENSER AIR CONDITIONING (SN)	BENT	1,028.45	1,028.45

Report Ref No. CS/UOI18001987/R1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NECESSARY-2PCS ONLY	20.20	10.10
4	BUMPER PDC SENSOR (A89 IMPERIABLAU) (SN)	NOT WORKING-2PCS ONLY	1,475.20	737.60
4	BLIND RIVET (SN) (ADDITIONAL)	NECESSARY	5.00	5.00
1	UNION (SN) (ADDITIONAL)	NECESSARY	21.70	21.70
1	AIR CHANNEL (5-8) (SN) (ADDITIONAL)	CUT	34.40	34.40
2	PLUG (SN) (ADDITIONAL)	NECESSARY	10.20	10.20
2	CLIP (SN) (ADDITIONAL)	NECESSARY	4.30	4.30
1	FRT BUMPER LH CONNECTOR (SN) (ADDITIONAL)	CRACKED	57.95	57.95
1	FRT BUMPER RH CONNECTOR (SN) (ADDITIONAL)	CRACKED	54.75	54.75
1	SUPPORT (SN) (ADDITIONAL)	NECESSARY	16.60	16.60
1	GRILLE AIR INLET OPEN RH (LINES) (SN) (ADDITIONAL)	CRACKED	68.30	68.30
1	LEVER LH (SN) (ADDITIONAL)	BENT	7.20	7.20
1	LH UPPER LOCK SECTION (SN) (ADDITIONAL)	BENT	66.90	66.90
1	RH UPPER LOCK SECTION (SN) (ADDITIONAL)	BENT	66.90	66.90
1	COVER RIGHT (SN) (ADDITIONAL)	CRACKED	10.95	10.95
1	FRT RH LOCATOR SEAL (SN) (ADDITIONAL)	NECESSARY	56.80	56.80
1	WIRING SET PDC FRT (SN) (ADDITIONAL)	NECESSARY	105.25	105.25
1	LH HIGH PRESSURE NOZZLE (SN) (ADDITIONAL)	CRACKED	179.30	179.30
2	SET GASKET (SN) (ADDITIONAL)	NECESSARY	87.90	87.90
1	NOTICE SAFETY CATCH (SN) (ADDITIONAL)	BENT	23.80	23.80
1	CHARGE AIR COOLER (SN)	SERVICEABLE	609.75	-
1	MODULE MOUNT LH (SN)	SERVICEABLE	73.85	-
			20,184.55	17,239.50
	LABOUR			
	TO REPLACE FRONT BUMPER, AIR DUCT (INNER SUPPORT), HEADLAMP SUPPORT LH & RH, BONNET AND ATTACHEMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT.		5,950.00	5,525.00
	PAINTING FRONT BUMPER AND BONNET.		3,695.00	3,695.00
	TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM AND CONDUCT CHECKS FOR LEAK. (FOR ALL MODELS EXCEPT 7 SERIES)	NOT NECESSARY	826.00	-
	TO REPLACE CHARGE AIR COOLER INCLUDING CONDUCT CHECKS FOR LEAK AND PROPER FUNCTION.	NOT NECESSARY	531.00	-

Report Ref No. CS/UOI18001987/R1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING TO VACUUM SYSTEM, TOP UP FREON GAS AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT FOR 7 SERIES)		1,003.00	852.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.		177.00	150.00
	TO REPLACE BOTH LEFT AND RIGHT HEADLIGHTS INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION.		1,062.00	902.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)		118.00	100.00
			13,362.00	11,224.00
GRAND TOTAL			33,546.55	28,463.50
RECOMMENDED COST OF REPAIRS				28,463.50
LESS EXCESS				-750.00
NETT LIABILITY				27,713.50

Report Ref No. CS/UOI18001987/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.