

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

APPOINTED L.B.S AUTOMOTIVE APPRAISAL PTE LTD

Policy Particulars: - THIRD PARTY DAMAGED CLAIM

Insured veh.	SJJ6504C	Excess.	\$ -
Policy No.	B29055450 MCX	Coverage.	Comprehensive
Claiming Against.	SKH9612C AXA		
Insured Under.	MSIG		

Vehicle Particulars & Condition

Make & Model	Toyota Vios
Engine No.	1NZX785740
Chassis No.	MR053HY9305074891
Odometer	
Engine CC.	1497
Year Of Reg.	2008
Colour.	Silver
Parf/COE Rebate.	\$ 7,538.00

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Rear portion damaged.

General Information

Accident Date. 18/1/2018
Survey held at

Yew Tee Automobile Tech Pte Ltd
SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S(417800)

Remarks

A) THE SURVEY WAS CONDUCTED ON A "LUMPSUM" BASIS
KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	Rear bumper	\$ 383.66
1	Boot lid	\$ 554.60
1	Rear end panel	\$ 595.85
	List	\$ 1,534.11
	Less 25%	\$ 383.53
	Total	\$ 1,150.58
1	Rear bumper side retainer LH	\$ 56.70
1	Rear bumper bracket LH	\$ 95.90
1	Rear bumper reflector LH	\$ 92.90
1	Boot lid hinges LH	\$ 49.20
1	Boot lid hinges RH	\$ 49.20
1	Boot lid rubber	\$ 175.40
1	Boot lid lock	\$ 145.60
1	Boot lid lock catch	\$ 89.00
1	Boot lid logo	\$ 32.60
1	Boot lid "VIOS" emblem	\$ 50.55
1	Boot lid "E" emblem	\$ 38.90
1	Boot lid outer garnish	\$ 187.00
1	Rear taillamp LH	\$ 320.00
1	Rear taillamp gasket LH	\$ 60.50
1	Rear taillamp panel LH	\$ 160.90
1	Rear end panel inner garnish	\$ 177.72
1	Rear spare tyre board	\$ 330.50
	Nett	\$ 2,112.57
	Less 10%	\$ 211.26
	Total	\$ 1,901.31
1	Rear bumper clips (1 set)	\$ 45.00
1	Rear bumper lower spoiler	\$ 680.00
1	Rear bumper reverse sensor (1 set)	\$ 220.00
1	Rear number plate	\$ 45.00
2	Rear taillamp clips	\$ 16.00
1	Rear end panel inner garnish clips (1 set)	\$ 35.00
	S/N	\$ 1,041.00

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 30.00
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 30.00
	To remove and refit rear bumper sensors.	\$ 80.00
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 700.00
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 700.00
	LABOUR	<u>\$ 1,540.00</u>
	Sub Total.	\$ 5,632.90
	7% GST	\$ 394.30
	Grand Total	<u><u>\$ 6,027.20</u></u>

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.