



Policy No : 8-V0014300-MVA-R001

Date of Accident : 29 January 2018

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department

QBE Insurance (Singapore) Pte Ltd

1 Raffles Quay #29-01

South Tower

Singapore 048583

Date : 30 January 2018

Estimate To Repair WC3086U - Mitsubishi FV51JKM4RDEA

Chassis No : FV51JKA00059

S/No	Quantity	Description	Amount
		<u>Cost</u>	
01	1 pc	front windscreen glass	\$ 0.00
02	1 pc	front windscreen glass weatherstrip	\$ 0.00
03	1 pc	front windscreen glass ERP bracket	\$ 0.00
04	1 pc	wiper panel	\$ 0.00
05	1 set	wiper linkage	\$ 0.00
06	1 pc	o/s wiper arm	\$ 0.00
07	1 pc	o/s wiper blade	\$ 0.00
08	1 pc	o/s wiper arm cover	\$ 0.00
09	1 pc	wiper arm centre	\$ 0.00
10	1 pc	wiper arm centre cover centre	\$ 0.00
11	1 pc	wiper blade centre	\$ 0.00
12	1 pc	n/s wiper blade centre	\$ 0.00
13	1 pc	n/s wiper arm	\$ 0.00
14	1 pc	n/s wiper arm cover	\$ 0.00
15	1 pc	n/s wiper arm blade	\$ 0.00
16	1 pc	wiper motor	\$ 0.00
17	1 pc	instrument dashboard	\$ 0.00
18	1 pc	instrument dashboard reinforcement	\$ 0.00
19	1 pc	instrument cluster facia lower outer n/s	\$ 0.00
20	1 pc	n/s instrument radio centre facia inner	\$ 0.00
21	1 pc	instrument speedo-meter facia	\$ 0.00
22	1 pc	instrument centre console box	\$ 0.00
23	1 pc	o/s instrument cluster facia	\$ 0.00
24	1 pc	speedo meter assy	\$ 0.00
25	1 pc	air-con evaporator assy	\$ 0.00
26	1 pc	air-con blower assy	\$ 0.00
27	1 pc	heater unit assy	\$ 0.00
28	2 ps	radiator bottom brackets @ \$.00	\$ 0.00
29	1 pc	air-con condenser main	\$ 0.00
30	1 pc	air-con condenser sub	\$ 0.00
31	1 pc	air-con liquid pipe	\$ 0.00
32	1 pc	air-con suction hose	\$ 0.00
33	1 pc	air-con liquid pipe	\$ 0.00
34	1 pc	horn	\$ 0.00
35	1 pc	turbo inter cooler assy	\$ 0.00
36	1 pc	turbo charger assy	\$ 0.00
37	2 ps	engine mounts @ \$.00	\$ 0.00



Policy No : 8-V0014300-MVA-R001
Date of Accident : 29 January 2018

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department
QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay #29-01
South Tower
Singapore 048583

Date : 30 January 2018

Estimate To Repair WC3086U - Mitsubishi FV51JKM4RDEA
Chassis No : FV51JKA00059

S/No	Quantity	Description	Amount
		<u>Cost</u>	
38	1 pc	gearbox mount	\$ 0.00
39	1 pc	cabin turn over rod	\$ 0.00
40	2 ps	cabin turn over dampers @ \$.00	\$ 0.00
41	2 ps	cabin turn over rod mount @ \$.00	\$ 0.00
42	1 pc	front centre brace panel	\$ 0.00
43	1 pc	heater hose inlet	\$ 0.00
44	1 pc	heater hose outlet	\$ 0.00
45	4 ps	brake pipe @ \$.00	\$ 0.00
46	1 pc	brake pipe fluid	\$ 0.00
47	1 pc	brake propation valve	\$ 0.00
48	1 pc	brake fluid	\$ 0.00
49	1 pc	gear selector linkage	\$ 0.00
50	1 pc	gear selector cable	\$ 0.00
51	2 ps	cabin mount bracket upper @ \$.00	\$ 0.00
52	2 ps	cabin mount balow @ \$.00	\$ 0.00
53	2 ps	cabin mount pump @ \$.00	\$ 0.00
54	1 pc	front body panel	\$ 0.00
55	1 pc	front body panel air vent outer	\$ 0.00
56	1 pc	front body panel air vent inner	\$ 0.00
57	1 pc	n/s front corner panel	\$ 0.00
58	1 pc	n/s front corner panel weatherstrip outer	\$ 0.00
59	1 pc	n/s front corner panel weatherstrip inner	\$ 0.00
60	1 pc	n/s front corner panel bracket	\$ 0.00
61	1 pc	n/s front corner panel indication lamp	\$ 0.00
62	1 pc	n/s front corner panel lower rubber	\$ 0.00
63	1 pc	front bumper	\$ 0.00
64	1 pc	front bumper upper centre garnish	\$ 0.00
65	2 ps	front bumper spot lamps @ \$.00	\$ 0.00
66	2 ps	front bumper spot lamp garnish @ \$.00	\$ 0.00
67	2 ps	front bumper side pad @ \$.00	\$ 0.00
68	2 ps	front bumper air scoop @ \$.00	\$ 0.00
69	1 pc	front bumper centre cross-member	\$ 0.00
70	2 ps	front bumper stays @ \$.00	\$ 0.00
71	1 pc	windscreen washer tank	\$ 0.00
72	1 pc	windscreen washer tank motor	\$ 0.00
73	1 pc	radiator assy	\$ 0.00
74	1 pc	radiator expansion tank	\$ 0.00



Policy No : 8-V0014300-MVA-R001

Date of Accident : 29 January 2018

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department

QBE Insurance (Singapore) Pte Ltd

1 Raffles Quay #29-01

South Tower

Singapore 048583

Date : 30 January 2018

Estimate To Repair WC3086U - Mitsubishi FV51JKM4RDEA

Chassis No : FV51JKA00059

S/No	Quantity	Description	Amount
		<u>Cost</u>	
75	1 pc	radiator top hose	\$ 0.00
76	1 pc	radiator bottom hose	\$ 0.00
77	1 pc	radiator fan shroud	\$ 0.00
78	1 pc	radiator fan blade	\$ 0.00
79	1 pc	radiator fan clutch	\$ 0.00
80	2 ps	n/s aircon louver @ \$.00	\$ 0.00
81	1 pc	n/s aircon louver facia	\$ 0.00
82	1 pc	aircon louver duct-hose	\$ 0.00
83	2 ps	aircon louver centre @ \$.00	\$ 0.00
84	1 pc	o/s aircon lower side	\$ 0.00
85	1 pc	roof panel	\$ 0.00
86	1 pc	roof head-lining	\$ 0.00
87	1 pc	o/s sunvisor	\$ 0.00
88	1 pc	o/s roof-glove box assy	\$ 0.00
89	1 pc	cabin view mirror	\$ 0.00
90	1 pc	roof-interior light assy	\$ 0.00
91	2 ps	front windscreen "A" pillar inner grille @ \$.00	\$ 0.00
92	1 pc	engine - ECU assy	\$ 0.00
93	1 pc	front hood	\$ 0.00
94	2 ps	front hood hinges @ \$.00	\$ 0.00
95	2 ps	front hood hinge handle @ \$.00	\$ 0.00
96	2 ps	front hood lock @ \$.00	\$ 0.00
97	2 ps	front hood lock cable @ \$.00	\$ 0.00
98	1 pc	front hood-emblem badge (fuso)	\$ 0.00
99	1 pc	front hood upper grille	\$ 0.00
100	1 pc	front hood lower grille	\$ 0.00
101	2 ps	front hood damper stays @ \$.00	\$ 0.00
102	2 ps	front hood rubber stoppers @ \$.00	\$ 0.00
103	1 pc	front hood weatherstrip	\$ 0.00
104	1 pc	front hood lower grille diamond badge	\$ 0.00
105	1 pc	n/s front hood air dam panel	\$ 0.00
106	2 ps	headlamps @ \$.00	\$ 0.00
107	2 ps	headlamp brackets @ \$.00	\$ 0.00
108	2 ps	headlamp stays @ \$.00	\$ 0.00
109	1 pc	n/s front door	\$ 0.00
110	1 pc	n/s front door hinge top	\$ 0.00
111	1 pc	n/s front door hinge bottom	\$ 0.00



Policy No : 8-V0014300-MVA-R001

Date of Accident : 29 January 2018

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department

QBE Insurance (Singapore) Pte Ltd

1 Raffles Quay #29-01

South Tower

Singapore 048583

Date : 30 January 2018

Estimate To Repair WC3086U - Mitsubishi FV51JKM4RDEA

Chassis No : FV51JKA00059

S/No	Quantity	Description	Amount
		<u>Cost</u>	
112	1 pc	n/s front door marker lamp	\$ 0.00
113	1 pc	n/s front door weatherstrip	\$ 0.00
114	1 pc	n/s front door inner trimboard	\$ 0.00
115	1 pc	n/s front door inner lock	\$ 0.00
116	1 pc	n/s front door inner lock stricker	\$ 0.00
117	1 pc	n/s front door lower finisher-rubber	\$ 0.00
118	1 pc	n/s front door window glass channel weatherstrip	\$ 0.00
119	1 pc	n/s front door outer weatherstrip moulding	\$ 0.00
120	1 pc	n/s front door step apron garnish upper	\$ 0.00
121	1 pc	n/s front door step cast iron plate upper	\$ 0.00
122	1 pc	n/s front door step cast iron plate lower	\$ 0.00
123	1 pc	n/s front door step apron garnish lower	\$ 0.00
124	1 pc	n/s front wheel arc garnish	\$ 0.00
125	1 pc	n/s front wheel arc flace	\$ 0.00
126	1 pc	n/s front wheel mudguard	\$ 0.00
			\$ 0.00
		Add 15 %	\$ 0.00
			\$ 0.00
		<u>Cost</u>	
127	1 set	sundries and clips	\$ 250.00
128	1 pc	front licence plate	\$ 80.00
129	1 pc	radiator coolant	\$ 25.00
130	1 pc	n/s front door view glass sealant	\$ 80.00
			\$ 435.00
		Add 15 %	\$ 65.25
			\$ 500.25
		<u>LABOUR & MISC. CHARGES</u>	
01		Towing charges.	\$ 250.00
02		To remove and refit front windscreen glass.	\$ 400.00
03		To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	\$ 1,000.00
04		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 550.00
05		To remove cabin front assy to facilitate repair assy.	\$ 1,800.00
06		To correct both front chassis frame to simulation position with the hydraulic pneumatic.	\$ 3,500.00
07		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 680.00
08		Check side slip	\$ 150.00



Policy No : 8-V0014300-MVA-R001
Date of Accident : 29 January 2018

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department
QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay #29-01
South Tower
Singapore 048583

Date : 30 January 2018

Estimate To Repair WC3086U - Mitsubishi FV51JKM4RDEA

Chassis No : FV51JKA00059

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
09		To remove and renew engine and gearbox mountings.	\$ 350.00
10		To transfer of door fittings and perform water seepage test.	\$ 120.00
11		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 4,800.00
12		Putty and spray painting of the affected portion.	\$ 3,800.00
			\$ 17,400.00
		Total	\$ 17,900.25

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2018 17:24
Date Of Accident	29/01/2018 15:00
Exact Location Of Accident	SENGKANG WEST ROAD X SENGKANG INDUSTRIAL AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	WC3086U
Insured/Policyholder	
Name Of Registered Owner	SINMIX PTE LTD
Co Reg No	200705861H
Email Address	CHEWHONG.SEE@SINMIX.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65011627

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FV51JKM4RDEA
Exact Purpose for which vehicle was being used at time of accident	CEMENT TRUCK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	8-V0014300-MVA-R001
Cover Note Number	22/11/2017 TO 30/11/2020

Driver

Name of Driver	CHEW PENG WENG
NRIC No	S1418180F
Date Of Birth	21/09/1960
Occupation	OUTDOOR
Date Of Driving Pass	21/04/1983
Driving Experience	34 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86618719
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLOCK 31 BENDEMEER ROAD #12-847
Postcode	330031
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 29/01/2018 at about 1500hrs, I was driving my vehicle (A: WC3086U) on the second lane from right along Sengkang West Road turning right into Sengkang Industrial Avenue 1. Suddenly the vehicle (B: WC5400H) which was travelling in front of me make an emergency stop, I immediately applied my brake to avoid collision but to not avail. Thus, my vehicle's front portion hit onto rear portion of vehicle B. Nobody was injured in this accident. Both vehicles have no passenger on board.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC5400H
Vehicle Make/Model/Colour	
Details Of Properties	CEMENT TRUCK
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SHEIK ISMAIL MUZEEBUR RAHIMAN
NRIC/Passport Number	G5245027L
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR PORTION
No. Of Passenger (Including Driver)	1


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 26/11/18


Driver's Signature
(If driver is not the policyholder)
Date & Time: 29/01/18 @ 1740h


Reporting Centre Personnel's Signature
Name: Lam Mei Shun
NRIC/FIN No.: 96864052K

Sketch Plan Pg. 2

SKETCH PLAN

EPG Lang. Incident
Overseas

Seagulls West Road

A: WC 30863

B: WC 5400H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to GIA report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 20/1/18

Driver's Signature

(If driver is not the policyholder)

Date & Time: 29/01/18 17:40h

Reporting Centre Personnel's Signature

Name: Tan Wei Sheng


NRIC/FIN No.: 65864052R

10 Sin Ming Drive Singapore 575701
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5829

12 Sep 2009

Our ref 1209090401N004018009

SINMIX PTE LTD
25 PLAYFAIR ROAD
LIAN BENG BUILDING
SINGAPORE 367990



Dear MR ONG PHANG HUI

NOTIFICATION OF SUCCESSFUL VEHICLE CONVERSION FOR VEHICLE NO. WC3086U

We are pleased to inform you that your vehicle, WC3086U, has been successfully converted from B30 - Goods (Open) Lorry (Wooden Body)/Normal to B69 - Goods (Open) Concrete Mixer/Cement Mixer/Normal with effect from 12 Sep 2009.

2. The owner particulars are as follows:

- | | | |
|----|-------------------------|------------------|
| 1. | Name | : SINMIX PTE LTD |
| 2. | Identification No. Type | : Company |
| 3. | Identification No. | : 200705861H |
| 4. | Place Of Passport Issue | : - |

3. The updated vehicle information is as follows:

- | | | |
|-----|--------------------------------------|--|
| 1. | Vehicle No. | : WC3086U |
| 2. | Previous Vehicle No. | : XD3590M |
| 3. | Effective Date of Ownership | : 07 Sep 2009 |
| 4. | Original Registration Date | : 07 Sep 2009 |
| 5. | First Registration Date | : 07 Sep 2009 |
| 6. | Vehicle Type | : B69 - Goods (Open) Concrete Mixer/Cement Mixer |
| 7. | Vehicle Scheme | : Normal |
| 8. | Attachment 1 | : No Attachment |
| 9. | Attachment 2 | : - |
| 10. | Attachment 3 | : - |
| 11. | Vehicle Make Description | : MITSUBISHI |
| 12. | Vehicle Model | : FV51JKM4RDEA |
| 13. | Year of Manufacture | : 2008 |
| 14. | Primary Colour | : White |
| 15. | Secondary Colour | : - |
| 16. | Passenger Capacity | : 2 |
| 17. | Chassis/Trailer Chassis No. | : FV51JKA00059 / - |
| 18. | Propellant | : Diesel |
| 19. | Engine No./Motor No. | : 6M70414299 / - |
| 20. | Engine Capacity(cc)/Power Rating(kw) | : 12882 / - |
| 21. | Unladen Weight(kg) | : 12020 |
| 22. | Maximum Laden Weight(kg) | : 28000 |
| 23. | Open Market Value | : \$86,824.00 |



24.	PARF Eligibility	: No
25.	PARF Eligibility Expiry Date	: -
26.	Minimum PARF Benefit	: -
27.	No. of Transfers	: 0
28.	IU Label No.	: 2010397584
29.	COE No.	: 2009080107000063W
30.	COE Expiry Date	: 06 Sep 2019
31.	COE Category	: E - Open Category
32.	Quota Premium/Prevailing Quota Premium	: \$17,501.00
33.	Actual Quota Premium/PQP Paid	: \$17,501.00
34.	Actual ARF Paid	: \$4,342.00
35.	Vehicle Lifespan Expiry Date	: -
36.	Nett Road Tax Amount	: -
37.	Road Tax Start Date	: -
38.	Road Tax End Date	: -
39.	Remarks	: COE rebate, if applicable, will be based on the QP of \$16,888.00. This is the lower of QP from Category E and the corresponding Category C in the same tender exercise. To renew the COE, the Prevailing Quota Premium payable is that of Category C.

4. Other information pertaining to the conversion is as follows:

- Please note that you are required to replace the existing vehicle number plate with the new vehicle number plate bearing the replaced vehicle number by 15 Sep 2009.

5. Please contact our customer service officers at tel: 1800-CALL LTA (1800-2255 582) should you require further assistance.

6. Thank you.

Yours sincerely

NG LAY CHOO (MS)
DEPUTY DIRECTOR, VRL SERVICE OPERATIONS
VEHICLE & TRANSIT LICENSING GROUP
LAND TRANSPORT AUTHORITY

(This is a computer-generated notice that requires no signature.)