



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SKZ 899 G

Finalised

Parts	(a) Cost / List Price Items	\$	5,798.00
	Plus/Less <u>20% 10%</u>	\$	1,159.60
	Total of Cost / List	\$	4,638.40
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	700.00
Total Parts Cost		\$	5,338.40
Labour		\$	2,000.00
Total		\$	7,338.40

1595

319

1276 1435.50

Not Authorised

Running B4 paint

680

1456 2115.50

The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kenneth

Company

:

UKK

Survey conducted on

:

6/2/17

at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

:

Le

Date:

6/2/18



ESTEEM PERFORMANCE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SKZ 899 G**
Make & Model : **MERC E200**
Chassis No : **WDD2130422A230581**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	4	\$700.00	S.N	✓
2	Rear bumper <i>Bn</i>	1	\$1,530.00		✓
3	Rear bumper clip <i>Nk</i>	10	\$65.00		✓
4	Rear bumper side retainer LH <i>Sn</i>	1	\$105.00		✗
5	Rear bumper side retainer RH <i>Sn</i>	1	\$105.00		✓
6	Rear bumper bracket LH <i>R</i>	1	\$75.00		✗
7	Rear bumper bracket RH <i>R</i>	1	\$75.00		✗
8	Rear bumper sponge <i>Sn</i>	1	\$95.00		✗
9	Rear bumper reinforcement <i>R</i>	1	\$765.00		✗
10	Bootlid <i>R</i>	1	\$2,207.00		✓
11	Bootlid lock <i>R</i>	1	\$288.00		✗
12	Bootlid emblem <i>nn</i>	1	\$55.00		✗
13	Wording "E200" <i>nn</i>	1	\$166.00		✓
14	Bootlid chrome <i>nn</i>	1	\$267.00		✗
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Vehicle No. : SKZ 899 G
Make & Model : MERC E200

Submit By : Carmen Lim
Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.