

INS. CASE OWNER:

Irene

CC3 / CTI180 02006 / K1h3n2

LKK:

IDAC:

Surveyor:

KALVIN

DOI:

31/01/18

Date / Time:

31/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Q80 5097T

Name of Insured:

LEAP TILING PTE LTD

Insured Tel No.:

HP:

Claim No.:

SNM18D00582C02

Policy No.:

DMCVEN3076741702

Make / Model:

NISSAN NV250 - 2.5D PANEL VAN CMT

Excess Sec II :\$S

D.O.A.:

31/01/18

Place of Accident:

PIE (CHANGE) NEAR KALLANG

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: LIN BOON WAH

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Driver Tel No.: 9146 3461

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHA 4296G



INSRS:

WSP: OGE (Layers)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

21/02/18 (v.c)

21/02/18 @ 5:18PM

26/02/18

30/03/18

06/06/18

CHA 4396G - CC3/180160701/3/11h3n2 021:03/04/18
 (- CC3/ECI:500532/9403 021:26/05/18
 - NA/ENC16017839/164 021:07/09/18
 - NA/ENC0801131/11 021:03/04/18

Q80 5097T - X
 RECEIVED 07 JUN 2018

FINALISED
 OIG WIFE CAUGHT IN CHANDANIN
 SPEAKING). SHE RETURNED VEHICLE FROM
 OIG. INFORMED HERE OIG APPOINTED
 LICK TO GETTING TP CLAIM. OIG
 REPAIR ENDED TP. AGREED TO GETTING.
 - WIK

- OIGNO LETTER TO OI.
 - ORIGINAL TP LOD IN.

26/02/18 - TYPE REPORT FOR WANDERER APPROVAL
 - REPORT DONE.

30/03/18 - SOME WANDERER TO OIG BY OIG
 - OIG APPROVED WANDERER. SEND 1ST
 OFFER TO TP.

06/06/18 - TP ACCEPTED OFFER. ALL BOOG IN

PRELIMINARY ADVICE

Date/Time:

01/02/18

Sent By:

01/02/18

ORDER.

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L16

SS

2,700.00

(2 days)

Reduction:

55 %

Email

Call

FINAL SETTLEMENT

Date/Time:

31/05/18

Confirm with:

WIK

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost: (w/ GST)

SS

2,889.00

(OIG KATE - ENDED TP)

Loss of Rental (LOR):

SS

196.50

(2 days)

X \$ 98.25

Loss of Use (LOU):

SS

100.00

50 x

2 days)

Loss of Income (LOI):

SS

-

(\$ x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LO ☒

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

-

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

-

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

-

3) Survey fee:

\$400.00

Total:

SS

3,192.99

Global Sum SS:

3,190.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3,190.00

Name 1:

COMPOUNDING ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

7/6/18
 COSENT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18002006/K1hs3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date : 01-02-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 5097T	Veh. Inspected	SHA 4396G	
Policy No.	DMCVSN3076741702	Coverage (\$)	0.00	
Claim No.	SNM18D00582C02	Excess (\$)	0.00	
Assign From		Assign Date	01/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/01/2018	Inspection Date	31/01/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI18002006/K1hs3

Date: 01.02.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA 4396G


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31.01.2018 at the premises of M/s Comfortdelgro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	6,049.34
Revised Estimate Amount	: S\$	2,867.36
"Check" Items Amount	: S\$	496.56
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

eam: SH ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.305112395

TOMER

REGN NO: **SHA4396G**

MILEAGE

MS **COMFORT TRANSPORTATION PTE LTD**

MAKE: **HYUNDAI**

FUEL

7010045

E.....1/2.....F

TOMER NO. **383 SIN MING DRIVE**

MODEL **SONATA**

DATE/TIME IN **31.01.2018 13:40**

RESS **Singapore SINGAPORE 575717**

YR OF MANU **17.03.2011**

TARGET DATE

65508755

(O)

(R)

(P)

CHINA

CHASSIS CODE **KMHET41VMBA806171**

COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 31.01.2018

NATURE: 3P 31.01.2018

:/NO

LABOR CODE

DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wledgement Slip

Exit Pass

3 No.: **SHA4396G**

LKE/KALVIN

Vehicle No.:

SHA4396G

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4396G

DATE 31/1/2018 14:41

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✗			\$ 110.90
	Boot Lid Lock Upper ✗			\$ 132.10
	Boot Lid Lock Lower ✗			\$ 30.30
	Boot Lid Sonata Plate ✓			\$ 43.60
	Boot Lid Hyundai Plate ✓			\$ 24.20
	Boot Lid 'H' Emblem ✓			\$ 26.10
	Boot Lid CRDI Plate ✓			\$ 22.70
	Boot Lid Lamp (LH/RH) LH✓ RH✗	\$	230.20	\$ 460.40
	Licence Lamp (LH/RH) ✗	\$	32.50	\$ 65.00
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ✗			\$ 185.80
	Rear Bumper Protector (LH/RH) ✗	\$	38.00	\$ 76.00
	Tail Lamp (LH/RH) ✗	\$	344.00	\$ 688.00
	Rear Panel ✗			\$ 391.80
	Rear Panel Garnish ✗			\$ 95.80
	SUB TOTAL			\$ 4,923.30
	LESS 20%			\$ 984.66
	DISCOUNTED TOTAL			\$ 3,938.64
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Rear No. Plate ✗			\$ 25.00
	Rear Bumper Reverse Sensor ✗			\$ 135.70
	Rear Bumper Advertisement Logo ✗			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓	\$	100.00	\$ 200.00
	Acknowledged by Repairer			\$ 440.70
	Signature:			
	Date:			
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 6,049.34
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4396G

DATE 31/1/2018 14:41

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber			\$ 110.90
	Boot Lid Lock Upper			\$ 132.10
	Boot Lid Lock Lower			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Lamp (LH/RH)		\$ 230.20	\$ 460.40
	Licence Lamp (LH/RH)		\$ 32.50	\$ 65.00
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover			\$ 185.80
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH)		\$ 344.00	\$ 688.00
	Rear Panel			\$ 391.80
	Rear Panel Garnish			\$ 95.80
	SUB TOTAL			\$ 4,923.30
	LESS 20%			\$ 984.66
	DISCOUNTED TOTAL			\$ 3,938.64
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Rear No. Plate			\$ 25.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)			\$ 200.00
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 6,049.34

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No 305112395

Date 08/02/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr KALVIN ANG

Vehicle Reg No. SHA4396G CTPL

31.01.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- GBD5097T
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c) Lumpsum Repair (if applicable)
 - Total for Lumpsum repair cost after Less: 20% \$2,700.00
 - Final Lumpsum Repair cost \$2,700.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : KALVIN ANG

Date : 9/2/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Shirley Hiew (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 5 February 2018 9:33 AM
To: Shirley Hiew (LKK Auto)
Subject: CTP REF NO. SNM18D00582C02 LKK REF NO. CC3/CTI18002006/K1HS3 - ACCIDENT INVOLVING GBD5097T AND SHA 4396G ON 31 JANUARY 2018
Attachments: GIA REPORT GBD5097T.pdf; TayHP_CLCR95.884.pdf

Dear Shirley,

We refer to the above matter and your email dated 01 February 2018.

Enclosed herewith our insured GIA Report and letter to our insured for your attention.

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 30 May, 2018 4:44 PM
To: William Tan Thoo Seng
Cc: Catherine Koh Mui Gek; Admin A; Vic (LKKAUTO)
Subject: Your Ref: T0118/SHA4396G/WT(st)_ACCIDENT INVOLING VEHICLES GBD 5097T AND SHA 4396G ON 31/01/2018
Attachments: DV.pdf

Your Ref: T0118/SHA4396G/WT(st)
Our Ref: CC3/CTI18002006/K1hs3

Without Prejudice

Dear William,

ACCIDENT INVOLING VEHICLES GBD 5097T AND SHA 4396G ON 31/01/2018

We refer to the subject matter.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we offer a global sum of **\$3,190.00** (all in) to settle your client's claim.

If agreeable, kindly chop and sign the attached DV and forward the original copy to us for payment processing.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and is for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18002006/K1ha3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 08-06-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 5097T	Veh. Inspected	SHA 4396G
Policy No.	DMCVSN3076741702	Coverage (\$)	0.00
Claim No.	SNM18D00582C02/7	Excess (\$)	0.00
Assign From		Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KMHET41VMBA806171	Colour	BLUE
Odometer	277184	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	MAXXIS	7 mm
L/H Front Tyre	215/60 R16	MAXXIS	7 mm
R/H Rear Tyre	215/60 R16	MAXXIS	7 mm
L/H Rear Tyre	215/60 R16	MAXXIS	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/01/2018	Inspection Date	31/01/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4396G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	DENTED	1,349.50	1,349.50
1	BOOT LID RUBBER	SERVICEABLE	110.90	-
1	BOOT LID LOCK UPPER	SERVICEABLE	132.10	-
1	BOOT LID LOCK LOWER	SERVICEABLE	30.30	-
1	BOOT LID SONATA PLATE	NECESSARY	43.60	43.60
1	BOOT LID HYUNDAI PLATE	NECESSARY	24.20	24.20
1	BOOT LID "H" EMBLEM	NECESSARY	26.10	26.10
1	BOOT LID CRDI PLATE	NECESSARY	22.70	22.70
2	BOOT LID LAMP (LH/RH) @\$230.20	N/S CRACKED / O/S SERVICEABLE	460.40	230.20
2	LICENCE LAMP (LH/RH) @\$32.50	SERVICEABLE	65.00	-
1	REAR BUMPER	DEFORMED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	CRACKED	483.30	483.30
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	TORN	137.40	137.40
1	REAR BUMPER UNDER COVER	SERVICEABLE	185.80	-
2	REAR BUMPER PROTECTOR (LH/RH) @\$38.00	SERVICEABLE	76.00	-
2	TAIL LAMP (LH/RH) @\$344.00	SERVICEABLE	688.00	-
1	REAR PANEL	SERVICEABLE	391.80	-
1	REAR PANEL GARNISH	SERVICEABLE	95.80	-
	LESS 20% DISCOUNT		-984.66	-583.48
			3,938.64	2,333.92
<u>SPECIAL NETT ITEMS</u>				
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NO PLATE (SN)	SERVICEABLE	25.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	SERVICEABLE	50.00	-
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
			440.70	230.00

Report Ref No. CC3/CT118002006/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.		850.00	400.00
	SPRAY PAINTING CHARGE.		600.00	360.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
			1,670.00	800.00
	GRAND TOTAL		6,049.34	3,363.92
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00

Report Ref No. CC3/CTI18002006/K1ha3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.