

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4396G

DATE 31/1/2018 14:41

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber X			\$ 110.90
	Boot Lid Lock Upper X			\$ 132.10
	Boot Lid Lock Lower X			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Lamp (LH/RH) LH✓ RH×	\$	230.20	\$ 460.40
	Licence Lamp (LH/RH) X	\$	32.50	\$ 65.00
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover X			\$ 185.80
	Rear Bumper Protector (LH/RH) X	\$	38.00	\$ 76.00
	Tail Lamp (LH/RH) X	\$	344.00	\$ 688.00
	Rear Panel X			\$ 391.80
	Rear Panel Garnish X			\$ 95.80
	SUB TOTAL			\$ 4,923.30
	LESS 20%			\$ 984.66
	DISCOUNTED TOTAL			\$ 3,938.64
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Rear No. Plate X			\$ 25.00
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper Advertisement Logo X			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) X			\$ 200.00
	Acknowledged by Repairer			\$ 440.70
	Signature:			
	Date:			
	Labour Charge			\$ 400
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 6,049.34
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				