



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 TOYOTA DYNA 3.0 MANUAL (GBE6181X)

Date of Loss

29 January 2018

Time of Loss

18.15

Loss Description

GBE6181X (INSD) HIT THE REAR OF SLE1716T (TP)

Comment

Workshop Details

Total Rebate Amount

4992

Nett Loss Amount

\$61,008.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

18/07/2018



Days of work completion *

167



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

GBE6181X

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

03/02/2016



Mileage

32022

Age of Vehicle

1

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2015

ASSESSMENT INFO...

2015

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

NEO JUNXIONG

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... DYNA 3.0 MANUAL

ASSESSMENT INFO... DYNA 3.0 MANUAL

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... KDY2318019476

CATEGORY Date of Birth

FNOL INFORMATI... 22 March 1982

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 36

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 1KD2504984

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 6

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2012

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... BLK 607 YISHUN STREET 61, #10-287,
760607, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S8209309E

POST SURVEY INFO...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

02/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

600

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195R15X8

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

155R12X8(D)

Front left side

YOKOHAMA9mm

Front right side

YOKOHAMA9mm

Rear left side

YOKOHAMA8/8mm

Rear right side

YOKOHAMA8/8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add	Approve	Deny
-----	---------	------

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRONT BUMPER			Bent	0				0	Reviewing
		2	1			FRONT BUMPER - LH			Damaged	0				0	Reviewing
		3	1			FRONT BUMPER - RH			Damaged	0				0	Reviewing
		4	1			FRONT BUMPER FOGLAMP - LH			Serviceable	0	0	0	0	0	Deny
		5	1			FRONT BUMPER FOGLAMP - RH			Serviceable	0	0	0	0	0	Deny
		6	1			FRONT BUMPER FOGLAMP COVER - LH			Damaged	0				0	Reviewing
		7	1			FRONT BUMPER FOGLAMP COVER - RH			Damaged	0				0	Reviewing
		8	1			HEADLAMP ASSY - LH			Cracked	0				0	Reviewing
		9	1			HEADLAMP ASSY - RH			Cracked	0				0	Reviewing
		10	1			FRONT GRILLE			Damaged	0				0	Reviewing
		11	1			FRONT GRILLE LOGO			Necessary	0				0	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		12	1			FRONT GRILLE TOP SEAL			Necessary	0				0	Reviewing
		13	1			HEADLAMP LOWER RUBBER LID - LH			Damaged	0				0	Reviewing
		14	1			HEADLAMP LOWER RUBBER LID - RH			Damaged	0				0	Reviewing
		15	1			FRONT PANEL			Bent	0				0	Reviewing
		16	1			FRONT PANEL "DYNA" STICKER			Necessary	0				0	Reviewing
		17	1			FRONT WIPER PANEL			Bent	0				0	Reviewing
		18	1			FRONT WIPER PANEL LOWER CENTRE GARNISH- BLACK			Damaged	0				0	Reviewing
		19	1			FRONT WIPER PANEL LOWER SIDE GARNISH - BLACK - LH			Cracked	0				0	Reviewing
		20	1			FRONT WIPER PANEL LOWER SIDE GARNISH - BLACK - RH			Damaged	0				0	Reviewing
		21	1			FRONT WIPER PANEL SIDE GARNISH - LH			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR / BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		22	1			FRONT WIPER PANEL SIDE GARNISH - RH			Cut	0				0	Reviewing
		23	1			FRONT WIPER ARM - LH			Damaged	0				0	Reviewing
		24	1			FRONT WIPER ARM - RH			Serviceable	0	0	0	0	0	Deny
		25	1			FRONT WIPER NOZZLE - LH			Cracked	0				0	Reviewing
		26	1			FRONT WIPER NOZZLE - RH			Damaged	0				0	Reviewing
		27	1			FRONT WIPER LINKAGE			Serviceable	0	0	0	0	0	Deny
		28	1			FRONT WIPER MOTOR			Serviceable	0	0	0	0	0	Deny
		29	1			FRONT WINDSCREEN GLASS RUBBER			Necessary	0				0	Reviewing
		30	1			FRONT LOWER CROSS MEMBER			Repair	0	0	0	0	0	Deny
		31	1			BEVEL GEAR (NPA)			Serviceable	0	0	0	0	0	Deny
		32	1			BRAKE MASTER			Serviceable	0	0	0	0	0	Deny
		33	1			BRAKE BOOSTER			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		34	1			FRONT NUMBER PLATE (SN)			Cracked	40				40	Reviewing
		35	1			FRONT PANEL HEAT INSULATION			Serviceable	0	0	0	0	0	Deny
		36	1			AIRCON BLOWER			Serviceable	0	0	0	0	0	Deny
		37	1			AIRCON COOLING COIL			Serviceable	0	0	0	0	0	Deny
		38	1			O/S FRONT DOOR ROC STICKER (SN)			Necessary	25				25	Reviewing

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMO
		1		TO.REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN REFIX AND TO RENEW AFFECTED PARTS	600	0	0	Reviewing		
		2		TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS	100	0	0	Reviewing		
		3		TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELTS ASSY, TO REWIRING AND RE-SETTING PROGRAM	0	0	0	Deny		
		4		TO REMOVE FRONT BRAKE BOOSTER, BRAKE MASTER, PUMP AND STEERING COLUMN	60	0	0	Reviewing		
		5		TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	600	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMO
		6		TO FOCUS HEADLAMPS, TO CHECK FRONT WIRING AND LIGHTING OPERATION	20	0	0	Reviewing		
		7		TO REMOVE AND REFIT FRONT WINDSCREEN GLASS IN ORDER TO FACILITATE REPAIRING WORKS	60	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 6 DAYS	Reviewing			
☐		2	PARTS SUPPLIED BY AXAS SUPPLIER \$2,271.00	Reviewing			
☐		3	WIPER NOZZLE SCREW NUT	Reviewing		CRACKED (SUPPLEMENTARY)	
☐		4	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORK	Reviewing	220	(SUPPLEMENTARY)	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$1,125.00

Claim Amount

\$1,125.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,440.00	\$1,440.00
Miscellaneous	\$220.00	\$220.00
Excess	-\$600.00	-\$600.00

Submit for Review