

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG18002009/KHA3S2**Date:** 18/09/2019REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700003793
Claimant Vehicle No :	SHD9881Z	Insured Vehicle No :	S6105CD
Date of Loss:	26/01/2018	Nature of Claim:	TP
		Claim No:	9991053432SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9881Z		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C001336
Reg. Date:	09/05/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC277536
Colour:	Metallic White/Red	Odometer:	400311 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Linglong 8 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Linglong 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,839.61	1,199.48	21,640.13	94.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,160.00	750.00	6,410.00	89.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,999.61	1,949.48	28,050.13	93.50
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	29,999.61	1,550.00	28,449.61	94.83
+ GST 7.00/7.00% (S\$)	2,099.97	108.50	1,991.47	94.83
Nett Amount (S\$)	32,099.58	1,658.50	30,441.08	94.83
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$101.46/day) (S\$)		202.92		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		1,966.77		
Global Sum Settlement (S\$)		1,950.00		

INSPECTION

Date of Assignment:	31/01/2018		
Date Inspected:	31/01/2018	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled / Dented	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
3	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
4	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
5	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
6	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.22 FL	*- FL
7	1		*BUMPER RETAINER FRT RH	Serviceable	151.41 FL	*- FL
8	1		*BUMPER BRACKET FRT RH	Repair	181.75 FL	*- FL
9	1		*HEADLAMP RH	Serviceable	1,184.43 FL	*- FL
10	1		*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*- FL
11	1		*FENDER PANEL FRT RH	Repair	783.83 FL	*- FL
12	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
13	1		*FENDER BRACKET FRT RH	Serviceable	34.14 FL	*- FL
14	1		*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
15	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
16	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	173.36 FL	*- FL
17	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
18	1		*FRAME FULL SUPPORT PANEL	Repair	615.90 FL	*- FL
19	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
20	1		*BONNET	Repair	1,941.63 FL	*- FL
21	1		*DOOR PANEL FRT RH	Repair	2,844.66 FL	*- FL
22	1		*DOOR HINGE UPPER RH	Repair	274.50 FL	*- FL
23	1		*DOOR HINGE LOWER	Repair	300.55 FL	*- FL
24	1		*DOOR CHECK FRT RH	Serviceable	194.77 FL	*- FL
25	1		*DOOR LOCK FRT RH	Repair	908.75 FL	*- FL
26	1		*DOOR CATCH FRT RH	Serviceable	131.23 FL	*- FL
27	1		*DOOR HANDLE OUTER FRT RH	Serviceable	258.12 FL	*- FL
28	1		*DOOR HANDLE CAP FRT RH	Serviceable	26.44 FL	*- FL
29	1		*DOOR HANDLE SEAL FRT RH	Serviceable	7.89 FL	*- FL
30	1		*DOOR HANDLE COVER FRT RH	Serviceable	13.22 FL	*- FL
31	1		*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	*- FL
32	1		*DOOR FINISHER FRT RH	Serviceable	515.06 FL	*- FL
33	1		*DOOR MOULDING FRT RH	Serviceable	176.82 FL	*- FL
34	1		*DOOR GRAB HANDLE FRT RH	Serviceable	210.96 FL	*- FL
35	1		*DOOR MIRROR RH	Serviceable	1,483.40 FL	*- FL
36	1		*DOOR MIRROR GLASS RH	Serviceable	148.20 FL	*- FL
37	1		*DOOR MIRROR BACK COVER RH	Serviceable	218.46 FL	*- FL
38	1		*DOOR WEATHERSTRIP FRT RH	Serviceable	474.21 FL	*- FL
39	1		*DOOR SEAL FRT RH	Serviceable	68.67 FL	*- FL
40	1		*ROCKER PANEL OUTER RH	Repair	987.40 FL	*- FL
41	1		*DOOR PANEL REAR RH	Repair	2,844.66 FL	*- FL
42	1		*SET WHEELARCH CLIP FRT RH	Not Necessary	66.00 FS	*- FS
43	1		*SET FRONT BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
44	1		*RIM RH FRT	Serviceable	385.00 FS	*- FS
45	1		*TYRE RH FRT	Serviceable	330.00 FS	*- FS
46	1		*DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
47	1		*DOOR STICKER CLASSIC	Not Necessary	30.00 FS	*- FS
48	1		*DOOR STICKER 6555-3333	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,262.12	1,325.42
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,422.51	125.94
Total Parts (\$\$)	22,839.61	1,199.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL CONCERNED.	New	170.00	10.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	2,800.00	300.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	3,000.00	440.00
4	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
5	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
7	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
8	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TOWING FEES.	New	120.00	0.00
10	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
Gross Labour Cost (\$\$)			7,160.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >