

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 02 Feb 2018

Preliminary Advice

Vehicle No	: SLJ729L	Accident Date	: 27/01/2018
Make	: PORSCHE PANAMERA	Policy No.	: B28973937MPQ
Assignment Date	: 31/01/2018	Excess	: S\$10,000.00
Date of Inspection	: 01/02/2018	Est. Duration of Repair	: 6.00
Inspection At	: STUTTGART AUTO PTE LTD (HQ) 12 SUNGEI KADUT AVE SINGAPORE 729648		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,697.48
Revised Amount	:S\$	11,650.62
Check Items (Estimated)	:S\$	2,236.86
Total	:S\$	13,887.48

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	160,000.00
COE / PARF Rebate	:S\$	89,694.00
Salvage Value	:S\$	
Margin for Repair	:S\$	70,306.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.