

ASS. REC. BY:

REF: CS/SPT 18002014 / Gmbz

Special Instruction:

Supervisor:

G0

ASSIGNMENT (Office)

From (Person):

Perry He

of

SPT

Date/Time:

31/01/2018 5:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

TP 35D

Insured:

at Workshop m/s

Bam Hock Hin

Tel:

6281 6520 x 220

of

No. 6 Detu Lane 4

Policy No:

Claim No:

HOMSPFT0216000399

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

01/02/2018 9:45am

Person Contacted:

Raymond

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

TP 35D - x

6/2/18

Revert to Perry by email

5/3/18

@10:20am check with Perry, can submit our report

5/3/18

Submit parts \$ 34,428.49, man - HR (84 HR)

Signature

X62

REF:

SPF

ASSIGNMENT

From _____ Date _____

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Ban Hock Hin

of _____

Insured:

Policy No. _____

Claims No. _____

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

Sunny - 8449 6770

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

TP350

Yr Regn:

2005 Jan 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha

C.C.

- 892

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

68816

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

120 / 70 ZR17

R:

150 / 70 ZR17

BS / DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4 mm

R/Bal.

4 mm

L/Bal.

4 mm

L/Bal.

4 mm

D.O.A.

D.O.I.

01-02-18

Survey held at

w/s

1 pm

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

RECEIVED 2010

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

s/b - typist

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

350

Survey Department Check List (Case Handler)

Reference No. : CS | SPF 1800 2014 | 6vb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	1			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	1			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	1			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 5/3/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18002014/Gvb

CONTRACT MANAGEMENT SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 01-02-2018



Code : SPF3

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	TP 35D
Policy No.	Coverage (\$)	0.00
Claim No. HOMSPFETQ16000399	Excess (\$)	0.00
Assign From PERRY HE	Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	Inspection Date	01/02/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 9 February 2018 3:53 PM
To: 'Perry HE (SPF)'
Cc: 'Wei Yea LIM (SPF)'; 'Kwee Huat TAN (SPF)'; 'Kim Pang CHAY (SPF)'; SUR; 'Bernard SEAH (SPF)'; assignments
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - TP35D
Attachments: TP35D.xls (REASSESS).xls

Dear Perry,

Enclosed herewith reassess.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 8 February 2018 8:46 AM
To: 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; SUR <sur@lkkauto.com>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; assignments <assignments@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - TP35D

Dear Perry,

Will get surveyor to reassess.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Wednesday, 7 February 2018 10:45 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; SUR <sur@lkkauto.com>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; assignments <assignments@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - TP35D

Hi Veron,

Majority of the items ~~are~~ are labelled as unconfirmed items.
Pls reassess it on as-needed basis as it is very difficult for us to evaluate.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 6 February, 2018 4:23 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - TP35D

Dear Perry,

Please refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Wednesday, 31 January 2018 5:31 PM
To: assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Shiao Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - TP35D

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-manhours) for the following SPF vehicle at Ban Hock Hin:

Vehicle No: TP35D

Parts:

1.1	ALIGNMENT BODY
1.2	AXLE WHEEL FRONT
1.3	BAR HANDLE
1.4	BEARING
1.5	BEARING
1.6	BEARING
1.7	BEARING (B6203) WHEEL FRONT
1.8	BEARING STEERING CONE LOWER
1.9	BEARING STEERING CONE UPPER
1.10	BEARING SWING ARM
1.11	BLOCK CYLINDER
1.12	BOLT
1.13	BOLT CYLINDER HOLDING 3
1.14	BOLT FLANGE
1.15	BOLT REAR SIGNAL LAMP
1.16	BOLT STUD
1.17	BOLT STUD
1.18	BOLT STUD
1.19	BOLT STUD
1.20	BOX SIDE LH
1.21	BOX SIDE RH
1.22	BRACKET BOX DOCUMENT
1.23	BRACKET FOOTREST REAR LH
1.24	BRACKET FOOTREST REAR RH
1.25	BRACKET LED LIGHT (50 MM)
1.26	BRACKET MUDGUARD
1.27	BRACKET SIGNAL LAMP REAR LH
1.28	BRACKET SIGNAL LAMP REAR RH
1.29	BRACKET UNDER FORK
1.30	CALIPER BRAKE FRONT LH ASSY
1.31	CALIPER BRAKE FRONT RH ASSY
1.32	CASE AXLE GEAR REAR ASSY

1.33	COLLAR
1.34	COLLAR
1.35	COVER CRANKCASE 2
1.36	COVER CYLINDER HEAD
1.37	COVER LED LIGHT (FOR 4 LED)
1.38	COVER OIL PUMP
1.39	COVER SIDE 1 LH (STK 19991) WITH
	SPRAY PAINTING POLICE LIVERY (LINING)
1.40	COVER SIDE 2 RH (STK 26550) WITH
	SPRAY PAINTING POLICE LIVERY (LINING)
1.41	COVER SIDE 6
1.42	COWLING FRONT ASSY
1.43	CRASH BAR FRONT
1.44	CRASH BAR REAR LH
1.45	CRASH BAR REAR RH
1.46	CROWN,HANDLE
1.47	DAMPER CHAIN 1
1.48	DAMPER CHAIN 2
1.49	EMBLEM (POLICE) COWLING FRONT *Sticker supply by AEMD
1.50	EMBLEM (YAMAHA) COWLING FRONT
1.51	FOOTREST FRONT LH
1.52	FOOTREST FRONT RH
1.53	FORK FRONT ASSY LH
1.54	FORK FRONT ASSY RH
1.55	GASKET
1.56	GASKET (PIN DOWEL)
1.57	GASKET CLUTCH COVER
1.58	GASKET CYLINDER BLOCK
1.59	GASKET CYLINDER HEAD 1
1.60	GASKET EXHAUST PIPE
1.61	GASKET HEAD COVER
1.62	GASKET SILENCER
1.63	GASKET TENSIONER

1.64	GAUGE LEVEL
1.65	HEAD CYLINDER ASSY
1.66	HEADLAMP ASSY
1.67	HOLDER NUMBER PLATE
1.68	LAMP SIGNAL REAR LH
1.69	LENS TAILLIGHT
1.70	LEVER BRAKE
1.71	LIGHT LED (JL) 4 LED BLUE - CLEAR LENS
1.72	LIGHT LED (JL) 4 LED RED - CLEAR LENS
1.73	LIGHT REVOLVING - RED - RED LENS
1.74	LOCK SIDE BOX (ATTACH BOX TO BODY FRAME)
1.75	METER ASSY
1.76	METER IU (12V) NEW MODEL - TP *SOR3
1.77	MID GASKET MUFFLER
1.78	MID PIN COTTER
1.79	MID PIN DOWEL
1.80	MUDGUARD FRONT
1.81	MUFFLER LH
1.82	MUFFLER RH
1.83	NUT
1.84	NUT
1.85	OIL BRAKE (KUTTEN KEULER) DOT 4
1.86	OIL GEAR (UNITED) GL-5
1.87	O-RING CYLINDER HEAD (SIDE COVER)
1.88	O-RING JOINT CARBURETOR
1.89	PANEL INNER
1.90	PANEL INNER RH
1.91	PIN FOOTREST
1.92	PIN PISTON
1.93	PIPE EXHAUST 1
1.94	PIPE EXHAUST 2
1.95	PIPE EXHAUST 3
1.96	PIPE EXHAUST 4

1.97	PISTON (STD)
1.98	PLATE DISC BRAKE FRONT
1.99	PLATE NUMBER FRONT (TP)
1.100	PLATE NUMBER REAR (TP)
1.101	POLE REAR FOR BEACON LIGHT (FIXED)
1.102	PROTECTOR LH
1.103	PROTECTOR RH
1.104	REAR ARM COMP.
1.105	RIM SPORT FRONT
1.106	RING PISTON (STD)
1.107	RIVET
1.108	RUBBER FOOTREST
1.109	RUBBER MOUNT
1.110	SCREW
1.111	SCREW PAN HEAD
1.112	SEAL OIL (25X40X5) SWINGING ARM
1.113	SEAL OIL CLUTCH
1.114	SEAL STEERING CONE
1.115	SEAL VALVE
1.116	SENSOR SPEED
1.117	SIREN (CR)
1.118	STAY COWLING FRONT
1.119	STICKER (YAMAHA) FUEL TANK
1.120	STOPPER MAINSTAND
1.121	STUD
1.122	SWITCH HANDLE LH
1.123	TYRE 120/70ZR-17 (METZELER) 58W ROADTEC Z8 TL *SOR
1.124	TYRE 150/70ZR-17 (METZELER) 69W ROADTEC Z8 *SOR
1.125	VALVE EXHAUST
1.126	VALVE INTAKE
1.127	VALVE RIM
1.128	WINDSHIELD

Labour:

1.1	REPAIR & SPRAY PAINT DOCUMENT BOX	Man Hour = 2
1.2	REPAIR & SPRAY PAINT WHOLE BIKE	Man Hour = 24
1.3	WELDING WORK - FRONT CRASH BAR BRACKET	Man Hour = 1
1.4	TO REPLACE ALL ABOVE ITEMS	Man Hour = 55

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

S/N	ITEM DESCRIPTION	PARTS			TOTAL PARTS COST (\$) AFTER MARK UP
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	
1	MATERIALS				
1.1	ALIGNMENT BODY	1	NECESSARY	\$448.40	\$448.40
1.2	AXLE WHEEL FRONT	1	BENT	\$49.56	\$49.56
1.3	BAR HANDLE	1	BENT	\$119.18	\$119.18
1.4	BEARING	1	NECESSARY	\$12.98	\$12.98
1.5	BEARING	1	NECESSARY	\$7.08	\$7.08
1.6	BEARING	2	NECESSARY	\$54.28	\$54.28
1.7	BEARING (B6203) WHEEL FRONT	2	NECESSARY	\$47.20	\$47.20
1.8	BEARING STEERING CONE LOWER	1	NECESSARY	\$56.64	\$56.64
1.9	BEARING STEERING CONE UPPER	1	NECESSARY	\$56.64	\$56.64
1.10	BEARING SWING ARM	2	NECESSARY	\$59.00	\$59.00
1.11	BLOCK CYLINDER	1	CRACKED	\$910.61	\$910.61
1.12	BOLT	2	NECESSARY	\$89.68	\$89.68
1.13	BOLT CYLINDER HOLDING 3	4	NECESSARY	\$44.37	\$44.37
1.14	BOLT FLANGE	2	NECESSARY	\$7.08	\$7.08
1.15	BOLT REAR SIGNAL LAMP	2	NECESSARY	\$113.28	\$113.28
1.16	BOLT STUD	2	NECESSARY	\$35.40	\$35.40
1.17	BOLT STUD	4	NECESSARY	\$26.90	\$26.90
1.18	BOLT STUD	2	NECESSARY	\$4.72	\$4.72
1.19	BOLT STUD	1	NECESSARY	\$3.54	\$3.54
1.20	BOX SIDE LH	1	CUT	\$2,006.00	\$2,006.00
1.21	BOX SIDE RH	1	CUT	\$2,006.00	\$2,006.00
1.22	BRACKET BOX DOCUMENT	1	BROKEN	\$564.04	\$564.04
1.23	BRACKET FOOTREST REAR LH	1	BENT	\$73.16	\$73.16

1.24	BRACKET FOOTREST REAR RH	1	BENT	\$73.16	\$73.16
1.25	BRACKET LED LIGHT (50 MM)	2	BENT	\$35.40	\$35.40
1.26	BRACKET MUDGUARD	1	BENT	\$29.50	\$29.50
1.27	BRACKET SIGNAL LAMP REAR LH	1	BENT	\$228.21	\$228.21
1.28	BRACKET SIGNAL LAMP REAR RH	1	BENT	\$219.48	\$219.48
1.29	BRACKET UNDER FORK	1	BENT	\$300.90	\$300.90
1.30	CALIPER BRAKE FRONT LH ASSY	1	UNCONFIRM	\$463.74	\$463.74
1.31	CALIPER BRAKE FRONT RH ASSY	1	UNCONFIRM	\$463.74	\$463.74
1.32	CASE AXLE GEAR REAR ASSY	1	UNCONFIRM	\$1,877.38	\$1,877.38
1.33	COLLAR	1	NECESSARY	\$12.98	\$12.98
1.34	COLLAR	2	NECESSARY	\$13.45	\$13.45
1.35	COVER CRANKCASE 2	1	CUT	\$143.96	\$143.96
1.36	COVER CYLINDER HEAD	1	CUT	\$232.46	\$232.46
1.37	COVER LED LIGHT (FOR 4 LED)	2	SCRATCHED	\$184.08	\$184.08
1.38	COVER OIL PUMP	1	UNCONFIRM	\$54.04	\$54.04
1.39	COVER SIDE 1 LH (STK 19991) WITH SPRAY PAINTING POLICE LIVERY (LINING)	1	CUT	\$260.78	\$260.78
1.40	COVER SIDE 2 RH (STK 26550) WITH SPRAY PAINTING POLICE LIVERY (LINING)	1	CUT	\$260.78	\$260.78
1.41	COVER SIDE 6	1	UNCONFIRM	\$34.22	\$34.22
1.42	COWLING FRONT ASSY	1	CUT	\$1,026.60	\$1,026.60
1.43	CRASH BAR FRONT	1	BENT	\$801.22	\$801.22
1.44	CRASH BAR REAR LH	1	BENT	\$169.92	\$169.92
1.45	CRASH BAR REAR RH	1	BENT	\$169.92	\$169.92
1.46	CROWN,HANDLE	1	UNCONFIRM	\$143.96	\$143.96
1.47	DAMPER CHAIN 1	1	UNCONFIRM	\$40.12	\$40.12
1.48	DAMPER CHAIN 2	1	UNCONFIRM	\$115.40	\$115.40
1.49	EMBLEM (POLICE) COWLING FRONT *Sticker supply by AEMD	1	NECESSARY		
1.50	EMBLEM (YAMAHA) COWLING FRONT	1	NECESSARY	\$9.44	\$9.44

1.51	FOOTREST FRONT LH	1	CUT	\$20.06	\$20.06
1.52	FOOTREST FRONT RH	1	CUT	\$20.06	\$20.06
1.53	FORK FRONT ASSY LH	1	BENT	\$401.20	\$401.20
1.54	FORK FRONT ASSY RH	1	BENT	\$401.20	\$401.20
1.55	GASKET	4	NECESSARY	\$9.44	\$9.44
1.56	GASKET (PIN DOWEL)	2	NECESSARY	\$11.80	\$11.80
1.57	GASKET CLUTCH COVER	1	NECESSARY	\$12.98	\$12.98
1.58	GASKET CYLINDER BLOCK	1	NECESSARY	\$36.58	\$36.58
1.59	GASKET CYLINDER HEAD 1	1	NECESSARY	\$74.34	\$74.34
1.60	GASKET EXHAUST PIPE	4	NECESSARY	\$23.60	\$23.60
1.61	GASKET HEAD COVER	1	NECESSARY	\$74.34	\$74.34
1.62	GASKET SILENCER	2	NECESSARY	\$33.04	\$33.04
1.63	GASKET TENSIONER	1	NECESSARY	\$1.18	\$1.18
1.64	GAUGE LEVEL	1	UNCONFIRM	\$14.40	\$14.40
1.65	HEAD CYLINDER ASSY	1	CRACKED	\$1,752.30	\$1,752.30
1.66	HEADLAMP ASSY	1	CRACKED	\$276.12	\$276.12
1.67	HOLDER NUMBER PLATE	2	MISSING	\$3.78	\$3.78
1.68	LAMP SIGNAL REAR LH	1	SCRATCHED	\$401.20	\$401.20
1.69	LENS TAILLIGHT	1	SCRATCHED	\$49.56	\$49.56
1.70	LEVER BRAKE	1	CUT	\$25.96	\$25.96
1.71	LIGHT LED (1L) 4 LED BLUE - CLEAR LENS	1	MISSING	\$306.80	\$306.80
1.72	LIGHT LED (1L) 4 LED RED - CLEAR LENS	1	MISSING	\$306.80	\$306.80
1.73	LIGHT REVOLVING - RED - RED LENS	1	SCRATCHED	\$2,002.46	\$2,002.46
1.74	LOCK SIDE BOX (ATTACH BOX TO BODY FRAME)	1	NECESSARY	\$743.40	\$743.40
1.75	METER ASSY	1	CRACKED	\$814.20	\$814.20
1.76	METER IU (12V) NEW MODEL - TP *SOR3	1	CUT	\$280.00	\$280.00
1.77	MID GASKET MUFFLER	4	NECESSARY	\$75.52	\$75.52
1.78	MID PIN COTTER	2	NECESSARY	\$7.08	\$7.08
1.79	MID PIN DOWEL	2	NECESSARY	\$7.08	\$7.08
1.80	MUDGUARD FRONT	1	CRACKED	\$107.38	\$107.38

1.81	MUFFLER LH	1	CUT	\$624.22	\$624.22
1.82	MUFFLER RH	1	DENTED	\$619.50	\$619.50
1.83	NUT	7	NECESSARY	\$33.04	\$33.04
1.84	NUT	8	NECESSARY	\$37.76	\$37.76
1.85	OIL BRAKE (KUTTEN KEULER) DOT 4	1	NECESSARY	\$17.23	\$17.23
1.86	OIL GEAR (UNITED) GL-5	0.3	NECESSARY	\$2.58	\$2.58
1.87	O-RING CYLINDER HEAD (SIDE COVER)	4	NECESSARY	\$22.18	\$22.18
1.88	O-RING JOINT CARBURETOR	4	NECESSARY	\$28.32	\$28.32
1.89	PANEL INNER	1	UNCONFIRM	\$69.62	\$69.62
1.90	PANEL INNER RH	1	UNCONFIRM	\$401.20	\$401.20
1.91	PIN FOOTREST	2	NECESSARY	\$4.72	\$4.72
1.92	PIN PISTON	4	NECESSARY	\$47.67	\$47.67
1.93	PIPE EXHAUST 1	1	BENT	\$143.96	\$143.96
1.94	PIPE EXHAUST 2	1	BENT	\$143.96	\$143.96
1.95	PIPE EXHAUST 3	1	BENT	\$143.96	\$143.96
1.96	PIPE EXHAUST 4	1	BENT	\$143.96	\$143.96
1.97	PISTON (STD)	4	NECESSARY	\$302.08	\$302.08
1.98	PLATE DISC BRAKE FRONT	2	BENT	\$526.28	\$526.28
1.99	PLATE NUMBER FRONT (TP)	1	MISSING	\$17.70	\$17.70
1.100	PLATE NUMBER REAR (TP)	1	BENT	\$21.24	\$21.24
1.101	POLE REAR FOR BEACON LIGHT (FIXED)	1	BENT	\$300.90	\$300.90
1.102	PROTECTOR LH	1	CUT	\$332.76	\$332.76
1.103	PROTECTOR RH	1	CUT	\$332.76	\$332.76
1.104	REAR ARM COMP.	1	UNCONFIRM	\$450.76	\$450.76
1.105	RIM SPORT FRONT	1	CUT	\$939.28	\$939.28
1.106	RING PISTON (STD)	4	NECESSARY	\$198.24	\$198.24
1.107	RIVET	2	NECESSARY	\$4.72	\$4.72
1.108	RUBBER FOOTREST	2	NECESSARY	\$30.68	\$30.68
1.109	RUBBER MOUNT	12	NECESSARY	\$84.96	\$84.96
1.110	SCREW	7	NECESSARY	\$16.52	\$16.52

1.111	SCREW PAN HEAD	1	NECESSARY	\$1.89	\$1.89
1.112	SEAL OIL (25X40X5) SWINGING ARM	2	NECESSARY	\$9.44	\$9.44
1.113	SEAL OIL CLUTCH	1	NECESSARY	\$4.72	\$4.72
1.114	SEAL STEERING CONE	1	NECESSARY	\$23.60	\$23.60
1.115	SEAL VALVE	8	NECESSARY	\$66.08	\$66.08
1.116	SENSOR SPEED	1	UNCONFIRM	\$286.15	\$286.15
1.117	SIREN (CR)	1	CUT	\$3,129.36	\$3,129.36
1.118	STAY COWLING FRONT	1	UNCONFIRM	\$401.20	\$401.20
1.119	STICKER (YAMAHA) FUEL TANK	2	NOT NECESSARY	\$28.32	
1.120	STOPPER MAINSTAND	1	NOT NECESSARY	\$6.14	
1.121	STUD	8	NECESSARY	\$68.91	\$68.91
1.122	SWITCH HANDLE LH	1	CUT	\$232.46	\$232.46
1.123	TYRE 120/70ZR-17 (METZELER) 58W ROADTEC Z8 TL *SOR	1	CUT	\$259.82	\$259.82
1.124	TYRE 150/70ZR-17 (METZELER) 69W ROADTEC Z8 *SOR	1	UNCONFIRM	\$245.24	\$245.24
1.125	VALVE EXHAUST	4	NECESSARY	\$198.24	\$198.24
1.126	VALVE INTAKE	4	NECESSARY	\$179.36	\$179.36
1.127	VALVE RIM	1	NECESSARY	\$10.62	\$10.62
1.128	WINDSHIELD	1	CUT	\$814.20	\$814.20
2	SCOPE OF REPAIRS				
2.1	REPAIR & SPRAY PAINT DOCUMENT BOX				
2.2	REPAIR & SPRAY PAINT WHOLE BIKE				
2.3	WELDING WORK-FRONT CRASH BAR BRACKET				
2.4	TO REPLACE ALL ABOVE ITEMS				
3	ADDITIONAL SERVICES				
3.1	TRANSPORT CHARGES (SOR 8) (BILL UNDER MONTH END SOR BILLING)				

COSTING	TOTAL PARTS COST	\$34,428.49
	TOTAL MAN-HOUR	

[illegible]

Catherine Chong (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Wednesday, 31 January, 2018 5:31 PM
To: assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto);
Shiau Chan (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - TP35D

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-manhours) for the following SPF vehicle at Ban Hock Hin:

Vehicle No: TP35D

Parts:

1.1	ALIGNMENT BODY
1.2	AXLE WHEEL FRONT
1.3	BAR HANDLE
1.4	BEARING
1.5	BEARING
1.6	BEARING
1.7	BEARING (B6203) WHEEL FRONT
1.8	BEARING STEERING CONE LOWER
1.9	BEARING STEERING CONE UPPER
1.10	BEARING SWING ARM
1.11	BLOCK CYLINDER
1.12	BOLT
1.13	BOLT CYLINDER HOLDING 3
1.14	BOLT FLANGE
1.15	BOLT REAR SIGNAL LAMP
1.16	BOLT STUD
1.17	BOLT STUD
1.18	BOLT STUD
1.19	BOLT STUD
1.20	BOX SIDE LH
1.21	BOX SIDE RH
1.22	BRACKET BOX DOCUMENT

1.23	BRACKET FOOTREST REAR LH
1.24	BRACKET FOOTREST REAR RH
1.25	BRACKET LED LIGHT (50 MM)
1.26	BRACKET MUDGUARD
1.27	BRACKET SIGNAL LAMP REAR LH
1.28	BRACKET SIGNAL LAMP REAR RH
1.29	BRACKET UNDER FORK
1.30	CALIPER BRAKE FRONT LH ASSY
1.31	CALIPER BRAKE FRONT RH ASSY
1.32	CASE AXLE GEAR REAR ASSY
1.33	COLLAR
1.34	COLLAR
1.35	COVER CRANKCASE 2
1.36	COVER CYLINDER HEAD
1.37	COVER LED LIGHT (FOR 4 LED)
1.38	COVER OIL PUMP
1.39	COVER SIDE 1 LH (STK 19991) WITH SPRAY PAINTING POLICE LIVERY (LINING)
1.40	COVER SIDE 2 RH (STK 26550) WITH SPRAY PAINTING POLICE LIVERY (LINING)
1.41	COVER SIDE 6
1.42	COWLING FRONT ASSY
1.43	CRASH BAR FRONT
1.44	CRASH BAR REAR LH
1.45	CRASH BAR REAR RH
1.46	CROWN,HANDLE
1.47	DAMPER CHAIN 1
1.48	DAMPER CHAIN 2
1.49	EMBLEM (POLICE) COWLING FRONT *Sticker supply by AEMD
1.50	EMBLEM (YAMAHA) COWLING FRONT
1.51	FOOTREST FRONT LH
1.52	FOOTREST FRONT RH
1.53	FORK FRONT ASSY LH

1.54	FORK FRONT ASSY RH
1.55	GASKET
1.56	GASKET (PIN DOWEL)
1.57	GASKET CLUTCH COVER
1.58	GASKET CYLINDER BLOCK
1.59	GASKET CYLINDER HEAD 1
1.60	GASKET EXHAUST PIPE
1.61	GASKET HEAD COVER
1.62	GASKET SILENCER
1.63	GASKET TENSIONER
1.64	GAUGE LEVEL
1.65	HEAD CYLINDER ASSY
1.66	HEADLAMP ASSY
1.67	HOLDER NUMBER PLATE
1.68	LAMP SIGNAL REAR LH
1.69	LENS TAILLIGHT
1.70	LEVER BRAKE
1.71	LIGHT LED (JL) 4 LED BLUE - CLEAR LENS
1.72	LIGHT LED (JL) 4 LED RED - CLEAR LENS
1.73	LIGHT REVOLVING - RED - RED LENS
1.74	LOCK SIDE BOX (ATTACH BOX TO BODY FRAME)
1.75	METER ASSY
1.76	METER IU (12V) NEW MODEL - TP *SOR3
1.77	MID GASKET MUFFLER
1.78	MID PIN COTTER
1.79	MID PIN DOWEL
1.80	MUDGUARD FRONT
1.81	MUFFLER LH
1.82	MUFFLER RH
1.83	NUT
1.84	NUT
1.85	OIL BRAKE (KUTTEN KEULER) DOT 4
1.86	OIL GEAR (UNITED) GL-5

1.87	O-RING CYLINDER HEAD (SIDE COVER)
1.88	O-RING JOINT CARBURETOR
1.89	PANEL INNER
1.90	PANEL INNER RH
1.91	PIN FOOTREST
1.92	PIN PISTON
1.93	PIPE EXHAUST 1
1.94	PIPE EXHAUST 2
1.95	PIPE EXHAUST 3
1.96	PIPE EXHAUST 4
1.97	PISTON (STD)
1.98	PLATE DISC BRAKE FRONT
1.99	PLATE NUMBER FRONT (TP)
1.100	PLATE NUMBER REAR (TP)
1.101	POLE REAR FOR BEACON LIGHT (FIXED)
1.102	PROTECTOR LH
1.103	PROTECTOR RH
1.104	REAR ARM COMP.
1.105	RIM SPORT FRONT
1.106	RING PISTON (STD)
1.107	RIVET
1.108	RUBBER FOOTREST
1.109	RUBBER MOUNT
1.110	SCREW
1.111	SCREW PAN HEAD
1.112	SEAL OIL (25X40X5) SWINGING ARM
1.113	SEAL OIL CLUTCH
1.114	SEAL STEERING CONE
1.115	SEAL VALVE
1.116	SENSOR SPEED
1.117	SIREN (CR)
1.118	STAY COWLING FRONT
1.119	STICKER (YAMAHA) FUEL TANK

1.120	STOPPER MAINSTAND
1.121	STUD
1.122	SWITCH HANDLE LH
1.123	TYRE 120/70ZR-17 (METZELER) 58W ROADTEC Z8 TL *SOR
1.124	TYRE 150/70ZR-17 (METZELER) 69W ROADTEC Z8 *SOR
1.125	VALVE EXHAUST
1.126	VALVE INTAKE
1.127	VALVE RIM
1.128	WINDSHIELD

Labour:

1.1	REPAIR & SPRAY PAINT DOCUMENT BOX	Man Hour = 2
1.2	REPAIR & SPRAY PAINT WHOLE BIKE	Man Hour = 24
1.3	WELDING WORK - FRONT CRASH BAR BRACKET	Man Hour = 1
1.4	TO REPLACE ALL ABOVE ITEMS	Man Hour = 55

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
•TRANSFORMATION 2025•
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



Scope Of Work
Home Team Agency

SCOPE OF WORK

I To provide labour, materials, transportation, tools and parts and others deem

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	TP
VEH NO :	TP35D	MC	REPAIR TYPE:	ACCH
VEH MAKE/MODEL:	YAMAHA XJ900P	Mileage:	68816	

S/N	PARTS DESCRIPTION	PART COST (\$)					st Per rk Up
1	Scope Of Repairs						
1.1	ALIGNMENT BODY	380.00					
1.2	AXLE WHEEL FRONT	42.00					
1.3	BAR HANDLE	101.00					
1.4	BEARING	11.00					
1.5	BEARING	6.00					
1.6	BEARING	23.00					
1.7	BEARING (B6203) WHEEL FRONT	20.00					
1.8	BEARING STEERING CONE LOWER	48.00					
1.9	BEARING STEERING CONE UPPER	48.00					
1.10	BEARING SWING ARM	25.00					
1.11	BLOCK CYLINDER	771.70					
1.12	BOLT	38.00					
1.13	BOLT CYLINDER HOLDING 3	9.40					
1.14	BOLT FLANGE	3.00					
1.15	BOLT REAR SIGNAL LAMP	48.00					
1.16	BOLT STUD	15.00					
1.17	BOLT STUD	5.70					
1.18	BOLT STUD	2.00					
1.19	BOLT STUD	3.00					
1.20	BOX SIDE LH	1700.00					
1.21	BOX SIDE RH	1700.00					
1.22	BRACKET BOX DOCUMENT	478.00					
1.23	BRACKET FOOTREST REAR LH	62.00					
1.24	BRACKET FOOTREST REAR RH	62.00					
1.25	BRACKET LED LIGHT (50 MM)	15.00					
1.26	BRACKET MUDGUARD	25.00					
1.27	BRACKET SIGNAL LAMP REAR LH	193.40					
1.28	BRACKET SIGNAL LAMP REAR RH	186.00					
1.29	BRACKET UNDER FORK	255.00					
1.30	CALIPER BRAKE FRONT LH ASSY	393.00					
1.31	CALIPER BRAKE FRONT RH ASSY	393.00					
1.32	CASE AXLE GEAR REAR ASSY	1591.00					
1.33	COLLAR	11.00					
1.34	COLLAR	5.70					
1.35	COVER CRANKCASE 2	122.00					
1.36	COVER CYLINDER HEAD	197.00					
1.37	COVER LED LIGHT (FOR 4 LED)	78.00					
1.38	COVER OIL PUMP	45.80					
1.39	COVER SIDE 1 LH (STK 19991) WITH SPRAY PAINTING POLICE LIVERY (LINING)	221.00	1		260.78	260.78	
1.40	COVER SIDE 2 RH (STK 26550) WITH SPRAY PAINTING POLICE LIVERY (LINING)	221.00	1	18%	260.78	260.78	
1.41	COVER SIDE 6	29.00	1	18%	34.22	34.22	
1.42	COWLING FRONT ASSY	870.00	1	18%	1026.60	1026.60	
1.43	CRASH BAR FRONT	679.00	1	18%	801.22	801.22	
1.44	CRASH BAR REAR LH	144.00	1	18%	169.92	169.92	
1.45	CRASH BAR REAR RH	144.00	1	18%	169.92	169.92	
1.46	CROWN HANDLE	122.00	1	18%	143.96	143.96	
1.47	DAMPER CHAIN 1	34.00	1	18%	40.12	40.12	
1.48	DAMPER CHAIN 2	97.80	1	18%	115.40	115.40	
1.49	EMBLEM (POLICE) COWLING FRONT *Sticker supply by AEMD	8.00	2	18%	0.00	0.00	
1.50	EMBLEM (YAMAHA) COWLING FRONT	8.00	1	18%	9.44	9.44	
1.51	FOOTREST FRONT LH	17.00	1	18%	20.06	20.06	
1.52	FOOTREST FRONT RH	17.00	1	18%	20.06	20.06	
1.53	FORK FRONT ASSY LH	340.00	1	18%	401.20	401.20	
1.54	FORK FRONT ASSY RH	340.00	1	18%	401.20	401.20	
1.55	GASKET	2.00	4	18%	2.36	9.44	
1.56	GASKET (PIN DOWEL)	5.00	2	18%	5.90	11.80	
1.57	GASKET CLUTCH COVER	11.00	1	18%	12.98	12.98	
1.58	GASKET CYLINDER BLOCK	31.00	1	18%	36.58	36.58	

1.59	GASKET CYLINDER HEAD	63.00	1	18%	74.34	74.34
1.60	GASKET EXHAUST PIPE	5.00	4	18%	5.90	23.60
1.61	GASKET HEAD COVER	63.00	1	18%	74.34	74.34
1.62	GASKET SILENCER	14.00	2	18%	16.52	33.04
1.63	GASKET TENSIONER	1.00	1	18%	1.18	1.18
1.64	GAUGE LEVEL	12.20	1	18%	14.40	14.40
1.65	HEAD CYLINDER ASSY	1485.00	1	18%	1752.30	1752.30
1.66	HEADLAMP ASSY	234.00	1	18%	276.12	276.12
1.67	HOLDER NUMBER PLATE	1.60	2	18%	1.89	3.78
1.68	LAMP SIGNAL REAR LH	340.00	1	18%	401.20	401.20
1.69	LENS TAILLIGHT	42.00	1	18%	49.56	49.56
1.70	LEVER BRAKE	22.00	1	18%	25.96	25.96
1.71	LIGHT LED (JL) 4 LED BLUE - CLEAR LENS	260.00	1	18%	306.80	306.80
1.72	LIGHT LED (JL) 4 LED RED - CLEAR LENS	260.00	1	18%	306.80	306.80
1.73	LIGHT REVOLVING - RED - RED LENS	1697.00	1	18%	2002.46	2002.46
1.74	LOCK SIDE BOX (ATTACH BOX TO BODY FRAME)	630.00	1	18%	743.40	743.40
1.75	METER ASSY	690.00	1	18%	814.20	814.20
1.76	METER IU (12V) NEW MODEL - TP *SOR3	280.00	1		280.00	280.00
1.77	MID GASKET MUFFLER	16.00	4	18%	18.88	75.52
1.78	MID PIN COTTER	3.00	2	18%	3.54	7.08
1.79	MID PIN DOWEL	3.00	2	18%	3.54	7.08
1.80	MUDGUARD FRONT	91.00	1	18%	107.38	107.38
1.81	MUFFLER LH	529.00	1	18%	624.22	624.22
1.82	MUFFLER RH	525.00	1	18%	619.50	619.50
1.83	NUT	4.00	7	18%	4.72	33.04
1.84	NUT	4.00	8	18%	4.72	37.76
1.85	OIL BRAKE (KUTTEN KEULER) DOT 4	14.60	1	18%	17.23	17.23
1.86	OIL GEAR (UNITED) GL-5	7.30	0.3	18%	8.61	2.58
1.87	O-RING CYLINDER HEAD (SIDE COVER)	4.70	4	18%	5.55	22.18
1.88	O-RING JOINT CARBURETOR	6.00	4	18%	7.08	28.32
1.89	PANEL INNER	59.00	1	18%	69.62	69.62
1.90	PANEL INNER RH	340.00	1	18%	401.20	401.20
1.91	PIN FOOTREST	2.00	2	18%	2.36	4.72
1.92	PIN PISTON	10.10	4	18%	11.92	47.67
1.93	PIPE EXHAUST 1	122.00	1	18%	143.96	143.96
1.94	PIPE EXHAUST 2	122.00	1	18%	143.96	143.96
1.95	PIPE EXHAUST 3	122.00	1	18%	143.96	143.96
1.96	PIPE EXHAUST 4	122.00	1	18%	143.96	143.96
1.97	PISTON (STD)	64.00	4	18%	75.52	302.08
1.98	PLATE DISC BRAKE FRONT	223.00	2	18%	263.14	526.28
1.99	PLATE NUMBER FRONT (TP)	15.00	1	18%	17.70	17.70
1.100	PLATE NUMBER REAR (TP)	18.00	1	18%	21.24	21.24
1.101	POLE REAR FOR BEACON LIGHT (FIXED)	255.00	1	18%	300.90	300.90
1.102	PROTECTOR LH	282.00	1	18%	332.76	332.76
1.103	PROTECTOR RH	282.00	1	18%	332.76	332.76
1.104	REAR ARM COMP.	382.00	1	18%	450.76	450.76
1.105	RIM SPORT FRONT	796.00	1	18%	939.28	939.28
1.106	RING PISTON (STD)	42.00	4	18%	49.56	198.24
1.107	RIVET	2.00	2	18%	2.36	4.72
1.108	RUBBER FOOTREST	13.00	2	18%	15.34	30.68
1.109	RUBBER MOUNT	6.00	12	18%	7.08	84.96
1.110	SCREW	2.00	7	18%	2.36	16.52
1.111	SCREW PAN HEAD	1.60	1	18%	1.89	1.89
1.112	SEAL OIL (25X40X5) SWINGING ARM	4.00	2	18%	4.72	9.44
1.113	SEAL OIL CLUTCH	4.00	1	18%	4.72	4.72
1.114	SEAL STEERING CONE	20.00	1	18%	23.60	23.60
1.115	SEAL VALVE	7.00	8	18%	8.26	66.08
1.116	SENSOR SPEED	242.50	1	18%	286.15	286.15
1.117	SIREN (CR)	2652.00	1	18%	3129.36	3129.36
1.118	STAY COWLING FRONT	340.00	1	18%	401.20	401.20
1.119	STICKER (YAMAHA) FUEL TANK	12.00	2	18%	14.16	28.32
1.120	STOPPER MAINSTAND	5.20	1	18%	6.14	6.14
1.121	STUD	7.30	8	18%	8.61	68.91
1.122	SWITCH HANDLE LH	197.00	1	18%	232.46	232.46
1.123	TYRE 120/70ZR-17 (METZELER) 58W ROADTEC Z8 TL *SOR	259.82	1		259.82	259.82
1.124	TYRE 150/70ZR-17 (METZELER) 69W ROADTEC Z8 *SOR	245.24	1		245.24	245.24
1.125	VALVE EXHAUST	42.00	4	18%	49.56	198.24
1.126	VALVE INTAKE	38.00	4	18%	44.84	179.36
1.127	VALVE RIM	9.00	1	18%	10.62	10.62
1.128	WINDSHIELD	690.00	1	18%	814.20	814.20
2	Additional Services					
				18%	0.00	0.00
Remarks:		SPARE PARTS SUBJECTED TO AVAILABILITY			Parts Total:	\$ 34,462.96

[illegible]

Not Authorized.

Gma Qiang - 82880282
CXXK
01/2/18

LKK Auto Consultants hence notify
the Repairer of the following:

Acknowledged by Repairer



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

AUTOMOTIVE ENGINEERING & MGT DIVISION					Ref : CS/SPF18002014/Gvbe2				
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333					Date : 08-03-2018				
					Code : SPF3				
1. Policy : Includes OWN DAMAGE									
Insured Veh.		Veh. Inspected			TP 35D				
Policy No.		Coverage (\$)			0.00				
Claim No.		HOMSPFETQ16000399			Excess (\$)			0.00	
Assign From		PERRY HE			Assign Date			31/01/2018	
2. Vehicle Condition									
Make & Model		YAMAHA			c.c		892		
Engine No.		HIDDEN			Year of Reg.		2005		
Chassis No.		JYA4KM00000121891			Colour		WHITE		
Odometer		68816			Steering		IN ORDER		
Brakes		IN ORDER			Modification		NIL		
General		GOOD							
3. Condition of Tyres									
		Size		Make		Balance			
	R/H Front Tyre	120/70Z R17		DUNLOP		4 mm			
	L/H Front Tyre					mm			
	R/H Rear Tyre	150/70Z R17		DUNLOP		4 mm			
	L/H Rear Tyre					mm			
4. Description of Damage									
THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.									
5. Survey Location									
Accident Date		Inspection Date			01/02/2018				
Survey held at		BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410							
5a. Remarks									



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Registration No. TP 35D

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	ALIGNMENT BODY	1	NECESSARY	\$448.40	\$448.40	
1.2	AXLE WHEEL FRONT	1	BENT	\$49.56	\$49.56	
1.3	BAR HANDLE	1	BENT	\$119.18	\$119.18	
1.4	BEARING	1	NECESSARY	\$12.98	\$12.98	
1.5	BEARING	1	NECESSARY	\$7.08	\$7.08	
1.6	BEARING	2	NECESSARY	\$54.28	\$54.28	
1.7	BEARING (B6203) WHEEL FRONT	2	NECESSARY	\$47.20	\$47.20	
1.8	BEARING STEERING CONE LOWER	1	NECESSARY	\$56.64	\$56.64	
1.9	BEARING STEERING CONE UPPER	1	NECESSARY	\$56.64	\$56.64	
1.10	BEARING SWING ARM	2	NECESSARY	\$59.00	\$59.00	
1.11	BLOCK CYLINDER	1	CRACKED	\$910.61	\$910.61	
1.12	BOLT	2	NECESSARY	\$89.68	\$89.68	
1.13	BOLT CYLINDER HOLDING 3	4	NECESSARY	\$44.37	\$44.37	
1.14	BOLT FLANGE	2	NECESSARY	\$7.08	\$7.08	
1.15	BOLT REAR SIGNAL LAMP	2	NECESSARY	\$113.28	\$113.28	
1.16	BOLT STUD	2	NECESSARY	\$35.40	\$35.40	
1.17	BOLT STUD	4	NECESSARY	\$26.90	\$26.90	
1.18	BOLT STUD	2	NECESSARY	\$4.72	\$4.72	
1.19	BOLT STUD	1	NECESSARY	\$3.54	\$3.54	
1.20	BOX SIDE LH	1	CUT	\$2,006.00	\$2,006.00	
1.21	BOX SIDE RH	1	CUT	\$2,006.00	\$2,006.00	
1.22	BRACKET BOX DOCUMENT	1	BROKEN	\$564.04	\$564.04	
1.23	BRACKET FOOTREST REAR LH	1	BENT	\$73.16	\$73.16	
1.24	BRACKET FOOTREST REAR RH	1	BENT	\$73.16	\$73.16	
1.25	BRACKET LED LIGHT (50 MM)	2	BENT	\$35.40	\$35.40	
1.26	BRACKET MUDGUARD	1	BENT	\$29.50	\$29.50	
1.27	BRACKET SIGNAL LAMP REAR LH	1	BENT	\$228.21	\$228.21	
1.28	BRACKET SIGNAL LAMP REAR RH	1	BENT	\$219.48	\$219.48	

1.29	BRACKET UNDER FORK	1	BENT	\$300.90	\$300.90	
1.30	CALIPER BRAKE FRONT LH ASSY	1	UNCONFIRM	\$463.74	\$463.74	
1.31	CALIPER BRAKE FRONT RH ASSY	1	UNCONFIRM	\$463.74	\$463.74	
1.32	CASE AXLE GEAR REAR ASSY	1	UNCONFIRM	\$1,877.38	\$1,877.38	
1.33	COLLAR	1	NECESSARY	\$12.98	\$12.98	
1.34	COLLAR	2	NECESSARY	\$13.45	\$13.45	
1.35	COVER CRANKCASE 2	1	CUT	\$143.96	\$143.96	
1.36	COVER CYLINDER HEAD	1	CUT	\$232.46	\$232.46	
1.37	COVER LED LIGHT (FOR 4 LED)	2	SCRATCHED	\$184.08	\$184.08	
1.38	COVER OIL PUMP	1	UNCONFIRM	\$54.04	\$54.04	
1.39	COVER SIDE 1 LH (STK 19991) WITH SPRAY PAINTING POLICE LIVERY (LINING)	1	CUT	\$260.78	\$260.78	
1.40	COVER SIDE 2 RH (STK 26550) WITH SPRAY PAINTING POLICE LIVERY (LINING)	1	CUT	\$260.78	\$260.78	
1.41	COVER SIDE 6	1	UNCONFIRM	\$34.22	\$34.22	
1.42	COWLING FRONT ASSY	1	CUT	\$1,026.60	\$1,026.60	
1.43	CRASH BAR FRONT	1	BENT	\$801.22	\$801.22	
1.44	CRASH BAR REAR LH	1	BENT	\$169.92	\$169.92	
1.45	CRASH BAR REAR RH	1	BENT	\$169.92	\$169.92	
1.46	CROWN,HANDLE	1	UNCONFIRM	\$143.96	\$143.96	
1.47	DAMPER CHAIN 1	1	UNCONFIRM	\$40.12	\$40.12	
1.48	DAMPER CHAIN 2	1	UNCONFIRM	\$115.40	\$115.40	
1.49	EMBLEM (POLICE) COWLING FRONT *Sticker supply by AEMD	1	NECESSARY			
1.50	EMBLEM (YAMAHA) COWLING FRONT	1	NECESSARY	\$9.44	\$9.44	
1.51	FOOTREST FRONT LH	1	CUT	\$20.06	\$20.06	
1.52	FOOTREST FRONT RH	1	CUT	\$20.06	\$20.06	
1.53	FORK FRONT ASSY LH	1	BENT	\$401.20	\$401.20	
1.54	FORK FRONT ASSY RH	1	BENT	\$401.20	\$401.20	
1.55	GASKET	4	NECESSARY	\$9.44	\$9.44	
1.56	GASKET (PIN DOWEL)	2	NECESSARY	\$11.80	\$11.80	
1.57	GASKET CLUTCH COVER	1	NECESSARY	\$12.98	\$12.98	
1.58	GASKET CYLINDER BLOCK	1	NECESSARY	\$36.58	\$36.58	
1.59	GASKET CYLINDER HEAD 1	1	NECESSARY	\$74.34	\$74.34	
1.60	GASKET EXHAUST PIPE	4	NECESSARY	\$23.60	\$23.60	
1.61	GASKET HEAD COVER	1	NECESSARY	\$74.34	\$74.34	
1.62	GASKET SILENCER	2	NECESSARY	\$33.04	\$33.04	
1.63	GASKET TENSIONER	1	NECESSARY	\$1.18	\$1.18	
1.64	GAUGE LEVEL	1	UNCONFIRM	\$14.40	\$14.40	
1.65	HEAD CYLINDER ASSY	1	CRACKED	\$1,752.30	\$1,752.30	

1.66	HEADLAMP ASSY	1	CRACKED	\$276.12	\$276.12	
1.67	HOLDER NUMBER PLATE	2	MISSING	\$3.78	\$3.78	
1.68	LAMP SIGNAL REAR LH	1	SCRATCHED	\$401.20	\$401.20	
1.69	LENS TAILLIGHT	1	SCRATCHED	\$49.56	\$49.56	
1.70	LEVER BRAKE	1	CUT	\$25.96	\$25.96	
1.71	LIGHT LED (JL) 4 LED BLUE - CLEAR LENS	1	MISSING	\$306.80	\$306.80	
1.72	LIGHT LED (JL) 4 LED RED - CLEAR LENS	1	MISSING	\$306.80	\$306.80	
1.73	LIGHT REVOLVING - RED - RED LENS	1	SCRATCHED	\$2,002.46	\$2,002.46	
1.74	LOCK SIDE BOX (ATTACH BOX TO BODY FRAME)	1	NECESSARY	\$743.40	\$743.40	
1.75	METER ASSY	1	CRACKED	\$814.20	\$814.20	
1.76	METER IU (12V) NEW MODEL - TP *SOR3	1	CUT	\$280.00	\$280.00	
1.77	MID GASKET MUFFLER	4	NECESSARY	\$75.52	\$75.52	
1.78	MID PIN COTTER	2	NECESSARY	\$7.08	\$7.08	
1.79	MID PIN DOWEL	2	NECESSARY	\$7.08	\$7.08	
1.80	MUDGUARD FRONT	1	CRACKED	\$107.38	\$107.38	
1.81	MUFFLER LH	1	CUT	\$624.22	\$624.22	
1.82	MUFFLER RH	1	DENTED	\$619.50	\$619.50	
1.83	NUT	7	NECESSARY	\$33.04	\$33.04	
1.84	NUT	8	NECESSARY	\$37.76	\$37.76	
1.85	OIL BRAKE (KUTTEN KEULER) DOT 4	1	NECESSARY	\$17.23	\$17.23	
1.86	OIL GEAR (UNITED) GL-5	0.3	NECESSARY	\$2.58	\$2.58	
1.87	O-RING CYLINDER HEAD (SIDE COVER)	4	NECESSARY	\$22.18	\$22.18	
1.88	O-RING JOINT CARBURETOR	4	NECESSARY	\$28.32	\$28.32	
1.89	PANEL INNER	1	UNCONFIRM	\$69.62	\$69.62	
1.90	PANEL INNER RH	1	UNCONFIRM	\$401.20	\$401.20	
1.91	PIN FOOTREST	2	NECESSARY	\$4.72	\$4.72	
1.92	PIN PISTON	4	NECESSARY	\$47.67	\$47.67	
1.93	PIPE EXHAUST 1	1	BENT	\$143.96	\$143.96	
1.94	PIPE EXHAUST 2	1	BENT	\$143.96	\$143.96	
1.95	PIPE EXHAUST 3	1	BENT	\$143.96	\$143.96	
1.96	PIPE EXHAUST 4	1	BENT	\$143.96	\$143.96	
1.97	PISTON (STD)	4	NECESSARY	\$302.08	\$302.08	
1.98	PLATE DISC BRAKE FRONT	2	BENT	\$526.28	\$526.28	
1.99	PLATE NUMBER FRONT (TP)	1	MISSING	\$17.70	\$17.70	
1.100	PLATE NUMBER REAR (TP)	1	BENT	\$21.24	\$21.24	
1.101	POLE REAR FOR BEACON LIGHT (FIXED)	1	BENT	\$300.90	\$300.90	
1.102	PROTECTOR LH	1	CUT	\$332.76	\$332.76	
1.103	PROTECTOR RH	1	CUT	\$332.76	\$332.76	
1.104	REAR ARM COMP.	1	UNCONFIRM	\$450.76	\$450.76	
1.105	RIM SPORT FRONT	1	CUT	\$939.28	\$939.28	

1.106	RING PISTON (STD)	4	NECESSARY	\$198.24	\$198.24	
1.107	RIVET	2	NECESSARY	\$4.72	\$4.72	
1.108	RUBBER FOOTREST	2	NECESSARY	\$30.68	\$30.68	
1.109	RUBBER MOUNT	12	NECESSARY	\$84.96	\$84.96	
1.110	SCREW	7	NECESSARY	\$16.52	\$16.52	
1.111	SCREW PAN HEAD	1	NECESSARY	\$1.89	\$1.89	
1.112	SEAL OIL (25X40X5) SWINGING ARM	2	NECESSARY	\$9.44	\$9.44	
1.113	SEAL OIL CLUTCH	1	NECESSARY	\$4.72	\$4.72	
1.114	SEAL STEERING CONE	1	NECESSARY	\$23.60	\$23.60	
1.115	SEAL VALVE	8	NECESSARY	\$66.08	\$66.08	
1.116	SENSOR SPEED	1	UNCONFIRM	\$286.15	\$286.15	
1.117	SIREN (CR)	1	CUT	\$3,129.36	\$3,129.36	
1.118	STAY COWLING FRONT	1	UNCONFIRM	\$401.20	\$401.20	
1.119	STICKER (YAMAHA) FUEL TANK	2	NOT NECESSARY	\$28.32		
1.120	STOPPER MAINSTAND	1	NOT NECESSARY	\$6.14		
1.121	STUD	8	NECESSARY	\$68.91	\$68.91	
1.122	SWITCH HANDLE LH	1	CUT	\$232.46	\$232.46	
1.123	TYRE 120/70ZR-17 (METZELER) 58W ROADTEC Z8 TL *SOR	1	CUT	\$259.82	\$259.82	
1.124	TYRE 150/70ZR-17 (METZELER) 69W ROADTEC Z8 *SOR	1	UNCONFIRM	\$245.24	\$245.24	
1.125	VALVE EXHAUST	4	NECESSARY	\$198.24	\$198.24	
1.126	VALVE INTAKE	4	NECESSARY	\$179.36	\$179.36	
1.127	VALVE RIM	1	NECESSARY	\$10.62	\$10.62	
1.128	WINDSHIELD	1	CUT	\$814.20	\$814.20	
2	SCOPE OF REPAIRS					
2.1	REPAIR & SPRAY PAINT DOCUMENT BOX					2
2.2	REPAIR & SPRAY PAINT WHOLE BIKE					24
2.3	WELDING WORK-FRONT CRASH BAR BRACKET					1
2.4	TO REPLACE ALL ABOVE ITEMS					55
3	ADDITIONAL SERVICES					
3.1	TRANSPORT CHARGES (SOR 8) (BILL UNDER MONTH END SOR BILLING)					2
COSTING		TOTAL PARTS COST			\$34,428.49	
		TOTAL MAN-HOUR				84

Vehicle Inspected By

XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.