

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9005 TAMPINES ST 93 #01-204

SINGAPORE 528840

TEL : 67853933 FAX: 67883933

R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S8600369D

LOW FATT SHENG

BLK 53 TAMPINES CENTRAL 7

07-06

SINGAPORE 528616

TEL : FAX :

PH : S8600369D

ATTN :

ESTIMATE BILL

Number : EBK0000232

Date : 01/02/2018

Case No : ADK0000304

Vehicle No : SKC835L

Chassis : JF1BM5KC2AG004159

Year of Mfr 2009

Policy No

Model : SUBARU LEGACY

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	RR BOOTLID	1.0	723.30	20	578.64
2	RR BOOTLID HINGE LH RH	2.0	153.30	20	245.28
3	RR BOOTLID REFLECTOR LH RH	2.0	250.30	20	400.48
4	RR TAILLAMP RH	1.0	501.30	20	401.04
5	RR TAILLAMP PANEL RH	1.0	99.80	20	79.84
6	RR BUMPER	1.0	720.30	20	576.24
7	RR BUMPER SIDE RETAINER LH RH	2.0	38.30	20	61.28
8	RR BUMPER CLIPS	12.0	3.90	20	37.44
9	RR BUMPER REINFORCEMENT	1.0	240.30	20	192.24
10	RR BUMPER REINFORCEMENT BRACKET LH RH	2.0	47.40	20	75.84
11	RR BUMPER INNER AIR DUCT RH	1.0	40.20	20	32.16
12	RR BUMPER EXHAUST COVER RH	1.0	106.00	20	84.80
13	RR BUMPER REFLECTOR RH	1.0	24.30	20	19.44
14	RR BUMPER BRACKET RH	1.0	32.30	20	25.84
15	RR FENDER RH	1.0	960.00	20	768.00
16	RR FENDER INNER PANEL RH	1.0	1,316.90	20	1,053.52
17	RR FENDER INNER SHIELD RH	1.0	72.00	20	57.60
18	RR FENDER INNER SHIELD CLIPS	10.0	3.90	20	31.20
19	RR FUEL TANK CAP	1.0	40.00	20	32.00
20	RR FUEL TANK NECK	1.0	191.60	20	153.28
21	RR FUEL TANK MOTOR	1.0	792.50	20	634.00
22	RR FUEL TANK	1.0	1,091.70	20	873.36
23	RR FUEL TANK DOOR	1.0	65.40	20	52.32
24	RR END PANEL	1.0	320.90	20	256.72
25	RR END PANEL TOP GARNISH	1.0	80.20	20	64.16
26	RR SPARE TYRE PANEL	1.0	460.80	20	368.64
27	RR SHOCK ABSORBER RH	1.0	792.00	20	633.60
28	RR ABSORBER STOPPER RH	1.0	28.00	20	22.40
29	RR ABSORBER MOUNTING RH	1.0	65.00	20	52.00
30	RR END PANEL TOP GARNISH CLIPS	8.0	3.90	20	24.96
31	RR KNUCKLE ARM RH	1.0	440.30	20	352.24
32	RR FENDER INNER GARNISH RH	1.0	156.00	20	124.80
33	RR KNUCKLE BEARING RH	1.0	236.40	20	189.12
34	RR BOOTLID LOGO LEGACY	1.0	48.00	20	38.40

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S8600369D
LOW FATT SHENG
BLK 53 TAMPINES CENTRAL 7
07-06
SINGAPORE 528616
TEL : FAX :
PH : S8600369D
ATTN :

ESTIMATE BILL

Number : EBK0000232
Date : 01/02/2018
Case No : ADK0000304
Vehicle No : SKC835L
Chassis : JF1BM5KC2AG004159
Year of Mfr : 2009
Policy No :
Model : SUBARU LEGACY

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
35	RR BOOTLID LOGO SUBARU & AWA <i>mc</i>	1.0	120.30	20	96.24
36	RR SUBARU EMBLEM <i>mc</i>	1.0	64.80	20	51.84
37	RR AXLE ASSY <i>n1</i>	1.0	860.80	20	688.64
38	RR LOWER ARM RH <i>n1</i>	1.0	220.80	20	176.64
39	RR BRAKE CALIPER RH <i>n1</i>	1.0	619.20	20	495.36
40	RR BOOTLID INNER RUBBER <i>twi</i>	1.0	132.80	20	106.24
41	RR BOOTLID TRIMBOARD <i>n1</i>	1.0	156.00	20	124.80
42	RR BOOTLID LOCK TOP	1.0	176.00	20	140.80
43	RR BOOTLID LOCK BOTTOM	1.0	22.70	20	18.16
44	RR SPARE TYRE PANEL TOP TRIMBOARD	1.0	692.40	20	553.92
45	RR WINDSCREEN MOULDING <i>mc</i>	1.0	86.00	20	68.80
46	RR BOOTLID DAMPER LH RH <i>n1</i>	2.0	136.50	20	218.40
List Price - Parts Sub Total					11,332.72
47	RR BUMPER REVERSE SENSOR LH RH <i>shubd</i>	1.0	250.00	0	250.00
48	SEALANT <i>Rear Windscreen</i>	2.0	20.00	0	40.00
Special Nett Price - Parts Sub Total					290.00
Parts Total					11,622.72
49	RR CHASSIS RH REPAIR <i>n1 x</i>	1.0			
50	RR DOOR RH REPAIR <i>n1 x</i>	1.0			
51	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	2,000.00	0	2,000.00
52	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,800.00	0	1,800.00
53	ANTI RUST COATING	1.0	200.00	0	200.00
54	COMPUTERIZED WHEEL ALIGNMENT	1.0	150.00	0	150.00
55	WIRING	1.0	80.00	0	80.00
56	REMOVE & REFIT RR CUSHION	1.0	300.00	0	300.00
57	LABOUR TO INSTALL REVERSE SENSOR	1.0	120.00	0	120.00
58	REMOVE & REFIT RR WINDSCREEN	1.0	180.00	0	180.00
59	REMOVE & REFIT FUEL TANK	1.0	200.00	0	200.00
60	LABOUR TO INSTALL UNDERCARRIAGE PARTS	1.0	400.00	0	400.00
Labour 1 Sub Total					5,430.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S8600369D
LOW FATT SHENG
BLK 53 TAMPINES CENTRAL 7
07-06
SINGAPORE 528616
TEL : FAX :
PH : S8600369D
ATTN :

ESTIMATE BILL

Number : EBK0000232
Date : 01/02/2018
Case No : ADK0000304
Vehicle No : SKC835L
Chassis : JF1BM5KC2AG004159
Year of Mfr : 2009
Policy No :
Model : SUBARU LEGACY

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
SINGAPORE DOLLARS : EIGHTEEN THOUSAND TWO HUNDRED FORTY-SIX AND CENTS FORTY-ONE ONLY			Less Excess		0.00
			SUBTOTAL		17,052.72
			GST 7.00%		1,193.69
			TOTAL		18,246.41

Date of accident : 01/01/2018 07:15 PM. Place : JALAN EUNOS

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE