


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB660P
Ref. No : TAX/01/18/2178
Reg. Date : 19/01/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : RAJOO TAMILSELVAM
Type of Accident : SIDE SWIPE
Date / Time of Accident : 30/01/2018 12:40:00 PM
Accident Reported Date / Time : 30/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094377
Special Instruction to ARC, if any :
GBG8889P - AIG - LKK / *Repair after repair*
Prepared Date : 30/01/2018 04:24:46 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U505768730


Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	845.00	0.00
Total Spray Painting Charges :	2,808.00	0.00
Total Material Charges :	5,116.97	5,116.97
Other Charges :	700.00	0.00
TOTAL :	9,469.97	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	6.00	0.00 6 days - 9/1
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	31/01/2018 01:32:30 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 31/01/2018 01:32:30 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 1/31/2018 2:26:47 PM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845.00	0.00 600
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
RESPRAY WHEEL CAP	360.00	0.00 X
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 20
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	2,808.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO TRANSFER DOOR MECHANISM	240.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 60
Total Other Costs	700.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>Repair</i>	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>Repair</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>Repair</i>	No
42602-47060		6505676	CAP SUB-ASSY, WHEEL	1	174.10	25.00	130.57	Replace	Replace <i>SCA</i>	No
67001-47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace <i>Repair</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>nan</i>	No
87910-47330		6505600	MIRROR ASSY, RH	1	1,307.10	25.00	980.32	Replace	Replace <i>Repair</i>	No
81730-52090		6505466	MIRROR LAMP RH	1	65.30	10.00	58.77	Replace	Replace <i>SCA</i>	No
879157-4010		6505598	COVER, OUTER MIRROR, RH	1	107.40	25.00	80.55	Replace	Replace <i>Repair</i>	No
69210-74030			DOOR OUTER HANDLE FRT/RH	1	370.80	25.00	278.10	Replace	Replace <i>Repair</i>	No
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace <i>Repair</i>	No
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace <i>Repair</i>	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace <i>nan</i>	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>nan</i>	No
42602-47060		6505676	CAP SUB-ASSY, WHEEL	1	174.10	25.00	130.57	Replace	Replace <i>X</i>	No
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>Repair</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>nan</i>	No
TOTAL MATERIALS							5,117.00	5,116.97		
TOTAL MATERIALS(Discounted)							5,116.97	5,116.97		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									