



# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

AXA/AIG(GBD4082D)  
DOA:29/01/2018@1100

AIG ASIA PACIFIC INSURANCE PTE LTD

1/2/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM  
ESTIMATE COST OF REPAIR FOR VEHICLE NO:  
EM 1313 M - HONDA AIRWAVE 1.5 A  
CHASSIS NO: GJ11114589 (2007)

|       |   |             |
|-------|---|-------------|
| 1 pc  | Rear bumper   | \$ 741.00   |
| 1 pc  | Rear bumper retainer LH   | \$ 28.00    |
| 1 pc  | Rar taillamp LH   | \$ 392.00   |
| 1 pc  | Rear boot lower   | \$ 451.00   |
| 1 pc  | Rear boot 'logo'  | \$ 26.00    |
|       |   | <hr/>       |
|       |   | \$ 1,638.00 |
|       | LESS 20%  | \$ 327.60   |
|       |   | <hr/>       |
|       |   | \$ 1,310.40 |
| 1 set | Reverse Sensor (S/NETT)   | \$ 200.00   |
|       | Check wiring function   | \$ 40.00    |
|       | Remove necessary action: jacking, panel beating,<br>repair and straighten rear inner panel, rear boot,<br>rear bumper and affected areas. | \$ 500.00   |
|       | Putty and respray rear inner panel, rear boot<br>and rear bumper.   | \$ 400.00   |
|       |   | <hr/>       |
|       |   | \$ 2,450.40 |
|       | ADD 7% GST  | \$ 171.53   |
|       |   | <hr/>       |
|       |   | \$ 2,621.93 |

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....