

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3220B

MAKE :

MODEL : HYUNDAI i40

Ag Big-45
LKK-Kalvin
DATE 31/1/2018

TS

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>X repair</i>			\$ 603.60	
	Rear Bumper Clips 10 pcs <i>X</i>			\$ 22.00	
	Rear Fender (RH) <i>X repair</i>			\$ 2,020.10	
	Rear Fender Inner Lining (RH) <i>X</i>			\$ 164.40	
	Rear Windscreen Moulding <i>X</i>			\$ 60.00	
	Rear Door (RH) <i>—</i>			\$ 1,351.10	
	Rear Wheel Hub-Cap (RH) <i>—</i>			\$ 150.70	
	<i>Front Door (RH) X repair</i>				
	<i>Locker Panel handle (RH) X repair</i>				
	SUB TOTAL			\$ 4,371.90	
	LESS 20%			\$ 874.38	
	DISCOUNTED TOTAL			\$ 3,497.52	
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00	Nett
	Rear Windscreen Sealant <i>X</i>			\$ 46.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>—</i>			\$ 80.00	Nett
	<i>Front Door sticker (L/RHS) —</i>			\$ 75.00	
				\$ 176.00	
	Labour Charge				
	Panel Beating			\$ 850.00	
	Spray Painting Charge			\$ 600.00	<i>1000.00</i>
	Wiring Charge			\$ 50.00	<i>X</i>
	Tuff Kote			\$ 50.00	<i>20</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	<i>X</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00	<i>X</i>
	Remove/Refix Reverse Sensor			\$ 120.00	<i>X</i>
	Transfer of Door			\$ 120.00	<i>50</i>
	Rear Wheel Alignment			\$ 120.00	<i>X</i>
	TOTAL LABOUR			\$ 2,180.00	
	ESTIMATE TOTAL			\$ 5,853.52	
	LKK Auto Consultants hence notify the Repairer of the following: • To survey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party surveys on a "Without prejudice" basis • No illegal modifications is allowed • Supplementary items must be surveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.				

Kalvin LKK

31/1/18 15:10 hr
2 Days

45
After Repair photo