

SS REC. BY:

REF:

CS/SMU/3002036 / D.opez

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Grou Teo of SMO Date/Time: 01/02/2018 3:46pm

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKU 2046P Insured: CB 7343Tat Workshop m/s Vermogen Tel: 6904 4396of 6 Bendi SectorPolicy No: _____ Claim No: CM701800538 / NSW

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 31/02/18
(Client's Record)CA / REV / REP. / REV 24 HRS 'wp' 02.02.2018 H.O.D. Endorsement: _____Date/Time: 01/02/2018 11:33pm Person Contacted: Ria Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKU 2046P - X</u>
	<u>CB 7343T - NA / TNCIHOFFULLS/d3</u> <u>DOA: 040914</u>
<u>06/07/18 @ 9.47am</u>	<u>Revised to Shawn Ngo by email.</u>
<u>29/9/18 @ 3pm</u>	<u>Confirmed with Erol is \$7000, 18 days.</u>
	<u>(Red to 77476.74, 76%)</u>

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TR RES / CD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop No: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bel. or Market value: \$5K

IDAC Accident Report: _____ Consistent? Yes or No

GIA - PR Seen: _____ Consistent? Yes or No

Est. Repairs: 18 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Serial: SKY 2046P V Reg: AUG 2013
 Type: MCA M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover
 Truck / Trailer: _____
 Make: TOYOTA V102. CC: 1497
 Colour: Berge A/C: Insured / Std / Nil / NA
 So Resing: 26399 T Resig: Insured / Std / Nil / NA
 Eng No: _____
 C No: MR2B59F 3801032199
 Gen. Con: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Mod: Nil / SR / STD A/Rim or
 Tyre Size: F: 175/55R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /
 TOYO / YOKO or Achilles
 Front: _____ Rear: _____
 R Bel: 8 mm R Bel: 8 mm
 L Bel: 8 mm L Bel: 8 mm
 D/OA: 31/12/08 D/O: 2/2/08
 Survey held at: _____
 Des. of Damages: Fr / Rear / O/S / N/S / U/O / Rooftop or
 The U/O / Chassis frame / Body Structure affected due to collision

Date / Time / Action / Instruction

max Repair to 7000

RECEIVED 20 SEP 2010

TGLin

15/8/18

Date/Time For Passout

18/9/2010
☐

Prel. Report

☐

Final Report

Date/Time For Return

Days Of Repair: 18Resurvey No. of Trip: 1

Survey Fee

Add Fee:

☐

State Tax: 13

☐

Harm: 6

☐

Taxes: 3

☐

Insurance: 3

Report Format

TP

Lump Sum

7000

450

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18002036/M1qb	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623		Date : 01-02-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	CB 7343T	Veh. Inspected	SKU 2046P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800538/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	01/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/01/2018	Inspection Date	02/02/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 1 February, 2018 3:46 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: pila.vermogenace@gmail.com; 'Edmond Lim jian zhi'; minokovermogenace@gmail.com; ezelvermogenace@gmail.com; Ngo, Sau Wei Shawn; Henry, Irene James
Subject: CMTD1800538/NSW - ACCIDENT INVOLVING CB7343T & SKU2046P ON 31.01.18

Our Reference: CMTD1800538/NSW

Dear LKK AUTO CONSULTANTS/ Mohd Taufikh,

Please make arrangement to conduct the survey for SKU2046P.

Please be informed that Shawn Ngo the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: pila.vermogenace@gmail.com [mailto:pila.vermogenace@gmail.com]

Sent: Thursday, February 01, 2018 3:22 PM

To: Teo, Grace

Cc: 'Edmond Lim jian zhi'; minokovermogenace@gmail.com; ezelvermogenace@gmail.com; Ngo, Sau Wei Shawn; Henry, Irene James

Subject: RE: CMTD1800538/NSW - ACCIDENT INVOLVING CB7343T & SKU2046P ON 31.01.18

Hi Grace,

Kindly arrange LKK Auto Consultants (Mohd Taufikh (West area) come to conduct the PRS matter.

Thanks & regards,

Pila

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Thursday, February 1, 2018 12:59 PM
To: pila.vermogenace@gmail.com
Cc: 'Edmond Lim jian zhi' <edmondvermogenace@gmail.com>; minokovermogenace@gmail.com; ezelvermogenace@gmail.com; Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1800538/NSW - ACCIDENT INVOLVING CB7343T & SKU2046P ON 31.01.18

Our Reference : CMTD1800538/NSW
Your Reference: SKU2046P

Without Prejudice

Date: 1st February 2018

Attention:
M/S VERMONGEN ACE PTE LTD

Dear Pila,

ACCIDENT INVOLVING CB7343T & SKU2046P ON 31.01.18

We refer to your Notice of Accident dated 31/01/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: pila.vermogenace@gmail.com [<mailto:pila.vermogenace@gmail.com>]

Sent: Wednesday, January 31, 2018 5:23 PM

To: Claims - Motor Survey

Cc: 'Edmond Lim jian zhi'; minokovermogenace@gmail.com; ezelvermogenace@gmail.com

Subject: FW: NTUC :PLEASE ARRANGE TP SURVEY (OUR REF:SKU2046P) YOUR REF:CB7343T DOA:31/1/2018

Dear Arrange survey dept

Kindly arrange TP survey on **01/02/2017 (THURSDAY)** following detail & attach here GIA report:

Survey before repair

Your Vehicle:CB7343T

Our Vehicle: SKU2046P

DOA : 01/02/2018

AOL :SLE TOWARDS MANDAI

Vehicle Location: 6 BENOI SECTOR SINGAPORE 629904

Thank You.

Best Regards,

PILA
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent

#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929

Shiau Chan (LKKAUTO)

From: ezel.t@vermogen-group.com
Sent: Thursday, 27 September 2018 3:00 PM
To: Shiau Chan (LKKAUTO)
Cc: Asher Sng (LKKAUTO); Admin-D (LKKAUTO); 'Baldoz Juan Paulo Bongon'; Hsiao Tong (LKKAUTO); SUR; Rasul (LKKAUTO); 'Vmg admin'; 'Glorioso Eric Paul Patambang'; 'Minoko Chan'; 'Pila Ng'; 'Desmond Kor'; 'Edmond Lim'; 'Lina Rosli'; 'Luis Tan'; 'Paul Tan'
Subject: RE: SKU2046P DOA: 31/01/2018 TO FINALISE (SOMPO TP)

Dear Ms Shiau,

We confirmed COR L/S \$7000.00 before GST and 18 repair days.

Thanks & Regards,
Ezel Tejano

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, September 14, 2018 4:20 PM
To: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>
Cc: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; SUR <sur@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tejano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>; Pila Ng <pila@vermogen-group.com>; Desmond Kor <desmond@vermogen-group.com>; Edmond Lim <edmond@vermogen-group.com>; Lina Rosli <linarosli@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>
Subject: RE: SKU2046P DOA: 31/01/2018 TO FINALISE (SOMPO TP)

Dear Baldoz Paulo,

WITHOUT PREJUDICE

Can confirm repair cost at Lump Sum \$7,000.00 before GST and 18 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 16 August 2018 5:06 PM
To: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>
Cc: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; SUR <sur@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tejano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>; Pila Ng <pila@vermogen-group.com>; Desmond Kor <desmond@vermogen-group.com>; Edmond Lim <edmond@vermogen-group.com>; Lina Rosli <linarosli@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>
Subject: RE: SKU2046P DOA: 31/01/2018 TO FINALISE (SOMPO TP)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 6 February 2018 9:47 AM
To: 'Teo, Grace'; assignments; 'Ngo, Sau Wei Shawn'
Cc: 'Henry, Irene James'; SUR
Subject: RE: CMTD1800538/NSW - ACCIDENT INVOLVING CB7343T & SKU2046P ON 31.01.18
Attachments: CSSMO18002036M1qb.pdf

Dear Shawn,

Enclosed herewith preliminary advice of SKU 2046P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 1 February 2018 4:25 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1800538/NSW - ACCIDENT INVOLVING CB7343T & SKU2046P ON 31.01.18

Dear Grace,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Thursday, 1 February, 2018 3:46 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: pila.vermogenace@gmail.com; 'Edmond Lim jian zhi' <edmondvermogenace@gmail.com>; minokovermogenace@gmail.com; ezelvermogenace@gmail.com; Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1800538/NSW - ACCIDENT INVOLVING CB7343T & SKU2046P ON 31.01.18

Our Reference: CMTD1800538/NSW

Dear LKK AUTO CONSULTANTS/ Mohd Taufikh,

Please make arrangement to conduct the survey for SKU2046P.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1800538/NSW

Date: 05 February 2018

Our Ref: CS/SMO18002036/M1qb

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKU 2046P


We thank you for the instruction on 01/02/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/02/2018 at the premises of M/s VERMOGEN and have the following to report:-

Workshop Estimate Amount	: S\$ <u>31,540.11</u>
Revised Estimate Amount	: S\$ <u>16,962.25</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 18 days.

We have NOT authorized repair.

Yours faithfully

Ma C.F.
Automobile Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SKU2046P
Vehicle to be Exported:	No
Intended De-registration Date:	05 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G GRADE AUTO
Primary Colour:	Beige
Manufacturing Year:	2013
Engine No.:	1NZY853062
Chassis No.:	MR2BT9F3801032199
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,681.00
Original Registration Date:	28 Aug 2013
First Registration Date:	28 Aug 2013
Transfer Count:	2
Actual ARF Paid:	\$9,681.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2023
PARF Rebate Amount:	\$7,260.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$76,223.00
COE Rebate Amount:	\$42,373.00
Total Rebate Amount:	\$49,633.00

The information contained herein is correct as at 05 Feb 2018

OK

- I'm a nurse. Ask me anything about nursing
- Upgrade to EC
- Apple iPhone 8 & iPhone X

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In And
Welcome! 100% Deposit Refund
For Unapproved Loan.
Classic Credit - 30kms



Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

1 vehicles

VIOS

Advanced Search 🔍

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	VIOS	Any	Any	2013	Any	Any	Any	Available
	Toyota Vios 1.5A E	\$56,800	\$10,010 /yr	18-Jun-2013	1,497 cc	110,000 km	Sedan	Available
Cheapest In Town! Premium Dealer Award Winner 2013 To 2018! \$6000 Down Payment, Excellent Condition, All Time Favorite Model, Fully Serviced And Maintained By Agent, Uber/Grab Welcome, Trade In Welcome...								
Heritage Auto Enterprise Pte Ltd								
Posted: 21-Jan-2018 Tags: 2013 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
For old advertisements, view Expired ads								
20 results/page								

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used VIOS, VIOS Singapore, used VIOS Singapore, used VIOS, used vehicles Singapore or even buy used VIOS Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that the information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/01/2018 14:04
Date Of Accident	31/01/2018 07:15
Exact Location Of Accident	SLE TOWARDS MANDAI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU2046P
Insured/Policyholder	
Name Of Registered Owner	LGRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995061
Cover Note Number	

Driver

Name of Driver	TAN CHOON PENG (CHEN JUNPING)
NRIC No	S7234578I
Date Of Birth	20/09/1972
Occupation	OUTDOOR
Date Of Driving Pass	13/12/2013
Driving Experience	4 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	44 BENOI ROAD BLOCK B (ENTTRANCE B) ENTRANCE 6 BENOI SECTOR
Postcode	629904
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JACK GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB7343T
Vehicle Make/Model/Colour	
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLF105H
Vehicle Make/Model/Colour	
Details Of Properties	VEH. C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

  Policyholder's Signature Date & Time:	 Driver's Signature (If driver is not the policyholder) Date & Time:	 Reporting Centre Personnel's Signature Name: NRIC/PRN No.:
--	--	---

Accident Sketch Plan Pg. 2

- (A) SKU 20101
- (B) CB7343T
- (C) SLF105H

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along SLE towards mandai with a passenger with a congested slow traffic. When the car in front of me stopped, I also stopped suddenly. I feel an impact from my rear, and makes my car surge forward and hit the car in front of me.

Then I realised, a van has collided into my car. I have video as proof.

DECLARATION



(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PR No.:

DRIVER NRIC AND LICENSE



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SKU2046P

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER :	<u>SOMPO</u>
OWN INSURER :	<u>AIG</u>
CLAIM TYPE :	<u>TP</u>
Date of Accident :	<u>31/1/2018</u>

Vehicle Reg. No. :	SKU2046P
Vehicle Reg. Date:	28-Aug-2013
Make / Model :	VIOS G GRADE AUTO
Engine No. :	1NZY853062
Chassis No. :	MR2BT9F3801032199

COST OF CLAIMS

Parts Cost / List Items :	\$	23,368.99
Plus/Less 25%	\$	5,842.25
Total Cost / List :	\$	17,526.74
Special Nett Items :	\$	1,530.00
Total Parts Amount :	\$	19,056.74
Total Labour Amount :	\$	10,420.00
Gross Total :	\$	29,476.74
GST % : 7%	\$	2,063.37
Nett Amount :	\$	31,540.11

Surveyor Name and Company :

Date of survey : _____

Part by Part / Lump Sum : _____ days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : _____

Fax No : _____

HP No : _____

This claim is handled by : EDMOND

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SKU2046P**

Vehicle Reg. Date: **28/8/2013**

Make / Model : **VIOS G GRADE AUTO**

Engine No. : **1NZY853062**

Chassis No. : **MR2BT9F3801032199**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Bonnet	low ✓	\$ 553.50	Acc ✓	✓
2	1	Bonnet lock	bt ✓	\$ 126.10	BT ✓	✓
3	2	Bonnet hinge LH/RH @ \$87.10	bt ✓	\$ 174.20	BT ✓	✓
4	1	Headlamp LH/RH @ \$568.10	low ✓	\$ 1,136.20	BR ✓	✓
5	1	Front support panel (complete)	bt ✓	\$ 788.00		
6	2	Front support panel LH/RH (top) @ \$100.10	low ✓	\$ 200.20	BR ✓	✓
7	1	Condenser	low X	\$ 1,293.00		
8	1	Radiator	low X	\$ 1,845.00		
9	1	Radiator top cover	low ✓	\$ 100.10		✓
10	1set	Radiator top cover clip	low ✓	\$ 40.00		✓
11	1	Radiator grille base	low ✓	\$ 313.30		✓
12	1	Radiator grille chrome moulding	low ✓	\$ 250.25		✓
13	1	Radiator grille emblem	low ✓	\$ 70.20		✓
14	1	Front bumper	det ✓	\$ 477.10		✓
15	1set	Front bumper clip	low ✓	\$ 50.00	40 ✓	✓
16	1	Front bumper top rubber	low X	\$ 44.20	low ✓	✓
17	1	Front bumper tow cover	low ✓	\$ 59.00		✓
18	1	Front bumper reinforcement	low ✓	\$ 435.50		✓
19	2	Front bumper side retainer LH/RH @ \$74.10	low ✓	\$ 148.20		✓
20	1	Front bumper lower grille	low ✓	\$ 55.90		✓
21	2	Front fog lamp LH/RH @ \$247.00	low X	\$ 494.00		
22	2	Front fog lamp cover LH/ RH @ \$75.00	low X	\$ 150.00		
23	1	Washer tank	low ✓	\$ 131.30		
24	1	Washer tank pump	low X	\$ 174.20		
25	1	Horn (high tone)	low X	\$ 117.00		
26	1	Horn (low tone)	low X	\$ 117.00		
27	2	LH/RH front fender @ \$510.00	low X	\$ 1,020.00	NIS Det ✓	OSTL
28	2	LH/RH front fender undershield @ \$168.00	low X	\$ 336.00	NIS Det ✓	OSTL
29	1set	LH/RH front fender undershield clip	low ✓	\$ 80.00	leg ✓	✓
30	2	LH/RH fender emblem "VVTI" @ \$70.20	low X	\$ 140.40		✓
31	2	Rear No.plate lamp LH/RH @ \$102.30	low ✓	\$ 204.60		✓
32	1	Rear bumper	det ✓	\$ 521.80	DIS ✓	✓
33	1set	Rear bumper clip	low ✓	\$ 50.00	40 ✓	✓
34	2	Rear bumper side retainer LH/RH @ \$93.80	low ✓	\$ 187.60		✓
35	2	Rear bumper side retainer no. 2 LH/RH @ \$93.80	low ✓	\$ 187.60	X NIS ✓	✓
36	2	Rear bumper reflector LH/RH @ \$115.40	low ✓	\$ 230.80		✓
37	2	Rear bumper watershield LH/RH @ \$168.00	low X	\$ 336.00		
38	1	Bootlid	low ✓	\$ 933.30		✓
39	1	Bootlid lock	low ✓	\$ 92.60		✓
40	1	Bootlid lock cable	low ✓	\$ 88.30		✓

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SKU2046P**

Vehicle Reg. Date: **28/8/2013**

Make / Model : **VIOS G GRADE AUTO**

Engine No. : **1NZY853062**

Chassis No. : **MR2BT9F3801032199**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Bootlid lock catch	Wt ✓	\$ 75.30		✓
42	2	Bootlid hinge LH/RH @ \$157.60	Wt ✓	\$ 315.20		✓
43	1	Bootlid logo	Wt ✓	\$ 104.20		✓
44	1	Bootlid emblem 'VIOS'	Wt ✓	\$ 93.80		✓
45	1	Bootlid emblem 'E'	Wt ✓	\$ 75.80		✓
46	2	Bootlid reflector LH/RH @ \$115.40	Nsg ✓	\$ 230.80		
47	1	Boot weatherstrip	Wt ✓	\$ 102.00	NN	
48	1	Bootlid outer chrome garnish	Wt ✓	\$ 627.20		✓
49	1	Rear windscreen moulding	Wt ✓	\$ 180.00		✓
50	1	Rear end panel	Wt ✓	\$ 627.20		✓
51	1	Rear end panel garnish	Wt ✓	\$ 200.30		
52	1	Rear end panel garnish clip - set	Wt ✓	\$ 50.00	20	✓
53	2	Rear fender LH/RH @ \$1105.00	Nsg ✓	\$ 2,210.00	Wt	
54	2	Rear fender inner trim LH/RH @ \$457.60	Wt ✓	\$ 915.20	Wt	
55	1set	Rear fender inner trim clip - set		\$ 80.00	40 / Wt	
56	2	Tail lamp LH/RH @ \$296.30	✓	\$ 592.60	Wt	✓
57	1set	Tail lamp clip - set		\$ 40.00	30 / Wt	
58	2	Tail lamp panel LH/RH @ \$160.10	Nsg ✓	\$ 320.20	Wt	
59	1	Spare tyre well panel	Wt ✓	\$ 845.90		✓
60	1	Spare tyre board	Wt ✓	\$ 415.80		✓
61	2	Spare tyre panel sponge LH/RH @ \$216.92	Wt ✓	\$ (433.84)	Nsg	
62	1	Spare tyre panel sponge centre	Nsg ✓	\$ 388.40		
63	1	Exhaust muffler	Wt ✓	\$ 617.20		
64	1	Exhaust muffler mounting	Wt ✓	\$ 75.60		
65	2	Front/Rear number plate @ \$50.00	Wt ✓	\$ 100.00	20	✓
66	1	Bootlid sealant	Wt ✓	\$ 80.00	60	✓
67	2	Rear end panel sealant	Wt ✓	\$ 80.00		✓
68	1	Spare tyre panel sealant	Wt ✓	\$ 80.00		✓
69	2	Rear fender LH/RH sealant	Wt ✓	\$ 160.00	20	✓
70	1	Tail lamp sealant	Wt ✓	\$ 160.00		
71	2	Tail lamp pad	Wt ✓	\$ 60.00		
72	2	Rear windscreen sealant	Wt ✓	\$ 80.00	60	✓
73	1	Rear windscreen primer/inner seal	Wt ✓	\$ 80.00	40	✓
74	1	Reverse sensor	Wt ✓	\$ 300.00	220	✓
75	1	Spare tyre	Wt ✓	\$ 350.00		✓
76	1	0				
77	1	0				
78	1	0				
79	1	0				
80	1	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SKU2046P**
 Vehicle Reg. Date: **28/8/2013**
 Make / Model : **VIOS G GRADE AUTO**
 Engine No. : **1NZY853062**
 Chassis No. : **MR2BT9F3801032199**

LKK Auto Consultants hence notify
 and Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To straighten and panel beating . To cut/weld panels. Front Portion.	\$ 1,500.00	1080
2	To putty, respray painting and polish affected areas. Front Portion.	\$ 1,600.00	1080
3	To check and rectify wiring after disconnect and connect.	\$ 100.00	30
4	To remove and refit radiator, condenser to facilitate repair and top up A/C gas.	\$ 200.00	150
5	To straighten and panel beating . To cut/weld panels. Rear Portion.	\$ 3,000.00	1800
6	To putty, respray painting and polish affected areas. Rear Portion.	\$ 2,500.00	1200
7	To remove and refit reverse sensor.	\$ 150.00	80
8	To remove and refit rear windscreen glass.	\$ 150.00	120
9	To remove and refit interior trims, seats, carpet and upholstery to facilitate repair.	\$ 400.00	80
10	To remove and refit exhaust pipe and align.	\$ 200.00	X
11	To remove and refit petrol tank to facilitate repair.	\$ 200.00	X
12	To remove and transfer bootlid components.	\$ 120.00	X
13	To rust proof affected areas.	\$ 300.00	100

I hereby notify
 the repairer of the following:
 To resurvey before/after spray painting
 To display damaged part(s) during resurvey
 Parts prices are subject to confirmation
 Third party survey is on a "Without Prejudice" basis
 No illegal modification(s) is allowed
 Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Not Anthony
 LKK Auto
 LKK Auto Consultants

2/2/2018
 18w days

12/2/18



SKU2046P

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : SOMPO
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 31/1/2018

Vehicle Reg. No. : SKU2046P
Vehicle Reg. Date : 28-Aug-2013
Make / Model : VIOS G GRADE AUTO
Engine No. : 1NZY853062
Chassis No. : MR2BT9F3801032199

COST OF CLAIMS

Parts Cost / List Items : \$ 23,368.99
Plus/Less 25% \$ 5,842.25
Total Cost / List : \$ 17,526.74
Special Nett Items : \$ 1,530.00
Total Parts Amount : \$ 19,056.74
Total Labour Amount : \$ 10,420.00
Gross Total : \$ 29,476.74
GST % : 7% \$ 2,063.37
Nett Amount : \$ 31,540.11

Surveyor Name and Company :

Date of survey : _____
Part by Part / Lump Sum : _____ days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : _____
Fax No : _____
HP No : _____

This claim is handled by : EDMOND

$$\begin{array}{r} P = 13580.27 \\ - 25\% \\ \hline 10189.70 \\ SM = 700 \\ L = 5560 \\ \hline 10449.70 \\ - 70\% \\ \hline 3157.76 \\ L/S = 13100 \end{array}$$

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SKU2046P**

Vehicle Reg. Date: **28/8/2013**

Make / Model : **VIOS G GRADE AUTO**

Engine No. : **1NZY853062**

Chassis No. : **MR2BT9F3801032199**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Bonnet	new ✓	\$ 553.50		
2	1	Bonnet lock	BT ✓	\$ 126.10		
3	2	Bonnet hinge LH/RH @ \$87.10	BT ✓	\$ 174.20		
4	1	Headlamp LH/RH @ \$568.10	new ✓	\$ 1,136.20		
5	1	Front support panel (complete)	BT ✓	\$ 788.00		
6	2	Front support panel LH/RH (top) @ \$100.10	new ✓	\$ 200.20		
7	1	Condenser	new X	\$ 1,293.00		
8	1	Radiator	new X	\$ 1,845.00		
9	1	Radiator top cover	new ✓	\$ 100.10		
10	1set	Radiator top cover clip	new ✓	\$ 40.00		
11	1	Radiator grille base	new ✓	\$ 313.30		
12	1	Radiator grille chrome moulding	new ✓	\$ 250.25		
13	1	Radiator grille emblem	new ✓	\$ 70.20		
14	1	Front bumper	new ✓	\$ 477.10		
15	1set	Front bumper clip	new ✓	\$ 50.00	40	
16	1	Front bumper top rubber	new X	\$ 44.20		
17	1	Front bumper tow cover	new ✓	\$ 59.00		
18	1	Front bumper reinforcement	new ✓	\$ 435.50		
19	2	Front bumper side retainer LH/RH @ \$74.10	new ✓	\$ 148.20		
20	1	Front bumper lower grille	new ✓	\$ 55.90		
21	2	Front fog lamp LH/RH @ \$247.00	new X	\$ 494.00		
22	2	Front fog lamp cover LH/ RH @ \$75.00	new ✓	\$ 150.00		
23	1	Washer tank	new X	\$ 131.30		
24	1	Washer tank pump	new X	\$ 174.20		
25	1	Horn (high tone)	new X	\$ 117.00		
26	1	Horn (low tone)	new X	\$ 117.00		
27	2	LH/RH front fender @ (\$510.00)	new ✓	\$ 1,020.00	NS DA	OS 12
28	2	LH/RH front fender undershield @ \$168.00	new ✓	\$ 336.00	NS dng	OS 9/1
29	1set	LH/RH front fender undershield clip	new ✓	\$ 80.00	40	
30	2	LH/RH fender emblem "VVTI" @ \$70.20	new X	\$ 140.40		
31	2	Rear No.plate lamp LH/RH @ \$102.30	new ✓	\$ 204.60		
32	1	Rear bumper	new ✓	\$ 521.80		
33	1set	Rear bumper clip	new ✓	\$ 50.00	40	
34	2	Rear bumper side retainer LH/RH @ \$93.80	new ✓	\$ 187.60		
35	2	Rear bumper side retainer no. 2 LH/RH @ \$93.80	new ✓	\$ 187.60	X NSP	
36	2	Rear bumper reflector LH/RH @ \$115.40	new ✓	\$ 230.80		
37	2	Rear bumper watershield LH/RH @ \$168.00	new X	\$ 336.00		
38	1	Bootlid	new ✓	\$ 933.30		
39	1	Bootlid lock	new ✓	\$ 92.60		
40	1	Bootlid lock cable	new ✓	\$ 88.30		

B-7801

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SKU2046P**

Vehicle Reg. Date: **28/8/2013**

Make / Model : **VIOS G GRADE AUTO**

Engine No. : **1NZY853062**

Chassis No. : **MR28T9F3801032199**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Bootlid lock catch	Wt ✓	\$ 75.30		
42	2	Bootlid hinge LH/RH @ \$157.60	Wt ✓	\$ 315.20		
43	1	Bootlid logo	Wt ✓	\$ 104.20		
44	1	Bootlid emblem 'VIOS'	Wt ✓	\$ 93.80		
45	1	Bootlid emblem 'E'	Wt ✓	\$ 75.80		
46	2	Bootlid reflector LH/RH @ \$115.40	Nsg ✓	\$ 230.80		
47	1	Boot weatherstrip	Wt ✓	\$ 102.00		
48	1	Bootlid outer chrome garnish	Wt ✓	\$ 627.20		
49	1	Rear windscreen moulding	Wt ✓	\$ 180.00		
50	1	Rear end panel	Wt ✓	\$ 627.20		
51	1	Rear end panel garnish	Wt ✓	\$ 200.30		
52	1	Rear end panel garnish clip - set	Wt ✓	\$ 50.00	20	
53	2	Rear fender LH/RH @ \$1105.00	Nsg ✓	\$ 2,210.00	Nsg	
54	2	Rear fender inner trim LH/RH @ \$457.60	Nsg ✓	\$ 915.20	Wt	
55	1set	Rear fender inner trim clip - set		\$ 80.00	40	
56	2	Tail lamp LH/RH @ \$296.30	Wt ✓	\$ 592.60	Wt	
57	1set	Tail lamp clip - set		\$ 80.00	30	
58	2	Tail lamp panel LH/RH @ \$160.10	Nsg ✓	\$ 320.20	Nsg	
59	1	Spare tyre well panel	Wt ✓	\$ 845.90		
60	1	Spare tyre board	Wt ✓	\$ 415.80		
61	2	Spare tyre panel sponge LH/RH @ \$216.92	Wt ✓	\$ 433.84	Nsg	
62	1	Spare tyre panel sponge centre	Nsg ✓	\$ 388.40		
63	1	Exhaust muffler	Wt ✓	\$ 617.20		
64	1	Exhaust muffler mounting	Wt ✓	\$ 75.60		
65	2	Front/Rear number plate @ \$50.00	Wt ✓	\$ 100.00	20	
66	1	Bootlid sealant	Wt ✓	\$ 80.00	60	
67	2	Rear end panel sealant	Wt ✓	\$ 80.00		
68	1	Spare tyre panel sealant	Wt ✓	\$ 80.00		
69	2	Rear fender LH/RH sealant	Wt ✓	\$ 160.00	20	
70	1	Tail lamp sealant	Wt ✓	\$ 160.00		
71	2	Tail lamp pad	Wt ✓	\$ 60.00		
72	2	Rear windscreen sealant	Wt ✓	\$ 80.00	60	
73	1	Rear windscreen primer/inner seal	Wt ✓	\$ 80.00	40	
74	1	Reverse sensor	Wt ✓	\$ 308.00	220	
75	1	Spare tyre	Wt ✓	\$ 350.00	Wt	
76	1	0				
77	1	0				
78	1	0				
79	1	0				
80	1	0				

P= 5725.30

SH= 700

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SKU2046P**
 Vehicle Reg. Date: **28/8/2013**
 Make / Model : **VIOS G GRADE AUTO**
 Engine No. : **1NZY853062**
 Chassis No. : **MR2BT9F3801032199**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To straighten and panel beating . To cut/weld panels. Front Portion.	\$ 2,500.00	1,000
2	To putty, respray painting and polish affected areas. Front Portion.	\$ 2,600.00	1,000
3	To check and rectify wiring after disconnect and connect.	\$ 100.00	30
4	To remove and refit radiator, condenser to facilitate repair and top up A/C gas.	\$ 200.00	150
5	To straighten and panel beating . To cut/weld panels. Rear Portion.	\$ 3,000.00	1,800
6	To putty, respray painting and polish affected areas. Rear Portion.	\$ 2,500.00	1,200
7	To remove and refit reverse sensor.	\$ 150.00	50
8	To remove and refit rear windscreen glass.	\$ 150.00	120
9	To remove and refit interior trims, seats, carpet and upholstery to facilitate repair.	\$ 400.00	80
10	To remove and refit exhaust pipe and align.	\$ 200.00	X
11	To remove and refit petrol tank to facilitate repair.	\$ 200.00	X
12	To remove and transfer bootlid components.	\$ 120.00	X
13	To rust proof affected areas.	\$ 300.00	100
	Not Aesthemic L/S Depn H/Acc paint job to ble Auto (m/s)		

chk m/s.

2/2/2018
18w days

L= 5500



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18002036/Dqbe2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 26-10-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 7343T	Veh. Inspected	SKU 2046P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800538/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	01/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	MR2BT9F3801032199	Colour	BEIGE
Odometer	263999	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	ACHILLES	8 mm
L/H Front Tyre	195/55 R15	ACHILLES	8 mm
R/H Rear Tyre	195/55 R15	ACHILLES	8 mm
L/H Rear Tyre	195/55 R15	ACHILLES	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/01/2018	Inspection Date	02/02/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	18 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EG18012528/Atbn2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 26-10-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 5199A	Veh. Inspected	SJW 6451C
Policy No.		Coverage (\$)	0.00
Claim No.	SJP5199A/SA/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	10/07/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GE61052338	Colour	WHITE
Odometer	148194	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/55 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/55 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/07/2018	Inspection Date	10/07/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 2046P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	BUCKLED	553.50	553.50
1	BONNET LOCK	BENT	126.10	126.10
2	BONNET HINGE LH/RH @\$87.10	BENT	174.20	174.20
2	HEADLAMP LH/RH @\$568.10	CRACKED / BROKEN	1,136.20	1,136.20
1	FRONT SUPPORT PANEL (COMPLETE)	BENT	788.00	788.00
2	FRONT SUPPORT PANEL LH/RH (TOP) @\$100.10	BENT / BROKEN	200.20	200.20
1	CONDENSER	SERVICEABLE	1,293.00	-
1	RADIATOR	SERVICEABLE	1,845.00	-
1	RADIATOR TOP COVER	DISTORTED	100.10	100.10
1	SET RADIATOR TOP COVER CLIP	NECESSARY	40.00	40.00
1	RADIATOR GRILLE BASE	DISTORTED	313.30	313.30
1	RADIATOR GRILLE CHROME MOULDING	DISTORTED	250.25	250.25
1	RADIATOR GRILLE EMBLEM	NECESSARY	70.20	70.20
1	FRONT BUMPER	DEFORMED	477.10	477.10
1	SET FRONT BUMPER CLIP	NECESSARY	50.00	40.00
1	FRONT BUMPER TOP RUBBER	NECESSARY	44.20	44.20
1	FRONT BUMPER TOW COVER	DISTORTED	59.00	59.00
1	FRONT BUMPER REINFORCEMENT	BENT	435.50	435.50
2	FRONT BUMPER SIDE RETAINER LH/RH @\$74.10	DISTORTED	148.20	148.20
1	FRONT BUMPER LOWER GRILLE	DISTORTED	55.90	55.90
2	FRONT FOG LAMP LH/RH @\$247.00	NO SUCH PARTS	494.00	-
2	FRONT FOG LAMP COVER LH/RH @\$75.00	SERVICEABLE	150.00	-
1	WASHER TANK	SERVICEABLE	131.30	-
1	WASHER TANK PUMP	SERVICEABLE	174.20	-
1	HORN (HIGH TONE)	SERVICEABLE	117.00	-
1	HORN (LOW TONE)	SERVICEABLE	117.00	-
2	LH/RH FRONT FENDER @\$510.00	N/S BENT / O/S TO REPAIR SEE LABOUR	1,020.00	510.00
2	LH/RH FRONT FENDER UNDERSHIELD @\$168.00	SERVICEABLE	336.00	-
1	SET LH/RH FRONT FENDER UNDERSHIELD CLIP	NECESSARY	80.00	40.00
2	LH/RH FENDER EMBLEM "VVTI" @\$70.20	NO SUCH PARTS	140.40	-
2	REAR NO.PLATE LAMP LH/RH @\$102.30	MISSING	204.60	204.60

Report Ref No. CS/SMO18002036/Dqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER	DEFORMED / DISTORTED	521.80	521.80
1	SET REAR BUMPER CLIP	NECESSARY	50.00	40.00
2	REAR BUMPER SIDE RETAINER LH/RH @\$93.80	DISTORTED	187.60	187.60
2	REAR BUMPER SIDE RETAINER NO. 2 LH/RH @\$93.80	NO SUCH PARTS	187.60	-
2	REAR BUMPER REFLECTOR LH/RH @\$115.40	CUT	230.80	230.80
2	REAR BUMPER WATERSHIELD LH/RH @\$168.00	SERVICEABLE	336.00	-
1	BOOTLID	BENT	933.30	933.30
1	BOOTLID LOCK	BENT	92.60	92.60
1	BOOTLID LOCK CABLE	DISTORTED	88.30	88.30
1	BOOTLID LOCK CATCH	BENT	75.30	75.30
2	BOOTLID HINGE LH/RH @\$157.60	BENT	315.20	315.20
1	BOOTLID LOGO	NECESSARY	104.20	104.20
1	BOOTLID EMBLEM 'VIOS'	NECESSARY	93.80	93.80
1	BOOTLID EMBLEM 'E'	NECESSARY	75.80	75.80
2	BOOTLID REFLECTOR LH/RH @\$115.40	NO SUCH PARTS	230.80	-
1	BOOT WEATHERSTRIP	NOT NECESSARY	102.00	-
1	BOOTLID OUTER CHROME GARNISH	DISTORTED	627.20	627.20
1	REAR WINDSCREEN MOULDING	NECESSARY	180.00	180.00
1	REAR END PANEL	BENT	627.20	627.20
1	REAR END PANEL GARNISH	DISTORTED	200.30	200.30
1	SET REAR END PANEL GARNISH CLIP	NECESSARY	50.00	20.00
2	REAR FENDER LH/RH @\$1105.00	N/S BUCKLED / O/S TO REPAIR SEE LABOUR	2,210.00	1,105.00
2	REAR FENDER INNER TRIM LH/RH @\$457.60	SERVICEABLE	915.20	-
1	SET REAR FENDER INNER TRIM CLIP	NECESSARY	80.00	40.00
2	TAIL LAMP LH/RH @\$296.30	CRACKED	592.60	592.60
1	SET TAIL LAMP CLIP	NECESSARY	40.00	30.00
2	TAIL LAMP PANEL LH/RH @\$160.10	N/S BUCKLED / O/S BENT	320.20	160.10
1	SPARE TYRE WELL PANEL	BUCKLED	845.90	845.90
1	SPARE TYRE BOARD	DISTORTED	415.80	415.80
2	SPARE TYRE PANEL SPONGE LH/RH @\$216.92	O/S DISTORTED / N/S SERVICEABLE	433.84	216.92
1	SPARE TYRE PANEL SPONGE CENTRE	NO SUCH PARTS	388.40	-
1	EXHAUST MUFFLER	SERVICEABLE	617.20	-
1	EXHAUST MUFFLER MOUNTING	SERVICEABLE	75.60	-

Report Ref No. CS/SMO18002036/Dqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-5,842.25	-3,396.57
			17,526.74	10,189.70
	SPECIAL NETT ITEMS			
2	FRONT / REAR NUMBER PLATE @\$50.00 (SN)	BENT	100.00	80.00
1	BOOTLID SEALANT (SN)	NECESSARY	80.00	60.00
2	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	80.00
1	SPARE TYRE PANEL SEALANT (SN)	NECESSARY	80.00	80.00
2	REAR FENDER LH/RH SEALANT (SN)	NECESSARY	160.00	80.00
1	TAIL LAMP SEALANT (SN)	NOT NECESSARY	160.00	-
2	TAIL LAMP PAD (SN)	NOT NECESSARY	60.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	REAR WINDSCREEN PRIMER / INNER SEAK (SN)	NECESSARY	80.00	40.00
1	REVERSE SENSOR (SN)	SHORTED	300.00	220.00
1	SPARE TYRE (SN)	SERVICEABLE	350.00	-
			1,530.00	700.00
	LABOUR			
	TO STRAIGHTEN AND PANEL BEATING. TO CUT / WELD PANELS. FRONT PORTION.		1,500.00	1,000.00
	TO PUTTY, RESPRAY PAINTING AND POLISH AFFECTED AREAS. FRONT PORTION.		1,600.00	1,000.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.		100.00	30.00
	TO REMOVE AND REFIT RADIATOR, CONDENSER TO FACILITATE REPAIR AND TOP UP A/C GAS.		200.00	150.00
	TO STRAIGHTEN AND PANEL BEATING. TO CUT/WELD PANELS. REAR PORTION. INCLUSIVE OF THE REPAIR OF RH FRONT FENDER AND REAR FENDER RH.		3,000.00	1,800.00
	TO PUTTY, RESPRAY PAINTING AND POLISH AFFECTED AREAS. REAR PORTION.		2,500.00	1,200.00
	TO REMOVE AND REFIT REVERSE SENSOR.		150.00	80.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE AND REFIT INTERIOR TRIMS, SEATS, CARPET AND UPHOLSTERY TO FACILITATE REPAIR.		400.00	80.00
	TO REMOVE AND REFIT EXHAUST PIPE AND ALIGN.	NOT NECESSARY	200.00	-
	TO REMOVE AND REFIT PETROL TANK TO FACILITATE REPAIR.	NOT NECESSARY	200.00	-
	TO REMOVE AND TRANSFER BOOTLID COMPONENTS.	NOT NECESSARY	120.00	-

Report Ref No. CS/SMO18002036/Dqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST PROOF AFFECTED AREAS.		300.00	100.00
			10,420.00	5,560.00
	GRAND TOTAL		29,476.74	16,449.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,000.00

Report Ref No. CS/SMO18002036/Dqbe2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.