

25/03/2018

ASS. REC. BY:

REF: CS/FCI 1800 2041 / Utd3n24 Special Instruction:

Surveyor: Mehrez ASSIGNMENT (Office)From (Person): rwS
Lurene jawof FCIDate/Time: 31/1/18 @ 5:13pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FX4471AInsured: SHB 2179Aat Workshop m/s: Hua Ho TradingTel: 6284 4487of Blk 6, Defu Lane 10 # 01-540Policy No: _____ Claim No: D18000910MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 28/01/201802/02/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement: _____

Date/Time: 9:29am @ 1/2/18Person Contacted: Mr. LeeVehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

FX4471A - XSHB 2179A - NA / MSG 1800 1890 / h4D.O.A.: 28/1/18

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FX 4471A
 at Workshop m/s ma ho
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 3800

IDA2 Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: 9

Consistent? : Yes or No

Est. Repairs: 3 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

10/2023

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FX 4471AYr Regn: 12 03Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda phantomc.c 197Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 23006

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 7A2000022017Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/80-17R: 130/90-15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 28/1/18D.O.I. 2/2/18

Survey held at _____

Des. of Damages: FR / Rear / O/S / N/S / UIC / Rooftop orO/S, n/s body.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/2/18 2/5 \$1000 Confirmed with Mr Lee (Red: 1394:58%)

RECEIVED 14 FEB 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 14/2 Typist☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format: TPLump Sum / I.B.I. (\$ 1000)

TOTAL

110505055265

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	30-01-2018	Our Ref No. D18000910MFSH
Accident Date	28-01-2018	Claim Type. Third Party
Insured Vehicle	SHB2179A	Third Party Vehicle. FX4471A
Survey Location	BLK 6 DEFU LANE 10 #01-540DEFU IND PARK C	
Contact Person.	NA	
Contact No.	62844487/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA HO TRADING	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234472)



PRI Documents



Close X

PRI Header Details

Claim No	D18000910MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	2 & HUA HO T
Workshop Name	HUA HO TRADING (Contact Person : NA)	Survey Location & Contact Details	BLK 6 DEFU LANE 10 #01-540DEFU IND PARK C Mobile: 0 , Phone: 62844487 , Fax: 0 EmailId: HUAHOTRADING@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2179A	TP Vehicle No	FX4471A
PRI Recieved Date	30-01-2018 05:34:18 PM	Surveyor Appointed Date	31-01-2018 05:11:31 PM	Surveyor Accept Date	01-02-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	01-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18002041/Utd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2179A	Veh. Inspected	FX 4471A
Policy No.		Coverage (\$)	0.00
Claim No.	D18000910MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	01/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/01/2018	Inspection Date	
Survey held at	HUA HO TRADING BLK 6 DEFU LANE 10 #01-540 SINGAPORE 539537		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	FX4471A
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HONDA
Vehicle Model:	PHANTOM200 M
Chassis No.:	TA2000022017
Propellant:	Petrol
Engine No.:	TA200E0022017
Engine Capacity:	197 cc
Maximum Power Output:	-
Maximum Laden Weight:	-
Unladen Weight:	-
Year Of Manufacture:	2003
Original Registration Date:	03 Dec 2003
Lifespan Expiry Date:	-
COE Category:	D - Motorcycle
PQP Paid:	\$1,700.00
COE Expiry Date:	31 Oct 2023

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 6593A

Vehicle Details

Vehicle No.: FX4471A
 Vehicle to be Exported: No
 Intended De-registration Date: 02 Feb 2018
 Vehicle Make: HONDA
 Vehicle Model: PHANTOM200 M
 Primary Colour: Blue
 Manufacturing Year: 2003
 Engine No.: TA200E0022017
 Chassis No.: TA2000022017
 Maximum Power Output: -
 Open Market Value: \$3,320.00
 Original Registration Date: 03 Dec 2003
 First Registration Date: 03 Dec 2003
 Transfer Count: 1
 Actual ARF Paid: \$498.00

Intended PARF Rebate Details


PARF Eligibility: No
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Oct 2023
 COE Category: D - Motorcycle
 COE Period(Years): 10
 PQP Paid: \$1,700.00
 COE Rebate Amount: \$976.00
Total Rebate Amount: \$976.00

The information contained herein is correct as at 02 Feb 2018

OK



REPORT ERROR > (/LISTING/LISTING/ERROR/USEDBIKE/5811/) + ADD TO SHORTLIST

SHARE (WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-TA200-PHANTOM/5811/)

Honda TA200 Phantom

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda TA200 Phantom (/listing/usedbike/model/honda-ta200-phantom/)
Engine Capacity	197cc
Classification	2B
Registration Date	01/08/2003
COE Expiry Date	31/07/2023 (5 years 5 months left)

Mileage

No. of owners

Type of Vehicle

Cruiser (/listing/usedbikes/listing/?bike_type=1)

Price: SGD\$5200

Details

Downpayments \$700 before insurance. Viewing at Bike Production Pte Ltd. Please kindly call to confirm availability before viewing. Address: 610, Serangoon Road S(218216) Tel: 63922555. Trade in/ Re-Financing and many other brands new and used models available too. Terms and conditions.



Online exclusive:
Enjoy \$30 bill rebate!
[LEARN MORE](#)

T&Cs apply

Similar Bikes

[View All \(/listing/usedbikes/listing/\)](/listing/usedbikes/listing/)



Honda TA200 Phantom
(/listing/usedbike/honda-honda-ta200-phantom/5939/)



Honda TA200 Phantom
(/listing/usedbike/honda-honda-ta200-phantom/4548/)



Honda TA200 Phantom
(/listing/usedbike/honda-honda-ta200-phantom/4276/)



Honda TA200 Phantom
(/listing/usedbike/honda-honda-ta200-phantom/4227/)

和 好 贸 易

HUA HO TRADING

新加坡德福工業區C德福十巷大牌6號門牌#01-540
Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,
Singapore 539187, Tel: 62844487 Fax: 62898180

Dear Sir,

Estimate cost repair for the accident motorcycle Vehicle No: FX4471A

Items	Price
Number Plate Rear	\$20 <i>sent 105.~</i>
Rear Fender	\$165 <i>no ✓</i>
Rear Signal <i>1/5</i>	\$49 <i>no ✓</i>
Exhaust Pipe	\$747 <i>no/sen ✓</i>
2 x Footrest	\$130 <i>0/57m 1pc</i>
Brake Pedal	\$52 <i>no x</i>
Mirror <i>0/5</i>	\$65 <i>no x</i>
Side Stand	\$56 <i>no ✓</i>
Gear Pedal	\$62 <i>no x</i>
Front Brake Disc	\$188 <i>no x</i>
Footrest Bracket	\$85 <i>no ✓</i>
Steering Stem Lower	\$185 <i>no x</i>
Steering Stem Upper	\$175 <i>no x</i>
Steering Cone	\$65 <i>no x</i>
Towing Fee	\$50 <i>35</i>
Labour Charge	\$300 <i>200</i>
Total	\$2394

10%

not Allowed

2/5 ~~1000~~

3 day

Take photo After repair

1167
107
1050.3
1295.3
1036.24

李友好



HUA HO TRADING
LEE YEW HO

- Auto Consultants hence notify the repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

DATE:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18002041/Utd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2179A	Veh. Inspected	FX 4471A	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18000910MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	31/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA PHANTOM	c.c	197	
Engine No.	HIDDEN	Year of Reg.	2003	
Chassis No.	TA2000022017	Colour	BLUE	
Odometer	83006	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/80-17	PIRELLI	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/90-15	PIRELLI	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/01/2018	Inspection Date	02/02/2018	
Survey held at	HUA HO TRADING BLK 6 DEFU LANE 10 #01-540 SINGAPORE 539537			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FX 4471A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER	CRACKED	165.00	165.00
1	REAR SIGNAL N/S	BROKEN	49.00	49.00
1	EXHAUST PIPE	DENTED / SCRATCHED	747.00	747.00
2	FOOTREST	O/S TWISTED	130.00	65.00
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	52.00	-
1	MIRROR O/S	NOT NECESSARY	65.00	-
1	SIDE STAND	BENT	56.00	56.00
1	GEAR PEDAL	NOT NECESSARY	62.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	188.00	-
1	FOOTREST BRACKET	BENT	85.00	85.00
1	STEERING STEM LOWER	NOT NECESSARY	185.00	-
1	STEERING STEM UPPER	NOT NECESSARY	175.00	-
1	STEERING CONE	NOT NECESSARY	65.00	-
	LESS 10% DISCOUNT		-	-116.70
			2,024.00	1,050.30
SPECIAL NETT ITEMS				
1	NUMBER PLATE REAR (SN)	BENT	20.00	10.00
			20.00	10.00
LABOUR				
	TOWING FEE.		50.00	35.00
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF BRAKE PEDAL.		300.00	200.00
	-		-	-
	-		-	-
	-		-	-
			350.00	235.00
GRAND TOTAL			2,394.00	1,295.30

Report Ref No. CS/FCI18002041/Utd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00
---	--	--	----------

Report Ref No. CS/FCI18002041/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.