

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5706D -

AAD1801-331

Not Authorised
21 Sep @ 9200h

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5706D - CANDY
VF1ABL15AUC280297
RENAULT
LATITUDE
30.01.2018
AIG

		PART	LIST	
1	1	BUMPER COVER REAR	\$	<i>Bm</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Bm</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Diy</i> 113.47 ✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sm</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>CRM</i> 43.61 ✓
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>Bm</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Diy</i> 225.95 ✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Bm</i> 225.95 ✓
13	1	BOOT REAR	\$	<i>Bm</i> 2,872.68 ✓
14	1	BOOT FINISHER	\$	<i>Sm</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>161.52 Sm Diy/Sm</i> 323.05 <i>508 Sm</i>
16	1	BOOT REFLECTOR LAMP LH	\$	<i>CRM</i> 493.35 ✓
17	1	BOOT REFLECTOR LAMP RH	\$	<i>CRM</i> 493.35 ✓
18	1	BOOT BADGE 'RENAULT'	\$	<i>Sm</i> 225.36
19	1	BOOT BADGE	\$	<i>Sm</i> 225.36
20	1	BOOT STRUT LH	\$	<i>Sm</i> 276.08
21	1	BOOT STRUT RH	\$	<i>Sm</i> 276.08
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84
24	1	BOOT INNER TRIM	\$	<i>Sm</i> 586.45 X
25	1	BOOT SWITCH	\$	<i>Sm</i> 168.13
26	1	BOOT LOCK	\$	<i>R</i> 202.67
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2	LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52
29	2	BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sm</i> 671.45
31	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
32	1	WHEELARCH REAR LH	\$	<i>Sm</i> 543.47
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Sm</i> 671.45
34	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-331**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5706D -

35	1	WHEELARCH REAR RH	\$	Sn	543.47	X
36	1	TAILLAMP RH	\$	cm	552.55	✓
37	1	TAILLAMP PANEL RH	\$	R	986.70	X
38	1	TAILLAMP LH	\$	m3cm	552.55	✓
39	1	TAILLAMP PANEL LH	\$	R	986.70	✓
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	—
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	cm	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET	PARKING AID	\$	Shan	700.00	✓
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	na	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	na	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	na	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	X
18	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	X
19	1	TAILLAMP CLIP RH	\$	na	5.00	—
20	1	TAILLAMP CLIP LH	\$	na	5.00	—
21	2	REAR WINDSCREEN SELANT	\$	na	80.00	X
22	1	WINDSCREEN MOULDING	\$	na	100.00	X
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X
25	1	SPARE TYRE	\$	Sn	330.00	X

TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.07

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6001
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	5,600.00	6601
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	nn 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	nn 380.00 X
Towing Fees	\$	120.00	nn 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	220.00	nn 220.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices and confirmation
- Third party survey
- No illegal work
- Supplier to be resurveyed and approved by Insurance Company

TOTAL \$ 14,060.00
Over All Total \$ 48,567.07

Repair Days 20 Days
 5 days

Acknowledged:
 Signature:
 Date: