

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.2 ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G  
**SHD9320B - AIG**

AAD1801-310

*Not Authorised*  
*L1 Sy & 320d*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHB9320B - CANDY**  
**KL1LA69RJBB069117**  
**CHEVROLET**  
**CHEVROLET EPICA 2.0**  
**27.01.2018**  
**AIG**

**PART**

**LIST**

- |    |   |                                      |
|----|---|--------------------------------------|
| 1  | 1 | Front Bumper                         |
| 2  | 1 | Front Bumper Lower Absorber          |
| 3  | 1 | Front Bumper Reinforcement           |
| 4  | 1 | Front Bumper Retainer RH             |
| 5  | 1 | Front Bumper Retainer LH             |
| 6  | 1 | Front Bumper Lower Grille            |
| 7  | 1 | Front Bumper Lower Stiffener         |
| 8  | 1 | Bumper Fog Lamp Cover RH             |
| 9  | 1 | Front Headlamp RH                    |
| 10 | 1 | Front Fender RH                      |
| 11 | 1 | Front Fender Liner RH                |
| 12 | 1 | Windscreen Washer Tank - Filler Neck |
| 13 | 1 | Windscreen Washer Tank               |
| 14 | 1 | Windscreen Washer Tank Motor         |
| 15 | 1 | Bonnet (Panel A-Hood)                |
| 16 | 1 | Bonnet Moulding                      |
| 17 | 1 | Bonnet hinge RH                      |
| 18 | 1 | Bonnet hinge LH                      |
| 19 | 1 | Bonnet lock                          |
| 20 | 1 | Radiator Grille (Grille A-Rad)       |
| 21 | 1 | Front Support Panel Assy             |
| 22 | 1 | Front brace panel                    |
| 23 | 1 | Front Shock Absorber Assy RH         |
| 24 | 1 | Front Lower Arm RH                   |
| 25 | 1 | Front Knuckle Arm RH                 |
| 26 | 1 | Radiator Assembly                    |
| 27 | 1 | Aircon Condenser                     |
| 28 | 1 | Horn Unit (High Tone)                |
| 29 | 1 | Air Intercooler                      |
| 30 | 1 | Fan Blade (Small )                   |

|    |                |          |     |
|----|----------------|----------|-----|
| \$ | <i>Buc 1cm</i> | 1,202.00 | ✓   |
| \$ | <i>Sm</i>      | 180.00   | ✓   |
| \$ | <i>R</i>       | 356.00   | ✓   |
| \$ | <i>cm</i>      | 102.00   | ✓   |
| \$ | <i>D.1</i>     | 102.00   | ✓   |
| \$ | <i>Sm</i>      | 78.00    | ✓   |
| \$ | <i>B1</i>      | 134.37   | ✓   |
| \$ | <i>Nm</i>      | 32.40    | ✓   |
| \$ | <i>cm</i>      | 816.00   | ✓   |
| \$ | <i>B1</i>      | 837.60   | ✓   |
| \$ | <i>cm</i>      | 47.00    | ✓   |
| \$ | <i>Sm</i>      | 4.80     | ✓   |
| \$ | <i>Sm</i>      | 62.00    | ✓   |
| \$ | <i>cm</i>      | 51.00    | ✓   |
| \$ | <i>R</i>       | 1,250.00 | } X |
| \$ | <i>Sm</i>      | 257.00   |     |
| \$ | <i>R</i>       | 36.00    |     |
| \$ | <i>R</i>       | 36.00    |     |
| \$ | <i>R</i>       | 200.00   |     |
| \$ | <i>Sm</i>      | 367.00   |     |
| \$ | <i>R</i>       | 1,222.32 |     |
| \$ | <i>R</i>       | 134.37   |     |
| \$ | <i>Sm</i>      | 216.17   |     |
| \$ | <i>Sm</i>      | 283.00   |     |
| \$ | <i>Sm</i>      | 230.00   |     |
| \$ | <i>Sm</i>      | 618.00   |     |
| \$ | <i>Sm</i>      | 600.00   |     |
| \$ | <i>Sm</i>      | 53.46    |     |
| \$ | <i>Sm</i>      | 652.00   |     |
| \$ | <i>Sm</i>      | 536.00   |     |

|    |   |                           |    |                     |
|----|---|---------------------------|----|---------------------|
| 31 | 1 | Fan Blade ( Big )         | \$ | <i>Sm</i> 634.00 X  |
| 32 | 1 | Front Door RH             | \$ | <i>n</i> 1,133.00 X |
| 33 | 1 | Front Side View Mirror RH | \$ | <i>Sm</i> 939.00 X  |

|              |    |                  |
|--------------|----|------------------|
| <b>TOTAL</b> | \$ | <b>13,402.49</b> |
| <b>10%</b>   | \$ | <b>1,340.25</b>  |
|              | \$ | <b>12,062.24</b> |

**Specical Nett**

|   |   |                                |    |                    |
|---|---|--------------------------------|----|--------------------|
| 1 | 1 | Set Front Bumper Fastener Clip | \$ | <i>Sm</i> 30.00 ✓  |
| 2 | 1 | Set Front Fender Liner Clip RH | \$ | <i>Sm</i> 30.00 ✓  |
| 3 | 1 | Front Wheel Rim Hub Cap RH     | \$ | <i>Sm</i> 166.30 X |
| 4 | 1 | Front Tyre RH                  | \$ | <i>Sm</i> 180.00 X |
| 5 | 1 | Front Tyre Rim RH              | \$ | <i>Sm</i> 126.00 X |
| 6 | 1 | Door Sticker "Trans-cab" RH    | \$ | <i>nn</i> 80.00 X  |

|                    |    |                  |
|--------------------|----|------------------|
| <b>TOTAL</b>       | \$ | <b>612.30</b>    |
| <b>TOTAL PARTS</b> | \$ | <b>12,674.54</b> |

Panel Beating, Knocking And Straightening The  
 Necessary Portion, Remove And Renewal Of  
 Parts, Adjust And Realign The Same

\$ 2,800.00 *400*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *30*

Putty and Spray Painting Of The Affected  
 Portion.

\$ 2,700.00 *440*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

To check steering geometry and computer wheel  
 alignment

\$ *nn* 220.00 X

Towing Fees.

\$ 120.00 *50*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To vacuum, replace, refix and recharge air  
 condenser

\$ *nn* 380.00 X

**TRANS-CAB AUTO SERVICES PTE LTD**  
NO.2 ANG MO KIO ST63 SINGAPORE 569111  
TEL NO. 6287 6666 FAX NO. 6257 1330  
CO/GST REG NO. 201019626G  
**SHD9320B - AIG**

**AAD1801-310**

To replace, refix and top up coolant for radiator \$ *nn* 170.00 X

To vacuum, replace, refix and recharge Air  
Intercooler \$ *nn* 170.00 X

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>TOTAL</b>          | <b>\$</b> | <b>7,120.00</b>  |
| <b>Over All Total</b> | <b>\$</b> | <b>19,794.54</b> |

**REPAIR DAYS**

~~10 DAYS~~

*2 1/2 day*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: