

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 818k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 03 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1/2 File parts to Carharm451 + 2150 (880 + 2118.05 50%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / LB.I: (\$

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee

Transportation

) \$ - RS. \$

) Photos

) Others

TOTAL

Veh No: SKP 325CYr Regn: 08, 08Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy mark Xc.c. 2499Colour: M. Black

A/C: Insured / Std / NI / NA

Sp. Reading: 152746

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GRX120 - 3059042Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / B/Rim / STD A/Rim orTyre Size: F: 225/458R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal: 6 mm

Rear

R/Bal: 7 mmL/Bal: 6 mmL/Bal: 7 mmD.O.A. 12/12/17D.O.I. 31/1/18

Survey held at _____

Des. of Damages: Nil / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC4/III18002048/Kes3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 01-02-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8803L		Veh. Inspected	SKP 3825C
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	01/02/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/12/2017		Inspection Date	31/01/2018
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

WONG SIT YENG
c/o 46 LENTOR PLAIN
SINGAPORE 786548

Not Attached
61 Bay @ 2150/-
Running After Repair
3dgs

Date: 31/1/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: TOYOTA MARK X / SKP3825C	
1 pc	front head lamp	1,445.20 ✓
1 pc	front bumper	1,017.00 ✓
1 pc	front bumper side retainer	68.20 ✓
1 pc	front fender L/H	647.00 X
	sub total	3,177.40
	Less 25%	794.35
	sub total	2,383.05
1 pc	alloy rim	s.nett 680.00 X
	sub-total	3,063.05
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	440.00 35.
	To spray painting on affected areas.	600.00 400
	To check wiring system.	40.00 201
	To replace alloy rim & perform wheel balancing	40.00 20
	To perform 4 wheels computerised alignment	85.00 X
	4,268.05	
	<p>KK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>	

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

WONG SIT YENG
c/o 46 LENTOR PLAIN
SINGAPORE 786548

Not Authorized
1/18/18
Resurvey After Repair
3dgs

Date: 31/1/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: TOYOTA MARK X / SKP3825C	
1 pc	front head lamp	1,445.20 ✓
1 pc	front bumper	1,017.00 ✓
1 pc	front bumper side retainer	68.20 ?
1 pc	front fender L/H	647.00 X
	sub total	3,177.40
	Less 25%	794.35
	sub total	2,383.05
1 pc	alloy rim	680.00 X
	sub-total	3,063.05
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	440.00 350
	To spray painting on affected areas.	600.00 400
	To check wiring system.	40.00 20
	To replace alloy rim & perform wheel balancing	40.00 20
	To perform 4 wheels computerised alignment	85.00 X
		4,268.05

LHK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 1 February 2018 9:33 AM
To: Dylan Chew; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sundari Nagarajan - III
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SKP3825C (Accident involving SKP3825C and SHC8803L on 12.12.2017)
Attachments: shc8803l_20180201092207.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKP3825C and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

9.49 am @ 1/2/2018
vehicle In
person @ Amanda
sur @ Kenneth

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.


Registration No. 198703792-K

AUTOWORX HOUSE

176 Sin Ming Drive, #02-01 Sin Ming Autocare Singapore 575721
• Tel: 6452 8211 • Fax: 6451 7420

India International Insurance Pte Ltd
Attn: Motor Claims Department

311118



Dear Sir,

RE: Request for PRI for SLP 3852C in an accident involving SHC 8803L
Bukit Batuk West Ave 6 on 12/12/17 @ 0845 hrs

We have been authorised by WONG SIF YONG, the registered owner of motor vehicle: SLP 3852C at the material time of accident to make a claim against your insured.

Please give us the list of panel of your 10 survey firms for our selection to inspect the above said vehicle or you may assign our choice from either one of the 3 survey firms.

- 1) Premier Appraiser Services
- 2) LKK Auto Consultants Pte Ltd
- 3) AJAX Inspection Services Pte Ltd

We will direct settle the claims with you if the survey is conduct by either of one the firms mentioned.

Kindly contact us at 64528211 before coming to ensure the vehicle is in the workshop.

Thank you.

Yours Sincerely,

Autoworx House
Email: autoworxhouse@hotmail.com

AUTOWORX HOUSE

176 Sin Ming Drive, #02-01 Sin Ming Autocare Singapore 575721

Email: autoworxhouse@hotmail.com

•TEL: 6452 8211 •FAX: 6451 7420

Direct Settlement THIRD PARTY CLAIM

Your ref:

Our ref: SKP3825C

INDIA INTERNATIONAL INSURANCE PTE LTD

Attn: Officer In Charge

(Motor Claim Department)

16/11/2018

Dear Sir,

RE : ACCIDENT INVOLVING SKP3825C AND SHC8803L AT BUKIT BATOK WEST AVE 6 ON 12/12/2017.

We have been authorized by WONG SIT YENG, the registered owner of vehicle number SKP3825C, which was involved in the above accident and at the material time to make a 3rd party claims against vehicle number SHC8803L.

The accident was clearly caused by your insured's negligence. We, therefore seeking compensation from you for our client financial losses as itemized below: -

Repair cost	S\$	2,150.00
Loss of Use (5 days x \$200.00)	S\$	1,000.00
Search Fee	S\$	0.00
Total	S\$	3,150.00

We have enclosed copies of relevant documents to support our claims.

Please settle this matter within 7 days.

Your prompt settlement of our claim would be much appreciated.

Do contact us at 64528211 for any clarification.

Thank you.

Yours faithfully,



Autoworx House

To: AUTONORX HOUSE
SINGAPORE

Letter of Authorisation

RE: ACCIDENT INVOLVING JKP 3823C & SHC 88032
ALONG/AT BUKIT BATOK WEST AVE 6
ON 12/12/2017.

1. I/We, Wong Sit Yeng (NRIC No. S1786593E),
owner/driver of motor vehicle no. JKP 3823C, & residing at
BLK 536 BUKIT BATOK ST 52 #10-653 S650636,
respectively in consideration of your workshop Autonox House
repairing my/our vehicle, I/we hereby authorise you to claim on my/our behalf for the costs of
repair and loss of use. I/We further confirm and authorise you to use my/our name/s to engage the
said service of a solicitor to proceed with negotiation with the defaulting party's insurance
company for payment of the same and in the event negotiation fails, to instruct the solicitor to issue
Summons on my/our behalf and in my/our name/s to claim for the same. Irrespective whether the
claim is successful or not, all legal costs incurred shall be borne by you, provided we rendered our
assistance as per second paragraph stated herein below.
2. I/We understand that by signing this Letter of Authorisation, I/we has/have to render whatever
reasonable assistance to you including signing all relevant Court's document and attendance in
Court to give evidence to enable the claim to succeed. If I/we failed or neglected to do so despite
request from you, you shall be entitled to claim from me/us the repair costs together with legal
costs, other incidental costs and expenses pertaining the issuance of Summons in order to obtain
payment from defaulting party.
3. You have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third
party and/or his insurers on such terms as you deem fit. Upon settlement of my/our claim, you are
authorised to sign any Discharge Voucher or any document to confirm my acceptance of the
settlement as full and final discharge of my/our claim, on my/our behalf. You also have my/our
full authority to collect all compensation monies pertaining to the above-mentioned accident from
insurance company or any other party, directly to your workshop M/s
Autonox House.
4. In the event the claim is settled or judgment is obtained against the defaulting party, payment after
deducing all costs and disbursements incurred should be drawn in your name or my/our name/s (at
your discretion) and will be forwarded to you.
5. This letter of Authorisation is irrevocable.

Signature: 

Name: WONG SIT YENG

NRIC NO: S1786593E

Date this 12 day of December 20 17.

LKK

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT17120488
Claimant Ref: SKP 3825C

We/I, AUTOWORK HOUSE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 2,150.00 (repair cost), S\$ 500.00 (loss of use/rental), S\$ — (search fee), vehicle no. SKP 3825C that was damaged pursuant to the accident which occurred on 12/12/2017 (date) at BLK 122 SUNGT BATOK CENTRAL (location) involving vehicle no. SHC 8803L (insured vehicle). This is pursuant to the inspection conducted on 31/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner WONG SIT YENG ("the third party claimant") of vehicle no. SKP 3825C to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKP 3825C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,650.00 to AUTOWORK HOUSE

Dated this 23 day of May 20 18

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Signed by "the workshop" (with chop)

Dylan Chew

87713752A

176 Sin Ming Drive

#02-01 S575721

S'PORE

Manager

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

—

—

AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 64528211 FAX: 64517423

Registration No. 5296929B


INVOICE

5327

INDIA INTERNATIONAL INSURANCE PTE LTD

16/11/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE : TOYOTA MARK X / SKP 3825 C</u>	
	Lump sum repair for the above mentioned vehicle.	2,150.00
	Total	2,150.00



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Feb 2018 Edit Reg		31 Jan 2018 00:00 Edit Adj Rpt	S\$2,150.00 Edit Estimates	S\$2,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	WONG SIT YENG, ID: S1786593E								
Vehicle Reg. No.:	SKP3825C	Date of Loss:	12/12/2017 08:00 - :59 [111 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT17120488	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHCB803L	Policy No. (Claimant):	SI17V12202/VPE/R02/E00						
		Excess:							
Repairer:	Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01, 575721 Sin Ming - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (11/01/2019): Alert - Adj Mandate Approved (S\$2650.00) - SKP3825C - Claim Handler: Sundari Nag... III_SG (23/02/2018): Alert - Adj Mandate Approved (S\$0.00) - SKP3825C - Claim Handler: Sundari Nagara... III_SG (22/02/2018): Alert - Adj Mandate Maintained - SKP3825C - Claim Handler: Sundari Nagarajan 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKP3825C (MCT17120488)
[SHC8803L]
TP
WONG SIT YENG
Dec 12 2017 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Autoworx House - Sin Ming

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	10/01/19 09:12	Video - Accident	Load MP4	
2	10/01/19 09:13	Video - Accident-TP	Load MP4	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
2	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
3	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/12/18 15:37	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
11	28/12/18 15:37	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
12	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/12/18 15:37	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/12/18 15:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
15	28/12/18 15:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
16	28/12/18 15:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	28/12/18 15:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	28/12/18 15:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	28/12/18 15:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	28/12/18 15:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	28/12/18 15:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	28/12/18 15:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>


Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/18 17:46	ACKNOWLEDGEMENT EMAIL TO III DD 01.02.2018	Load PDF	
2	01/02/18 17:47	NOTIFICATION FROM WORKSHOP	Load PDF	
3	02/02/18 10:06	TP GIA REPORT	Load PDF	
4	02/02/18 10:06	TP ESTIMATE- MARKED	Load PDF	
5	02/01/19 08:12	WORKSHOP INVOICE	Load PDF	
6	02/01/19 08:12	LOD	Load PDF	
7	11/06/19 09:33	DISCHARGE VOUCHER	Load PDF	
8	11/06/19 09:33	AUTHORISATION TO ACT FORM	Load PDF	

1 per page

No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 08:39	Singapore Accident Statement	Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
2	11/01/19 09:43	TP has only this video as he got it from other party in the car park as per LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18002048/KEA3Q2

Date: 11/06/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle
No : SKP3825C

Insured Vehicle No : SHC8803L

Date of Loss: 12/12/2017

Nature of Claim:

TP

Claim No: MCT17120488

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKP3825C

Make & Model: TOYOTA MARK X, 2.5 (A)

Reg. Date: 21/08/2008 (Man. Year: 2008)

Colour: Metallic Black

Engine Capacity: 2499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 4GR0452119

Chassis No: GRX1203059042

Odometer: 152746 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R18

Rear Tyre Size: 225/45Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,063.05	1,897.80	1,165.25	38.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,205.00	790.00	415.00	34.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,268.05	2,687.80	1,580.25	37.03
Approved Total (Overridden) (S\$)		2,150.00		
Nett Amount (S\$)	4,268.05	2,150.00	2,118.05	49.63
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		2,650.00		

INSPECTION

Date of Assignment: 31/01/2018

Date Inspected: 31/01/2018 Inspected At:

Autoworx House - Sin Ming (HQ)
176 SIN MING DRIVE #02-01
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2019)
Parts:	143	TOYOTA MARK X 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP3825C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEAD LAMP	Cut	1,445.20 FL	*1,445.20 FL
2	1		*FRONT BUMPER	Dented / Cracked	1,017.00 FL	*1,017.00 FL
3	1		*FRONT BUMPER SIDE RETAINER	Cracked	68.20 FL	*68.20 FL
4	1		*FRONT FENDER L/H	Repair	647.00 FL	*- FL
5	1		*ALLOY RIM	Repair	680.00 FS	*- FS
					Sub Total (S\$)	3,857.40 2,530.40
					- List Item Discount on L Items 25.00/25.00% (S\$)	794.35 632.60
					Total Parts (S\$)	3,063.05 1,897.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	440.00	350.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	600.00	400.00
3	TO CHECK WIRING SYSTEM	New	40.00	20.00
4	TO REPLACE ALLOY RIM & PERFORM WHEEL BALANCING	New	40.00	20.00
5	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT	New	85.00	0.00
Gross Labour Cost (S\$)			1,205.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >