

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

WONG SIT YENG
c/o 46 LENTOR PLAIN
SINGAPORE 786548

Not Authorized
1 Rep @ ?
Running After Repair
3d9,

Date: 31/1/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: TOYOTA MARK X / SKP3825C	
1 pc	front head lamp	1,445.20 ✓
1 pc	front bumper	1,017.00 2
1 pc	front bumper side retainer	68.20 ?
1 pc	front fender L/H	647.00 X
	sub total	3,177.40
	Less 25%	794.35
	sub total	2,383.05
1 pc	alloy rim s.nett	680.00 X
	sub-total	3,063.05
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	440.00 35.
	To spray painting on affected areas.	600.00 400
	To check wiring system.	40.00 201
	To replace alloy rim & perform wheel balancing	40.00 201
	To perform 4 wheels computerised alignment	85.00 X
	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature:	4,268.05