

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1807C
 Ref. No : TAX/01/18/2181
 Reg. Date : 11/02/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : OW LEONG SAN
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 31/01/2018 08:35:00 AM
 Accident Reported Date / Time : 31/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 31/01/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094387
 Special Instruction to ARC, if any :
 TOWED \$90 / SJU2098B
 Prepared Date : 31/01/2018 11:07:06 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

7 Days .
part by mt.

before paint photos.

Guo Qiao - 8288082

02/2/18

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205758530

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,352.00	0.00
Total Spray Painting Charges :	2,214.00	0.00
Total Material Charges :	7,732.78	7,732.78
Other Charges :	1,952.88	0.00
TOTAL :	13,251.66	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	8.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	01/02/2018 11:58:33 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/02/2018 11:58:33 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1- Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,352.00	0.00 800
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 150
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 150
TO RESPRAY REAR MEMBER,LH	180.00	0.00 X
TO RESPRAY REAR MEMBER,RH	180.00	0.00 X
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 X
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 X
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	2,214.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	126.00	0.00 ?
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 40
TO ALIGN CHASSIS	350.00	0.00 ?
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	0.00 60
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 X
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 ?
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 ?
TO WASH AND VACUUM	60.00	0.00 ?
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
Total Other Costs	1,952.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR / <i>cc</i>	1	458.60	25.00	343.95	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR / <i>BT</i>	1	205.70	25.00	154.27	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH ?	1	139.60	25.00	104.70	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH ?	1	139.60	25.00	104.70	Replace	Replace	No
			SENSOR REVERSE / <i>DM</i>	1	180.00	0.00	180.00	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH / <i>MC</i>	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH / <i>MC</i>	1	94.80	25.00	71.10	Replace	Replace	No
			PIXEL STICKER / <i>MC</i>	2	60.00	0.00	120.00	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER RR/LH / <i>MC</i>	1	72.20	25.00	54.15	Replace	Replace	No
76087-47020		6505618	BUMPER LIP COVER RR/RH / <i>MC</i>	1	118.10	25.00	88.57	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR / <i>MC</i>	1	228.90	25.00	171.67	Replace	Replace	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR / <i>cc</i>	1	514.50	25.00	385.87	Replace	Replace	No
58307-47060		6505522	END PANEL / <i>BT</i>	1	602.10	25.00	451.57	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX / <i>MC</i>	1	37.00	0.00	37.00	Replace	Replace	No
58311-47071		6505523	SPARE TYRE PANEL / <i>Repair</i>	1	667.70	25.00	500.77	Replace	Replace	No
57604-47030			MEMBER SUB-ASSY, RR LH ?	1	174.10	25.00	130.57	Replace	Replace	No
57603-47030			MEMBER SUB-ASSY, RR RH ?	1	174.10	25.00	130.57	Replace	Replace	No
58303-47301			FLOOR PANEL RR/LH / <i>NN</i>	1	102.00	25.00	76.50	Replace	Replace	No
58302-47030			FLOOR PANEL RR/RH / <i>NN</i>	1	209.90	25.00	157.42	Replace	Replace	No
17430-37380			EXHAUST TAIL PIPE ?	1	656.20	25.00	492.15	Replace	Replace	No
67005-47241			TAILGATE ASY / <i>Repair</i>	1	1,007.90	25.00	755.92	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) / <i>MC</i>	1	51.90	25.00	38.92	Replace	Replace	No
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1 / <i>NN</i>	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN / <i>NN</i>	1	37.00	0.00	37.00	Replace	Replace	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH / <i>NN</i>	1	29.40	25.00	22.05	Replace	Replace	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH / <i>NN</i>	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN / <i>NN</i>	2	37.00	0.00	74.00	Replace	Replace	No
			NUMBER PLATE FRAME / <i>NN</i>	1	12.00	0.00	12.00	Replace	Replace	No

Part Number	Portion	Stock NO	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
67881-47022			TAILGATE DOOR WEATHER STRIP ?	1	353.40	25.00	265.05 ?	Replace	Replace	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE /CPA	1	46.10	25.00	34.57 /	Replace	Replace	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR /Cut	1	121.10	25.00	90.82 /	Replace	Replace	No
64993-47020			BOX, DECK FLOOR, RR ?	1	649.70	25.00	487.27 ?	Replace	Replace	No
58416-47030B3			BOX, RR FLOOR, BOARD ?	1	679.60	25.00	509.70 ?	Replace	Replace	No
61604-47090			FENDER RR/RH X Repair	1	766.80	25.00	575.10 ?	Replace	Replace	No
65637-47021		6505480	FENDER LINER RR/RH ? X Repair	1	141.30	25.00	105.97 ?	Replace	Replace	No
52591-47021			BUMPER SEAL, RR RH ?	1	65.70	25.00	49.27 ?	Replace	Replace	No
65631-47041			SILL MEMBER PLATE RR/RH X NN	1	57.50	25.00	43.12 ?	Replace	Replace	No
	COMMON		SMRT LOGO / MC	1	7.80	0.00	7.80 /	Replace	Replace	No
			STICKER DECAL 6555 8888 / MC	1	21.60	0.00	21.60 /	Replace	Replace	No
52562-47010			TAIL LAMP BRACKET, RH ?	1	30.70	25.00	23.02 ?	Replace	Replace	No
62710-47130			QUARTER GLASS RR/RH X NN	1	846.50	25.00	634.87 ?	Replace	Replace	No
	COMMON		SEALANT W/SCREEN X NN	1	37.00	0.00	37.00 ?	Replace	Replace	No
TOTAL MATERIALS							7,695.88	7,695.78		
TOTAL MATERIALS(Discounted)							7,732.78	7,732.78		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									