

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: INDIA INTERNATIONAL PTE LTD	DATE	: 30/01/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJE9454U	Ashes	
MODEL	: HONDA CIVIC 1.8A	FD11201616	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 29-Jan-18
		TIME	: 20:15HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 65.90	\$ 65.90
2	HID HEADLAMP LH <i>cut</i>	1	\$ 989.60	\$ 989.60
3	HID HEADLAMP LOWER BRACKET LH <i>new set</i>	1	\$ 65.90	\$ 65.90
4	FRONT FENDER LH <i>Dented</i>	1	\$ 762.30	\$ 762.30
5	FRONT FENDER INNER COWLING RH <i>Rehd</i>	1	\$ 148.90	\$ 148.90
6	FRONT ENGINE COVER <i>new</i>	1	\$ 190.00	\$ 190.00
7	FRONT LOWER ARM LH <i>new</i>	1	\$ 266.00	\$ 266.00
8	FRONT KNUCKLE ARM LH <i>new</i>	1	\$ 274.60	\$ 274.60
9	FRONT KNUCKLE ARM BEARING LH <i>new</i>	1	\$ 138.00	\$ 138.00
10	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 342.40	\$ 342.40
11	FRONT WHEEL HUP LH <i>new</i>	1	\$ 190.20	\$ 190.20

TOTAL PRICE \$ 3,433.80

LESS 20% \$ 686.76

SUB TOTAL PRICE \$ 2,747.04

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00

2	FRONT BUMPER (SPECIAL TYPE) <i>del</i>	1	\$ 1,200.00	\$ 1,200.00	<i>600</i>
3	FRONT BUMPER LOWER LID(SPECIAL TYPE) <i>del</i>	1	\$ 800.00	\$ 800.00	<i>450</i>
4	FRONT FENDER INNER COWLING CLIP (SET) <i>u</i>	1	\$ 20.00	\$ 20.00	<i>-</i>
5	FRONT GRILLE WITH LOGO <i>could</i>	1	\$ 350.00	\$ 350.00	<i>280</i>
6	FRONT WHEEL RIM (SET) <i>ut</i>	1	\$ 1,200.00	\$ 1,200.00	<i>400</i>
7	FRONT TYRE LH <i>pen</i>	1	\$ 350.00	\$ 350.00	<i>x</i>
TOTAL			\$ 3,980.00		<i>1780</i>

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	<i>400</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>600</i>	
3	REMOVE AND REFIX FRONT WINDSCREEN	\$ 180.00	<i>x</i>	
4	WIRING CHECK	\$ 100.00	<i>30</i>	
5	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 280.00	<i>x.</i>	
6	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>	

1110

TOTAL \$2,680.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,727.04
TOTAL LABOUR COST : \$ 2,680.00
TOTAL REPAIR COST : \$ 9,407.04

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :

NO OF DAYS :

FAX :

Adrian Lj
31/01/18
h/s 04 Rys.
h/s 32K.
total: 4291.92
h/s: 32K.