



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

MUC/DK
CFR.

NTUC/AIG(SFX1688L)
DOA: 26/01/2018@1325

AIG ASIA PACIFIC INSURANCE PTE LTD

01/02/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SKM 7007 L - TOYOTA CAMRY 2.0 AUTO ABS AIRBAG
CHASSIS NO: MR053BK4107005404 (2007)

1 pc	Front bumper	\$ 609.90	de✓
1 pc	Front bumper retainer RH	\$ 65.30	ex
1 pc	Front bumper tow cover	\$ 15.00	ut✓
1 pc	Front foglight top chrome RH	\$ 104.10	aut✓
1 pc	Front foglight cover RH	\$ 50.30	?
1 pc	Front grille	\$ 526.50	?
1 pc	Front grille logo	\$ 75.10	?
		\$ 1,446.20	
	LESS 20%	\$ 289.24	
		\$ 1,156.96	
	Front no.plate (S/NETT)	\$ 35.00	bt✓
	Remove necessary parts: Jacking, panel beating, repair, straighten and align front inner panel and front bumper.	\$ 350.00	250
	Putty and respray front inner panel and front bumper.	\$ 300.00	250
		\$ 1,841.96	
	ADD 7% GST	\$ 128.94	
		\$ 1,970.90	

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjah 97495747
- WP
6/2/18 @ 1130
02 days
Resurvey after repair
Lumpsum