

REF: CS / LCR18002058 / Svbgr

Special Instruction

US: \$ 10000.00

Third Parties:

Claimant:

Surveyor: Sheng Li Lai

Workshop: Automax Survey

From (Person): Angie Chan of LCR Date/Time: 18012618
Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: PC 7188R Insured: SLE 8053B
at Workshop m/s Sheng Li Lai Tel: 6842 0302
of 2 Kakit Bukit Ave 2 #0136

Policy No: _____ Claim No: 207363208556003

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06092017

(Client's Record)

06/02/2018 (Tuesday) @ 2pm

H.O.D. Endorsement/Date

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red S _____ / _____ %; Original 10 days)

Date/Time: 13/2/18 Submit Final Fig 154700, 6 days (Red \$ 5300 / 53 %; Original days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

200

1) Date/Time 13/2-2018 File Pass to _____ 2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____

16

Veh No: PC 7100K Yr Page: 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer on _____

Make: Toyota Hine. CC: 2985

Colour	Silver	A/C	Insured / Std / NI / NA
--------	--------	-----	-------------------------

Sp. Reading: 338431- T/Ratio: Insured / Std / NI / NA

C/Nº: JTF-14702 P300201050.

Gen. Cond: Good / ~~Fair~~ / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: ☐ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: ☒ NI / ☐ S/Rim / ☐ STD A/Rim or

Type: Other File: 195-R15

E: 175 K₀

R:

	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

RS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Ohatsu*Front _____ Rear /

R. Bal. 6 mm R. Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

DOA 6/26/2 DOJ 6/2/18

DATE: 8/1/14 PAGE: 1

Survey held at 4 Sy Radt Loop

Dist. of Damages: ☐ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Data/Time File Return to?

Add Fee: Site Insp. (\$

Site Inc. (\$)

Interview 15

Tech. level 12

Western 0

Report Format :

Lump Sum / I.B.H. / S




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/LCR18002058/vb	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 01-02-2018	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SLE 8053B	Veh. Inspected	PC 7188R
Policy No.		Coverage (\$)	0.00
Claim No.	2073632085SG003	Excess (\$)	0.00
Assign From	ANGIE GAN	Assign Date	18/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/09/2017	Inspection Date	06/02/2018
Survey held at	NO 29 SUNGEI KADUT LOOP		
Repairer	SHENG LI LAI		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Yvonne <yvonne@ealc.com.sg>
Sent: Tuesday, 23 January, 2018 12:56 PM
To: Gan, Angiegeokling
Cc: Catherine Chong (LKK Auto); assignments@lkkauto.com
Subject: [Reinspection] #2073632085SG003#023# AIG ref ; Your ref: 2017.5140.EA.MK.YA
-- REINSPECTION PC7188R

Dear Sir/Madam

CLAIMANT: NKH CONSTRUCTION EQUIPMENT PTE LTD
ACCIDENT INVOLVING PC7188R & SLE8053E ON 06 SEPTEMBER 2017 ALONG JUNCTION OF WHITLEY ROAD BEFORE WAYANG SATU FLYOVER AT ABOUT 1150 HOURS

Refer to the above matter.

Our client's vehicle **PC7188R** is available as follows, for the re-inspection:

Date/time: Tuesday 6 February 2018 at 2pm
Contact person: Ms Carol 62696088
Place: No 29 Sungei Kadut Loop, Singapore 729469

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Gan, Angiegeokling [mailto:Angiegeokling.Gan@aig.com]
Sent: Thursday, 18 January 2018 2:49 PM
To: Law <law@ealc.com.sg>; Yvonne <yvonne@ealc.com.sg>
Cc: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; assignments@lkkauto.com
Subject: #2073632085SG003#023# AIG ref ; Your ref: 2017.5140.EA.MK.YA -- REINSPECTION PC7188R

WITHOUT PREJUDICE

Dear Sirs,

We refer to your LOD dated 05/01/2018.

We wish to conduct reinspection on your client's vehicle PC7188R.

Kindly advise the preferred date and time at least one week in advance and arrange with our surveyor in copy.

Aside to LKK, for your necessary action please. Documents will follow shortly.

Thank you.

Best Regards,

Angie Gan

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +(65) 6419 1013 | Fax +(65) 6835 7416

Angiegeokling.Gan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



ACRA Reg. No.
200309625D

EAST ASIA LAW CORPORATION

Advocates & Solicitors

133 New Bridge Road #10-02
Chinatown Point Singapore 059413
Tel: 65 6323 2565 Fax: 65 6323 2373
E-mail: law@ealc.com.sg
Website: www.ealc.com.sg

Kasturibai Manickam
Jocinda Wong Jia Heng

(Service of Court documents by way of fax is not accepted)

474078

Our Ref: 2017.5140 EA.MK.YA
Your Ref: SLE8053E

5-Jan-2018

WITHOUT PREJUDICE

PDX#8181
AIG Asia Pacific Insurance Pte Ltd
76 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Department

CERTIFICATE OF POSTING
LCRF PTE LTD
60 Anson Road #11-01 Mapletree Anson
Singapore 079914

PDX Intercompany Exchange Pte Ltd



010808273398

FROM EAST ASIA LAW CORP.
PDX Box No. 8080

Dear Sir,

CLAIMANT: NKH CONSTRUCTION EQUIPMENT PTE LTD
ACCIDENT INVOLVING PC7188R & SLE8053E ON 06 SEPTEMBER 2017 ALONG JUNCTION OF WHITLEY ROAD BEFORE WAYANG SATU FLYOVER AT ABOUT 1150 HOURS

NKH CONSTRUCTION EQUIPMENT
We act for PTE LTD, the owner of vehicle no. PC7188R, whose vehicle was damaged as a result of the abovementioned accident by vehicle no. SLE8053E and our search reveals that you were the insurers of motor vehicle no. SLE8053E

We are instructed that the accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1) Costs of repair	\$ 10,000.00
2) Rental fee	\$ 1,600.00
3) Survey report fee	\$ 780.00
4) LTA search fee	\$ 8.00
5) GIA search fee/report fee	\$ 29.00
6) Costs + GST	\$ 963.00
7) Incidentals + GST	\$ 53.50
Total:	\$ 13,433.50

We enclose copies of the following documents supporting our client's claim for your attention:-

- 1) GIA accident report of our client's repo PC7188R
- 2) LTA search for SLE8053E
- 3) Final repair bill for PC7188R
- 4) Rental agreement/receipt/invoice
- 5) Original Survey report enclosing original color copies of photographs depicting damages to vehicle no. PC7188R
Enclosed document may be photocopied on both sides to save paper and be environment friendly

Please note that if you are insured and you wish to claim your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgment of receipt of this letter within 14 days from the receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on the supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

Kasturibai Manickam
East Asia Law Corporation

Enc.
cc:

Ref: PC7188R

RECEIVED BY AIG Claims Dept	
08 JAN 2018	
CL No.	207362085
Team	SG003
ADJ	



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/09/2017 12:25
Date Of Accident	06/09/2017 11:50
Exact Location Of Accident	JUNCTION OF WHITLEY RD BEFORE WAYANG SATU FLYOVER
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PC7188R
Insured/Policyholder	
Name Of Registered Owner	M/S NKH CONSTRUCTION EQUIPMENT PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62696088
Vehicle Particulars	
Manufacturer	TOYOTA
Model	-
Exact Purpose for which vehicle was being used at time of accident	WORKING USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMB1SN1555401601
Cover Note Number	
Driver	
Name of Driver	NAGARAJAN PANDIARAJAN
NRIC No	G8480405W
Date Of Birth	04/06/1986
Occupation	OUTDOOR
Date Of Driving Pass	10/12/2015
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84546149
Fax Number	
Contact Number	OFFICE-84546149
Email Address	NOEMAIL

Address	BLK 29 SUNGEI KADUT LOOP
Postcode	729469
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE8053B
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	TAN BOON HONG
NRIC/Passport Number	S2168622J
Contact Number	
Address	BLK 57 HUME AVENUE #04-09
Postcode	598753
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Details of Witness

Name	
Phone Number	
Email Address	

Accident Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Sketch Plan


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



Vehicle A - H 3182
Vehicle B - 3110655

Accident Sketch Plan

Describe Circumstances of the Accident

On 04/07/2019, I was stationary waiting the traffic light turn green before
Junction 4 Whitley road before entering onto Mylor near to the bus stop.
Suddenly vehicle B (SLEP0513) hit the back portion of my vehicle.

Declaration

We declare the foregoing particulars are true in every respect



Policyholder's Signature / Date &
Time

N. M.
Driver's Signature (if driver is not the policyholder) / Date
& Time

M. M. 7/9/19
Witnessed by Reporting Centre
Personnel

Enquire Vehicle & Owner Information (Vehicle No. SLE8053B As At 06 Sep 2017 / 11:50:00)**Law Firm Search Details****Search Reason:** Insurance claim in relation to traffic accident**Law Firm Case No.:** SLL-PC7188R**Current Owner Details****Owner ID Type:** Company**Owner ID:** 201624597K**Owner Name:** LCRF PTE LTD**Registered Address Type:** Private Residential (Condo Apt or House) / Shopping / Office Complexes**Registered Block/House No.:** 60**Registered Street Name:** ANSON ROAD**Registered Unit No.:** # 11 - 01**Registered Building Name:** MAPLE TREE ANSON**Registered Postal Code:** 079914**Current Vehicle Details****Vehicle No.:** SLE8053B**Make Description/Model:** MITSUBISHI / LANCER EX 1.6 AT LED TAIL LAMP**Insurance Company Name:** AIG ASIA PACIFIC INSURANCE PTE. LTD.

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Help the Website](#)
Last updated on 27 Aug 2017 at 01:09 AM

11/21/2017

Invoice



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-174526

Date of Request: 21/11/2017

Your Ref No: 2017.5140

EAST ASIA LAW CORPORATION
133 New Bridge Road #10-02
Chinatown Point
Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 06/09/2017

Name of Accident: WHITLEY

Client Vehicle No: PC7188R

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

11/22/2017

Invoice

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-174527

Date of Request: 21/11/2017

Your Ref No: 2017.5140

EAST ASIA LAW CORPORATION
133 New Bridge Road #10-02
Chinatown Point
Singapore 059413

Dear Sir/Madam,

Date of Accident: 06/09/2017

File No: PC7188R

Place of Accident: JUNCTION OF WHITLEY RD BEFORE WAYANG SATU FLYOVER

Involving Vehicle No: SLE8053B

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLE8053B	JUNCTION OF WHITLEY RD BEFORE WAYANG SATU FLYOVER	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

GIARMC Official use:
Date:
☒ GIRO ☐ Cash ☐ Cheque



WIN WIN CAR RENTAL

PHOTOCOPY

Invoice

PC7188R
N. PANDIA RAJAN
29 SUNGEI KADUT LOOP
S(729469)

Invoice No : WWIN0001718
Invoice Date : 21/9/2017
Due Date : 21/9/2017
VHA No : 33650
Referral ID : S004

Description :	Amount
Rental for 8 Day/s @ \$200 per Day	\$1,600

Vehicle No : SGE 9363 J

Vehicle Description : Toyota Picnic 2.0 A

Rental Period : 13/09/2017 to 21/09/2017

Total Amount Payable : \$1,600

PHOTOCOPY


WIN WIN CAR RENTAL8 Kaki Bukit Ave 4 #06-04 Premier @ Kaki Bukit Singapore 415875
Tel: 6315 8479 H/P: 9833 0807

VHA No: 33650

WINWIN1718

ROC No: 52987753E

VEHICLE RENTAL AGREEMENT**HIRER'S PARTICULAR**Name: (as in I/C) N. PANDJARAN
NRIC/PASSPORT No: 98480405 W
Address (Res): 129 SUNGAI KEDUT
100P Singapore 729469
Name & Address of Employer _____Occupation: _____ Driving Exp: _____
Driving Licence No: _____ D/L Type: Local / International
Issue Date: _____ Date of Birth: _____
Tel: (O) _____ (R) _____ HP 845A6149**ADDITIONAL DRIVER'S PARTICULARS**Name: (as in I/C) _____
NRIC/PASSPORT No: _____
Address (Res): _____
Driving License No: _____ D/L Type: Local / International
Issue Date: _____ Date of Birth: _____
Occupation: _____ Driving Exp: _____**VEHICLE CHECK LIST**D - DENTS
S - SCRATCHES

INDICATE:
A - ACCIDENTS**ACCESSORIES CHECK**
☐ Ashtray ☐ Cig Lighter ☐ S/Tyre
☐ STD Tools ☐ Jack ☐ Hub Caps
☐ Radio/Cass ☐ CD ☐ Cartridges

Vehicle No: <u>SEA 9363J</u>	Replace Veh No: _____
Mileage Out: <u>172770</u>	Mileage Out: _____
Make & Model: <u>TOYOTA PICNIC</u>	Auto / Manual Group: _____
Out : Date <u>13/09/2017</u>	Time: <u>11-45</u>
HIRE / PERIOD EXPIRY	Time: _____
NON-WAIVER EXCESS=\$ <u>3000</u>	
CHARGES	
Daily <u>8</u> @ \$ <u>200</u> per day	\$ <u>1600</u> -
Weekly @ \$ _____ per week	
Monthly @ \$ _____ per month	
Hours @ \$ _____ per hour	
Others @ \$ _____	
CDW @ \$ _____ per day/month	
PAI @ \$ _____ per day/month	
Delivery/Collection Service	
SUB-TOTAL \$	

PETROL LEVEL

Out	E	1/4	1/2	3/4	F
In	E	1/4	1/2	3/4	F

EXTENSION

Misc. _____

TOTAL CHARGES \$

Hirer's Signature

N. Pandj

Additional Driver's Signature _____

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment. I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN CAR RENTAL in connection with this agreement is true.

*** IMPORTANT**

- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN CAR RENTAL.

RETURN OF VEHICLE. THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN " SINGAPORE OF HIRER / DRIVER " FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
<u>21/9/17</u>	<u>10.35am</u>	<u>172770</u>			<u>N. Pandj</u>

SHENG LI LAI

No. 2 Kaki Bukit Avenue 2, #01-36 Kaki Bukit Autohub, Singapore 417921
Tel: 68420302 Fax: 67460295

Date : 18 November 2017
Name : NKH CONSTRUCTION EQUIPMENT PTE LTD
Address : C/O 2 KAKI BUKIT AVE 2
#01-36 KAKI BUKIT AUTOHUB
SINGAPORE 417921
Vehicle No. : PC7188R
Model : TOYOTA HIACE
Accident date : 6 September 2017

Final Repair Bill for Vehicle no. PC7188R

To supply labour and replaced parts, labour charges for
repairing, knocking-panel beating, welding and respray
(Lump Sum Repair)

\$ 10,000.00

Singapore Dollars: **TEN THOUSAND ONLY**

PHOTOCOPY

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Billing To: M/S NKH CONSTRUCTION EQUIPMENT PTE LTD
c/o Sheng li Lai
2 Kaki Bukit Ave 2
01 - 36
Kaki Bukit Autohub
Singapore 417921
Vehicle no: PC 7188 R

Invoice no.: TP17090038

Date: 15 NOV 2017

Model : TOYOTA HIACE

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 13 SEP 2017 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 780.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 780.00

Notes :

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.

Official Stamp

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP17090038

Date: 15 NOV 2017

M/S NKH CONSTRUCTION EQUIPMENT PTE LTD

c/o Sheng li Lai
2 Kaki Bukit Ave 2
01 - 36

Kaki Bukit Autohub
Singapore 417921

THIRD PARTY SURVEY

ACCIDENT OCCURED ON 06 September 2017

Workshop Name and Address

Sheng Li Lai
2 Kaki Bukit Ave 2
01 - 36
Kaki Bukit Autohub
Singapore 417921

As per your instruction dated
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

13 SEP 2017

with regard to the above matter.
PC 7188 R

1. VEHICLE PARTICULARS

Registration No : PC 7188 R
Model : TOYOTA HIACE
Year / Capacity : 2016 / 2985 cc
Chassis No : JTFHT02P300201080

Engine No : 1KD2632181
Mileage : N.A km
Colour : Multi colour

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Normal
REAR O/S :	195/50/R15	Bridgestone	9.00 mm	Normal
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Normal
REAR N/S :	195/50/R15	Bridgestone	9.00 mm	Normal

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **Rear & side** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 10 working days to complete
5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : PC 7188 R

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

<u>List Items</u>				
1 pc	Tailgate ✓ BT	bent	\$ 1,891.53	\$ 1,891.53
1 pc	Tail gate w/screen moulding ✓ NEC	Damaged	\$ 83.00	\$ 83.00
1 pc	Tailgate inner lock ✓ JM	bent	\$ 281.75	\$ 281.75
1 pc	Tailgate outer handle X NN	bent	\$ 119.25	\$ 119.25
1 pc	Tailgate 'TOYOTA' emblem ✓ NEC	essential	\$ 70.05	\$ 70.05
1 pc	Tailgate "HIACE" emblem ✓ NEC	Essential	\$ 39.20	\$ 39.20
1 pc	Tailgate rubber seal ✓ NEC	essential	\$ 328.48	\$ 328.48
1 pc	Tailgate inner lock catch ✓ BT	Damaged	\$ 30.80	\$ 30.80
1 pc	Tailgate inner lock linkage / pump ✓ DMG	Damaged	\$ 285.00	\$ 285.00
2 pcs	Tail Gate Hinge X NN	distorted	\$ 364.40	\$ 364.40
2 pcs	Tail Gate Absorber X NN	distorted	\$ 575.50	\$ 575.50
1 pc	Tail Gate Stopper ✓ NEC	wrapped/deformed	\$ 43.90	\$ 43.90
4 pcs	Tail Gate Side Stopper (Male & Female) ✓ NEC	wrapped/deformed	\$ 174.80	\$ 174.80
1 pc	Tailgate key lock ✓ DMG	damaged	\$ 128.10	\$ 128.10
1 pc	Rear end panel ✓ BT	bent/distorted	\$ 431.33	\$ 431.33
1 pc	Rear end panel top garnish X NN	warped/deformed	\$ 138.70	\$ 138.70
1 pc	Rear end panel lock latch ✓ BT	bent/distorted	\$ 81.97	\$ 81.97
1 pc	Rear bumper ✓ Deform	damaged	\$ 427.50	\$ 427.50
6 pcs	Rear bumper clip ✓ NEC	essential	\$ 21.00	\$ 21.00
2 pcs	Rear bumper side bracket ✓ BT	bent/distorted	\$ 38.24	\$ 38.24
2 pcs	Rear bumper bracket ✓ BT	bent/distorted	\$ 66.60	\$ 66.60
1 pc	Tail Lamp Assy ✓ CRK	electronically shocked	\$ 283.20	\$ 283.20
1 pc	Tail Lamp Base Panel R	dent/distorted	\$ 372.65	\$ 372.65
1 pc	Tail Lamp Sealant ✓ NEC	necessary	\$ 50.00	\$ 50.00
1 pc	Rear corner garnish ✓ Deform	dent/distorted	\$ 181.50	\$ 181.50
1 pc	Rear corner garnish clips ✓ NEC	necessary	\$ 12.90	\$ 12.90
1 pc	Spare Tyre Bracket X NN	distorted	\$ 171.80	\$ 171.80
1 pc	Spare Tyre Bracket Adjusting Screw X NN	dent/distorted	\$ 181.10	\$ 181.10
1 pc	Spare Tyre Bracket Adjusting Screw Hook X NN	bent/distorted	\$ 131.75	\$ 131.75

List Parts Sub-Total	\$	7,006.00	\$	7,006.00
Less 25% discount	\$	1,751.50	\$	1,751.50
Discounted sub-total	\$	5,254.50	\$	5,254.50

4626.14
- 25%
3469.60

Vehicle Number : PC 7188 R

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Nett Items</u>				
1 pc	Rear windscreen glass sealant	necessary	\$ 65.00	\$ 65.00 40
1 pc	Reverse camera	electronically shocked	\$ 520.00	\$ 520.00 250
1 set	Reverse sensor	electronically shocked	\$ 380.00	\$ 350.00 200
1 pc	" 70 KM/H" sticker	necessary	\$ 45.00	\$ 45.00 250
Special Nett Sub-Total			\$ 1,010.00	\$ 980.00
Spare Parts Total			\$ 6,264.50	\$ 6,234.50


2) 535

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
	Spare Parts Total c/f	\$ 6,264.50	\$ 6,234.50
1	To transfer tailgate fittings to new tailgate	\$ 180.00	100 150.00 60 Δ
2	To remove/reinstall upholstery, trims & windscreen glass.	\$ 280.00	150 250.00 120 Δ
3	Labour charges to repair and panel beat rear fender inner structure chassis members, bootfloor cutting/welding and replacing the above mentioned parts.	\$ 2,200.00	800 2,000.00
4	To remove and replace reverse sensor & camera	\$ 320.00	100 300.00 70 Δ
5	To check wiring functions & conduct water leakage test.	\$ 180.00	60 150.00 30 Δ
6	To remove/repair exhaust silencer	\$ 180.00	150.00 X
7	To putty, apply primer & spray-paint the affected areas.	\$ 1,800.00	800 1,600.00
8	To apply rust-proofing on repaired/replaced panels.	\$ 180.00	50 150.00
	Total	\$ 11,584.50	\$ 10,984.50

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of:

Fong Kok Heng
Qualified Appraiser



\$ 10,000.00

3) 2000

1) Parts : \$ 3469.60
2) S/Nett : \$ 535.00
3) Labour : \$ 2060.00

6064.60

Lump Sum - 20%

4851.68

L/s : \$ 4850 @ 6 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/LCR18002058/Svbs2

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120
ATTN: ANGIE GAN

Date : 13-02-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SLE 8053B	Veh. Inspected	PC 7188R
Policy No.		Coverage (\$)	0.00
Claim No.	2073632085SG003	Excess (\$)	0.00
Assign From	ANGIE GAN	Assign Date	18/01/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2985
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTFHT02P300201080	Colour	SILVER
Odometer	338435	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	OHTSU	6 mm
L/H Front Tyre	195 R15	OHTSU	6 mm
R/H Rear Tyre	195 R15	OHTSU	6 mm
L/H Rear Tyre	195 R15	OHTSU	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	06/09/2017	Inspection Date	06/02/2018
Survey held at	NO 29 SUNGEI KADUT LOOP SPORE 729469		
Repairer	SHENG LI LAI		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 7188R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	REPLACED	1,891.53	1,755.30
1	TAIL GATE W/SCREEN MOULDING	REPLACED	83.00	83.00
1	TAILGATE INNER LOCK	REPLACED	281.75	281.75
1	TAILGATE OUTER HANDLE	NOT NECESSARY	119.25	-
1	TAILGATE 'TOYOTA' EMBLEM	REPLACED	70.05	70.05
1	TAILGATE "HIACE" EMBLEM	REPLACED	39.20	39.20
1	TAILGATE RUBBER SEAL	REPLACED	328.48	150.00
1	TAILGATE INNER LOCK CATCH	REPLACED	30.80	30.80
1	TAILGATE INNER LOCK LINKAGE / PUMP	REPLACED	285.00	285.00
2	TAIL GATE HINGE	NOT NECESSARY	364.40	-
2	TAIL GATE ABSORBER	NOT NECESSARY	575.50	-
1	TAIL GATE STOPPER	REPLACED	43.90	43.90
4	TAIL GATE SIDE STOPPER (MALE & FEMALE)	REPLACED	174.80	174.80
1	TAILGATE KEY LOCK	REPLACED	128.10	128.10
1	REAR END PANEL	REPLACED	431.33	431.33
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	138.70	-
1	REAR END PANEL LOCK LATCH	REPLACED	81.97	81.97
1	REAR BUMPER	REPLACED	427.50	427.50
6	REAR BUMPER CLIP	REPLACED	21.00	21.00
2	REAR BUMPER SIDE BRACKET	REPLACED	38.24	38.24
2	REAR BUMPER BRACKET	REPLACED	66.60	66.60
1	TAIL LAMP ASSY	REPLACED	283.20	283.20
1	TAIL LAMP BASE PANEL	REPAIRED SEE LABOUR	372.65	-
1	TAIL LAMP SEALANT	REPLACED	50.00	40.00
1	REAR CORNER GARNISH	REPLACED	181.50	181.50
1	REAR CORNER GARNISH CLIPS	REPLACED	12.90	12.90
1	SPARE TYRE BRACKET	NOT NECESSARY	171.80	-
1	SPARE TYRE BRACKET ADJUSTING SCREW	NOT NECESSARY	181.10	-
1	SPARE TYRE BRACKET ADJUSTING SCREW HOOK	NOT NECESSARY	131.75	-

Report Ref No. CS/LCR18002058/Svbs2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-1,751.50	-1,156.53
			5,254.50	3,469.61
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN GLASS SEALANT (SN)	REPLACED	65.00	40.00
1	REVERSE CAMERA (SN)	REPLACED	520.00	250.00
1	SET REVERSE SENSOR (SN)	REPLACED	380.00	200.00
1	"70KM/H" STICKER (SN)	REPLACED	45.00	25.00
			1,010.00	515.00
	<u>LABOUR</u>			
	TO TRANSFER TAILGATE FITTINGS TO NEW TAILGATE.		180.00	60.00
	TO REMOVE / REINSTALL UPHOLSTERY, TRIMS & WINDSCREEN GLASS.		280.00	120.00
	LABOUR CHARGES TO REPAIR AND PANEL BEAT REAR FENDER INNER STRUCTURE CHASSIS MEMBERS, BOOTFLOOR CUTTING / WELDING AND REPLACING THE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF TAIL LAMP BASE PANEL.		2,200.00	800.00
	TO REMOVE AND REPLACE REVERSE SENSOR & CAMERA.		320.00	70.00
	TO CHECK WIRING FUNCTIONS & CONDUCT WATER LEAKAGE TEST.		180.00	30.00
	TO REMOVE / REPAIR EXHAUST SILENCER.	NOT NECESSARY	180.00	-
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS.		1,800.00	800.00
	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.		180.00	50.00
			5,320.00	1,930.00
	GRAND TOTAL		11,584.50	5,914.61
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,700.00

Report Ref No. CS/LCR18002058/Svbs2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)**BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.