

Ref: 18002069/mijs3 mij3

6482 1296

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/AMK

Claim Type: Third Party

Accident Date: 31/01/2018

TP Veh Reg No: SHA4162P

Estimate No: ES1890109/AMK

Date: 01 Feb 2018

Policy No: 5076553417-02

Veh Reg No: SKX8155C

Make/Model: HONDA VEZEL 1.5X
CVT

Chassis No: RU11106026

Engine No: L15B4026031

Reg. Date: 29/12/2015

Estimate Repair Cost to Vehicle No :SKX8155C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	459.80	1 PC	✓ 459.80 def.	
2 FRONT BUMPER LOWER SPOILER	195.60	1 PC	✓ 195.60 cut.	
3 FRONT BUMPER LH SIDE RETAINER	15.70	1 PC	✓ 15.70 dis.	
4 FRONT BUMPER LH FOG LAMP GARNISH	45.00	1 PC	✓ 45.00	
5 FRONT BUMPER CLIP	3.90	5 PC	✓ 19.50 nec	
6 FRONT GRILLE	280.60	1 PC	✓ 280.60 dis.	
7 FRONT GRILLE LOGO	24.70	1 PC	✓ 24.70 nec	
8 FRONT GRILLE CHROME	56.90	2 PC	✓ 113.80 nec	
9 HEADLAMP LH	1,784.50	1 PC	✓ 1,784.50 over	
10 HEADLAMP LH LOWER BRACKET	35.00	1 PC	✓ 35.00 . b	
11 FRONT LH FENDER	580.00	1 PC	✓ 580.00 da	
12 FRONT LH FENDER INNER SHIELD	130.00	1 PC	✓ 130.00 dis.	
13 FRONT LH FENDER INNER SHIELD CLIP	3.90	6 PC	✓ 23.40 nec	
14 FRONT LH FENDER WHEEL ARC GARNISH	195.00	1 PC	✓ 195.00 cut	
15 FRONT LH DOOR	1,080.50	1 PC	✓ 1,080.50 da	
16 FRONT LH DOOR FRAME STICKER	21.20	1 PC	✓ 21.20 nec	
17 LH SIDE SKIRT	377.50	1 PC	✓ 377.50 dis.	
18 REAR LH FENDER WHEEL ARCH GARNISH	150.30	1 PC	✓ 150.30 cut	
19 SPORT RIM LH 16"	765.80	2 PC	✗ 1,531.60 R	
20 REAR LH DOOR	930.60	1 PC	✓ 930.60 R	
21 REAR LH DOOR FRAME STICKER	28.00	1 PC	✗ 28.00 NIN	
			8,022.30	
		Less 20%	1,604.46	6,417.84
Special Net				
22 DOOR VISOR	150	1 SET	150.00	
			150.00	150.00
Labour				
23 REMOVE & REFIX FRT BUMPER,FRT GRILLE, HEADLAMP,FRT LH FENDER,FRT LH DOOR & ATTACHMENTS,LH SIDE SKIRT;KNOCKING & REPAIR REAR LH DOOR PILLAR & REALIGN THE SAME	900.00	1 LA	900.00	900
24 PUTTY & RESPRAY FRT BUMPER,BONNET,FRT LH FENDER,BOTH LH DOORS,REAR LH FENDER,REAR LH SIDE BUMPER & ALL AFFECTED AREAS	1,200.00	1 LA	1,200.00	1100
25 REMOVE & REFIX BOTH LH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	120	1 LA	120.00	100
26 REMOVE & REFIX BOTH LH RIMS,TYRES & BALANCE	60	1 LA	60.00	✓

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST-201001158E RCB NO: 201001158E

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

ATTN: Motor Claim Department

TP Veh Reg No: SHA4162P

Reg. Date: 29/12/2015

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts-prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: