

SERVICE @ RIVERVIEW PTE LTD

10, Ang Mo Kio Autopoint #04-11
Ang Mo Kio Industrial Park 2A
Singapore 568047

Tel : 6481 9810 / 6481 4849 Fax : 6481 6256

Email : riverview@singnet.com.sg

Buss.reg.No : 200910700K

Lump Sum repair

Len 20%

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(Signature) 2/1/07

SDS 7191M

Parts

Bottled Copper/spray paint

Bottled Hyundai Emblem

Bottled Hyundai Logo

Bottled "S" emblem

Rear Bumper

Rear Bumper sponge

Rear end panel (Copper/spray paint) X 6602

Special net item

Reverse parking sensor (1 set) eloft 220

Rear Bumper clips (1 set) net Price 250

Labour charge

1) To Renew damaged parts & repair Accident area 550

2) To assemble Reverse parking sensor and 60 sheet for proper functions. 80

3) To spray paint Bottled, Rear Bumper and 600 rear End panel 800

4) To carry out anti-rust treatment at the 80 accident Area 40.

List Price \$

Hyundai Len 20%

907

55 net

56 net

44 net

546 def

140 torn

\$1700k

21 days

net Price

250

40