

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 06 Feb 2018

Preliminary Advice

Insured Vehicle No	: SKM8318H		
TP Vehicle No	: SGM419A	Accident Date	: 26/01/2018
Make	: HONDA CIVIC	Assignment Date	: 01/02/2018
Date of Inspection	: 02/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: ETHICARZ PTE LTD (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,924.36
Revised Amount	:S\$	4,150.72
Check Items (Estimated)	:S\$	2,774.36
Total	:S\$	6,925.08

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.