

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

XD2671U Nissan GKB4CLB00263

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,800.00 200
2	To putty and spray painting rear portion.	\$ 1,000.00 x
3	To check rear lighting and wiring.	\$ 50.00 30
4	To apply anti rust proofing to rear affected area.	\$ 100.00 x
5	To remove and install exhaust pipe complete assy.	\$ 150.00 x
6	To repair, straighten and align rear chassis assy to specification.	\$ 450.00 x
7	To conduct chassis alignment.	\$ 450.00 x
8	To conduct wheel alignment.	\$ 150.00 x 30
9	To remove and install rear undercarriage parts.	\$ 450.00 x
10	Towing service.	\$ 250.00 x
Total labour :		\$ 4,850.00

Total parts : \$ 15,730.40

Total labour : \$ 4,850.00

Total repair cost : \$ 20,580.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
w/s 20/03/18.
03 Rys

total 1369.10
w/s 1.1K

1.1K