

22/05/2001

ASS. REC. BY:

REF: CS/CT118002093/Kvd387

Special Instruction:

Surveyor:
MerimenKenneth
Adeline Chng

ASSIGNMENT (Office)

Gdeline.chng@sg.ctaiping.com

From (Person):

of

CTI

Date/Time:

02/02/18 @ 9:18pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

EU6999J

Insured:

at Workshop m/s

K. Kim Hin Auto

Tel:

64527018

of 160 Sin Ming Drive # 02-20

Policy No: DMPCSN1621931600

Claim No:

SNM18D00584C01

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A. 29/01/2018

11:30am.

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:23am @ 2/2/18

Person Contacted:

shuman

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

Interview Insured; check further details of TP vehicle & consistency of damages.

EU6999J-x

5/2/18

Revert by merimen, pending interview insured.

7/2/18

Rece approved from Alfred by merimen

Survey Department Check List (Case Handler)

Reference No.: CS/CTI 18002093/Krd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges	✓			
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 10/7/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI18002093/Kvd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 02-02-2018	
			Code : CTI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.			Veh. Inspected	EU 6999J
Policy No.	DMPCSN1621931600		Coverage (\$)	0.00
Claim No.	SNM18D00584C01		Excess (\$)	500.00
Assign From	MERIMEN (ADELINE CHNG)		Assign Date	02/02/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/01/2018		Inspection Date	02/02/2018
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Feb 2018 Sendback Est	01 Feb 2018 17:01 S\$10,624.47	02 Feb 2018 09:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: CHEN BIAO , ID: S2656139F, Tel: +6590037146, Email: NOEMAIL	
Vehicle Reg. No.: EU6999J	Date of Loss: 29/01/2018 09:00 - :59
Claim Type: OD / SNM18D00584C01	Policy/Cover Note No.: DMPCSN1621931600 (Comprehensive) Coverage: 15/04/2017 - 14/04/2018
	Excess: S\$500.00
Repairer: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018	
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/02/2018]	
Driver/Custodian: CHEN BIAO (53 / Male) , NRIC: S2656139F, Tel: +6590037146	
Adj Asg. Remarks: PLEASE INTERVIEW INSURED & REVERT:- -CHECK FURTHER DETAILS OF TP VEHICLE -CONSISTENCY OF DAMAGES	

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS [-]

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Tuesday, February 20, 2018 11:53 AM
To: 'service@kkimhin.com.sg'
Cc: 'Simon'; SUR
Subject: EU 6999J CTI OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **EU 6999J (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	01 Feb 2018 16:54	Clim Veh Model Changed	(200368) JAGUAR XJ8 4.2 (A).	[R] Wong Shu Man
2	01 Feb 2018 16:54	Clim Created	Reg No: EU6999J. Policy No: DMPCSN1621931600. Acct Date: 2018/01/29. Cla im Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Wor kshop: K Kim Hin Auto Pte Ltd (HQ). Created from SAS:MKKH18015514	[R] Wong Shu Man
3	01 Feb 2018 17:01	Clim Submitted	10624.47.	[R] Wong Shu Man
4	02 Feb 2018 09:18	Clim Registration Modified	Excess: -> 500.00.	[I] Adeline Chng Pei Wen
5	02 Feb 2018 09:18	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE INTERVIEW INSURED & REVERT:- CHECK FURTHER DETAILS OF TP VEHICLE -CONSISTENCY OF DAMAGES	[I] Adeline Chng Pei Wen
6	02 Feb 2018 09:18	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/13	[I] Adeline Chng Pei Wen
7	02 Feb 2018 09:18	Adj Mandate Set	Approved:0.00.	[I] Adeline Chng Pei Wen
8	02 Feb 2018 09:21	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	02 Feb 2018 12:07	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Nivitha Govindasamy
10	05 Feb 2018 16:48	Adj Rpt Initiated		[A] VERON CHEN
11	05 Feb 2018 16:56	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/13	[A] VERON CHEN
12	05 Feb 2018 17:03	Adj Mandate Request	Cur.Reg:8670.72:Repair Cost Economical Pending interview insured.	[A] VERON CHEN
13	07 Feb 2018 10:25	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/13. Mandate Remarks: Please proceed to authorize repairs at \$8,654.26 BEFORE excess of \$500.00.	[I] Alfred Toh
14	07 Feb 2018 10:25	Adj Mandate Set	Approved:8654.26:Please proceed to authorize repairs at \$8,654.26 BEFORE e xcess of \$500.00.Reinsp:Adj decides.	[I] Alfred Toh

ACTIVITY

[02/02/2018 09:24] Nivitha Govindasamy:
Vehicle not in workshop, repairer will arrange.

Merimen Billing for this case - Transaction History							
Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1713165	01/02/2018 16:54	Motor	K Kim Hin Auto Pte Ltd (HQ)	K Kim Hin Auto Pte Ltd (HQ)	EU6999J		xx.xx
1715823	05/02/2018 16:48	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	EU6999J		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 05 Feb 2018

Preliminary Advice

Vehicle No	: EU6999J	Accident Date	: 29/01/2018
Make	: JAGUAR XJ8	Policy No.	: DMPCSN1621931600
Assignment Date	: 02/02/2018	Excess	: S\$500.00
Date of Inspection	: 02/02/2018	Est. Duration of Repair	: 4.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,624.47
Revised Amount	:S\$	8,670.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,670.72

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	51,685.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,315.00

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 6/6 mm
Tyre Condition (Rear)	: 6/6 mm

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending interview insured.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/01/2018 17:05
Date Of Accident	29/01/2018 09:30
Exact Location Of Accident	BLK 5032 ANG MO KIO AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EU6999J
Insured/Policyholder	
Name Of Registered Owner	CHEN BIAO
NRIC No	S2656139F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90037146
Alternative Phone No	OFFICE-90037146

Vehicle Particulars

Manufacturer	JAGUAR
Model	XJ8-4.2 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1621931600
Cover Note Number	

Driver

Name of Driver	CHEN BIAO
NRIC No	S2656139F
Date Of Birth	14/11/1964
Occupation	INDOOR
Date Of Driving Pass	11/10/2004
Driving Experience	13 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90037146
Fax Number	
Contact Number	OFFICE-90037146
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6139F
Vehicle Details	
Vehicle No.:	EU6999J
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	JAGUAR
Vehicle Model:	XJ8 4.2S LWB
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	0410141004SC
Chassis No.:	SAJAC80F25SG44999
Maximum Power Output:	224.0 kW (300 bhp)
Open Market Value:	\$94,971.00
Original Registration Date:	15 Apr 2005
First Registration Date:	15 Apr 2005
Transfer Count:	3
Actual ARF Paid:	\$104,469.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Apr 2025
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$71,730.00
COE Rebate Amount:	\$51,685.00
Total Rebate Amount:	\$51,685.00

The information contained herein is correct as at 31 Jan 2018

K.KIM HIN AUTO PTE LTD
160 Sin Ming Drive
#02-20 Sin Ming AutoCity
Singapore 575722

Claim Reference:
Assessment Number: KKHC0211
Version: K.KIMHIN/1
Date Calculated: 01/02/2018 08:02

Full Report - V1
Registration: EU6999J
Printed: 01/02/2018 16:04

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	29/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN1621931600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	JAGUAR
Model:	XJ
Sub Model:	XJ8 EXEC LAST EDIT
Model Sheet Number:	F06 49
Registration:	EU6999J
Registration Month:	
Registration Year:	
VIN Number:	SAJAC80F25SG44999
Odometer:	Not Known
Colour:	
Engine Number:	0410141004SC
Fuel Level:	%

Model Specs

BI-XENON HEADLAMPS	HEADLAMP WASHER UNIT
TWO COAT METALLIC	PREPARE OFF VEHICLE



Not Authorized
1. B1
Resurvey B & paint
Ex @ 500
4 days
Ref: 62564315

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	31/01/2018
Pre-Accident Damage:	
Tyres Condition:	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	

K.K. Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

K.KIM HIN AUTO PTE LTD

Claim Reference:
Assessment Number: KKHC0211
Version: K.KIMHIN/1
Date Calculated: 01/02/2018 08:02

Full Report - V1
Registration: EU6999J
Printed: 01/02/2018 16:04



Addresses

Cost Summary

Total Labour	\$818.80
Total Paint/Material	\$218.92
Total Parts	\$9,544.75
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$10,624.47
7 % GST:	\$743.71
Grand Total Inc GST:	\$11,368.18

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)	
10-10-10	PREPARATION TIME	1.0	4.60	
NO NUMBER	BODYSHELL PANEL WORK PREPARATION TIME	3.0	13.80	
74-20-05)	R + R LEFT FRONT WHEEL	1.0	4.60	
76-22-83	R + R FRONT BUMPER COVER	9.0	41.40	
	INCLUDES: R + R WHEELARCH TRIMS AND LOWER PROTECTION			
76-22-73)	R + R L/F BUMPER MOULDING	4.0	18.40	
76-22-73)	R + R R/F BUMPER MOULDING	4.0	18.40	
86-41-54)	R + R L/XENON HEADLAMP (BUMPER REMOVED)	7.0	32.20	
86-41-53)	R + R R/XENON HEADLAMP (BUMPER REMOVED)	7.0	32.20	X
77-51-10	REMOVE/REFIT BONNET PANEL	2.0	9.20	
76-16-01)	RENEW BONNET (REMOVED)	5.0	23.00	
77-51-05)	R + R L/F WING (BUMPER REMOVED)	13.0	59.80	
	INCLUDES: R + R DOOR SILL TRIM AND WHEELARCH TRIM			
77-51-05	RENEW L/F WING (REMOVED)	3.0	13.80	
	INCLUDES: R + R REPEATER LAMP AND MUDFLAP			
86-40-17	ADJUST HEADLAMPS	2.0	9.20	X
NO NUMBER	APPLY CAVITY PROTECTION L/F WING	4.0	18.40	X
NO NUMBER	APPLY CAVITY PROTECTION BONNET	4.0	18.40	X
LABOUR COST				
Total Work Units		69.0		
Corrosion Protection				
Corrosion Protection External Labour		0.0HRS	0.00	
Corrosion Protection Internal Labour		0.8HRS	36.80	
Sub Total		6.9HRS	\$317.40	

K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHC0211

Version: K.KIMHIN/1

Date Calculated: 01/02/2018 08:02

Full Report - V1

Registration: EU6999J

Printed: 01/02/2018 16:04

Paint Labour	10.9HRS	\$501.40
Total Labour	17.8HRS	\$818.80

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	11.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
471	BONNET REPAIR PAINTING >50%	49.0	
742	R/F WING SURFACE PAINT	6.0	
LABOUR COST - PAINT			
TIME(PAINT)		79.0	
Preparation Main Work Plastic		5.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		109.0	
Total Paintwork Labour		10.9HRS	\$501.40
MATERIAL COST - PAINT			Cost Price
New Part Painting			\$23.74
New Part Painting - Plastic K1R			\$61.99
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$11.45
Repair Painting			\$84.14
Material-Const Main Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$218.92
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$218.92

PARTS

Guide No. Qty		Description	Part Number	Supplier	Bet.	Price (\$)	
293	1	L/F BUMPER MOULDING	C2C1593	Sm	0%	230.00*	X
294	1	R/F BUMPER MOULDING	C2C1592	Sm	0%	230.00*	X
431	1	RAD GRILLE BADGE	C2C25678		0%	85.00*	X
432	1	JAGUAR FIGURE	C2C39767		0%	450.00*	X
471	1	BONNET	C2C37987	(Aluminium)	0%	3,500.00*	✓
561	1	LEFT HEADLAMP ASSY	C2C22630		0%	2,300.00*	✓
741	1	L/F WING	C2C25397	(Aluminium)	0%	1,400.00*	✓
1000	1	FRT BUMP NOZZLE	4PCS @100		0%	400.00*	X
1000	1	FRT BUMP JET BRKT	4PCS @ 100		0%	400.00*	X
f: OEM Parts			Sub Total			\$8,995.00	
g: Original			Mark Up From Cost	(5 %)		\$449.75	
h: Secondhand			Sundry Parts	(Fixed)		\$100.00	
p: Parallel			Total Parts			\$9,544.75	
x: Exchange							

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
SPECIALIST		
Total Extras		\$42.00

Final Calculation

K.KIM HIN AUTO PTE LTD

Claim Reference:
Assessment Number: KKHC0211
Version: K.KIMHIN/1
Date Calculated: 01/02/2018 08:02

Full Report - V1
Registration: EU6999J
Printed: 01/02/2018 16:04

Total Parts		\$9,544.75
Labour		
Total Panel/Mechanical	\$280.60	211.60
Total Paintwork	\$501.40	529
Corr Prot Internal 8 WU	\$36.80	X
Total Labour		\$818.80
Additional Costs		
Corr Prot Materials External	\$0.00	
Cost of Specialist	\$42.00	
Total of Additional Costs		\$42.00
Total Paint/Material Costs		\$218.92
Grand Total Excludes GST		\$10,624.47
GST @ 7 %		\$743.71
Grand Total Includes GST		\$11,368.18

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Revert

Claim Reference:
Assessment Number: KKHC0211
Version: LKKAUTOC/3
Date Calculated: 05/02/2018 08:10

Full Report - V1
Registration: EU6999J
Printed: 05/02/2018 16:10

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	MR LAU	Date of Incident:	29/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN1621931600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	JAGUAR
Model:	XJ
Sub Model:	XJ8 EXEC LAST EDIT
Model Sheet Number:	F06 49
Registration:	EU6999J
Registration Month:	
Registration Year:	
VIN Number:	SAJAC80F25SG44999
Odometer:	Not Known
Colour:	
Engine Number:	0410141004SC
Fuel Level:	%

Model Specs

BI-XENON HEADLAMPS	HEADLAMP WASHER UNIT
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status



Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
	Date of Inspection: 31/01/2018
Brakes Pedal Travel:	
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	

Claim Reference:

Assessment Number: KKHC0211

Version: LKKAUTOC/3

Date Calculated: 05/02/2018 08:10

Registration: EU6999J
Printed: 05/02/2018 16:10**Addresses****Cost Summary**

Total Labour	\$749.80
Total Paint/Material	\$218.92
Total Parts	\$7,660.00
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$8,670.72
7 % GST:	\$606.95
Grand Total Inc GST:	\$9,277.67

Repair Information**LABOUR**Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
10-10-10	PREPARATION TIME	1.0	4.60
NO NUMBER	BODYSHELL PANEL WORK PREPARATION TIME	3.0	13.80
74-20-05)	R + R LEFT FRONT WHEEL	1.0	4.60
76-22-83	R + R FRONT BUMPER COVER	9.0	41.40
	INCLUDES: R + R WHEELARCH TRIMS AND LOWER PROTECTION		
86-41-54)	R + R L/XENON HEADLAMP (BUMPER REMOVED)	7.0	32.20
77-51-10	REMOVE/REFIT BONNET PANEL	2.0	9.20
76-16-01)	RENEW BONNET (REMOVED)	5.0	23.00
77-51-05)	R + R L/F WING (BUMPER REMOVED)	13.0	59.80
	INCLUDES: R + R DOOR SILL TRIM AND WHEELARCH TRIM		
77-51-05	RENEW L/F WING (REMOVED)	3.0	13.80
	INCLUDES: R + R REPEATER LAMP AND MUDFLAP		
86-40-17	ADJUST HEADLAMPS	2.0	9.20
NO NUMBER	APPLY CAVITY PROTECTION L/F WING	4.0	18.40
NO NUMBER	APPLY CAVITY PROTECTION BONNET	4.0	18.40
LABOUR COST		54.0	
Total Work Units			
Corrosion Protection			
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.8HRS	36.80
Sub Total		5.4HRS	\$248.40
Paint Labour		10.9HRS	\$501.40
Total Labour		16.3HRS	\$749.80

Claim Reference:

Assessment Number: KKHC0211

Version: LKKAUTOC/3

Date Calculated: 05/02/2018 08:10

Registration: EU6999J
Printed: 05/02/2018 16:10

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	11.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
471	BONNET REPAIR PAINTING >50%	49.0	
742	R/F WING SURFACE PAINT	6.0	
LABOUR COST - PAINT		79.0	
TIME(PAINT)		5.0	
Preparation Main Work Plastic		25.0	
Preparation Main Work Metal		0.0	
Preparation Work Multi Layer Paint		109.0	
Total Work Units (10WU/HR)		10.9HRS	
Total Paintwork Labour			\$501.40
MATERIAL COST - PAINT			
New Part Painting			\$23.74
New Part Painting - Plastic K1R			\$61.99
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$11.45
Repair Painting			\$84.14
Material-Const Main Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$218.92
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$218.92

PARTS

Guide No. Qty		Description	Part Number	Supplier	Bet.	Price (\$)
471	1	BONNET	C2C37987		0%	3,500.00*
1000	1	FRT BUMP JET BRKT	4PCS @ 100		0%	0.00
1000	1	FRT BUMP NOZZLE	4PCS @100		0%	0.00
741	1	L/F WING	C2C25397		0%	1,400.00*
561	1	LEFT HEADLAMP ASSY	C2C22630		0%	2,300.00*
f: OEM Parts			Sub Total			\$7,200.00
g: Original			Mark Up From Cost	(5 %)		\$360.00
h: Secondhand			Sundry Parts	(Fixed)		\$100.00
p: Parallel			Total Parts			\$7,660.00
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	SPECIALIST	Betterment	Price
AUDATEX FEE		0%	\$42.00
		Total Extras	\$42.00

Final Calculation

Total Parts			\$7,660.00
Labour			
Total Panel/Mechanical		\$211.60	
Total Paintwork		\$501.40	
Corr Prot Internal 8 WU		\$36.80	
Total Labour			\$749.80

Claim Reference:

Assessment Number: KKHC0211

Version: LKKAUTOC/3

Date Calculated: 05/02/2018 08:10

Registration: EU6999J
Printed: 05/02/2018 16:10**Additional Costs**

Corr Prot Materials External

\$0.00

Cost of Specialist

\$42.00

\$42.00

Total of Additional Costs

\$218.92

Total Paint/Material Costs

\$8,670.72

Grand Total Excludes GST

\$606.95

GST @ 7 %

\$9,277.67

Grand Total Includes GST**Assessment Notes**

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER**

079909

Claim Reference:
Assessment Number: KKHC0211
Version: LKKAUTOC/4
Date Calculated: 07/02/2018 02:05

Full Report - V1
Registration: EU6999J
Printed: 07/02/2018 10:05

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Eddie Sim	Date of Incident:	29/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN1621931600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	JAGUAR
Model:	XJ
Sub Model:	XJ8 EXEC LAST EDIT
Model Sheet Number:	F06 49
Registration:	EU6999J
Registration Month:	
Registration Year:	
VIN Number:	SAJAC80F25SG44999
Odometer:	Not Known
Colour:	
Engine Number:	0410141004SC
Fuel Level:	%

Model Specs

BI-XENON HEADLAMPS	HEADLAMP WASHER UNIT
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
	Date of Inspection:
Brakes Pedal Travel:	31/01/2018
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:
Assessment Number: KKHC0211
Version: LKKAUTOC/4
Date Calculated: 07/02/2018 02:05

Full Report - V1
Registration: EU6999J
Printed: 07/02/2018 10:05



Addresses

Cost Summary

Total Labour	\$740.60
Total Paint/Material	\$211.66
Total Parts	\$7,660.00
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$8,654.26
7 % GST:	\$605.80
Grand Total Inc GST:	\$9,260.06

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
10-10-10	PREPARATION TIME	1.0	4.60
NO NUMBER	BODYSHELL PANEL WORK PREPARATION TIME	3.0	13.80
74-20-05)	R + R LEFT FRONT WHEEL	1.0	4.60
76-22-83	R + R FRONT BUMPER COVER	9.0	41.40
	INCLUDES: R + R WHEELARCH TRIMS AND LOWER PROTECTION		
86-41-54)	R + R L/XENON HEADLAMP (BUMPER REMOVED)	7.0	32.20
77-51-10	REMOVE/REFIT BONNET PANEL	2.0	9.20
76-16-01)	RENEW BONNET (REMOVED)	5.0	23.00
77-51-05)	R + R L/F WING (BUMPER REMOVED)	13.0	59.80
	INCLUDES: R + R DOOR SILL TRIM AND WHEELARCH TRIM		
77-51-05	RENEW L/F WING (REMOVED)	3.0	13.80
	INCLUDES: R + R REPEATER LAMP AND MUDFLAP		
86-40-17	ADJUST HEADLAMPS	2.0	9.20
LABOUR COST		46.0	
	Total Work Units	0.0HRS	0.00
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	4.6HRS	\$211.60
	Sub Total	11.5HRS	\$529.00
	Paint Labour	16.1HRS	\$740.60
	Total Labour		

PAINT WORK

Guide Number Description

Time Basis 10 WU = 1 HR. Price = \$46.00/HR
WU Cost Price (\$)

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: KKHC0211

Version: LKKAUTOC/4

Date Calculated: 07/02/2018 02:05

Full Report - V1

Registration: EU6999J

Printed: 07/02/2018 10:05

	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	11.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
471	BONNET REPAIR PAINTING >50%	49.0	
742	R/F WING SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	82.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	115.0	
	Total Paintwork Labour	11.5HRS	\$529.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$23.74
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$11.45
	Repair Painting		\$84.14
	Repair Painting Plastic		\$51.03 (A)
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$211.66
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$211.66

PARTS

Price Valid: 01/01/2001

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
471	1	BONNET	C2C37987		0%	3,500.00*
561	1	LEFT HEADLAMP ASSY	C2C22630		0%	2,300.00*
741	1	L/F WING	C2C25397		0%	1,400.00*
f: OEM Parts			Sub Total			\$7,200.00
g: Original			Mark Up From Cost	(5 %)		\$360.00
h: Secondhand			Sundry Parts	(Fixed)		\$100.00
p: Parallel			Total Parts			\$7,660.00
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
SPECIALIST		
Total Extras		\$42.00

Final Calculation

Total Parts		\$7,660.00
Labour		
Total Panel/Mechanical	\$211.60	
Total Paintwork	\$529.00	
Total Labour		\$740.60
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$42.00	
Total of Additional Costs		\$42.00
Total Paint/Material Costs		\$211.66

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: KKHC0211

Version: LKKAUTOC/4

Date Calculated: 07/02/2018 02:05

Full Report - V1

Registration: EU6999J

Printed: 07/02/2018 10:05

Grand Total Excludes GST

GST @ 7 %

Grand Total Includes GST

→ \$8,654.26

\$605.80

\$9,260.06

Assessment Notes

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER**

079909

Finalised

Claim Reference:
Assessment Number: KKHC0211
Version: CHINATAI/3
Date Calculated: 07/02/2018 02:05

Full Report - V1
Registration: EU6999J
Printed: 05/07/2018 17:29

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	29/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN1621931600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	JAGUAR
Model:	XJ
Sub Model:	XJ8 EXEC LAST EDIT
Model Sheet Number:	F06 49
Registration:	EU6999J
Registration Month:	
Registration Year:	
VIN Number:	SAJAC80F25SG44999
Odometer:	Not Known
Colour:	
Engine Number:	0410141004SC
Fuel Level:	%

Model Specs

BI-XENON HEADLAMPS	HEADLAMP WASHER UNIT
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	31/01/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:
Assessment Number: KKHC0211
Version: CHINATAI/3
Date Calculated: 07/02/2018 02:05

Full Report - V1
Registration: EU6999J
Printed: 05/07/2018 17:29



Addresses

Cost Summary

Total Labour	\$740.60
Total Paint/Material	\$211.66
Total Parts	\$7,660.00
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$8,654.26
7 % GST:	\$605.80
Grand Total Inc GST:	\$9,260.06

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
10-10-10	PREPARATION TIME	1.0	4.60
NO NUMBER	BODYSHELL PANEL WORK PREPARATION TIME	3.0	13.80
74-20-05)	R + R LEFT FRONT WHEEL	1.0	4.60
76-22-83	R + R FRONT BUMPER COVER	9.0	41.40
	INCLUDES: R + R WHEELARCH TRIMS AND LOWER PROTECTION		
86-41-54)	R + R L/XENON HEADLAMP (BUMPER REMOVED)	7.0	32.20
77-51-10	REMOVE/REFIT BONNET PANEL	2.0	9.20
76-16-01)	RENEW BONNET (REMOVED)	5.0	23.00
77-51-05)	R + R L/F WING (BUMPER REMOVED)	13.0	59.80
	INCLUDES: R + R DOOR SILL TRIM AND WHEELARCH TRIM		
77-51-05	RENEW L/F WING (REMOVED)	3.0	13.80
	INCLUDES: R + R REPEATER LAMP AND MUDFLAP		
86-40-17	ADJUST HEADLAMPS	2.0	9.20
LABOUR COST			
	Total Work Units	46.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	4.6HRS	\$211.60
	Paint Labour	11.5HRS	\$529.00
	Total Labour	16.1HRS	\$740.60

PAINT WORK

Guide Number Description

Time Basis 10 WU = 1 HR. Price = \$46.00/HR
WU Cost Price (\$)

Claim Reference:

Assessment Number: KKHC0211

Version: CHINATAI/3

Date Calculated: 07/02/2018 02:05

Registration: EU6999J

Printed: 05/07/2018 17:29

	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	11.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
471	BONNET REPAIR PAINTING >50%	49.0	
742	R/F WING SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	82.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	115.0	
	Total Paintwork Labour	11.5HRS	\$529.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$23.74
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$11.45
	Repair Painting		\$84.14
	Repair Painting Plastic		\$51.03
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$211.66
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$211.66

PARTS

Guide No. Qty		Description	Part Number	Supplier	Bet.	Price (\$)
471	1	BONNET	C2C37987		0%	3,500.00*
561	1	LEFT HEADLAMP ASSY	C2C22630		0%	2,300.00*
741	1	L/F WING	C2C25397		0%	1,400.00*
f: OEM Parts			Sub Total			\$7,200.00
g: Original			Mark Up From Cost	(5 %)		\$360.00
h: Secondhand			Sundry Parts	(Fixed)		\$100.00
p: Parallel			Total Parts			\$7,660.00
x: Exchange						

Price Valid: 01/01/2001

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
SPECIALIST		
Total Extras		\$42.00

Final Calculation

Total Parts		\$7,660.00
Labour		
Total Panel/Mechanical	\$211.60	
Total Paintwork	\$529.00	
Total Labour		\$740.60
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$42.00	
Total of Additional Costs		\$42.00
Total Paint/Material Costs		\$211.66

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: KKHC0211

Version: CHINATAI/3

Date Calculated: 07/02/2018 02:05

Full Report - V1

Registration: EU6999J

Printed: 05/07/2018 17:29

Grand Total Excludes GST	\$8,654.26
GST @ 7 %	\$605.80
Grand Total Includes GST	\$9,260.06

Assessment Notes

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 6 July 2018 5:31 PM
To: 'survey@kkimhin.com.sg'
Cc: SUR
Subject: RE: EU 6999J -DOA: 29/1/2018

Dear Meng Huat,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: survey@kkimhin.com.sg [mailto:survey@kkimhin.com.sg]
Sent: Friday, 6 July 2018 3:40 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: EU 6999J -DOA: 29/1/2018

Hi Ms Veron,

Confirm you figure P/P=\$8,654.26

Thank you.

Regard

Meng Huat

K.Kim Hin Auto Pte Ltd

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: 06 July 2018 Friday 10:11 AM
To: survey@kkimhin.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: FW: EU 6999J -DOA: 29/1/2018

Dear Meng Huat/Simon,

Kindly confirmed finalize amount \$8,654.26 before excess \$500

No of days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 5 July 2018 5:50 PM

To: 'service@kkinhin.com.sg' <service@kkinhin.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: EU 6999J -DOA: 29/1/2018

Dear Meng Huat/Simon,

Kindly confirmed finalize amount \$8,654.26 before excess \$500

No of days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

PARTS EXPRESS LLP

28 Sin Ming Lane #02-139 Midview City, Singapore 573972
Tel: 9848 5712 Email: sunny@partsexpress.com.sg
Co. Reg: T16LL1563D GST Reg no: M90371132E

Tax Invoice

K KIM HIN AUTO PTE LTD

160 SIN MING DRIVE #02-18/19/20/21 SIN MING AUTOCITY
Singapore 575722

Remarks: EU6999J

Inv No. : CI18030056

Date : 06 Mar 2018

A/C No. : KKIMHIN

Ref :

Currency : SGD

Terms : 30 Days

Sales : Sunny

#	No.	Description	Qty	UOM	U/P	Amt
	CDO18030057					
1	C2C26694	LH HEADLAMP	1.00	PC	2,300.00	2,300.00
2	C2C37724	BONNET	1.00	PC	3,500.00	3,500.00
3	C2C9567	FRONT LH FENDER	1.00	PC	1,400.00	1,400.00

Subtotal : S\$ 7,200.00
GST 7.0% : S\$ 504.00
Total : S\$ 7,704.00

Customer acknowledge goods received in good condition

For Parts Express LLP

(Customer's Signature and Company Stamp)

(Authorised Signature)
Sunny

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Feb 2018 Sendback Est	01 Feb 2018 17:01 S\$10,624.47	02 Feb 2018 09:18 Edit Adj Rpt	S\$8,654.26 Edit Estimates	S\$8,654.26 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: CHEN BIAO , ID: S2656139F, Tel: +6590037146, Email: NOEMAIL									
Vehicle Reg. No.: EU6999J		Date of Loss: 29/01/2018 09:00 - :59 [153 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D00584C01		Policy/Cover Note No.: DMPCSN1621931600 (Comprehensive) Coverage: 15/04/2017 - 14/04/2018							
		Excess: S\$500.00							
Repairer: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/02/2018]									
Driver/Custodian: CHEN BIAO (53 / Male), NRIC: S2656139F, Tel: +6590037146									
Adj Asg. Remarks: PLEASE INTERVIEW INSURED & REVERT:- -CHECK FURTHER DETAILS OF TP VEHICLE -CONSISTENCY OF DAMAGES									
				View All Compose Case Mail					
ASSOCIATED MAIL RECEIVED									
• CHINA_TAIPIING (07/02/2018): Alert - Adj Mandate Approved (S\$8654.26) - EU6999J - Claim Handler: Adeline Chng...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

EU6999J (SNM18D00584C01)

OD

Jan 29 2018 9:00AM

[CHEN BIAO]

K Kim Hin Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
			1 per page	<input checked="" type="checkbox"/>
Assessment Reports			Thumbnail	Print
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		
1	31/01/18 17:42	Accident Statement	1 Load HTM	
2	01/02/18 17:01	Repairer Estimates	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/02/18 16:56	Adjuster Immediate Advice	1 Load HTM	
			3 per page	<input checked="" type="checkbox"/>
Photos/Images			Thumbnail	Print
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		
1	31/01/18 17:39	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
2	31/01/18 17:39	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
3	31/01/18 17:39	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
4	31/01/18 17:39	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
5	31/01/18 17:39	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
6	31/01/18 17:39	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
7	31/01/18 17:39	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
8	31/01/18 17:40	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
2	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
3	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
4	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
5	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
6	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
7	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
8	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
9	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
10	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
11	05/02/18 08:58	General View	1 Load JPG	<input checked="" type="checkbox"/>
12	05/07/18 17:35	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
13	05/07/18 17:35	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
14	05/07/18 17:35	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
15	05/07/18 17:35	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
			1 per page	<input checked="" type="checkbox"/>
Documentation			Thumbnail	Print
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		
1	31/01/18 17:39	Sketch Plan [Linked Accident Report Documents]	1 Load TIF	
2	01/02/18 16:57	Certificate of Insurance	1 Load PDF	

Assessment Reports				<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
3	01/02/18 16:57	K Kim Hin Auto Pte Ltd (HQ)		<input checked="" type="checkbox"/>
4	01/02/18 16:57	Log card (if available)		<input checked="" type="checkbox"/>
5	01/02/18 16:57	Insured's NRIC		<input checked="" type="checkbox"/>
5	01/02/18 16:57	TRANSFER FEE		<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	07/02/18 10:20	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		<input checked="" type="checkbox"/>
1	07/02/18 10:20	Revised Estimate		<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	05/02/18 16:58	LKK Auto Consultants Pte Ltd (HQ)		<input checked="" type="checkbox"/>
2	12/07/18 12:10	MARKING		<input checked="" type="checkbox"/>
2	12/07/18 12:10	PARTS INVOICE		<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On		1 per page	<input checked="" type="checkbox"/>
1	31/01/18 17:42	K Kim Hin Auto Pte Ltd (HQ)		<input checked="" type="checkbox"/>
1	31/01/18 17:42	Accident Statement		<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	31/01/18 17:39	K Kim Hin Auto Pte Ltd (HQ)		<input checked="" type="checkbox"/>
1	31/01/18 17:39	Accident Photo		<input checked="" type="checkbox"/>
2	31/01/18 17:39	Accident Photo		<input checked="" type="checkbox"/>
3	31/01/18 17:39	Accident Photo		<input checked="" type="checkbox"/>
4	31/01/18 17:39	Accident Photo		<input checked="" type="checkbox"/>
5	31/01/18 17:39	Accident Photo		<input checked="" type="checkbox"/>
6	31/01/18 17:39	Accident Photo		<input checked="" type="checkbox"/>
7	31/01/18 17:39	Accident Photo		<input checked="" type="checkbox"/>
8	31/01/18 17:40	Accident Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	31/01/18 17:39	K Kim Hin Auto Pte Ltd (HQ)		<input checked="" type="checkbox"/>
1	31/01/18 17:39	Sketch Plan		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18002093/KVD3S2
Date: 12/07/2018

REFERENCE

Insured/Claimant: CHEN BIAO Policy No: DMPCSN1621931600 Claim No: SNM18D00584C01
Date of Loss: 29/01/2018 Nature of Claim: OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EU6999J** Engine No: 0410141004SC
Make & Model: JAGUAR XJ8, 4.2 (A) Chassis No: SAJAC80F25SG44999
Reg. Date: 15/04/2005 (Man. Year: 2005) Odometer: 109473 km
Colour: Metallic Silver
Engine Capacity: 4196 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,586.75	7,702.00	1,884.75	19.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,037.72	952.26	85.46	8.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,624.47	8,654.26	1,970.21	18.54
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	10,624.47	8,154.26	2,470.21	23.25
+ GST 7.00/7.00% (S\$)	743.71	570.80	172.91	23.25
Nett Amount (S\$)	11,368.18	8,725.06	2,643.12	23.25

INSPECTION

Date of Assignment: 02/02/2018 Present Location: K Kim Hin Auto Pte Ltd (HQ)
Date Inspected: 02/02/2018 Inspected At: K Kim Hin Auto Pte Ltd (HQ)
Estimated Period of Repair: 4.0 days 160 Sin Ming Drive #02-20, Sin Ming AutoCity
Singapore 575722

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jul 2018)

Parts: 143 JAGUAR XJ8 4.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for EU6999J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET (ALUMINIUM) (WCP)	Bent	3,500.00 F	*3,500.00 F
2	4	NA	*FRT BUMP JET BRKT (WCP)	Serviceable	400.00 F	*- F
3	4	NA	*FRT BUMP NOZZLE (WCP)	Serviceable	400.00 F	*- F
4	1	NA	*JAGUAR FIGURE (WCP)	Serviceable	450.00 F	*- F
5	1	NA	*L/F BUMPER MOULDING (WCP)	Serviceable	230.00 F	*- F
6	1	NA	*L/F WING (ALUMINIUM) (WCP)	Buckled	1,400.00 F	*1,400.00 F
7	1	NA	*LEFT HEADLAMP ASSY (WCP)	Cracked	2,300.00 F	*2,300.00 F
8	1	NA	*R/F BUMPER MOULDING (WCP)	Serviceable	230.00 F	*- F
9	1	NA	*RAD GRILLE BADGE (WCP)	Serviceable	85.00 F	*- F
10	1	NA	*SPECIALIST AUDATEX FEE		42.00 FS	*42.00 FS
11	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS
					Sub Total (\$\$)	9,137.00 7,342.00
					+ Margin on L,N Items 5.00/5.00% (\$\$)	449.75 360.00
					Total Parts (\$\$)	9,586.75 7,702.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	501.40	529.00
2	Total Paint Materials	New	218.92	211.66
3	Total Panel/Mechanical Labour	New	317.40	211.60
Gross Labour Cost (S\$)			1,037.72	952.26

Report was unsubmitted during this print-out.

< END OF ESTIMATES >