

**K.KIM HIN AUTO PTE LTD**  
**160 Sin Ming Drive**  
**#02-20 Sin Ming AutoCity**  
**Singapore 575722**

**Claim Reference:**  
**Assessment Number: KKHC0211**  
**Version: K.KIMHIN/1**  
**Date Calculated: 01/02/2018 08:02**

**Full Report - V1**  
**Registration: EU6999J**  
**Printed: 01/02/2018 16:04**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SANDRA KHONG	Date of Incident:	29/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN1621931600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	JAGUAR
Model:	XJ
Sub Model:	XJ8 EXEC LAST EDIT
Model Sheet Number:	F06 49
Registration:	EU6999J
Registration Month:	
Registration Year:	
VIN Number:	SAJAC80F25SG44999
Odometer:	Not Known
Colour:	
Engine Number:	0410141004SC
Fuel Level:	%

**Model Specs**

BI-XENON HEADLAMPS	HEADLAMP WASHER UNIT
TWO COAT METALLIC	PREPARE OFF VEHICLE



*Not Authorised*  
*1.2.1*  
*Re-survey B4 paint*  
*Ex @ 500*  
*4 days*  
*for 62564313*

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	31/01/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**K.KIM HIN AUTO PTE LTD****Claim Reference:****Assessment Number: KKHC0211****Version: K.KIMHIN/1****Date Calculated: 01/02/2018 08:02****Full Report - V1****Registration: EU6999J****Printed: 01/02/2018 16:04****Addresses****Cost Summary**

Total Labour	\$818.80
Total Paint/Material	\$218.92
Total Parts	\$9,544.75
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$10,624.47
7 % GST:	\$743.71
Grand Total Inc GST:	\$11,368.18

**Repair Information****LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR****Price/Dent = \$46.00/HR****Repair /****Guide Number Repair Details**

	WU	Cost Price (\$)
10-10-10 PREPARATION TIME	1.0	4.60
NO NUMBER BODYSHELL PANEL WORK PREPARATION TIME	3.0	13.80
74-20-05) R + R LEFT FRONT WHEEL	1.0	4.60
76-22-83 R + R FRONT BUMPER COVER	9.0	41.40
INCLUDES: R + R WHEELARCH TRIMS AND LOWER PROTECTION		
76-22-73) R + R L/F BUMPER MOULDING	4.0	18.40
76-22-73) R + R R/F BUMPER MOULDING	4.0	18.40
86-41-54) R + R L/XENON HEADLAMP (BUMPER REMOVED)	7.0	32.20
86-41-53) R + R R/XENON HEADLAMP (BUMPER REMOVED)	7.0	32.20 X
77-51-10 REMOVE/REFIT BONNET PANEL	2.0	9.20
76-16-01) RENEW BONNET (REMOVED)	5.0	23.00
77-51-05) R + R L/F WING	13.0	59.80
(BUMPER REMOVED)		
INCLUDES: R + R DOOR SILL TRIM AND WHEELARCH TRIM		
77-51-05 RENEW L/F WING (REMOVED)	3.0	13.80
INCLUDES: R + R REPEATER LAMP AND MUDFLAP		
86-40-17 ADJUST HEADLAMPS	2.0	9.20
NO NUMBER APPLY CAVITY PROTECTION L/F WING	4.0	18.40
NO NUMBER APPLY CAVITY PROTECTION BONNET	4.0	18.40

**LABOUR COST****Total Work Units****69.0****Corrosion Protection****Corrosion Protection External Labour****0.0HRS****0.00****Corrosion Protection Internal Labour****0.8HRS****36.80****Sub Total****6.9HRS****\$317.40**

# K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHC0211

Version: K.KIMHIN/1

Date Calculated: 01/02/2018 08:02

Full Report - V1

Registration: EU6999J

Printed: 01/02/2018 16:04

Paint Labour	10.9HRS	\$501.40
Total Labour	17.8HRS	\$818.80

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	11.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
471	BONNET REPAIR PAINTING >50%	49.0	
742	R/F WING SURFACE PAINT	6.0	
<b>LABOUR COST - PAINT</b>			
	<b>TIME(PAINT)</b>	<b>79.0</b>	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	109.0	
	Total Paintwork Labour	10.9HRS	\$501.40
<b>MATERIAL COST - PAINT</b>			<b>Cost Price</b>
	New Part Painting		\$23.74
	New Part Painting - Plastic K1R		\$61.99
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$11.45
	Repair Painting		\$84.14
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$218.92
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$218.92

## PARTS

Guide No. Qty		Description	Part Number	Supplier	Price Valid: 01/01/2001	Bet.	Price (\$)	
293	1	L/F BUMPER MOULDING	C2C1593	Sm	0%		230.00*	X
294	1	R/F BUMPER MOULDING	C2C1592	Sm	0%		230.00*	X
431	1	RAD GRILLE BADGE	C2C25678		0%	Sm	85.00*	X
432	1	JAGUAR FIGURE	C2C39767		0%	Sm	450.00*	X
471	1	BONNET	C2C37987	(Aluminium)	0%	Am	3,500.00*	✓
561	1	LEFT HEADLAMP ASSY	C2C22630		0%	CM	2,300.00*	✓
741	1	L/F WING	C2C25397	(Aluminium)	0%	Bu	1,400.00*	✓
1000	1	FRT BUMP NOZZLE	4PCS @100		0%	Sm	400.00*	X
1000	1	FRT BUMP JET BRKT	4PCS @ 100		0%	Sm	400.00*	X
f: OEM Parts			Sub Total				\$8,995.00	
g: Original			Mark Up From Cost	(5 %)			\$449.75	
h: Secondhand			Sundry Parts	(Fixed).			\$100.00	
p: Parallel			<b>Total Parts</b>				<b>\$9,544.75</b>	
x: Exchange								

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
SPECIALIST		
<b>Total Extras</b>		<b>\$42.00</b>

## Final Calculation

**K.KIM HIN AUTO PTE LTD****Claim Reference:****Assessment Number: KKHC0211****Version: K.KIMHIN/1****Date Calculated: 01/02/2018 08:02****Full Report - V1****Registration: EU6999J****Printed: 01/02/2018 16:04**

<b>Total Parts</b>		<b>\$9,544.75</b>
<b>Labour</b>		
Total Panel/Mechanical	\$280.60	
Total Paintwork	\$501.40	
Corr Prot Internal   8 WU	\$36.80	
<b>Total Labour</b>		<b>\$818.80</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Cost of Specialist	\$42.00	
<b>Total of Additional Costs</b>		<b>\$42.00</b>
<b>Total Paint/Material Costs</b>		<b>\$218.92</b>
<b>Grand Total Excludes GST</b>		<b>\$10,624.47</b>
GST @ 7 %		<b>\$743.71</b>
<b>Grand Total Includes GST</b>		<b>\$11,368.18</b>

**Assessment Notes**