

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/JHI/096/2018
DATE : 01-FEB-2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD, #18-01 SUNTEC TOWER 4

S(038986)
TEL : 68208888
FAX :

OWNER'S NAME : LIM CHWEE HWA
ADDRESS : BLK 54 CANBERRA DRIVE
#01-28
S(768440)
TELEPHONE NO : 9657 3320

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : PNPV2017-00007809
VEHICLE NO : SFE2231P
MODEL CODE : SJGDKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20B857723
CHASSIS NO : JF1SJGK85GG079871
MILEAGE : 1 KM
DATE IN : 01/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 01/02/2018

Print Date : 01/02/2018
Print Time : 17:31:31

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFE2231P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	1W0001W	TO CONDUCT 4-WHEEL ALIGNMENT	250.00	
2	NANOSIEL	TO CONDUCT WHOLE CAR POLISHING AND NANOSIEL PAINTWORK PROTECTION	600.00	
3	SOUND	TO CONDUCT SOUND PROOFING/DEADENING FOR UNDER-CARRIAGE WITH SOUND DEADENING COATING	550.00	
4	UNDERPANEL	TO CONDUCT PANEL PROTECTION FOR UNDERCARRIAGE	550.00	
5	ZZ/001	REPLACE FRONT LHS/RHS HEADLAMP, LHS/RHS FENDER, BUMPER, BONNET, ENERGY ABSORBER, BUMPER BEAM, GRILLE	5600.00	
6	ZZ/003	RESPRAY FRONT BUMPER, BUMPER BEAM, BONNET, LHS/RHS FENDER, REAR RHS DOOR.	2880.00	
7	ZZ/004	REMOVE & REFIX WIRE HARNESS	300.00	
8	ZZ/005	TRANSFER DOOR (REAR RHS) MECHANISM	220.00	
9	ZZ/007	TRANSFER/BALANCE TYRE/RIM (FRONT LHS/RHS)	100.00	
10	ZZ/008	TO SUPPLY AND REPLACE TYRE 225/55R/18 (FRONT BOTH SIDE)	530.00	
11	ZZ/009	REMOVE & REFIX A/CON CONDENSER & RADIATOR TO FACILITATE REPAIR	250.00	
12	ZZ/011	TO SUPPLY AND INSTALL (REAR RHS) SOLAR FILM	60.00	
13	ZZ/012	DISMENTLE & REFIX UNDERCARRIAGE (FRONT RHS/LHS) TO FACILITATE REPAIR /PER SIDE \$300	600.00	
14	ZZ/013	DISMENTLE & REFIX UNDERCARRIAGE (REAR RHS) TO FACILITATE REPAIR	300.00	
15	ZZ/014	TO CONDUCT CAR 'O' TRONIC CHASSIS ALIGNMENT & MEASUREMENT	1050.00	
16	ZZ/015	SUNDRIES	150.00	
17	ZZ/10	COOLING SYSTEM PRESSURE TEST	150.00	
TOTAL LABOUR CHARGES			14140.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFE2231P

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	CROSS MBR COMPL F	20101VA010	472.00			
2	ARM ASSY F RH	20202SG000	493.20			
3	ARM ASSY F LH	20202SG010	493.20			
4	ARM ASSY R UPR RH	20252SG001	432.00			
5	ARM ASSY R UPR LH	20252SG011	432.00			
6	STRUT COMPL F RH	20310SG140	306.00			
7	STRUT COMPL F LH	20310SG150	306.00			
8	STRUT MT F	20320FG012	144.00			
9	HELPER F	20321AG011	50.40			
10	DUST COVER F (M)	20322AA000	32.00			
11	DUST COVER-INNER	20322SC000	28.80			
12	SPRING SEAT UPR F	20323FA000	40.00			
13	RUBBER SEAT F UPR	20325FA000	32.00			
14	COIL SPRING F	20330SG140	180.00			
15	SHOCK ABS COMPL R	20365SG100	468.00			
16	MOUNT SHOCK R	20370SG000	208.80			
17	HELPER R	20371FG000	57.60			
18	DUST CVR R	20372SC000	57.60			
19	RUBBER SEAT R	20375FG000	43.20			
20	COIL SPRING R	20380SG120	180.00			
21	STABILIZER FRONT D24	20401SG000	169.20			
22	RUB BUSH STAB F	20414SG000	28.80			
23	STABILIZER LK	20420XA000	165.60			
24	DISC WHEEL AL 18 C75	28111SG140	2250.00			
25	HOUSING F RH	28313SC001	237.60			

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFE2231P

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	HOUSING F LH	28313SC011	237.60			
27	DRIVE SHAFT ASSEMBLY-FRONT (F92)	28321SG010	720.00			
28	HUB UNIT COMPL F	28373FL000	331.20			
29	HOUSING ASSY R RH	28411SG021	270.00			
30	HUB BEARING REAR	28473FL040	216.00			
31	HUB BEARING FRONT	28473FL040	432.00			
32	GR BOX ASSY P/S EPS	34110SG060	2520.00			
33	RADIATOR ASSY	45111SG010	810.00			
34	SHROUD	45122SG000	86.40			
35	MOTOR	45131FG003	272.00			
36	PACKING RAD SD	45167SG000	8.64			
37	DUCT COMPL	46011SG000	72.00			
38	DUCT AIR INTAKE	46012YC000	50.40			
39	BOOT AIR INTAKE	46013AJ000	64.80			
40	BOOT AIR INTAKE B	46013AJ010	75.60			
41	CASE-AIR CLNR UPR	46052SG010	32.40			
42	CASE-AIR CLNR LWR	46052SG020	32.40			
43	FRT FENDER RH	57120SG0209P	270.00			
44	FRT FENDER LH (W/O SIGNAL LP)	57120SG0309P	270.00			
45	HOOD F CPL	57229SG0009P	882.00			
46	HINGE COMPL F HD RH	57260SG0009P	43.20			
47	HINGE COMPL F HD LH	57260SG0109P	43.20			
48	LOCK ASSY F HOOD RHD	57310SG000	54.00			
49	BRKT SD F RH	57707SG020	12.60			

MOTORIMAGE ENTERPRISES PTE. LTD.
 25 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFE2231P

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
50	BRKT SD F LH	57707SG030	12.60			
51	BUMPER FACE F (FOR HL/W)	57709SG011	594.00			
52	BACK BEAM CPL F	57711SG0009P	288.00			
53	ENERGY ABSOR F	57722SG020	126.00			
54	MUD GUARD ASSY F RH	59110SG021	86.40			
55	MUD GUARD ASSY F LH	59110SG031	86.40			
56	MUD GUARD R RH	59122SG060	57.60			
57	PNL COMPL DR RRH	60409SG0019P	684.00			
58	GLASS ASSY DR R RH	62011SG100	475.20			
59	WEATHER STRIP-DOOR, REAR OUTER RIGHT	62280SG020	100.80			
60	WEATHER STRIP-REAR DOOR,RIGHT	63512SG001	144.00			
61	CONDENSER ASSY	73210SG011	579.31			
62	SHROUD	73313SG000	64.80			
63	LAMP ASSY HEAD EOF	84002SG220	2380.00			
64	LAMP ASSY HEAD EOF	84002SG230	2380.00			
65	FOG LAMP ASSY F	84501AJ060	544.00			
66	HORN ASSY (L)	86012SG000	57.80			
67	HORN ASSY (H)	86029FG000	57.80			
68	NOZZLE COVER ASSYRH	86636SG340Q1	54.00			
69	NOZZLE H L WASHERRH	86636SG361	79.20			
70	TAPE-REAR DOOR SASH, RIGHT	90422SG060	18.00			
71	TAPE-REAR DOOR SASH, CENTER RIGHT	90422SG080	10.80			
72	TAPE-REAR DOOR SASH, REAR RIGHT	90422SG100	14.40			
73	INSULATOR HOOD TBRH	90815SG061	36.00			
74	INSULATOR HOOD TBLH	90815SG071	36.00			

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFE2231P

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS

75 GRILLE ASSY F UPRHG	91121SG210	140.40
76 GRILLE ASSY F CTRHG	91121SG240	180.00
77 GRILLE ASSY F LWRHG	91121SG280	316.80
78 BKT GRILLE LWR	91165SG010	21.60

SUB TOTAL	24740.35	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)	4948.07	0.00	0.00	0.00
GRAND TOTAL	19792.28	0.00	0.00	0.00
OVERALL TOTAL	19792.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFE2231P

TOTAL LABOUR CHARGES	14140.00
TOTAL SPARE PARTS CHARGES	19792.28

GRAND TOTAL	33932.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.