

ASS. REC. BY:

REF:

CS / ICS 18000097 / 44ber

Special Instruction:

Survivor

Melimen

ASSIGNMENT (Office)

From (Person): Jania Goh of ICS Date/Time: 02022018 11:12am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBJ 8711C Insured: SJE 2495Y

at Workshop m/s Ban Hock Hin Tel: 6781 6520 X 220

of No. 6 Defu Lane 4

Policy No: Claim No: DMPL 1800041H

Sum Insured: Excess:

Make of Veh: D.O.A. 29012018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBJ 8711C - X
	SJE 2495Y - X

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ECIS 7

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **FBJ8711C**at Workshop m/s **RHH**

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

G/A / PR Seen: **2** Consistent?: Yes or NoEst. Repairs: **4** days Res.: Yes or NoLum Sum: **131** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **FBJ8711C** Yr Regn: **12/14**Type: M.Car / **M.Cycle** / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Yamaha** F216 c.c. **153**Colour: **Black** A/C: Insured / Std / NI / NASp. Reading: **31148** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **ME145503702012632**Gen. Cond: **Good** / Fair / Poor / BurntSteering: **In order** / Jammed / Leaked / Burnt orBrake: **In order** / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **100/80-17**R: **140/80-17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **metre/e**

Front

R/Bal. **6** mm

Rear

R/Bal. **6** mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. **29/1/18**D.O.I. **2/2/18**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Left, N/S body
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

+ 742863

23/4/18 **Constant Level Rg & 787.25 with Regard**
(Red. 12/140, 60%)

RECEIVED 30 JUL 2018

Date/Time, File Pass to?



Preli. Report

1) 27/7 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: **4**Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) S + RS. SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format: **TP**Lump Sum / I.B.I. (\$ **787.50**)

TOTAL

260

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Thursday, 26 July, 2018 3:14 PM
To: 'assignments'
Subject: FW: Accident Involving FBJ8711C & SJE2495Y on 29/01/2018
Attachments: 11094_LOD.pdf

Hi all

We have received TP LOD.
Please forward the survey report to us.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Raymond [mailto:raymond@bhh.com.sg]
Sent: Thursday, 3 May, 2018 9:39 AM
To: ECICS Claims
Subject: RE: Accident Involving FBJ8711C & SJE2495Y on 29/01/2018

Dear Sir / Madam,

We attached the Letter of Demand for your perusal.

Pre-repair inspection was conducted by LKK Auto Consultants Pte Ltd.

Appreciate for you to revert with the DV to us by email or fax at 62842969.

Thanks

Best Regards,
Raymond
Ban Hock Hin Co., Pte Ltd
Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969
Visit us at <http://www.bhh.com.sg>
Facebook: <http://www.facebook.com/bhhsg>

Denise Tay (LKKAUTO)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 30 July 2018 9:39 AM
To: Denise Tay (LKKAUTO); Admin-D (LKKAUTO); ECICS Claims; SUR
Cc: assignments
Subject: RE: Accident Involving FBJ8711C & SJE2495Y on 29/01/2018

Hi Denise

Our claim no. DMPC1800041H.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Friday, 27 July, 2018 5:43 PM
To: Admin-D (LKKAUTO); ECICS Claims; SUR
Cc: assignments
Subject: RE: Accident Involving FBJ8711C & SJE2495Y on 29/01/2018

Dear Janice,

Kindly provide claim number

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 26 July 2018 3:17 PM
To: 'ECICS Claims' <claims@ecics.com.sg>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: FW: Accident Involving FBJ8711C & SJE2495Y on 29/01/2018



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |



From: Raymond <raymond@bhh.com.sg>
Sent: Wednesday, 25 April, 2018 9:15 AM
To: 'ECICS Claims' <claims@ecics.com.sg>
Subject: FW: Accident Involving FBJ8711C & SJE2495Y on 29/01/2018

Dear Sir / Madam,

We refer to our email dated 02/02/2018.

Please advise the status of the above mentioned third party claim as soon as possible.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |



From: Raymond <raymond@bhh.com.sg>
Sent: Friday, 2 February, 2018 11:12 AM
To: 'ECICS Claims' <claims@ecics.com.sg>
Subject: Accident Involving FBJ8711C & SJE2495Y on 29/01/2018

Dear Sir / Madam,

We attached the third party claim documents for your perusal.

Appreciate for you to arrange for pre-repair survey.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |



<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	FBJ8711C
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	YAMAHA
Vehicle Model :	FZ16ST MANUAL
Chassis No. :	ME145S0B7D2012632
Propellant :	Petrol
Engine No. :	45SB012772
Engine Capacity :	153 cc
Maximum Power Output :	-
Maximum Laden Weight :	330 kg
Unladen Weight :	141 kg
Year Of Manufacture :	2013
Original Registration Date :	04 Dec 2014
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
Quota Premium :	\$4,189.00
COE Expiry Date :	03 Dec 2024

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/01/2018 17:01
Date Of Accident	29/01/2018 21:40
Exact Location Of Accident	JURONG WEST ST 91 JUNCTION OF JURONG WEST ST 92
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ8711C
Insured/Policyholder	
Name Of Registered Owner	BAN HOCK HIN COMPANY PRIVATE LIMITED
Co Reg No	197000288K
Email Address	SATHEES@AJA.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-90663235
Vehicle Particulars	
Manufacturer	YAMAHA
Model	FZ16ST
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	AVFMSB0000611700
Cover Note Number	N.A.

Driver

Name of Driver	ARIVAZHAGAN SATHEES
NRIC No	G3066326N
Date Of Birth	29/06/1990
Occupation	OUTDOOR
Date Of Driving Pass	28/01/2015
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90663235
Fax Number	
Contact Number	
Email Address	SATHEES@AJA.COM.SG

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
 - (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


AIZAM BIN ATAN

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan





Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0288K
Vehicle Details	
Vehicle No.:	FBJ8711C
Vehicle to be Exported:	No
Intended De-registration Date:	02 Feb 2018
Vehicle Make:	YAMAHA
Vehicle Model:	FZ16ST MANUAL
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	45SB012772
Chassis No.:	ME145S0B7D2012632
Maximum Power Output:	-
Open Market Value:	\$2,463.00
Original Registration Date:	04 Dec 2014
First Registration Date:	04 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$370.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Dec 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,189.00
COE Rebate Amount:	\$2,863.00
Total Rebate Amount:	\$2,863.00

The information contained herein is correct as at 02 Feb 2018

OK



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000283K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32338

ECICS LIMITED

T TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
Singapore 038987

MOTOR CLAIMS DEPT

DATE : 01/02/2018

CLAIM NO. : 11094

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBJ8711C

MAKE/MODEL : YAM / FZ16ST

Not Aided
2/8/18
4 dy.
2/2/18
Weight After rep - 91/787.05

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 44885	REPLACE	1.00	\$24.00	24.00
2	COVER SIDE LH	REPLACE	1.00	\$45.00	45.00
3	COVER TANK SIDE LH	REPLACE	1.00	\$98.00	98.00
4	COWLING FRONT (BLACK)	REPLACE	1.00	\$75.00	75.00
5	CROWN HANDLE	REPLACE	1.00	\$86.00	86.00
6	FRONT FORK ASSY P/N: 55940	REPLACE	1.00	\$966.00	966.00
7	HEADLAMP ASSY P/N: 50280	REPLACE	1.00	\$245.00	245.00
8	HEADLAMP ASSY 1 POSITION ASSY P/N: 50285	REPLACE	1.00	\$30.00	30.00
9	LABOUR P/N: 06766 - LABOUR FOR DISMANTLING AND ASSEMBLING OF PARTS		6.00	\$35.00	210.00
10	PANEL CONSOLE 1	REPLACE	1.00	\$10.00	10.00
11	RIVET P/N: 40604	REPLACE	1.00	\$1.50	1.50
12	STAY 1	REPLACE	1.00	\$102.00	102.00
13	STAY SUPPORT 1	REPLACE	1.00	\$30.00	30.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT. NO. 2022-0363
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	STAY SUPPORT 2	REPLACE	1.00	\$15.00	15.00
15	STEERING CONE SET P/N: 33765	REPLACE	1.00	\$54.00	54.00
16	WASHER PLATE P/N: 50658	REPLACE	1.00	\$7.00	7.00

SUB TOTAL

\$1,998.50

GST @ 7 %

\$139.90

GRAND TOTAL

\$2,138.40

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-674.5
107
607.05
787.05





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000268K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32338

- Rev. 1

ECICS LIMITED
T TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
Singapore 038987
MOTOR CLAIMS DEPT

DATE : 01/02/2018
CLAIM NO. : 11094
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBJ8711C
MAKE/MODEL : YAM / FZ16ST

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 44885	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
2	COVER TANK SIDE LH	REPLACE	1.00	\$98.00 Disc %: 10.00	88.20
3	COWLING FRONT (BLACK)	REPLACE	1.00	\$75.00 Disc %: 10.00	67.50
4	HEADLAMP ASSY P/N: 50280	REPLACE	1.00	\$245.00 Disc %: 10.00	220.50
5	HEADLAMP ASSY 1 POSITION ASSY P/N: 50285	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00
6	LABOUR P/N: 06766 - LABOUR FOR DISMANTLING AND ASSEMBLING OF PARTS		6.00	\$30.00	180.00
7	RIVET P/N: 40604	REPLACE	1.00	\$1.50 Disc %: 10.00	1.35
8	STAY 1	REPLACE	1.00	\$102.00 Disc %: 10.00	91.80
9	STAY SUPPORT 1	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00
10	STAY SUPPORT 2	REPLACE	1.00	\$15.00 Disc %: 10.00	13.50
11	STEERING CONE SET P/N: 33765	REPLACE	1.00	\$54.00 Disc %: 10.00	48.60

SUB TOTAL

\$787.05

GST @ 7 %

\$55.09

GRAND TOTAL

\$842.14



CERT NO: 2002-1-0303
ISO 9001:2008

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

CERT NO.: 2002-1-0383
ISO 9001: 2008



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

ECICS LIMITED
T TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
Singapore 038987

MOTOR CLAIMS DEPT

VEHICLE NO. : FBJ8711C
MAKE/MODEL : YAM / FZ16ST

NO. : 32338

DATE : 01/02/2018

CLAIM NO. : 11094

POLICY NO. :

FROM : RAYMOND

not added
2/5/18
4 days
2/2/18
to light after rep-

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 44885	REPLACE	1.00	\$24.00	24.00 ?
2	COVER SIDE LH	REPLACE	1.00	\$45.00	45.00 ?
3	COVER TANK SIDE LH	REPLACE	1.00	\$98.00	98.00 ?
4	COWLING FRONT (BLACK)	REPLACE	1.00	\$75.00	75.00 ?
5	CROWN HANDLE	REPLACE	1.00	\$86.00	86.00 ?
6	FRONT FORK ASSY P/N: 55940	REPLACE	1.00	\$966.00	966.00 ?
7	HEADLAMP ASSY P/N: 50280	REPLACE	1.00	\$245.00	245.00 ?
8	HEADLAMP ASSY 1 POSITION ASSY P/N: 50285	REPLACE	1.00	\$30.00	30.00 ?
9	LABOUR P/N: 06766 - LABOUR FOR DISMANTLING AND ASSEMBLING OF PARTS		6.00	\$35.00	210.00
10	PANEL CONSOLE 1	REPLACE	1.00	\$10.00	10.00 ?
11	RIVET P/N: 40604	REPLACE	1.00	\$1.50	1.50
12	STAY 1	REPLACE	1.00	\$102.00	102.00 ?
13	STAY SUPPORT 1	REPLACE	1.00	\$30.00	30.00 ?



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
14	STAY SUPPORT 2	REPLACE	1.00	\$15.00	15.00 ?
15	STEERING CONE SET P/N: 33765	REPLACE	1.00	\$54.00	54.00 ?
16	WASHER PLATE P/N: 50658	REPLACE	1.00	\$7.00	7.00 ?
SUB TOTAL					\$1,998.50
GST @ 7 %					\$139.90
GRAND TOTAL					\$2,138.40

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:








































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018 15:19 Edit Reg		02 Feb 2018 00:00 Edit Adj Rpt	S\$787.05 Edit Estimates	S\$787.05 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -, Email: SATHEES@AJA.COM.SG									
Main Claimant: BAN HOCK HIN COMPANY PRIVATE LIMITED , Co. Reg. No.: 197000288K									
Vehicle Reg. No.: FBJ8711C		Date of Loss: 29/01/2018 21:00 - :59 [37 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SJE2495Y		Policy No. (Claimant):							
		Excess:							
Repairer: Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 06/08/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBJ8711C
[SJE2495Y]
TP
BAN HOCK HIN COMPANY PRIVATE LIMITED
Jan 29 2018 9:00PM
[-]
Ban Hock Hin Co. Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
2	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
3	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
4	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
5	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
6	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
7	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
8	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
9	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
10	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
11	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
12	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
13	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
14	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
15	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
16	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
17	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
18	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
19	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
20	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
21	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
22	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
23	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
24	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
25	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
26	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
27	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
28	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
29	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
30	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
31	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
32	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
33	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
34	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
35	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
36	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
37	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
41	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
43	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
44	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
45	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
46	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
47	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
48	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
49	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
50	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
51	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
52	30/07/18 10:35	General View	 Load JPG	<input checked="" type="checkbox"/>
53	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	30/07/18 10:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18002097/UTBE2

Date: 30/07/2018

REFERENCE

Handling Insurer: ECICS Limited	Policy No:		
Claimant Vehicle No : FBJ8711C	Insured Vehicle No :	SJE2495Y	
Date of Loss: 29/01/2018	Nature of Claim:	TP	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ8711C	Engine No:	45SB012772
Make & Model:	YAMAHA FZ16, 153cc (M)	Chassis No:	ME145S0B7D2012632
Reg. Date:	04/12/2014 (Man. Year: 2013)	Odometer:	31148 km
Colour:	Black		
Engine Capacity:	153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/80-17	Rear Tyre Size:	140/60-17
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,778.50	607.05	1,171.45	65.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	220.00	180.00	40.00	18.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,998.50	787.05	1,211.45	60.62
+ GST 7.00/7.00% (S\$)	139.90	55.09	84.81	60.62
Nett Amount (S\$)	2,138.40	842.14	1,296.26	60.62

INSPECTION

Date of Assignment:	02/02/2018		
Date Inspected:	02/02/2018	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jul 2018)	
Parts:	N/A	YAMAHA FZ16 153cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBJ8711C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AXLE WHEEL FRONT	Bent	24.00 F	*24.00 FL
2	1		*COVER SIDE LH	Not Necessary	45.00 F	*- FL
3	1		*COVER TANK SIDE LH	Cracked	98.00 F	*98.00 FL
4	1		*COWLING FRONT (BLACK)	Broken	75.00 F	*75.00 FL
5	1		*CROWN HANDLE	Not Necessary	86.00 F	*- FL
6	1		*FRONT FORK ASSY	Repair	966.00 F	*- FL
7	1		*HEADLAMP ASSY	Scratched	245.00 F	*245.00 FL
8	1		*HEADLAMP ASSY 1 POSITION ASSY	Cracked	30.00 F	*30.00 FL
9	1		*RIVET	Necessary	1.50 F	*1.50 FL
10	1		*STAY 1	Bent	102.00 F	*102.00 FL
11	1		*STAY SUPPORT 1	Bent	30.00 F	*30.00 FL
12	1		*STAY SUPPORT 2	Bent	15.00 F	*15.00 FL
13	1		*SET STEERING CONE	Necessary	54.00 F	*54.00 FL
14	1		*WASHER PLATE	Not Necessary	7.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,778.50	674.50
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	67.45
Total Parts (S\$)	1,778.50	607.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR - LABOUR FOR DISMANTLING AND ASSEMBLING OF PARTS	New	210.00	180.00
2	PANEL CONSOLE 1	New	10.00	0.00
Gross Labour Cost (S\$)			220.00	180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >