

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Cheong

Date: 05 Feb 2018

**Preliminary Advice**

Vehicle No	: SJN1325P	Accident Date	: 30/01/2018
Make	: SUZUKI SWIFT	Policy No.	: DMPPHQ17-000615
Assignment Date	: 02/02/2018	Excess	: S\$500.00
Date of Inspection	: 02/02/2018	Est. Duration of Repair	: 0.00
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rooftop, 4 pillars, front and rear windscreen and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	14,000.00
COE / PARF Rebate	:S\$	9,345.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,655.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( x ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :