

22/05/2018

ASS. REC. BY:

REF:

CS/CTI/8002102/Kcd357

Special Instructions:

Surveyor

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time: 02022018 10:26am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC7 3644L

Insured:

at Workshop m/s

Cheng Hoe Motor

Tel:

6755 6142

of

Blk 1019 Yishun Ind Park A # 01-374

Policy No: DMCVSN3060421700

Claim No:

SNM13D 00583C01

Sum Insured:

Excess:

\$ 350.00

Make of Veh:

D.O.A. 30012018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Woodlands

H.O.D. Endorsement:

Date/Time: 02022018 11:05am

Person Contacted:

Wei Ling

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC7 3644L - 703/CTI/8002027/d3 DCA: 30012018
	sent preli thru menmen
7/2/18	Authorise repair and inform repairer to proceed for repair.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18002102/Krb

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-02-2018



Code : CTI

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBG 3644L
Policy No.	DMCVSN3060421700	Coverage (\$)	0.00
Claim No.	SNM18D00583C01	Excess (\$)	350.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	02/02/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	30/01/2018	Inspection Date	02/02/2018
Survey held at	38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05		
Repairer	CHENG HOE MOTOR PL		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Feb 2018 Sendback Est	01 Feb 2018 17:21 S\$14,942.80	02 Feb 2018 10:26 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

Insured:	EFICAZ PEST MANAGEMENT PTE LTD, Co. Reg. No.: 201717718D		
Vehicle Reg. No.:	GBG3644L	Date of Loss:	30/01/2018 15:00 - :59
Claim Type:	OD / SNM18D00583C01	Policy/Cover Note No.:	DMCVSN3060421700 (Comprehensive) Coverage: 27/07/2017 - 26/07/2018
		Excess:	S\$350.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/02/2018]		
Driver/Custodian:	SUNG YUNG RAN ( / Male), NRIC: S8807040B		
Adj Asg. Remarks:	SURVEY REVERT		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

02/02/2018 @ 11:05am  
Wei Ling veh in Woodland

## Celine Fong (LKKAuto)

---

**From:** Celine Fong (LKKAuto)  
**Sent:** Monday, 15 July 2019 8:58 AM  
**To:** June Phua (Cheng Hoe)  
**Cc:** SUR  
**Subject:** OD CLAIM VEHICLE NO. GBG 3644L (DOA: 30.01.2018)

Dear June,

Confirmed final fig \$14,936.05 before excess.

Days of repair: 10 Days

Best Regards,

**Celine Fong**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [celinefong@lkkauto.com](mailto:celinefong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Print Received Message

This mail is associated with :

**GBG3644L (SNM18D00583C01)**

OD

Jan 30 2018 3:00PM

[EFICAZ PEST MANAGEMENT PTE LTD]

Cheng Hoe Motor Pte Ltd

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 30/11/2018 09:49 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$17317.15) - GBG3644L - Claim Handler: Chong Boon Sen

Approved:17317.15:Please proceed to authorize repairs UP TO \$14,432.80 BEFORE Excess of \$350.00. RE-INSPECTION OF VEHICLE REQUIRED.

## Print Received Message

This mail is associated with :

**GBG3644L (SNM18D00583C01)**

OD

Jan 30 2018 3:00PM

[EFICAZ PEST MANAGEMENT PTE LTD]

Cheng Hoe Motor Pte Ltd

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 07/02/2018 10:17 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$14432.80) - GBG3644L - Claim Handler: Chong Boon Sen

Approved:14432.80:Please proceed to authorize repairs UP TO \$14,432.80 BEFORE Excess of \$350.00. RE-INSPECTION OF VEHICLE REQUIRED.

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Wednesday, February 07, 2018 11:55 AM  
**To:** 'chmotor@singnet.com.sg'  
**Cc:** SUR  
**Subject:** GBG 3644L CTI OD DOA : 30.01.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBG 3644L (excess \$350.00/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 21 Nov 2018

## Preliminary Advice

Vehicle No	: GBG3644L	Accident Date	: 30/01/2018
Make	: TOYOTA HIACE	Policy No.	: DMCVSN3060421700
Assignment Date	: 02/02/2018	Excess	: S\$350.00
Date of Inspection	: 02/02/2018	Est. Duration of Repair	: 10.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,827.15	(Include supplementary \$2,884.35)
Revised Amount	:S\$	13,448.20	
Check Items (Estimated)	:S\$	3,868.95	
Total	:S\$	17,317.15	

Lump Sum Repair :S\$

## Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	29,503.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,497.00

## Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 05 Feb 2018

**Preliminary Advice**

Vehicle No	: GBG3644L	Accident Date	: 30/01/2018
Make	: TOYOTA HIACE	Policy No.	: DMCVSN3060421700
Assignment Date	: 02/02/2018	Excess	: S\$350.00
Date of Inspection	: 02/02/2018	Est. Duration of Repair	: 10.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,942.80
Revised Amount	:S\$	10,563.85
Check Items (Estimated)	:S\$	3,868.95
Total	:S\$	14,432.80

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	29,503.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,497.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/01/2018 18:17
Date Of Accident	30/01/2018 15:20
Exact Location Of Accident	PIE TWDS CHANGI
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG3644L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	EFICAZ PEST MANAGEMENT PTE LTD
Co Reg No	201717718D
Email Address	HR@EFICAZPM.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62553303

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3060421700
Cover Note Number	27/07/17 - 26/07/18

### Driver

Name of Driver	SUNG YUNG RAN
NRIC No	S8807040B
Date Of Birth	21/02/1988
Occupation	OUTDOOR
Date Of Driving Pass	13/03/2012
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85496983
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 834 WOODLANDS ST.83 #07-85
Postcode	730834
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : WORKER GENDER: : MALE
Passenger 2	NAME: : WORKER GENDER: : MALE
Passenger 3	NAME: : WORKER GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

At the time I was driving along PIE towards Paya Lebar exit. I had accident with 2 other lorries. Time of traffic is slightly heavy and when I was about to exit the express way, I had the accident. When accident happen, I did not realise the vehicle in front of me and when I saw already crash.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD2043T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RASEL HASAN ABDUL HALIM GAZI
NRIC/Passport Number	G8378497R

**SKETCH PLAN**

VEHICLE NO.: GAG 3644 L  
INSURER : LAHIA TAIPING  
DATE & TIME: 30/01/18 3:20 PM

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



X  
Policyholder's Signature  
Date & Time:

30/01/18  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Wardy 30/01/2018  
Reporting Centre Personnel's Signature  
Name: (WL)  
NRIC/FIN No.:

GBG3644L

00/CHINA

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7718D
Vehicle Details	
Vehicle No.:	GBG3644L
Vehicle to be Exported:	Yes
Intended De-registration Date:	30 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 3.0 A
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2688879
Chassis No.:	KDH2010217025
Maximum Power Output:	-
Open Market Value:	\$32,358.00
Original Registration Date:	27 Jul 2017
First Registration Date:	27 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$1,618.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$29,503.00
<b>Total Rebate Amount:</b>	<b>\$29,503.00</b>

The information contained herein is correct as at 30 Jan 2018

OK

張建福 (機件) 拖車服務  
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 17941

Date: 30/11/08

寶號

Messrs: 清源

車號

Vehicle No: 9BG 3644 L

由

From: 212

時間 (日/夜)

Time (day/night):

其他

Others: 601

車型

Model No: Vn

到

To: windadi 5-00

CASH \$:

CHEQUE:

經手人

Authorised by:


收貨人

Received by:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.



**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD CHINA
Policy No:	DMCVSN3060421700	Date of Loss:	30/01/2018
Vehicle Reg. No.:	GBG3644L	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	EFICAZ PEST MANAGEMENT PTE LTD		
Driver:	SUNG YUNG RAN		
Make/Model:	TOYOTA HIACE, 3.0 (A)	Vehicle Reg. Date:	27/07/2017
Vehicle Colour:	WHITE	Chassis No:	KDH2010217025
Engine No:	1KD2688879		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0 <i>10 days</i>		
Description of Accident/Loss	PLS REFER EFILE REPORT		
Present Location:	CHENG HOE MOTOR PTE LTD (WOODLANDS WORKSHOP)		

*Handwritten notes:*  
 Not At fault  
 Resurvey by point  
 Ex 83501  
 Fax: 82564315

COST OF CLAIMS	Amount
Parts	11,377.80
Miscellaneous Items	185.00
Labour	3,380.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>14,942.80</b>
<b>+ GST 7.00% (\$\$)</b>	<b>1,046.00</b>
<b>Nett Amount (\$\$)</b>	<b>15,988.80</b>

This claim is handled by: **JUNE PHUA LIAN HUA**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Handwritten:* 17827.15



## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 01 Feb 2018)

Parts: N/A TOYOTA HIACE 3.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/GBG3644L/01/02/2018 17:21

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

GBG 3644L

OD/CH/MA

DCA: 30/1/18

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 pc frt bumper	0.00	0.00	Am *180.00 F	✓
2	1		*1 pc frt bumper reinforcement	0.00	0.00	Am *105.00 F	✓
3	1		*6 pcs frt bumper clip @1.50/pce	0.00	0.00	Am *9.00 F	✓
4	1		*1 pc frt grille	0.00	0.00	CM *450.00 F	✓
5	1		*1 pc frt lip	0.00	0.00	Am *245.00 F	✓
6	1		*1 pc frt lip logo	0.00	0.00	Am *30.00 F	✓
7	1		*1 pc frt lip inner lock	0.00	0.00	Am *35.00 F	✓
8	1		*2 pcs headlamp @850/pce	0.00	0.00	*1,700.00 F	✓
9	1		*1 pc frt windscreen glass	0.00	0.00	CM *420.00 F	✓
10	1		*1 set frt windscreen glass moulding	0.00	0.00	Am *90.00 F	✓
11	1		*1 pc frt wiper garnish	0.00	0.00	*205.00 F	✓
12	1		*1 pc frt inner panel	0.00	0.00	Am *480.00 F	✓
13	1		*1 pc aircon condenser	0.00	0.00	Am *450.00 F	✓
14	1		*1 pc aircon condenser gas hose (receiver)	0.00	0.00	Am *185.00 F	✓
15	1		*1 pc aircon gas discharge hose	0.00	0.00	Am *135.00 F	✓
16	1		*1 pc engine inter cooler	0.00	0.00	Am *490.00 F	✓
17	1		*1 pc engine inter cooler top garnish	0.00	0.00	Am *55.00 F	✓
18	1		*1 pc frt top panel	0.00	0.00	Am *115.00 F	✓
19	1		*1 pc frt top panel top garnish	0.00	0.00	CM *85.00 F	✓
20	1		*4 pcs frt top panel top garnish clip @2/pce	0.00	NN	Am *8.00 F	✓
21	1		*2 pcs headlamp panel @175/pce	0.00	0.00	*350.00 F	✓
22	1		*1 pc frt wiper tank	0.00	0.00	Am *155.00 F	✓
23	1		*1 pc radiator	0.00	0.00	Am *600.00 F	✓
24	1		*1 pc radiator fan cowling	0.00	0.00	CM *120.00 F	✓
25	1		*1 pc radiator fan blade	0.00	0.00	Am *68.00 F	✓
26	1		*1 pc radiator fan motor	0.00	0.00	Am *380.00 F	✓
27	1		*1 pc radiator spare tank	0.00	0.00	*150.00 F	✓
28	1		*1 pc aircon evaporator	0.00	0.00	*1,500.00 F	✓
29	1		*1 pc aircon blower	0.00	0.00	*485.00 F	✓
30	1		*1 pc horn	0.00	0.00	Am *48.00 F	✓
31	1		*1 pc dash board	0.00	0.00	CM *415.00 F	✓
32	1		*1 pc dash board housing (reinforcement)	0.00	0.00	Am *280.00 F	✓
33	1		*1 pc dash board glove top	0.00	0.00	Am *145.00 F	✓
34	1		*1 pc dash board glove lower	0.00	0.00	Am *120.00 F	✓
35	1		*1 pc dash board lower garnish lh	0.00	0.00	Am *195.00 F	✓
36	1		*1 pc dash board centre garnish	0.00	0.00	Am *305.00 F	✓
37	1		*1 pc dash board corner garnish rh	0.00	0.00	Am *48.00 F	✓

F=Franchise part.

Sub Total (\$\$)

10,836.00

+ Margin on L,N Items 5.00% (\$\$)

541.80

Total Parts (\$\$)

11,377.80

Cheng Hoe Motor Pte Ltd/GBG3644L/01/02/2018 17:21. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	1 pc ERP bracket	25.00 ✓
2	1	1 pc frt no. plate	30.00 X
3	1	1 pc frt windscreen gum	40.00 ✓
4	1	3 litres coolant @30/lit	90.00 ✓
Sub Total (S\$)			185.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	1) To remove and refix frt windscreen glass	New	100.00 ✓
2	2) To remove and refix aircon, vacuum and refill gas	New	100.00 ✓
3	3) To remove and refix dash baord assy and check wiring	New	250.00 ✓
4	4) To perform panel beating works on accident areas	New	1,600.00
5	5) To putty and respray on accident affected areas	New	1,000.00
6	6) To remove and refix seqt, carpat, garnish in order to facilitate on repairs	New	120.00 100%
7	7) To remove and refix radiator, fan cowling motor, check engine and engine mountings and system	New	150.00 100%
8	8) To towing	New	60.00 X
Gross Labour Cost (S\$)			3,380.00


Cheng Hoe Motor Pte Ltd/GBG3644L/01/02/2018 17:21. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before water spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary works must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:



# CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

## (SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

### PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD CHINA
Policy No:	DMCVSN3060421700	Date of Loss:	30/01/2018
Vehicle Reg. No.:	<b>GBG3644L</b>	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	EFICAZ PEST MANAGEMENT PTE LTD		
Driver:	SUNG YUNG RAN		

Make/Model:	TOYOTA HIACE, 3.0 (A)	Vehicle Reg. Date:	27/07/2017
Vehicle Colour:	WHITE		
Engine No:	1KD2688879	Chassis No:	KDH2010217025
Odometer:	0 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	0		

Description of Accident/Loss	PLS REFER EFILE REPORT
Present Location:	CHENG HOE MOTOR PTE LTD (WOODLANDS WORKSHOP)

### COST OF CLAIMS

Parts	2,884.35
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>2,884.35</b>
<b>+ GST 7.00% (S\$)</b>	<b>201.90</b>
<b>Nett Amount (S\$)</b>	<b>3,086.25</b>

<b>+ Previous Estimates (S\$)</b>	<b>15,988.80</b>
-----------------------------------	------------------

<b>Claim Total (S\$)</b>	<b>19,075.05</b>
--------------------------	------------------

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

## REPAIR DETAILS

### Reference

Part Source: (Last Synchronised: 13 Feb 2018)

Parts: N/A TOYOTA HIACE 3.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/GBG3644L/13/02/2018 12:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 pc frt bumper tow cover (LH)	Nil	0.00	*15.00 F	✓
2	1		*1 pc frt bumper centre beam	B <sub>1</sub>	0.00	*70.00 F	✓
3	1		*1 pc frt bumper lower centre grille	CR <sub>1</sub>	0.00	*70.00 F	✓
4	1		*1 pc frt bumper top centre reinforcement	B <sub>1</sub>	0.00	*170.00 F	✓
5	1		*2 pcs bonnet hinges @ \$30/pc	D <sub>1</sub>	0.00	*60.00 F	✓
6	1		*1 pc brake booster	nd	0.00	*800.00 F	✓
7	1		*1 pc air filter housing assy	CR <sub>1</sub>	0.00	*300.00 F	✓
8	1		*1 pc frt brace panel	B <sub>1</sub>	0.00	*35.00 F	✓
9	1		*1 pc firewall insulator	CR <sub>1</sub>	0.00	*290.00 F	✓
10	1		*1 pc radiator by-pass pipe	nd	0.00	*40.00 F	✓
11	1		*2 pcs heater pipes @ \$65/pc	nd	0.00	*130.00 F	✓
12	1		*1 pc air-con duct (RH)	CR <sub>1</sub>	0.00	*70.00 F	✓
13	1		*1 pc air-con duct (LH)	CR <sub>1</sub>	0.00	*60.00 F	✓
14	1		*1 pc air-con duct (centre)	CR <sub>1</sub>	0.00	*52.00 F	✓
15	1		*1 pc air-con blower assy top cover	CR <sub>1</sub>	0.00	*65.00 F	✓
16	1		*1 pc air-con evaporator assy top cover	CR <sub>1</sub>	0.00	*75.00 F	✓
17	1		*2 pcs frt bumper side brackets @ \$40/pc	D <sub>1</sub>	0.00	*80.00 F	✓
18	1		*1 pc air-con discharge pipe (inner)	nd	0.00	*255.00 F	✓
19	1		*1 pc air-con receiver pipe (inner)	nd	0.00	*110.00 F	✓

F=Franchise part.

Sub Total (S\$)	2,747.00
+ Margin on L,N Items 5.00% (S\$)	137.35
<b>Total Parts (S\$)</b>	<b>2,884.35</b>

Cheng Hoe Motor Pte Ltd/GBG3644L/13/02/2018 12:10. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/GBG3644L/13/02/2018 12:10. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

H. KENNEDY

## Estimate Report

Page 2 of 3

## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 01 Feb 2018)  
 Parts: N/A TOYOTA HIACE 3.0 (A) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Cheng Hoe Motor Pte Ltd/GBG3644L/01/02/2018 17:21  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

GBG 3644L

OD/LH/NA

D.A. 30/1/18

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 pc frt bumper	0.00	0.00	*180.00 F	✓
2	1		*1 pc frt bumper reinforcement	0.00	0.00	*105.00 F	✓
3	1		*6 pcs frt bumper clip @1.50/pc	0.00	0.00	*9.00 F	✓
4	1		*1 pc frt grille	0.00	0.00	*450.00 F	✓
5	1		*1 pc frt lip	0.00	0.00	*245.00 F	✓
6	1		*1 pc frt lip logo	0.00	0.00	*30.00 F	✓
7	1		*1 pc frt lip inner lock	0.00	0.00	*35.00 F	✓
8	1		*2 pcs headlamp @850/pc	0.00	0.00	*1,700.00 F	✓
9	1		*1 pc frt windscreen glass	0.00	0.00	*420.00 F	✓
10	1		*1 set frt windscreen glass moulding	0.00	0.00	*90.00 F	✓
11	1		*1 pc frt wiper garnish	0.00	0.00	*205.00 F	✓
12	1		*1 pc frt inner panel	0.00	0.00	*489.00 F	✓
13	1		*1 pc aircon condenser	0.00	0.00	*450.00 F	✓
14	1		*1 pc aircon condenser gas hose (receiver)	0.00	0.00	*185.00 F	✓
15	1		*1 pc aircon gas discharge hose	0.00	0.00	*136.00 F	✓
16	1		*1 pc engine inter cooler	0.00	0.00	*480.00 F	✓
17	1		*1 pc engine inter cooler top garnish	0.00	0.00	*55.00 F	✓
18	1		*1 pc frt top panel	0.00	0.00	*115.00 F	✓
19	1		*1 pc frt top panel top garnish	0.00	0.00	*85.00 F	✓
20	1		*4 pcs frt top panel top garnish clip @2/pc	0.00	0.00	*8.00 F	✓
21	1		*2 pcs headlamp panel @175/pc	0.00	0.00	*350.00 F	✓
22	1		*1 pc frt wiper tank	0.00	0.00	*155.00 F	✓
23	1		*1 pc radiator	0.00	0.00	*600.00 F	✓
24	1		*1 pc radiator fan cowling	0.00	0.00	*120.00 F	✓
25	1		*1 pc radiator fan blade	0.00	0.00	*88.00 F	✓
26	1		*1 pc radiator fan motor	0.00	0.00	*380.00 F	✓
27	1		*1 pc radiator spare tank	0.00	0.00	*150.00 F	✓
28	1		*1 pc aircon evaporator	0.00	0.00	*1,500.00 F	✓
29	1		*1 pc aircon blower	0.00	0.00	*485.00 F	✓
30	1		*1 pc horn	0.00	0.00	*48.00 F	✓
31	1		*1 pc dash board	0.00	0.00	*415.00 F	✓
32	1		*1 pc dash board housing (reinforcement)	0.00	0.00	*280.00 F	✓
33	1		*1 pc dash board glove top	0.00	0.00	*145.00 F	✓
34	1		*1 pc dash board glove lower	0.00	0.00	*120.00 F	✓
35	1		*1 pc dash board lower garnish lh	0.00	0.00	*195.00 F	✓
36	1		*1 pc dash board centre garnish	0.00	0.00	*305.00 F	✓
37	1		*1 pc dash board corner garnish rh	0.00	0.00	*48.00 F	✓

\*Franchise part

Sub Total (\$)

8854

10,838.00

+ Margin on L.N Items 5.00% (\$)

442.70

541.80

Total Parts (\$)

9,296.70

11,379.80

Cheng Hoe Motor Pte Ltd/GBG3644L/01/02/2018 17:21. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

[https://www.giarnac.org.sg/claims/index.cfm?fusebox=MTRclaim&fuseaction=gen\\_docview...](https://www.giarnac.org.sg/claims/index.cfm?fusebox=MTRclaim&fuseaction=gen_docview...) 01/02/2018