

Page 3 of 3

Estimate Report

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 pc ERP bracket	25.00 ✓
2	1	1 pc frt no. plate	30.00 X
3	1	1 pc frt windscreen gum	40.00 ✓
4	1	3 litres coolant @30/lit	90.00 ✓
Sub Total (S\$)			185.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	1) To remove and refix frt windscreen glass	New	100.00 ✓
2	2) To remove and refix aircon, vacuum and refill gas	New	100.00 ✓
3	3) To remove and refix dash board assy and check wiring	New	250.00 ✓
4	4) To perform panel beating works on accident areas	New	1,600.00
5	5) To putty and respray on accident affected areas	New	1,000.00
6	6) To remove and refix seat, carpat, garnish in order to facilitate on repairs	New	120.00 100
7	7) To remove and refix radiator, fan cowling motor, check engine and engine mountings and system	New	150.00 100
8	8) To towing	New	60.00 ?X
Gross Labour Cost (S\$)			3,280.00 2600

Cheng Hoe Motor Pte Ltd/GBG3644L/01/02/2018 17:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey body after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Parts #8854
Add supp #2247
#11601
\$80.05
155 SN
Labour #2600
#14,736.05

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Feb 2018)
Parts:	N/A TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairs (Price-denominated Standard List)
Print Code:	Cheng Hoe Motor Pte Ltd/GBG3644L/13/02/2018 12:10
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/Values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No. Qty Part No. Particulars

%Disc %Depr Amount

1	1	*1 pc frt bumper tow cover (LH)	0.00	0.00	*15.00F ✓
2	1	*1 pc frt bumper centre beam	0.00	0.00	*70.00F ✓
3	1	*1 pc frt bumper lower centre grille	0.00	0.00	*70.00F ✓
4	1	*1 pc frt bumper top centre reinforcement	0.00	0.00	*170.00F ✓
5	1	*2 pcs bonnet hinges @ \$30/pc	0.00	0.00	*60.00F ✓
6	1	*1 pc brake booster	0.00	0.00	*800.00F ✓
7	1	*1 pc air filter housing assy	0.00	0.00	*300.00F ✓
8	1	*1 pc frt brace panel	0.00	0.00	*35.00F ✓
9	1	*1 pc firewall insulator	0.00	0.00	*290.00F ✓
10	1	*1 pc radiator by-pass pipe	0.00	0.00	*40.00F ✓
11	1	*2 pcs heater pipes @ \$65/pc	0.00	0.00	*130.00F ✓
12	1	*1 pc air-con duct (RH)	0.00	0.00	*70.00F ✓
13	1	*1 pc air-con duct (LH)	0.00	0.00	*60.00F ✓
14	1	*1 pc air-con duct (centre)	0.00	0.00	*52.00F ✓
15	1	*1 pc air-con blower assy top cover	0.00	0.00	*65.00F ✓
16	1	*1 pc air-con evaporator assy top cover	0.00	0.00	*75.00F ✓
17	1	*2 pcs frt bumper side brackets @ \$40/pc	0.00	0.00	*80.00F ✓
18	1	*1 pc air-con discharge pipe (inner)	0.00	0.00	*255.00F ✓
19	1	*1 pc air-con receiver pipe (inner)	0.00	0.00	*110.00F ✓

F=Franchise part

Sub Total (S\$) 2,747.00
+ Margin on L.N Items 5.00% (S\$) 137.35

Total Parts (S\$) 2,884.35

Cheng Hoe Motor Pte Ltd/GBG3644L/13/02/2018 12:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no relevant miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/GBG3644L/13/02/2018 12:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgprnet@mbox3.singnet.com.sg
RCB Reg No.: 198301435R

NISSAN TOYOTA OPEL
Genuine Parts GENUINE PARTS GENUINE

MAZDA
Genuine Parts

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

NISSAN TOYOTA OPEL OEM PARTS

TEL: 62954551
67496954

MITSUBISHI/PROTON

TEL: 62970688 64542288
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997

MAZDA
Genuine Parts

TAX INVOICE
TAX INVOICE NO.: CL381168
INVOICE DATE : 10/02/2018
CREDIT TERMS : 30 Days
SALES ORDER NO.:

SALESMAN : YKN
PAGE(S) : 1

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON

TEL: 62970688 64542288
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997

INVOICE TO: CHENG HOE MOTOR PTE LTD (AMK)
BLOCK 10 ANG MO KIO AUTOPOINT
#01-04
SINGAPORE 568047

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
T90975-02086 F/EMBLEM		1 PCS	(SIN) 30.000
T53510-26060 HOOD LOCK		1 PCS	35.000
T81145-26832 HEADLAMP RH		1 PCS	850.000
T88450-26120 AIR-CON CONDENSER		1 PCS	450.000
T88716-2N120 LIQUID PIPE		1 PCS	185.000
T88715-26390 AIRCON PIPE		1 PCS	135.000
T53301-26080 HOOD		1 PCS	245.000
T53201-26082 SUPPORT PANEL		1 PCS	115.000
T53292-26070 RADIATOR SUPPRT SEAL		1 PCS	85.000
T85315-26100 WASHER TANK		1 PCS	55.000

ONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

2185

THORISED SIGNATURE

SIGNATURE



豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgprnet@mbox3.singnet.com.sg
RCB Reg No.: 198301435R

NISSAN TOYOTA OPEL
Genuine Parts GENUINE PARTS GENUINE P

MAZDA
Genuine Parts

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

NISSAN TOYOTA OPEL OEM PARTS

TEL: 62954551
67496954

MITSUBISHI/PROTON

TEL: 62970688 64542288
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997

MAZDA
Genuine Parts

TAX INVOICE
TAX INVOICE NO.: CL381168
INVOICE DATE : 10/02/2018
CREDIT TERMS : 30 Days
SALES ORDER NO.:

SALESMAN : YKN
PAGE(S) : 2

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

INVOICE TO: CHENG HOE MOTOR PTE LTD (AMK)
BLOCK 10 ANG MO KIO AUTOPOINT
#01-04
SINGAPORE 568047

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
T87050-26210 COOLER COIL ASSY		1 PCS	(SIN) 1500.000
T55330-26310 REINFORCEMENT DASHBOV		1 PCS	280.000
T52127-26120 TOWING COVER		1 PCS	15.000
T57053-26030 F/BUMPER REINFORCEMENT		1 PCS	70.000
T53112-26070 F/B CENTER GRILL		1 PCS	70.000
T57109-26020 F/DASH REINFORCEMENT		1 PCS	170.000
T53410-26040 HOOD HINGE		1 PCS	30.000
T53420-26040 HOOD HINGE		1 PCS	30.000
T44610-26820 BRAKE BOOSTER		1 PCS	800.000
T17700-30280 AIR CLEANER ASSY		1 PCS	300.000
T53209-26100 FRONT BRACE PANEL		1 PCS	35.000

NG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

3300





日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

=====**GST REG. NO. M2-0119201-3 CO. REG. NO. T99307741M**=====

CHENG HOE MOTOR PTE LTD

BLK 10 #01-04

ANG MO KIO AUTO POINT

TEL : 64812001 FAX : 64821296

ATTN : WEI LING/DORLYN

WIPERBLADE GLASS
Dept Direct: 6417 9791 / 8745 9939



TOYOTA
ENGINE PARTS

LEXUS

Dept Direct: 6306 9610

Dept Direct: 6306 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct:

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE AR201802-0938

DATE 21/02/201

CUSTOMER ID CHE00

VEH REG. NO. GBG3644

TERMS 30 day

PO NO.

PAGE NO. Page 1 of

CURR. SGI

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. WT56101-26011 KDH200	FRT W/S GLASS	WH W	1	420.00	420.00
2. MLD T75531-26080 MV HI-ACE 04"KDH200/222	12-8689 FRT W/S MLD	WH W	1	90.00	90.00

SUB-TOTAL : 510.00

ADD GST 7.00 % 35.70

E. & O.E

TOTAL AMOUNT SGD : 545.70

[P] 21/02/2018 4:03:27PM

[E] 21/02/2018 4:01:42PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : STEVEN



* AR201802-09389 *

Goods Received in Good Order

This is computer generated document.

No signature is required.

ORIGINAL

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9939

Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

CHENG HOE MOTOR PTE LTD

BLK 10 #01-04

ANG MO KIO AUTO POINT

TEL : 64812001 FAX : 64821296

ATTN : WEI LING/DORLYN

TAX INVOICE : AR201802-055

DATE : 08/02/20

CUSTOMER ID : CHEO

VEH REG. NO. : GBG364

TERMS : 30 da

PO NO. :

PAGE NO. : Page 1 of

CURR : SC

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T55550-26010-B0 KDH200	GLOVE BOX	PA PL2-E1-040	1	120.00	120.
2.	T16400-30280/1 KDH201	RADIATOR	PA PL2-A1-090	1	600.00	600.
3.	T52119-26650 HIACE-KDH201 13"	FRT BUMPER	PA PL4-E1-19	1	180.00	180.
4.	T52131-26020 KDH201	FRT BPR REINFORCEMENT	PA PL2-G1-07B	1	105.00	105.
5.	T90467-09185 KDH200	STEP GARNISH CLIP	PA PL2-K1-03I	6	1.50	9.
6.	D2533-KDH201-CHROME KDH201	GRILLE ASSY	PA PL2-P1-11A	1	450.00	450.
7.	T81185-26841/2 HIACE-KDH223	HEAD LAMP LH	PA PL2-F1-09A	1	850.00	850.

CONTINUE NEXT PAGE

[P] 08/02/2018 4:41:07PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 08/02/2018 4:31:30PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9599



Dept Direct: 6306 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9754

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

CHENG HOE MOTOR PTE LTD
BLK 10 #01-04
ANG MO KIO AUTO POINT

TEL : 64812001 FAX : 64821296
ATTN : WEI LING/DORLYN

TAX INVOICE : AR201802-055
DATE : 08/02/20
CUSTOMER ID : CHE0
VEH REG. NO. : GBG364
TERMS : 30 da
PO NO. :
PAGE NO. : Page 2 of
CURR : SC

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUN
8	T55708-26080/90 KDH200	WIPER GARNISH	PA PL2-H1-09A	1	205.00	205.

SUB-TOTAL : 2,519
ADD GST 7.00 % 176

E. & O.E

TOTAL AMOUNT SGD : 2,695

[P] 08/02/2018 4:41:07PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 08/02/2018 4:31:30P

JAE Auto Pte. Ltd.

Sales Executive: STEVEN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

CHENG HOE MOTOR PTE LTD
BLK 10 #01-04
ANG MO KIO AUTO POINT

TEL : 64812001 FAX : 64821296
ATTN : WEI LING/DORLYN

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6417 9796

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9796

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201802-0550
DATE : 08/02/2018
CUSTOMER ID : CHE00
VEH REG. NO. : GBG3644
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1 of
CURR. : SGI

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T55041-26070B1 KDH223	LH DASH TOP DOOR	U1	1	145.00	145.00
2. T16470-75121/2OE HACE-KDH200	RADIATOR SPARE TANK	U1	1	150.00	150.00
3. T16712-75122 KDH200 2014	FAN COWLING NO.2	U1	1	120.00	120.00
	SUPPLIER				

SUB-TOTAL : 415.0
ADD GST 7.00 % 29.0

E. & O.E

TOTAL AMOUNT SGD : 444.0

[P] 08/02/2018 4:42:00PM

[E] 08/02/2018 4:29:45PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : STEVEN



* AR201802-05501 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



明我汽车私人有限公司

MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building
Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)
E-mail : info@minghee.com
Website : http://www.minghee.com

TAX INVOICE

INV NO : 8097583

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: CHEONGH2 TIME: 09:38
CHENG HOE MOTOR PTE LTD
BLK 1019, YISHUN INDUSTRIAL
PARK 1, #01-374/382,
SINGAPORE 768761

Telephone No : 67556142 768761

ROUTE
SEND

DELIVER TO:

Cheng Hoe Motor Pte Ltd
10, ang Mo Kio Ind, Park 2a
01-04 AMK AUTOPOINT



PART NO.

- 1 TY17940-30050
- 2 TY17311-30050
- 3 TY55300-26110 B0
- 4 TY87130-26230

PARTICULARS

INTERCOOLER KDH200
DUST GARNISH KDH203
DASHBOARD KDH201
BLOWER MOTOE KDH201 2014 -

LOC
5C-07C
10-14I
5D-00
5D-00

QUANTITY
1 PC
1 PC
1 PC
1 PC

UNIT PRICE

490.00
55.00
415.00
485.00

AMOUNT

490.00
55.00
415.00
485.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE
*OVERDUE ACCOUNTS SHALL
BEAR INTEREST AT UOB'S PREVAILING
LENDING RATE
*CASH INVOICE MUST BE
PAID WITHIN 7 DAYS
FROM DATE OF INVOICE

Exclusive Distributor

HDK

CLV JOINT
MADE IN JAPAN

Stockists



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

Signature

For MIN GHEE AUTO PTE. LTD.

豐達汽車私人有限公司
FONG TAT MOTOR CO. PTE. LTD.
 Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Fax: 62982156, 62942354, 62935021
 Email: ftrpnet@mbx3.singnet.com.sg
 RCB Reg No.: 198301435R

INVOICE TO: **CHENG HOE MOTOR PTE LTD (AMK)**
BLOCK 10 ANG MO KIO AUTOPOINT
#01-04
SINGAPORE 568047

GST Reg. No.: M2-0059747-8

NISSAN **TOYOTA** **OPEL**
 Genuine Parts
MAZDA **FORD**
 Genuine Parts
HYUNDAI

NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426889 62949832 67479292
 67426878 62985333 67455824
MITSUBISHI/PROTON
 TEL: 62954551
 67496954
CHINA/HYUNDAI DIV
 TEL: 62970688 64542288
 67433588
MAZDA/FORD DIV
 TEL: 62935722
 67420368
AIRCON/W/S GLASS
 TEL: 62952336
 67495997

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
T55223-26030 GBG3644L FIRE WALL INSULATOR		1 PCS	(SIN) 290.00
GST Excl Amount : Special Discount : GST @ 7 %			290.00 20.30

FONG TAT MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH
 PRINT BY :
 YKN 13/02/2018 09:42:34

AUTHORISED SIGNATURE
 SIGNATURE

TOTAL
 310.30

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Feb 2018 Sendback Est	01 Feb 2018 17:21 \$S\$14,942.80	02 Feb 2018 10:26 Edit Adj Rpt	\$S\$14,936.05 Edit Estimates	\$S\$14,936.05 View Rpt		Pending for Survey Report Cancel Case
Supp #1	13 Feb 2018 12:03	13 Feb 2018 12:10 \$S\$2,884.35	13 Feb 2018 12:10			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	EFICAZ PEST MANAGEMENT PTE LTD , Co. Reg. No.: 201717718D		
Vehicle Reg. No.:	GBG3644L	Date of Loss:	30/01/2018 15:00 - :59 [6 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D00583C01	Policy/Cover Note No.:	DMCVSN3060421700 (Comprehensive) Coverage: 27/07/2017 - 26/07/2018
		Excess:	\$S\$350.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/02/2018]		
Driver/Custodian:	SUNG YUNG RAN (/ Male), NRIC: S8807040B Email:		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (30/11/2018): Alert - Adj Mandate Approved (\$S\$17317.15) - GBG3644L - Claim Handler: Chong Boon...
- CHINA_TAIPING (07/02/2018): Alert - Adj Mandate Approved (\$S\$14432.80) - GBG3644L - Claim Handler: Chong Boon...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBG3644L (SNM18D00583C01)
OD
Jan 30 2018 3:00PM
[EFICAZ PEST MANAGEMENT PTE LTD]
Cheng Hoe Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	01/02/18 17:21	Repairer Estimates		Load HTM	
2	13/02/18 12:10	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/02/18 16:44	Adjuster Immediate Advice		Load HTM	
2	21/11/18 14:43	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/02/18 17:51	General View		Load PDF	
2	21/11/18 15:07	GBG 3644L RE-INSPECTION PHOTO		Load PDF	
Documentation				1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	01/02/18 17:20	E-filed GIA report		Load PDF	
2	01/02/18 17:21	Driver's Driving License		Load JPG	☒
3	01/02/18 17:21	Driver's Driving License		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/02/18 17:05	WORKSHOP ESTIMATE		Load PDF	
2	21/11/18 14:38	GBG 3644L SUPPLEMENTARY EST		Load PDF	
3	16/07/19 09:23	PARTS INVOICE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

 (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

 China Taiping Insurance (Singapore) Pte. Ltd.
 3 Anson Road, #16-00 Springleaf Tower
 Singapore 079909

Our File No: CS/CTI18002102/KCD3S2

Date: 16/07/2019

REFERENCE

 Insured/Claimant: EFICAZ PEST MANAGEMENT PTE LTD
 Date of Loss: 30/01/2018

Policy No: DMCVSN3060421700

Nature of Claim: OD

Claim No: SNM18D00583C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

 Reg No: **GBG3644L**
 Make & Model: TOYOTA HIACE, 3.0 (A)
 Reg. Date: 27/07/2017 (Man. Year: 2017)
 Colour: White
 Engine Capacity: 2982 cc
 Market Value/New Car Price: S\$78,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

 Engine No: 1KD2688879
 Chassis No: KDH2010217025
 Odometer: 1852 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/80R15	Rear Tyre Size:	195/80R15
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,262.15	12,181.05	2,081.10	14.59
Miscellaneous Items	185.00	155.00	30.00	16.22
Labour	3,380.00	2,600.00	780.00	23.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,827.15	14,936.05	2,891.10	16.22
- Excess (S\$)	0.00	350.00	-350.00	
(S\$)	17,827.15	14,586.05	3,241.10	18.18
+ GST 7.00/7.00% (S\$)	1,247.90	1,021.02	226.88	18.18
Nett Amount (S\$)	19,075.05	15,607.07	3,467.98	18.18

INSPECTION

Date of Assignment: 02/02/2018

Date Inspected: 02/02/2018 Inspected At:

38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05

Estimated Period of Repair: 10.0 days

Repairer: Cheng Hoe Motor Pte Ltd

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Jul 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG3644L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc frt bumper (WCP)	Buckled	180.00 F	*180.00 F
2	1		*1 pc frt bumper reinforcement (WCP)	Bent	105.00 F	*105.00 F
3	1		*6 pcs frt bumper clip @1.50/pce (WCP)	Necessary	9.00 F	*9.00 F
4	1		*1 pc frt grille (WCP)	Cracked	450.00 F	*450.00 F
5	1		*1 pc frt lip (WCP)	Bent	245.00 F	*245.00 F
6	1		*1 pc frt lip logo (WCP)	Necessary	30.00 F	*30.00 F
7	1		*1 pc frt lip inner lock (WCP)	Bent	35.00 F	*35.00 F
8	1		*2 pcs headlamp @850/pce (WCP)	O/s Broken / N/s Mtg Cracked	1,700.00 F	*1,700.00 F
9	1		*1 pc frt windscreen glass (WCP)	Cracked	420.00 F	*420.00 F
10	1		*1 set frt windscreen glass moulding (WCP)	Necessary	90.00 F	*90.00 F
11	1		*1 pc frt wiper garnish (WCP)	Warped / Cut	205.00 F	*205.00 F
12	1		*1 pc frt inner panel (WCP)	Repair	480.00 F	*- F
13	1		*1 pc aircon condenser (WCP)	Bent	450.00 F	*450.00 F
14	1		*1 pc aircon condenser gas hose (receiver) (WCP)	Dented	185.00 F	*185.00 F
15	1		*1 pc aircon gas discharge hose (WCP)	Punctured	135.00 F	*135.00 F
16	1		*1 pc engine inter cooler (WCP)	Punctured	490.00 F	*490.00 F
17	1		*1 pc engine inter cooler top garnish (WCP)	Dented	55.00 F	*55.00 F
18	1		*1 pc frt top panel (WCP)	Bent	115.00 F	*115.00 F
19	1		*1 pc frt top panel top garnish (WCP)	Cracked	85.00 F	*85.00 F
20	1		*4 pcs frt top panel top garnish clip @2/pce (WCP)	Not Necessary	8.00 F	*- F
21	1		*2 pcs headlamp panel @175/pce (WCP)	Repair	350.00 F	*- F
22	1		*1 pc frt wiper tank (WCP)	Dented	155.00 F	*55.00 F
23	1		*1 pc radiator (WCP)	Punctured	600.00 F	*600.00 F
24	1		*1 pc radiator fan cowl (WCP)	Cracked	120.00 F	*120.00 F
25	1		*1 pc radiator fan blade (WCP)	Serviceable	68.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*1 pc radiator fan motor (WCP)	Serviceable	380.00 F	*- F
27	1		*1 pc radiator spare tank (WCP)	Mtg Cracked	150.00 F	*150.00 F
28	1		*1 pc aircon evaporator (WCP)	Housing Cracked	1,500.00 F	*1,500.00 F
29	1		*1 pc aircon blower (WCP)	Cracked	485.00 F	*485.00 F
30	1		*1 pc horn (WCP)	Serviceable	48.00 F	*- F
31	1		*1 pc dash board (WCP)	Cracked	415.00 F	*415.00 F
32	1		*1 pc dash baord housing (reinforcement) (WCP)	Bent	280.00 F	*280.00 F
33	1		*1 pc dash bord glove top (WCP)	Buckled	145.00 F	*145.00 F
34	1		*1 pc dash baord glove lower (WCP)	Dented	120.00 F	*120.00 F
35	1		*1 pc dash board lower garnish lh (WCP)	Serviceable	195.00 F	*- F
36	1		*1 pc dash baord centre garnish (WCP)	Serviceable	305.00 F	*- F
37	1		*1 pc dash board cornal garnish rh (WCP)	Serviceable	48.00 F	*- F
Supplementary #1						
38	1		*1 pc frt bumper tow cover (LH) (WCP)	Missing	15.00 F	*15.00 F
39	1		*1 pc frt bumper centre beam (WCP)	Bent	70.00 F	*70.00 F
40	1		*1 pc frt bumper lower centre grille (WCP)	Cracked	70.00 F	*70.00 F
41	1		*1 pc frt bumper top centre reinforcement (WCP)	Bent	170.00 F	*170.00 F
42	1		*2 pcs bonnet hinges @ \$30/pc (WCP)	Distorted	60.00 F	*60.00 F
43	1		*1 pc brake booster (WCP)	Dented	800.00 F	*800.00 F
44	1		*1 pc air filter housing assy (WCP)	Cracked	300.00 F	*300.00 F
45	1		*1 pc frt brace panel (WCP)	Bent	35.00 F	*35.00 F
46	1		*1 pc firewall insulator (WCP)	Cracked	290.00 F	*290.00 F
47	1		*1 pc radiator by-pass pipe (WCP)	Dented	40.00 F	*40.00 F
48	1		*2 pcs heater pipes @ \$65/pc (WCP)	Dented	130.00 F	*130.00 F
49	1		*1 pc air-con duct (RH) (WCP)	Cracked	70.00 F	*70.00 F
50	1		*1 pc air-con duct (LH) (WCP)	Cracked	60.00 F	*60.00 F
51	1		*1 pc air-con duct (centre) (WCP)	Cracked	52.00 F	*52.00 F
52	1		*1 pc air-con blower assy top cover (WCP)	Cracked	65.00 F	*65.00 F
53	1		*1 pc air-con evaporator assy top cover (WCP)	Cracked	75.00 F	*75.00 F
54	1		*2 pcs frt bumper side brackets @ \$40/pc (WCP)	Distorted	80.00 F	*80.00 F
55	1		*1 pc air-con discharge pipe (inner) (WCP)	Dented	255.00 F	*255.00 F
56	1		*1 pc air-con receiver pipe (inner) (WCP)	Dented	110.00 F	*110.00 F

F=Franchise part.

Sub Total (\$\$)	13,583.00	11,601.00
+ Margin on L,N Items 5.00/5.00% (\$\$)	679.15	580.05

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						14,262.15
						12,181.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 pc ERP bracket (NECESSARY)	25.00	25.00
2	1	1 pc frt no. plate (SERVICEABLE)	30.00	0.00
3	1	1 pc frt windscreen gum (NECESSARY)	40.00	40.00
4	1	3 litres coolant @30/lit (NECESSARY)	90.00	90.00
Sub Total (\$\$)			185.00	155.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	1) To remove and refix frt windscreen glass	New	100.00	100.00
2	2) To remove and refix aircon, vacuum and refill gas	New	100.00	100.00
3	3) To remove and refix dash board assy and check wiring	New	250.00	250.00
4	4) To perform panel beating works on accident areas	New	1,600.00	1,200.00
5	5) To putty and respray on accident affected areas	New	1,000.00	750.00
6	6) To remove and refix seqt, carpat, garnish in order to facilitate on repairs	New	120.00	100.00
7	7) To remove and refix radiator, fan cowling motor, check engine and engine mountings and system	New	150.00	100.00
8	8) To towing	New	60.00	0.00
Gross Labour Cost (\$\$)			3,380.00	2,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >