

ASS. REC. BY:

REF: CS/FCI 18002103/Urd3n2 Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

CWS

From (Person):

Joanne Yong

of

FCI

Date/Time:

02/02/18 @ 12:08 pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MY7CS

To Inspect Vehicle No:

SFE 8827G

Insured:

SHB6387P

at Workshop m/s

Chin Meng Motors

Tel:

6747 4810

of

1 kaki Bkt Ave 6 #01-40 Autobay

Policy No:

Claim No:

D18000997MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 31/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 12:35pm @ 2/2/18

Person Contacted:

Kim Seng

Vehicle ☒ IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SFE 8827G - X

SHB6387P - NA / INC 08030270/s/

D.O.A. 10/11/2008

Sent preli thm email

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

*3/1/18* *conf. with 2/s & 6500 with Kimsey*  
*Red 8577.08, 571.*

RECEIVED 01 MAR 2018

MV: \$13,800 (EST) LTA: \$6699 HV: \$7101

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Preli. Report

1) *typist*

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / H.B.I. (\$) *6500*

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

5x15: 75

1701 75

50

50

114

459

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

|                    |                                                             |                               |
|--------------------|-------------------------------------------------------------|-------------------------------|
| Date               | 01-02-2018                                                  | Our Ref No. D18000997MFSH     |
| Accident Date      | 31-01-2018                                                  | Claim Type. Third Party       |
| Insured Vehicle    | SHB6387P                                                    | Third Party Vehicle. SFE8827G |
| Survey Location    | 1 KAKI BUKIT AVE 6 #01-40 AUTOBAY@KAKI BUKIT                |                               |
| Contact Person.    | QUEK KIM SENG                                               |                               |
| Contact No.        | 67474810/ 91912829                                          | Fax No. 67455018              |
| Survey Type        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                                |                               |
| Contact Person     | NA                                                          | Fax No. 68416315              |
| Contact Number.    | NA                                                          |                               |

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

|                   |                  |                         |
|-------------------|------------------|-------------------------|
| Cc : Workshop     | CHIN MENG MOTORS | Attention. NIL          |
| Cc : TP Solicitor | NA               | TP Solicitor Fax No. NA |
| Officer Incharge  | JOANNEY          |                         |

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234585)



PRI Documents



Close



## PRI Header Details

|                   |                                                      |                                   |                                                                                                                               |                      |              |
|-------------------|------------------------------------------------------|-----------------------------------|-------------------------------------------------------------------------------------------------------------------------------|----------------------|--------------|
| Claim No          | D18000997MFSH                                        | Policy No                         | D-18088936MFSH                                                                                                                | Claimant S.No & Name | 1 & CHIN MEN |
| Workshop Name     | CHIN MENG MOTORS<br>(Contact Person : QUEK KIM SENG) | Survey Location & Contact Details | 1 KAKI BUKIT AVE 6 #01-40 AUTOBAY@KAKI BUKIT<br>Mobile: 91912829 , Phone: 67474810 , Fax: 67455011<br>EmailId: KIMSENG@CMM.SG |                      |              |
| Our Surveyor      | LKK AUTO CONSULTANTS PTE LTD                         | Instructions To Surveyor          | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM                                                                                 |                      |              |
| Insured Name      | COMFORT TRANSPORTATION PTE LTD                       | Insured Vehicle No                | SHB6387P                                                                                                                      | TP Vehicle No        | SFE8827G     |
| PRI Recieved Date | 01-02-2018 10:04:17 PM                               | Surveyor Appointed Date           | 02-02-2018 12:07:09 PM                                                                                                        | Surveyor Accept Date | 02-02-2018 1 |

## Survey Report Upload

|                             |  |                      |            |                         |                                            |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|
| Surveyor Inspection Date *: |  | Surveyor Report Date | 02-02-2018 | Upload Survey Report *: | <input type="button" value="Choose File"/> |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|

## Vehicle Particulars

|           |                                                 |                |                                                  |         |                                          |
|-----------|-------------------------------------------------|----------------|--------------------------------------------------|---------|------------------------------------------|
| Make      | <input type="text" value="Please Select Make"/> | Model          | <input type="text" value="Please Select Model"/> | Year    | <input type="text" value="Select Year"/> |
| Chasis No | <input type="text"/>                            | Engine No      | <input type="text"/>                             | Mileage | <input type="text"/>                     |
| Color     | <input type="text"/>                            | Cubic Capacity | <input type="text"/>                             |         |                                          |

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002103/Urd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-02-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                       |                |            |
|--------------|-----------------------|----------------|------------|
| Insured Veh. | SHB 6387P             | Veh. Inspected | SFE 8827G  |
| Policy No.   |                       | Coverage (\$)  | 0.00       |
| Claim No.    | D18000997MFSH         | Excess (\$)    | 0.00       |
| Assign From  | MERIMEN (JOANNE YONG) | Assign Date    | 02/02/2018 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |  |
|--|--|
|  |  |
|--|--|

## 5. General Information

|                |                                                                          |                 |            |
|----------------|--------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 31/01/2018                                                               | Inspection Date | 02/02/2018 |
| Survey held at | CHIN MENG MOTORS<br>1 KAKI BUKIT AVE 6<br>#01-40/63<br>SINGAPORE 417883. |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

Your Ref: D18000997MFSHOur Ref: CS/FCI18002103/Urd3The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SFE 8827G.**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02/02/2018 at the premises of M/s CHIN MENG MOTORS PTE LTD and have the following to report:-

|                          |                           |
|--------------------------|---------------------------|
| Workshop Estimate Amount | : S\$ <u>15,077.08</u> .  |
| Revised Estimate Amount  | : S\$ <u>8,087.15</u> .   |
| "Check" Items Amount     | : S\$ <u>          </u> . |
| Market Value             | : S\$ <u>          </u> . |
| LTA Reimbursement Value  | : S\$ <u>          </u> . |
| Nett Value               | : S\$ <u>          </u> . |

Description of Damage:  
The vehicle sustained damages  
at rear and front portion.

Yours faithfully  
MARCUS  
Automotive Assessor

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Thursday, March 01, 2018 4:09 PM  
**To:** 'Claim Workflow System'  
**Cc:** JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18000997MFSH/1  
**Attachments:** SFE 8827G.pdf

Dear Sir,

Enclosed preliminary revised for **SFE 8827G**.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Friday, February 02, 2018 12:38 PM

**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

**Cc:** JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

**Subject:** RE: SURVEY ASSESSMENT - D18000997MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

**Sent:** Friday, 2 February 2018 12:07 PM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [JOANNEYONG@MSFIRSTCAPITAL.COM.SG](mailto:JOANNEYONG@MSFIRSTCAPITAL.COM.SG)

**Subject:** PRI: SURVEY ASSESSMENT - D18000997MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

## Enquire PARF/COE Rebate for Registered Vehicle

|                                |                          |
|--------------------------------|--------------------------|
| Vehicle Owner Particulars      |                          |
| Owner ID Type:                 | Company                  |
| Owner ID:                      | 7488D                    |
| Vehicle Details                |                          |
| Vehicle No.:                   | SFE8827G                 |
| Vehicle to be Exported:        | No                       |
| Intended De-registration Date: | 02 Feb 2018              |
| Vehicle Make:                  | TOYOTA                   |
| Vehicle Model:                 | VIOSE AUTO               |
| Primary Colour:                | Red                      |
| Manufacturing Year:            | 2008                     |
| Engine No.:                    | 1NZX794157               |
| Chassis No.:                   | MR053HY9305080249        |
| Maximum Power Output:          | 80.0 kW (107 bhp)        |
| Open Market Value:             | \$11,834.00              |
| Original Registration Date:    | 05 Sep 2008              |
| First Registration Date:       | 05 Sep 2008              |
| Transfer Count:                | 1                        |
| Actual ARF Paid:               | \$11,834.00              |
| Intended PARF Rebate Details   |                          |
| PARF Eligibility:              | Yes                      |
| PARF Eligibility Expiry Date:  | 04 Sep 2018              |
| PARF Rebate Amount:            | \$5,917.00               |
| Intended COE Rebate Details    |                          |
| COE Expiry Date:               | 04 Sep 2018              |
| COE Category:                  | A - Car (1600cc & below) |
| COE Period(Years):             | 10                       |
| QP Paid:                       | \$13,289.00              |
| COE Rebate Amount:             | \$782.00                 |
| <b>Total Rebate Amount:</b>    | <b>\$6,699.00</b>        |

The information contained herein is correct as at 02 Feb 2018

OK

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools &amp; Tips



UP TO  
**64% OFF**  
CAR INSURANCE

Starting from  
**\$411.69\***  
Receive \$50  
CapitaVouchers\*  
T&Cs apply

BUY NOW

income

TOYOTA VIOS

Price Range

Depreciation

2008

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Zion Auto Gallery » Toyota Vios 1.5A E

## Tools &amp; Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

## Car Leasing



#BankRakyatCares



## Toyota Vios 1.5A E

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

Price

\$13,800

Depreciation

Reg Date

10-Jul-2008  
(5mths 4days COE left)

Manufactured

2008

Mileage

-

Transmission

Auto

Engine Cap

1,497 cc

Road Tax

\$684 /yr

Power

80.0 kW (107 bhp)  
View specs of the Toyota Vios (2007-2013)

Curb Weight

1,095 kg

Features

1.5L DOHC VVT-i Engine, 4 Speed Automatic Transmission, SRS Airbags, Reverse Sensors, Auto Climatic Air-con Control.

Accessories

Leather Seats, Factory Fitted Audio System, Retractable Side Mirrors With Indicators, Knockdown Rear Seats.

Description

Well Maintained And Timely Serviced, Excellent Fuel Efficiency Ideal For Short Term Drive Or Even Renewal Of COE. Renowned Reliable Work Horse, You Don't Even Have To Worry! Loan And Trade In Available.

COE

\$14,590

OMV

\$12,344

ARF

\$12,344

Dereg Value

\$6,788 as of today (change)

No. of Owners

4

Type of Veh

Mid-Sized Sedan

Category

PAP Car

Availability

Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 21 Dec 2017 | Last Updated on: 01 Feb 2018

Tags: Toyota Vios, 2008 Toyota Vios, Toyota, Vios, Used Toyota

## Upfront Payment

» more Financial info

Transfer Fee

\$25

Down Payment

\$4,140 (change)

Maximum 70% Loan

1st Instalment

\$1,956

Total Upfront Payment

\$6,121 (excluding insurance)

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

## Items for Toyota Vios

» View All

Door Visit  
\$30

## Seller Information

Company

Zion Auto Gallery

» dealer's pricelist  
» 12 vehs sold | 11 vehs available

Address

159 Sin Ming Road #01-01

Search cars nearby this location

Location

Amtech Building

Office No

64552535

Contact Person(s)

|        |          |
|--------|----------|
| Laura  | 96677190 |
| Vivien | 84999020 |
| Edwin  | 94882373 |

## Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools



Toyota Vios Price Range Depreciation 2008 Vehicle Type Submit

Home » Used Cars » Zion Auto Gallery » Toyota Vios 1.5A E

## Tools &amp; Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

## Toyota Vios 1.5A E

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist  
Tweet

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

|                      |                                                                                                                                                                                                                                                      |                                           |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|
| <b>Price</b>         | <b>\$14,800</b>                                                                                                                                                                                                                                      |                                           |
| <b>Depreciation</b>  | \$15,440 /yr                                                                                                                                                                                                                                         | View models with similar depreciation     |
| <b>Reg Date</b>      | 01-Sep-2008                                                                                                                                                                                                                                          | (6mths 29days COE left)                   |
| <b>Manufactured</b>  | 2008                                                                                                                                                                                                                                                 |                                           |
| <b>Mileage</b>       | -                                                                                                                                                                                                                                                    |                                           |
| <b>Transmission</b>  | Auto                                                                                                                                                                                                                                                 |                                           |
| <b>Engine Cap</b>    | 1,497 cc                                                                                                                                                                                                                                             |                                           |
| <b>Road Tax</b>      | \$684 /yr                                                                                                                                                                                                                                            |                                           |
| <b>Power</b>         | 80.0 kW (107 bhp)                                                                                                                                                                                                                                    | View specs of the Toyota Vios (2007-2013) |
| <b>Curb Weight</b>   | 1,095 kg                                                                                                                                                                                                                                             |                                           |
| <b>Features</b>      | Smooth 1.5L DOHC VVT-i Engine. 4 Speed Automatic Transmission. SRS Airbags. ABS.                                                                                                                                                                     |                                           |
| <b>Accessories</b>   | Leather Seats. Reverse Sensors. Sports Rims. Solar Film. Retractable Side Mirrors.                                                                                                                                                                   |                                           |
| <b>Description</b>   | Most Wanted Sedan Car Is Here, Very Well Maintain By A Lady Driver, Original Condition From Inside Out, No Repair Needed, Best For Short Term Drive, Flexible Loan Available For Bank And In House, So What You Wait For, Call Now Before It's Gone! |                                           |
| <b>COE</b>           | \$14,101                                                                                                                                                                                                                                             |                                           |
| <b>OMV</b>           | \$11,834                                                                                                                                                                                                                                             |                                           |
| <b>ARF</b>           | \$11,834                                                                                                                                                                                                                                             |                                           |
| <b>Dereg Value</b>   | \$6,728 as of today (change)                                                                                                                                                                                                                         |                                           |
| <b>No. of Owners</b> | 2                                                                                                                                                                                                                                                    |                                           |
| <b>Type of Veh</b>   | Mid-Sized Sedan                                                                                                                                                                                                                                      |                                           |
| <b>Category</b>      | PARF Car                                                                                                                                                                                                                                             |                                           |
| <b>Availability</b>  | Available                                                                                                                                                                                                                                            |                                           |

Add to Shortlist

Add to Compare

Add a Note



## Seller Information

|                          |                                                                           |     |
|--------------------------|---------------------------------------------------------------------------|-----|
| <b>Company</b>           | Zion Auto Gallery<br>» dealer's pricelist<br>» 11 vehs sold   12 vehs ava |     |
| <b>Address</b>           | 159 Sin Ming Road #01-01<br>Search cars nearby this locat                 |     |
| <b>Location</b>          | Amtech Building                                                           |     |
| <b>Office No</b>         | 64552535                                                                  |     |
| <b>Contact Person(s)</b> | Laura                                                                     | 966 |
|                          | Vivien                                                                    | 849 |
|                          | Edwin                                                                     | 948 |

## Useful Services

|                                  |                                                                               |
|----------------------------------|-------------------------------------------------------------------------------|
| <b>STA</b><br>VEHICLE INSPECTION | Make sure of this car condition with STA Evaluation.<br>Vehicle Evaluation    |
|                                  | Find out the market value for you Get a free Car Valuation.<br>Free Valuation |

Compare

Posted on: 21-Dec-2017 | Last Updated on: 01-Feb-2018

# 振明摩哆

## CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018

cmmotors@singnet.com.sg

Our Ref: EST035/18/TP

Your Ref: TP claim against SHB6387P

31-Jan-18

**MS First Capital Insurance Ltd**

36 Robinson Road

#16-01 City House

Singapore 068877

Attn: Motor Claims Department

Dear Sir/Ms,

**Re: Estimated cost of repair to Toyota Vios no: SFE8827G**

Date of accident: 31-01-2018

Parts supply:

|                                        |                 |    |                 |           |
|----------------------------------------|-----------------|----|-----------------|-----------|
| 1 pc Boot                              | W/BUC           | SS | 499.60          | —         |
| 1 pc Boot emblem - VIOS                | neu             |    | 41.50           | —         |
| 1 pc Boot emblem - Logo                | neu             |    | 42.50           | —         |
| 1 pc Boot emblem - E                   | neu             |    | 32.50           | —         |
| 1 pc Boot inner lock                   | TW1             |    | 95.90           | —         |
| 2 pcs Boot stoppers @\$10.00           | 11              |    | 20.00           | x         |
| 2 pcs Boot hinges @\$65.95             | R               |    | 131.90          | x         |
| 1 pc Boot weatherstrip                 | TW1             |    | 85.90           | —         |
| 2 pcs Taillamps @\$288.90              | M/S BAO o/s cno |    | 577.80          | —         |
| 2 pcs Taillamp clips @\$10.00          | 11              |    | 20.00           | q         |
| 2 pcs Taillamp lower brackets @\$65.95 | 11              |    | 131.90          | q         |
| 1 pc Rear bumper                       | W/BUC           |    | 399.60          | —         |
| 2 pcs Rear bumper retainers @\$65.90   | M/S BUC         |    | 131.80          | 1cc 65.90 |
| 2 pcs Rear bumper brackets @\$         | BT              |    | 171.80          | ?         |
| 8 pcs Rear bumper clips @\$3.50        | neu             |    | 28.00           | —         |
| 1 pc Rear end panel                    | 300/27          |    | 569.50          | ?         |
| 1 pc Rear end panel garnish            | TW1             |    | 219.60          | ?         |
| 1 pc Rear spare tyre board             | 10.1            |    | 198.60          | —         |
| 1 pc Rear spare tyre panel             | R               |    | 687.50          | q         |
| 1 pc Exhaust muffler                   | 11              |    | 593.60          | q         |
| 1 pc Exhaust muffler bush              | 11              |    | 56.80           | x         |
| 1 pc Bonnet                            | R               |    | 545.90          | x         |
| 2 pcs Bonnet hinges @\$46.90           | 11              |    | 91.80           | q         |
| 1 pc Bonnet lock                       | 11              |    | 96.90           | q         |
| 2 pcs Bonnet rubber @\$35.10           | 11              |    | 70.20           | q         |
| 2 pcs Bonnet stopper @\$10.00          | 11              |    | 20.00           | x         |
| 2 pcs Headlamp @\$455.23               | CM              |    | 910.46          | ?         |
| 2 pcs Headlamp clips @\$10.00          | 11              |    | 20.00           | x         |
| 1 pc Front bumper                      | W/BUC           |    | 411.80          | —         |
| 12 pcs Front bumper clips @\$3.50      | neu             |    | 42.00           | ?         |
| 1 pc Front bumper reinforcement        | M               |    | 350.90          | —         |
| 2 pcs Front bumper retainers @\$65.90  | BT              |    | 131.80          | ?         |
| 2 pcs Front bumper brackets @\$285.90  | BT              |    | 571.80          | ?         |
|                                        |                 |    | <u>7,999.86</u> |           |

### ESTIMATE

Not Aclm  
L/5 46500/2  
2/2/18  
to high After repair  
S Ly.

# 振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883  
Tel: 6747-4810 Fax: 6745-5018  
cmmotors@singnet.com.sg

## Re: Estimated cost of repair to Toyota Vios no: SFE8827G

Date of accident: 31-01-2018

### Parts supply:

Balance b/f:

- 1 pc Front bumper tow cover *u 1*
- 1 pc Front bumper grille *one*
- 1 pc Front bumper grille moulding *one*
- 1 pc Front bumper emblem - Logo *one*
- 1 pc Front bumper lower grille *T.S. 1*
- 6 pcs Front bumper lower lip clips @\$3.50 *one*
- 2 pcs Front bumper fog lamp @\$377.80 *1 1*
- 2 pcs Front bumper fog lamp cover @\$65.90 *1 1*
- 1 pc Front bumper top garnish (support) *Yuy*
- 1 pc Radiator *1 1*
- 1 pc Aircon condenser *1 1*
- 1 pc Radiator fan cowling *1 1*
- 1 pc Radiator fan blade *1 1*
- 1 pc Radiator fan motor *1 1*
- 1 pc Radiator top hose *1 1*
- 1 pc Radiator lower hose *1 1*

|           |            |                                  |
|-----------|------------|----------------------------------|
| S\$       | 7,999.86   |                                  |
|           | 18.90      | <i>x</i>                         |
|           | 85.90      | <i>—</i>                         |
|           | 99.60      | <i>—</i>                         |
|           | 45.90      | <i>—</i>                         |
|           | 89.50      | <i>—</i>                         |
|           | 21.00      | <i>—</i>                         |
|           | 755.60     | <i>x</i>                         |
|           | 131.80     | <i>x</i>                         |
|           | 233.50     | <i>2</i>                         |
|           | 1,839.60   | <i>x</i>                         |
|           | 1,293.90   | <i>x</i>                         |
|           | 246.90     | <i>x</i>                         |
|           | 201.95     | <i>x</i>                         |
|           | 283.70     | <i>x</i>                         |
|           | 89.60      | <i>x</i>                         |
|           | 78.90      | <i>x</i>                         |
|           | 13,516.11  |                                  |
| Less 25%: | (3,379.03) | <i>6022.68</i><br><i>4517.64</i> |

### S/Nett Items

- 1 pc Front no. plate with cover (S/Nett)
- 1 pc Rear no. plate with cover (S/Nett)
- 1 pc Rear bumper lower lip (S/Nett)
- 1 pc Rear reverse sensor (S/Nett)
- 1 pc Front bumper lower lip (S/Nett) *R*
- 1 pc Boot spoiler (S/Nett)

|            |        |            |
|------------|--------|------------|
| <i>sub</i> | 45.00  | <i>40</i>  |
| <i>sub</i> | 45.00  | <i>40</i>  |
| <i>D.S</i> | 450.00 | <i>—</i>   |
| <i>sub</i> | 250.00 | <i>200</i> |
| <i>R</i>   | 450.00 | <i>x</i>   |
| <i>1 1</i> | 450.00 | <i>x</i>   |

### Labour charges:

- To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.
- To respray affected part.
- To remove & refit rear windscreen.
- To remove & refit rear reverse sensor.
- To apply underseal.
- To check wirings.

|            |           |             |
|------------|-----------|-------------|
|            | 1,400.00  | <i>1200</i> |
|            | 1,600.00  | <i>1500</i> |
| <i>1 1</i> | 100.00    | <i>x</i>    |
|            | 60.00     | <i>50</i>   |
|            | 60.00     | <i>—</i>    |
|            | 30.00     | <i>—</i>    |
|            | 15,077.08 | <i>—</i>    |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                          |                       |                             |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------------------|-----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                          |                       | Ref : CS/FCI18002103/Urd3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                          |                       | Date : 05-03-2018           |  |
|                                                                                                                                                                                        |                                                                          |                       | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                          |                       |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHB 6387P                                                                | Veh. Inspected        | SFE 8827G                   |                                                                                     |
| Policy No.                                                                                                                                                                             | D-18088936MFSH                                                           | Coverage (\$)         | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                              | D18000997MFSH                                                            | Excess (\$)           | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                            | JOANNE YONG                                                              | Assign Date           | 02/02/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                          |                       |                             |                                                                                     |
| Make & Model                                                                                                                                                                           | TOYOTA VIOS (A)                                                          | c.c                   | 1497                        |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                   | Year of Reg.          | 2008                        |                                                                                     |
| Chassis No.                                                                                                                                                                            | MR053HY9305080249                                                        | Colour                | RED                         |                                                                                     |
| Odometer                                                                                                                                                                               | 146770                                                                   | Steering              | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                 | Modification          | SPORTS RIM                  |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                     |                       |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                          |                       |                             |                                                                                     |
|                                                                                                                                                                                        | Size                                                                     | Make                  | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 195/50 R15                                                               | TOYO                  | 6 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 195/50 R15                                                               | TOYO                  | 6 mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 195/50 R15                                                               | TOYO                  | 6 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 195/50 R15                                                               | TOYO                  | 6 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                          |                       |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                                                                   |                                                                          |                       |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                          |                       |                             |                                                                                     |
| Accident Date                                                                                                                                                                          | 31/01/2018                                                               | Inspection Date       | 02/02/2018                  |                                                                                     |
| Survey held at                                                                                                                                                                         | CHIN MENG MOTORS<br>1 KAKI BUKIT AVE 6<br>#01-40/63<br>SINGAPORE 417883. |                       |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                          |                       |                             |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                       |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                          |                       |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                          | <b>8 Working Days</b> |                             |                                                                                     |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFE 8827G

| Qty                         | Description of Parts             | Condition                | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|----------------------------------|--------------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                  |                          |                           |                   |
| 1                           | BOOT                             | DENTED / BUCKLED         | 499.60                    | 499.60            |
| 1                           | BOOT EMBLEM-VIOS                 | NECESSARY                | 41.50                     | 41.50             |
| 1                           | BOOT EMBLEM-LOGO                 | NECESSARY                | 42.50                     | 42.50             |
| 1                           | BOOT EMBLEM-E                    | NECESSARY                | 32.50                     | 32.50             |
| 1                           | BOOT INNER LOCK                  | TWISTED                  | 95.90                     | 95.90             |
| 2                           | BOOT STOPPERS @\$10.00           | NOT NECESSARY            | 20.00                     | -                 |
| 2                           | BOOT HINGES @\$65.95             | TO REPAIR SEE LABOUR     | 131.90                    | -                 |
| 1                           | BOOT WEATHERSTRIP                | TWISTED                  | 85.90                     | 85.90             |
| 2                           | TAILLAMPS @\$288.90              | N/S BROKEN / O/S CRACKED | 577.80                    | 577.80            |
| 2                           | TAILLAMP CLIPS @\$10.00          | NOT NECESSARY            | 20.00                     | -                 |
| 2                           | TAILLAMP LOWER BRACKETS @\$65.95 | NOT NECESSARY            | 131.90                    | -                 |
| 1                           | REAR BUMPER                      | DENTED / BENT            | 399.60                    | 399.60            |
| 2                           | REAR BUMPER RETAINERS @\$65.90   | N/S BENT                 | 131.80                    | 65.90             |
| 2                           | REAR BUMPER BRACKETS             | BENT                     | 171.80                    | 171.80            |
| 8                           | REAR BUMPER CLIPS @\$3.50        | NECESSARY                | 28.00                     | 28.00             |
| 1                           | REAR END PANEL                   | BADLY DENTED             | 569.50                    | 569.50            |
| 1                           | REAR END PANEL GARNISH           | TWISTED                  | 219.60                    | 219.60            |
| 1                           | REAR SPARE TYRE BOARD            | TORN                     | 198.60                    | 198.60            |
| 1                           | REAR SPARE TYRE PANEL            | TO REPAIR SEE LABOUR     | 687.50                    | -                 |
| 1                           | EXHAUST MUFFLER                  | NOT NECESSARY            | 593.60                    | -                 |
| 1                           | EXHAUST MUFFLER BUSH             | NOT NECESSARY            | 56.80                     | -                 |
| 1                           | BONNET                           | TO REPAIR SEE LABOUR     | 545.90                    | -                 |
| 2                           | BONNET HINGE @\$46.90            | NOT NECESSARY            | 91.80                     | -                 |
| 1                           | BONNET LOCK                      | NOT NECESSARY            | 96.90                     | -                 |
| 2                           | BONNET RUBBER @\$35.10           | NOT NECESSARY            | 70.20                     | -                 |
| 2                           | BONNET STOPPER @\$10.00          | NOT NECESSARY            | 20.00                     | -                 |
| 2                           | HEADLAMP @\$455.23               | CRACKED                  | 910.46                    | 910.46            |

Report Ref No. CS/FC118002103/Urd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                 | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------|----------------------|---------------------------|-------------------|
| 2   | HEADLAMP CLIPS @\$10.00              | NOT NECESSARY        | 20.00                     | -                 |
| 1   | FRONT BUMPER                         | DENTED / DEFORMED    | 411.80                    | 411.80            |
| 12  | FRONT BUMPER CLIPS @\$3.50           | NECESSARY            | 42.00                     | 42.00             |
| 1   | FRONT BUMPER REINFORCEMENT           | DENTED               | 350.90                    | 350.90            |
| 2   | FRONT BUMPER RETAINERS @\$65.90      | BENT                 | 131.80                    | 131.80            |
| 2   | FRONT BUMPER BRACKETS @\$285.90      | BENT                 | 571.80                    | 571.80            |
| 1   | FRONT BUMPER TOW COVER               | NOT NECESSARY        | 18.90                     | -                 |
| 1   | FRONT BUMPER GRILLE                  | CRACKED              | 85.90                     | 85.90             |
| 1   | FRONT BUMPER GRILLE MOULDING         | CRACKED              | 99.60                     | 99.60             |
| 1   | FRONT BUMPER EMBLEM-LOGO             | NECESSARY            | 45.90                     | 45.90             |
| 1   | FRONT BUMPER LOWER GRILLE            | TORN                 | 89.50                     | 89.50             |
| 6   | FRONT BUMPER LOWER LIP CLIPS @\$3.50 | NECESSARY            | 21.00                     | 21.00             |
| 2   | FRONT BUMPER FOG LAMP @\$377.80      | NOT NECESSARY        | 755.60                    | -                 |
| 2   | FRONT BUMPER FOG LAMP COVER @\$65.90 | NOT NECESSARY        | 131.80                    | -                 |
| 1   | FRONT BUMPER TOP GARNISH (SUPPORT)   | TWISTED              | 233.50                    | 233.50            |
| 1   | RADIATOR                             | NOT NECESSARY        | 1,839.60                  | -                 |
| 1   | AIRCON CONDENSER                     | NOT NECESSARY        | 1,293.90                  | -                 |
| 1   | RADIATOR FAN COWLING                 | NOT NECESSARY        | 246.90                    | -                 |
| 1   | RADIATOR FAN BLADE                   | NOT NECESSARY        | 201.95                    | -                 |
| 1   | RADIATOR FAN MOTOR                   | NOT NECESSARY        | 283.70                    | -                 |
| 1   | RADIATOR TOP HOSE                    | NOT NECESSARY        | 89.60                     | -                 |
| 1   | RADIATOR LOWER HOSE                  | NOT NECESSARY        | 78.90                     | -                 |
|     | LESS 25% DISCOUNT                    |                      | -3,379.03                 | -1,505.71         |
|     |                                      |                      | 10,137.08                 | 4,517.15          |
|     | <b>SPECIAL NETT ITEMS</b>            |                      |                           |                   |
| 1   | FRONT NO PLATE WITH COVER (SN)       | BENT                 | 45.00                     | 40.00             |
| 1   | REAR NO PLATE WITH COVER (SN)        | BENT                 | 45.00                     | 40.00             |
| 1   | REAR BUMPER LOWER LIP (SN)           | DISTORTED            | 450.00                    | 450.00            |
| 1   | REAR REVERSE SENSOR (SN)             | SHORTED              | 250.00                    | 200.00            |
| 1   | FRONT BUMPER LOWER LIP (SN)          | TO REPAIR SEE LABOUR | 450.00                    | -                 |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                         | Description of Parts                                                                                                                                                                                                               | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                                                                           | BOOT SPOILER (SN)                                                                                                                                                                                                                  | NOT NECESSARY | 450.00                    | -                 |
|                                                                             |                                                                                                                                                                                                                                    |               | 1,690.00                  | 730.00            |
|                                                                             | <b>LABOUR</b>                                                                                                                                                                                                                      |               |                           |                   |
|                                                                             | TO PANEL BEATING, WELDING, REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC. INCLUSIVE OF THE REPAIR OF BOOT HINGES, REAR BUMPER BRACKETS, REAR SPARE TYRE PANEL, BONNET AND FRONT BUMPER LOWER LIP. |               | 1,400.00                  | 1,200.00          |
|                                                                             | TO RESPRAY AFFECTED PART.                                                                                                                                                                                                          |               | 1,600.00                  | 1,500.00          |
|                                                                             | TO REMOVE & REFIT REAR WINDSCREEN.                                                                                                                                                                                                 | NOT NECESSARY | 100.00                    | -                 |
|                                                                             | TO REMOVE & REFIT REAR REVERSE SENSOR.                                                                                                                                                                                             |               | 60.00                     | 50.00             |
|                                                                             | TO APPLY UNDERSEAL.                                                                                                                                                                                                                |               | 60.00                     | 60.00             |
|                                                                             | TO CHECK WIRINGS.                                                                                                                                                                                                                  |               | 30.00                     | 30.00             |
|                                                                             |                                                                                                                                                                                                                                    |               | 3,250.00                  | 2,840.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                                                                                                                                    |               | <b>15,077.08</b>          | <b>8,087.15</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                                                                                                    |               |                           | <b>6,500.00</b>   |

Report Ref No. CS/FCI18002103/Urd3n2

MARKET VALUE: \$13,800.00 (EST)-LTA REIMBURSEMENT VALUE: \$6,699.00=NETT VALUE: \$7,101.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.