


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4060P
 Ref. No : TAX/01/18/2187
 Reg. Date : 29/12/2010
 Vehicle Type : TAXI
 Make : CHRYSLER
 Model : C300
 Name of Driver : WEE LIANG JUAN
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 29/01/2018 10:40:00 PM
 Accident Reported Date / Time : 31/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094396
 Special Instruction to ARC, if any :
 SH8745P (COMFORT) - III
 Prepared Date : 31/01/2018 04:03:00 PM



3 Days.
 Cao Qiang - 8288 0282
 02/2/18
 Lump sum Rep
 After repair photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : 1C3H9E3M69Y500770


Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	338.00	0.00
Total Spray Painting Charges :	473.00	0.00
Total Material Charges :	5,142.24	5,142.24
Other Charges :	360.00	0.00
TOTAL :	6,313.24	0.00
Lum Sum Total :	6,300.00	0.00
No. of Repair Days :	3.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	01/02/2018 02:53:44 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/02/2018 02:53:13 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	338.00	0.00
Total Labour	338.00	0.00 200

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	473.00	0.00
Total Spray Painting & Panel Beating	473.00	0.00 200 400

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO TRANSFER DOOR MECHANISM	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 ?
TO WASH AND VACUUM	60.00	0.00 ?
Total Other Costs	360.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
05134170	RIGHT AN		DOOR ASSY-FRONT RH <i>huc</i>	1	3,680.00	10.00	3,312.00	Replace	Replace	No
1JK90TZ	RIGHT ZAB		MOULDING - FRONT DOOR OUTER RH <i>ne</i>	1	380.00	10.00	342.00	Replace	Replace	No
04575748	RIGHT AE		HINGE LOWER-FRONT DOOR RH ?	1	380.00	10.00	342.00	Replace	Replace	No
55113468	RIGHT AA		HINGE UPPER-FRONT DOOR RH ?	1	390.00	10.00	351.00	Replace	Replace	No
			FRONT DOOR RH REGULATOR ?	1	890.00	10.00	801.00	Replace	Replace	No
05065474	RIGHT AE		MOTOR ASSY - POWER WINDOW RH ?	1	872.00	10.00	784.80	Replace	Replace	No
			FRT DOOR RH WIRING ?	1	550.00	10.00	495.00	Replace	Replace	No
TOTAL MATERIALS								6,427.80	6,427.80	
TOTAL MATERIALS(Discounted)							5,142.24	5,142.24		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									