

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4060P

Ref. No : TAX/01/18/2187

Reg. Date : 29/12/2010

Vehicle Type : TAXI

Make : CHRYSLER

Model : C300

Name of Driver : WEE LIANG JUAN

Type of Accident : HEAD TO SIDE

Date / Time of Accident : 29/01/2018 10:40:00 PM

Accident Reported Date / Time: 31/01/2018 12:00:00 AM

Surveyor is Required? : Yes

Survey by :

Vehicle is Towed Back? : No

Towed Back Date/Time

Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024094396

Special Instruction to ARC, if any:

SH8745P (COMFORT) - III

Prepared Date : 31/01/2018 04:03:00 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: 1C3H9E3M69Y500770 Mileage: 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

Total Labout Charges : 338.00 0.00

Total Spray Painting Charges : 473.00 0.00

Total Material Charges : 5,142.24 5,142.24

Other Charges : 360.00 0.00

TOTAL : 6,313.24 0.00

 Lum Sum Total
 : 6,300.00
 0.00

 No. of Repair Days
 : 3.00
 0.00

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 01/02/2018 02:53:44 PM 01/01/1900 12:00:00 AM

7

Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/02/2018 02:53:13 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	338.00	0.00
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

TO RESPRAY FRONT DOOR RH	473.00	0.00
Total Spray Painting & Panel Beating	473.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00		
TO TRANSFER DOOR MECHANISM	120.00	0.00		
TO REPLACE SUNDRY PARTS	100.00	0.00		
TO WASH AND VACUUM	60.00	0.00		
Total Other Costs	360.00	0.00		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
05134170 AN	RIGHT		DOOR ASSY-FRONT RH	1	3,680.00	10.00	3,312.00	Replace	Replace	No
1JK90TZ ZAB	RIGHT		MOULDING - FRONT DOOR OUTER RH	1	380.00	10.00	342.00	Replace	Replace	No
04575748 AE	RIGHT		HINGE LOWER- FRONT DOOR RH	1	380.00	10.00	342.00	Replace	Replace	No
55113468 AA	RIGHT		HINGE UPPER - FRONT DOOR RH	1	390.00	10.00	351.00	Replace	Replace	No
			FRONT DOOR RH REGULATOR	1	890.00	10.00	801.00	Replace	Replace	No
05065474 AE	RIGHT		MOTOR ASSY - POWER WINDOW RH	1	872.00	10.00	784.80	Replace	Replace	No
			FRT DOOR RH WIRING	1	550.00	10.00	495.00	Replace	Replace	No
TOTAL MATERIALS								6,427.80	6,427.80	
TOTAL MATERIALS(Discounted)							5,142.24	5,142.24		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	TOTAL SUPPLEMENTARY MATERIALS								