

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SLK1294L
Chassis No : JHMRU1830GX201569
Model : HRV LX-SIN CVT YM 2016
Owner's Name : TAN AI LIANG IRENE
Ins Policy No. :
Date of Accident : 12/12/2017

Document No. : SQT18002495
Date : 19. Jun 2018
Customer No. : WZM003
Svc Advisor :
Engine No : L15B4531570
Date | Time : 19. Jun 2018 9:33:29 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH: SUPPLEMENTARY						
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
Sum Item					351.22	24.58	375.80

Survey By

Date & Time

Excess

Status

Signature

Total Amount 351.22 24.58 375.80

Total (Inclusive of GST) 375.80

Printed on 19/6/2018 9:36:38 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)