

SFF28185

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

02 FEB 2018

Estimate No. : b1 45751
Date Estimated : 02/02/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ng Yan Ching
11 Mount Faber Road
#04-18

Singapore 099209

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFF2818S	F253919	30/03/2012	328iA/4	0

DESCRIPTIONVALUE

To replace rear bumper & attachments including to knock out tail panel and dented area caused by the accident	850/day	1700	2,550.00
To respray rear bumper and tail panel	Bumper 1038 End Panel 743	1603	1,781.00
To remove and install boot compartment carpet and garnish to facilitate repairs.		231	271.00
To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.		? 561	661.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.		150	177.00
To check electrical wiring systems and lightings at the rear section for proper function.		150	177.00
Sundries.			80.00

Total Labour 1: **5,697.00**DESCRIPTIONQTYPRICVALUE

RR BUMPER BOTTOM REINFORCEMENT ?	1	66.10	66.10
REAR BUMPER CENTRE GUIDE ?	1	32.10	32.10
REAR BUMPER CARRIER (ECE) ?	1	432.90	432.90
DECORATIVE STRIP (LUXURY LINE) ✓ NEC	1	145.05	145.05
REAR BUMPER PANEL PRIMED (LINES) ✓ Deform	1	1,100.25	1,100.25
RR BUMPER FLAP TOWING EYE PRIMED ✓ Cut	1	42.20	42.20
REAR PDC HOLDER SET ✓ NEC	1	23.10	23.10
GUIDE FOR BUMPER SIDE RH ✓ NEC	1	57.05	57.05
PLUG BLACK D=5MM ✓ NEC	10	0.90	9.00
SENSOR WIRE FOR SMART OPENER TOP ?	1	42.10	42.10
SENSOR WIRE FOR SMART OPENER BOTTOM ?	1	40.50	40.50
EXPANDING NUT ✓ NEC	10	0.55	5.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45751
Date Estimated : 02/02/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFF2818S	F253919	30/03/2012	328iA/4	0

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER RH REFLECTOR ✓ CRK	1	35.20	35.20
REAR RH LIGHT IN THE SIDE PANEL ✓ CRK	1	356.90	356.90
REAR RH LIGHT IN TRUNK LID ✓ CRK	1	249.80	249.80
DECOUPLING RING PDC TORQUE CONVERTE ✓ NEC	2	5.05	10.10
# PDC SENSOR HAVANNA (A17) ✓ DMG	2	368.80	737.60
(DG) ADHESIVE SET K6 ✓ NEC	1	53.05	53.05

Total Parts : 3,438.50

5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 5/3/18. Excess \$5

Surveyor's Name Sebastian. Sign [Signature]

Surveyor's Tel 9003621 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail Sebastianyeang@lkkauto.com

No. of Working Days Recommend _____

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint.

Labour 1	:	5,697.00
Parts	:	3,438.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	639.49
Grand Total	:	9,774.99

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **