


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6420R
 Ref. No : TAX/01/18/2182
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : LAU CHEE CHOON
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 31/01/2018 09:22:00 AM
 Accident Reported Date / Time : 31/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 31/01/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094389
 Special Instruction to ARC, if any :
 SHC5132J (TRANSCAB) - AXA
 Prepared Date : 31/01/2018 11:44:55 AM



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary items must be surveyed and is subject to final approval from the Insurance Company

Acknowledged by Repairer

Signature

Date

4 Days.
 part by part
 before paint photos.
 Gm Qiy - 81880282
 02/2/18.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU903576828

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,183.00	0.00
Total Spray Painting Charges :	1,872.00	0.00
Total Material Charges :	13,322.92	13,322.92
Other Charges :	660.00	0.00
TOTAL :	17,037.92	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	7.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	01/02/2018 02:07:36 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/02/2018 02:07:28 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 2/1/2018 2:19:34 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	1,183.00	0.00
Total Labour	1,183.00	0.00 600

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 150
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY APRON PANEL LH	180.00	0.00
Total Spray Painting & Panel Beating	1,872.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO TOP UP A/C GAS	120.00	0.00 ?
TO REMOVE AND REFILL FAN AUXILIARY, AIR CON CONDENSER	200.00	0.00 ?
TO REPLACE SUNDRY PARTS	100.00	0.00 ?
TO WASH AND VACUUM	60.00	0.00 ?
Total Other Costs	660.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119479 62			COVER, FR BUMPER <i>rel</i>	1	495.50	25.00	371.62	Replace	Replace	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER <i>mbu</i>	10	1.50	25.00	11.25	Replace	Replace	No
52128479 06			COVER, FR BUMPER LH <i>mbu</i>	1	28.10	25.00	21.07	Replace	Replace	No
52127479 07			COVER, FR BUMPER RH <i>mbu</i>	1	28.10	25.00	21.07	Replace	Replace	No
52114471 90			BRACKET, FR BUMPER <i>mbu</i>	1	99.80	25.00	74.85	Replace	Replace	No
			NUMBER PLATE <i>mbu</i>	1	35.00	0.00	35.00	Replace	Replace	No
			NUMBER PLATE FRAME <i>mbu</i>	1	25.00	0.00	25.00	Replace	Replace	No
53101470 80			GRILLE SUB-ASSY <i>mbu</i>	1	335.60	25.00	251.70	Replace	Replace	No
53112472 40			GRILLE, RADIATOR <i>mbu</i>	1	165.00	25.00	123.75	Replace	Replace	No
75310470 60			EMBLEM ASSY FRONT <i>mbu</i>	1	87.10	25.00	65.32	Replace	Replace	No
52116470 50			SUPPORT, FR BUMPER LH <i>mbu</i>	1	82.30	25.00	61.72	Replace	Replace	No
52115470 50			SUPPORT, FR BUMPER RH <i>mbu</i>	1	76.90	25.00	57.67	Replace	Replace	No
51420470 30			COVER ASSY, ENGINE <i>mbu</i>	1	180.10	25.00	135.07	Replace	Replace	No
52611471 40			ABSORBER, FR BUMPER <i>mbu</i>	1	70.30	25.00	52.72	Replace	Replace	No
52618470 90			ABSORBER, FR BUMPER LOWER <i>mbu</i>	1	117.00	25.00	87.75	Replace	Replace	No
52132470 10			REINFORCEMENT FRONT LOWER <i>mbu</i>	1	238.50	25.00	178.87	Replace	Replace	No
52021471 10			REINFORCEMENT FRONT UPPER <i>mbu</i>	1	691.10	25.00	518.32	Replace	Replace	No
52103470 10			EXTENSION SUB-ASSY, LH <i>mbu</i>	1	116.30	25.00	87.22	Replace	Replace	No
52102470 20			EXTENSION SUB-ASSY, RH <i>mbu</i>	1	116.30	25.00	87.22	Replace	Replace	No
16592370 20			GUIDE, RADIATOR AIR, <i>mbu</i>	1	93.90	25.00	70.42	Replace	Replace	No
53301471 10			HOOD SUB-ASSY <i>mbu</i>	1	938.40	25.00	703.80	Replace	Replace	No
53420471 30			HINGE ASSY, HOOD, LH <i>mbu</i>	1	57.00	25.00	42.75	Replace	Replace	No
53410471 30			HINGE ASSY, HOOD, RH <i>mbu</i>	1	57.00	25.00	42.75	Replace	Replace	No
53510471 40			LOCK ASSY, HOOD <i>mbu</i>	1	131.10	25.00	98.32	Replace	Replace	No
53630470 90			CABLE ASSY, HOOD <i>mbu</i>	1	53.20	25.00	39.90	Replace	Replace	No
53395470 40			SEAL, HOOD TO FR END <i>mbu</i>	1	24.40	25.00	18.30	Replace	Replace	No
53205479 00			SUPPORT S/A UPPER <i>mbu</i>	1	364.90	25.00	273.67	Replace	Replace	No
53203479 01			SUPPORT S/A LH <i>mbu</i>	1	237.00	25.00	177.75	Replace	Replace	No
53028470 10			SUPPORT SUB-ASSY LOWER <i>mbu</i>	1	397.40	25.00	298.05	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5321447050			SUPPORT, RADIATOR UPPER LH ?	1	76.70	25.00	57.52	Replace	Replace	No
8118547691			UNIT, HEADLAMP, LH ?	1	2,558.90	10.00	2,303.01	Replace	Replace	No
8105647690			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1 ?	1	486.40	10.00	437.76	Replace	Replace	No
5380847020			SEAL SUB-ASSY, LH ?	1	50.20	25.00	37.65	Replace	Replace	No
2880037130			BATTERY X	1	1,584.90	10.00	1,426.41	Replace	Replace	No
7440447030			CLAMP SUB-ASSY, BATTERY X	1	41.40	25.00	31.05	Replace	Replace	No
7448247010			CLAMP, BATTERY, NO.2 X	1	43.30	25.00	32.47	Replace	Replace	No
1656337010			SEAL, RADIATOR TO LH ?	1	24.80	25.00	18.60	Replace	Replace	No
1659537050			GUIDE, RADIATOR AIR, LH ?	1	58.80	25.00	44.10	Replace	Replace	No
8262047090			BLOCK ASSY, FUSIBLE LINK ?	1	99.80	10.00	89.82	Replace	Replace	No
8267147040			BLOCK, JUNCTION ?	1	15.80	10.00	14.22	Replace	Replace	No
8846010320			AIR CON CONDENSER ASSY ?	1	1,317.70	25.00	988.27	Replace	Replace	No
1640037310			RADIATOR ASSY ?	1	1,841.10	25.00	1,380.82	Replace	Replace	No
5380247100			FENDER SUB-ASSY, FR, LH X / <i>Blue</i>	1	933.10	25.00	699.82	Replace	Replace	No
7537447140			EMBLEM, SIDE PANEL (HYBRID) X / <i>MC</i>	1	52.90	25.00	39.67	Replace	Replace	No
5382847070			PROTECTOR, FR FENDER LH ?	1	90.40	25.00	67.80	Replace	Replace	No
5387647110			LINER, FR FENDER, LH ?	1	194.30	25.00	145.72	Replace	Replace	No
5370647901			BRACE SUB-ASSY, FENDER APRON, LH ?	1	282.70	25.00	212.02	Replace	Replace	No
5372047070			APRON ASSY, FRONT FENDER, LH ?	1	171.20	25.00	128.40	Replace	Replace	No
5373247020			MEMBER, FR APRON TO COWL SIDE UPPER FRONT LH ?	1	106.30	25.00	79.72	Replace	Replace	No
5373447020			MEMBER, FR APRON TO COWL SIDE LOWER FRONT LH ?	1	60.90	25.00	45.67	Replace	Replace	No
6700247162			PANEL SUB-ASSY, FRONT DOOR LH X / <i>MC</i>	1	1,249.60	25.00	937.20	Replace	Replace	No
			STICKER DECAL SMRT (DOOR) X / <i>MC</i>	1	60.00	0.00	60.00	Replace	Replace	No
			COOLANT ?	1	12.30	0.00	12.30	Replace	Replace	No
TOTAL MATERIALS								13,323.05	13,322.92	
TOTAL MATERIALS(Discounted)								13,322.92	13,322.92	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									