

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 08 Feb 2018

**Preliminary Advice**

|                    |                                                                                             |                         |              |
|--------------------|---------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SKA8672Y                                                                                  | Accident Date           | : 26/01/2018 |
| TP Vehicle No      | : SJD2408E                                                                                  | Assignment Date         | : 02/02/2018 |
| Make               | : MITSUBISHI LANCER                                                                         | Est. Duration of Repair | : 4.00       |
| Date of Inspection | : 06/02/2018                                                                                |                         |              |
| Inspection At      | : WEI LEE MOTOR WORKS (HQ)<br>BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32<br>SINGAPORE 575644 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 3,584.90 |
| Revised Amount              | :S\$ | 2,277.10 |
| Check Items (Estimated)     | :S\$ | 877.50   |
| Total                       | :S\$ | 3,154.60 |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.