

Surveyor:

Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSIG

Date/Time: 02/02/18 @ 2:16pm

Estimated Cost:

Bill to:

OD / HP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 2408E

Insured:

SKA 8672Y

at Workshop m/s

Wei Lee Motor Works

Tel:

6456 9830

of Blk 9, Sin Ming Ind. Est # 01-32

Policy No: P28700705DMA

Claim No: 547869

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 2:44pm @ 2/2/18

Person Contacted:

Karen

Vehicle: IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SJD 2408E - COG / AIG 11004844 / Tija3r1

D.O.A. 12/3/2011

SKA 8672Y - X

8/2/18

Send preli revised by merimen

22/2/18

11 Pm @ 95% confirmed with Karen (Red) 2634.90, 7490

@ 140pm

ASS. REC. BY:


REF: MSG/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MY
 To Inspect Vehicle No: _____
 at Workshop m/s Wei Lee
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: 2 Consistent? : Yes or No
 Est. Repairs: 64 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STD 2408E Yr Regn: 04, 08
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mit Lanch c.c. 1499
 Colour: M. Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 203306 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JMY SREY 2APU006775
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: NII / S/Rlm / STD A/Rlm or
 Tyre Size: F. Fikun 205/60R16
 R: B.S
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 3 mm R/Bal. 5 mm
 L/Bal. 3 mm L/Bal. 5 mm
 D.O.A. 26/1/18 D.O.I. 6/2/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/2 File pass to Catherine

26/2/18 Check with Kenneth all (N) Items

23/2/2018

RECEIVED 26 FEB 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 26/2 - typist

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

200

S + RS SI

10

Photos

Others

TOTAL

210

Report Format:

Merimen

Lump Sum / I.B.I. (\$

950/2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002121/Kvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 02-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKA 8672Y	Veh. Inspected	SJD 2408E
Policy No.	P28700705DMA	Coverage (\$)	0.00
Claim No.	547869	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/01/2018	Inspection Date
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jan 2018		02 Feb 2018 14:16 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN WOO TONG, ID: S70085111		
Main Claimant:	KH LEASING PTE LTD, Co. Reg. No.: 201611813C		
Vehicle Reg. No.:	SJD2408E	Date of Loss:	26/01/2018 14:00 - :59
Claim Type:	TP / 547869	Policy/Cover Note No.:	P28700705DMA (Comprehensive) Coverage: 08/04/2017 - 07/04/2018
Vehicle Reg. No. (Insured):	SKA8672Y	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/02/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Irene Tan Gek Ing	Date: 08 Feb 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: SKA8672Y	Accident Date	: 26/01/2018
TP Vehicle No	: SJD2408E	Assignment Date	: 02/02/2018
Make	: MITSUBISHI LANCER	Est. Duration of Repair	: 4.00
Date of Inspection	: 06/02/2018		
Inspection At	: WEI LEE MOTOR WORKS (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,584.90
Revised Amount	:S\$	2,277.10
Check Items (Estimated)	:S\$	877.50
Total	:S\$	3,154.60
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Wong Shih Yin

From: karen Seah <weileemotorworks@gmail.com>
Sent: Friday, 2 February, 2018 11:24 AM
To: Wong Shih Yin
Subject: Re: TP survey for vehicle No: SJD2408E/SKA8672Y

Vehicle No: SJD2408E

Hi, Shih Yin
I would like to have Kenneth Kong to survey the vehicle,
Thank you.

On Fri, Feb 2, 2018 at 9:54 AM, Wong Shih Yin <shihyin_wong@sg.msig-asia.com> wrote:

OUR REF - 547869

WITHOUT PREJUDICE

Dear Sirs,

We refer to your email dated 1/02/2018.

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert) .

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong

- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Thank you.

Have A Great Week Ahead!

Wong Shih Yin

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2470 | Direct fax +65 6225 7402 | shihyin_wong@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: karen Seah [<mailto:weileemotorworks@gmail.com>]
Sent: 01 February 2018 16:49
To: Claims <claims@sg.msig-asia.com>
Subject: TP survey for vehicle No: SJD2408E

Your insured vehicle No: SKA8672Y

Accident involving vehicle No: SJD2408E/SKA8672Y

DOA: 26/01/2018

Dear officer incharge

I Refer to the above.

Attached with the accident report n estimate of repair, kindly arrange to survey the vehicle.

Thank u.

Best Regards,

Karen Seah

Wei Lee Motor Works

Block 9 Sin Ming Industrial Estate

#01-32 Singapore 575644

Tel: 6456 9830

Fax: 6458 0128

Company registration: 269436/00J

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

--
Best Regards,

Karen Seah

Wei Lee Motor Works
Block 9 Sin Ming Industrial Estate
#01-32 Singapore 575644
Tel: 6456 9830
Fax: 6458 0128
Company registration: 269436/00J

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1813C
Vehicle Details	
Vehicle No.:	SJD2408E
Vehicle to be Exported:	No
Intended De-registration Date:	08 Feb 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC GLS 4A/T
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	4A910084197
Chassis No.:	JMYSRCY2A8U006775
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,142.00
Original Registration Date:	17 Apr 2008
First Registration Date:	17 Apr 2008
Transfer Count:	3
Actual ARF Paid:	\$18,857.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2018
PARF Rebate Amount:	\$9,428.00
Intended COE Rebate Details	
COE Expiry Date:	16 Apr 2018
COE Category:	A - Car (1600cc & below)

COE Period(Years):	10
QP Paid:	\$12,856.00
COE Rebate Amount:	\$242.00
Total Rebate Amount:	\$9,670.00

The information contained herein is correct as at 08 Feb 2018

OK

KV 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455 3986-6458-0128
Business Regn No : 269436/00J

*Not Authorised
L1 Sm 89501
Resurvey After Paint
2 days*

MSIG Insurance (S)PL
4 Shenton Way #21-01
SGX Centre 2
S 068807

Attn Motor claim-3rd party claim
Claiming against your insured vehicle No:SKA8672Y
Accident involving vehicle No: SJD2408E/SKA8672Y
DOA: 26/01/2018
PL: 145 Teck Whye Ave

Dear officer incharge
Estimate cost of repair for vehicle No: SJD2408E
To supply—

Description	Qty	Amount
Rear bumper	1 <i>CM/R</i>	862.00 ✓
Bumper retainer,Lh	1 <i>dis</i>	32.00 N ✓
Bumper reflector	1 <i>N-L (CM)</i>	96.00 X
Taillamp,Lh	1 <i>Sm</i>	320.00 N X
End panel	1 <i>R</i>	506.00 N X
End panel top garnish	1 <i>Sm</i>	149.00 N X
Lid-lancer emblem	1 <i>nn Rm</i>	52.00 N +
Lid-EX emblem	1 <i>nn Rm</i>	39.00 N +
Lid lock	1 <i>R</i>	67.00 N X
Parts		958.00
Less 20% <i>10%</i>		191.60
		766.40
Nett parts		1,165.00
Less 10%		116.50
		1,048.50
All parts		1,814.90

Reverse sensor
Remove damaged parts and attachments.
Repair/reshape dented/ lid,panels.
Replace/align above parts ito poition.
Painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sm
220.00 *2 days X*
950.00 *6 days 2001*

600.00 *at 2001*
3584.90
3620.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002121/KVD3N2

Date: 27/02/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	P28700705DMA
Claimant Vehicle No :	SJD2408E	Insured Vehicle No :	SKA8672Y
Date of Loss:	26/01/2018	Nature of Claim:	TP
		Claim No:	547869

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD2408E	Engine No:	4A910084197
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A)	Chassis No:	JMYSRCY2A8U006775
Reg. Date:	17/04/2008 (Man. Year: 2008)	Odometer:	203306 km
Colour:	Metallic Red		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Falken 3 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Falken 3 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,130.70	804.60	1,326.10	62.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	400.00	1,150.00	74.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,680.70	1,204.60	2,476.10	67.27
Approved Total (Overridden) (S\$)		950.00		
Nett Amount (S\$)	3,680.70	950.00	2,730.70	74.19

INSPECTION

Date of Assignment:	02/02/2018	
Date Inspected:	06/02/2018	Inspected At:
		Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 Singapore 575644

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2018)
Parts:	143	MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD2408E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Cracked/Bent	862.00 FN	*862.00 FN
2	1	*BUMPER REFLECTOR (CRACKED)	Not Consistent With The Impact	96.00 FN	*- FN
3	1	*BUMPER,RETAINER,LH	Distorted	32.00 FN	*32.00 FN
4	1	*TAILLAMP,LH	Serviceable	320.00 FN	*- FN
5	1	*END PANEL	Repair	506.00 FN	*- FN
6	1	*END PANEL TOP GARNISH	Serviceable	149.00 FN	*- FN
7	1	*LID-LANCER EMBLEM	Not Necessary	52.00 FN	*- FN
8	1	*LID-EX EMBLEM	Not Necessary	39.00 FN	*- FN
9	1	*LID LOCK	Repair	67.00 FN	*- FN
10	1	*REVERSE SENSOR	Serviceable	220.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc

Sub Total (\$\$)	2,343.00	894.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	212.30	89.40
Total Parts (\$\$)	2,130.70	804.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE DAMAGED PARTS AND ATTACHMENTS.REPAIR/RESHAPE DENTED/LID,PANELS.REPLACE/ALIGN ABOVE PARTS INTO POSITION	New	950.00	200.00
2	PAINTING	New	600.00	200.00
Gross Labour Cost (S\$)			1,550.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >