

22/03/2012

ASS REC. BY:

REF:

CS/FCU8002125 / Tig6⁷

Special Instruction:

Survivor:

Tangish

ASSIGNMENT (Office)

From (Person):

CWS Eileen Lee

of

FCL

Date/Time: 02022018 2:43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 9336E

Insured:

SH 7428L

at Workshop m/s

Volkswagen Yee Auto

Tel:

6305 7133

of

247 Alessandro Rd

Policy No:

D-18088 936 MFSH

Claim No:

D18000909 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29012018

CA / REV / REP. / REV 24 HRS 'w/p'

06-02-2018 @ 4pm

H.O.D. Endorsement:

Date/Time:

02022018 3:33pm

Person Contacted:

Charmaine

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 9336E - NBA / LIP18001770/Y DM: 29012018
	SH 7428L - CS / CTP18009425/KW03 DM: 13052017

01/02/18 @ 2:27pm revised to Eileen Lee by email.

02/2/18 @ 1:37pm 2nd revised to Eileen Lee by email. (The vehicle tow out from Volkswagen to Yee Auto).

04/6/18 @ 11:48am confirmed with Mr Chan is \$3250, 6 days by email.
(Red \$12635.30, 77%).

Tanglin

REF: FCI

ASSIGNMENT

From: _____ Date: 06/02/18
Estimated Cost: _____
OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SKZ 9336 E
at Workshop no: Volkswagen
of: 247 Alexandra Rd
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record) *4pm*
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Ball on / Market Value: _____
IDAO Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *6* days Res: Yes or No
Lump Sum: _____ % S.Val: Yes or No
CA / REV / REP. / 24 HRS *wp*
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SKZ 9336 E Reg: 2016 Feb
Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover
Truck / Trailer or
Make: Volkswagen Polo 1.2. *1197*
Colour: Red A/C Insured / Std / NI / NA
Sp. Reading: 22867 TP Ratio: Insured / Std / NI / NA
Eng No: _____
C No: *WVV Z276KZG 4028464*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / S Rim / STD A/Rim or
Tyre Size: *185/60K18*
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Continental*
Front: *6* mm Rear: *6* mm
R.Bal: *6* mm L.Bal: *6* mm
D.O.A: _____ D.O.I: *6/2/18 @ 6/15*
Survey held at: *VW Alexandra*
Des. of Damages: Frt / Rear / O/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 04 JUN 2018

Date/Time File Pass to: ☐ Preli. Report
04/6 11:15 ☐ Final Report
Date/Time File Return to: _____
Report Format: *TP*
Lump Sum / I.B. / S: *3750*

Days Of Repair: *6*
Resurvey No. of Trip: _____
Add Fee: ☐ Site Insp: \$
☐ Interpreter: \$
☐ Tech: \$
☐ Weekend: \$
Survey Fee: *6x15=90*
Transportation: *170+90*
Total: *50*
43
353



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18002125/T1qb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7428L	Veh. Inspected	SKZ 9336E
Policy No.		Coverage (\$)	0.00
Claim No.	D18000909MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	02/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	29/01/2018	Inspection Date	06/02/2018
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000909MFSH

Date: 23 Febuary 2018

Our Ref: CS/FCI18002125/T1qb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKZ 9336E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/02/2018 at the premises of 247 ALEXANDRA ROAD, repair at M/s: YEE AUTO. and have the following to report:-

Workshop Estimate Amount	: S\$ 16,385.30 .
Revised Estimate Amount	: S\$ 4,730.50 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s portion.



Yours faithfully

Taufikh
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	30-01-2018	Our Ref No. D18000909MFSH
Accident Date	29-01-2018	Claim Type. Third Party
Insured Vehicle	SH7428L	Third Party Vehicle. SKZ9336E
Survey Location	247 ALEXANDRA ROAD	
Contact Person.	EDMUND GOH	
Contact No.	63057133/ 63057299	Fax No. 64743643
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VOLKSWAGEN CENTRE SINGAPORE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234470)



PRI Documents



Close



PRI Header Details

Claim No	D18000909MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & VO SINGAI
Workshop Name	VOLKSWAGEN CENTRE SINGAPORE (Contact Person : EDMUND GOH)	Survey Location & Contact Details	247 ALEXANDRA ROAD Mobile: 63057299 , Phone: 63057133 , Fax: EmailId: EDMUND.GOH@VW.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7428L	TP Vehicle No	SKZ93:
PRI Recieved Date	01-02-2018 03:11:00 PM	Surveyor Appointed Date	02-02-2018 02:48:51 PM	Surveyor Accept Date	02-02-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	02-02-2018	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 23 February 2018 1:37 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000909MFSH/1

Dear Eileen,

Enclosed herewith 2nd preliminary advice of SKZ 9336E.
Please note that the vehicle tow out from M/s: Volkswagen to M/s: Yee Auto Pte Ltd.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 7 February 2018 2:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000909MFSH/1

Dear Eileen,

Enclosed herewith preliminary advice of SKZ 9336E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 2 February 2018 3:43 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000909MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 7 February 2018 2:27 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000909MFSH/1
Attachments: CSFCI18002125T1qb.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SKZ 9336E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 2 February 2018 3:43 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000909MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 2 February, 2018 2:49 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000909MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000909MFSH

Date: 07 Febuary 2018

Our Ref: CS/FCI18002125/T1qb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKZ 9336E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/02/2018 at the premises of M/s VOLKSWAGEN, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>13,882.53</u> .
Revised Estimate Amount	: S\$ <u>11,275.55</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the n/s portion.



Yours faithfully

Taufikh
Automotive Assessor

Tan Shih Ern 97495749
WP

6/2/18 @ 1615

Resurvey before paint

Sur @ 1615 hours

7 days

PDI TUAS

PDI TUAS

TAN SHIH ERN, JESSICA
301C PUNGGOL CENTRAL
#14-754
Singapore, 823301
Singapore

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV038982
Quote No. SER/QUO/1800184
QuoteDate 31/01/18
Salesperson
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Polo GP 1.2 BMT DSG SR LED	22,079	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKZ9336E	WVWZZZ6RZGU028464	16/02/16	
Engine Code	Labor Type	Engine No.	Model Code
	1L	CJZ 763464	6C13EZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	6	UNIT	3360	5,040.00
P B&P ALEX LABOUR	TRANSFER DOOR PARTS	1	UNIT	2520	420 840.00
P B&P ALEX PAINT	SPRAY PAINT	1	UNIT	3200	5,600.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		280.00
	Nett				
P B&P PARTS	WHEEL RIM	1	Time Un		1,280.00
	KEY IN PARTS NUMBER				
P B&P PARTS	WHEEL VALVE	1	Time Un		2.53
	KEY IN PARTS NUMBER				
P B&P WHEEL ALIGNMENT	B&P WHEEL ALIGNMENT NETT	1	Time Un		360.00
	Sum Labor				13,882.53
P 6C0807217B GRU	FRONT BUMPER	1	Pieces	Rx	600.11
P 6R0821105J	FENDER LHS	1	Pieces	ddl	396.53
P 6R4833055J	DOOR LHR	1	Pieces	ddl	1,375.47
	Use Predecessor 6R4833055H				
P 6R6839697A 5AP	DOOR SEAL LHS	1	Pieces	ddl	74.80
P D 378500A2	DOOR INSULATOR	1	Pieces	ddl	46.22
Sum carried forward					16,375.66

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN SHIH ERN, JESSICA
301C PUNGGOL CENTRAL
#14-754
Singapore, 823301
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV038982
Quote No. SER/QUO/1800184
QuoteDate 31/01/18
Salesperson
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Polo GP 1.2 BMT DSG SR LED	22,079	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKZ9336E	WVWZZZ6RZGU028464	16/02/16	
Engine Code	Labor Type	Engine No.	Model Code
	1L	CJZ 763464	6C13EZ
Continued			16,375.66
Sum Item			2,493.13
Sum Labor			13,882.53
Sum Item			2,493.13
Total SGD			16,375.66
7% GST			1,146.30
Total SGD Incl. GST			17,521.96

Explanations

P = Proportionately Charged

Payment Terms No Credit

Yee Auto Pte Ltd

160 Sin Ming Dr, #02-17 Sin Ming Autocity Singapore 575722.

Mobile: 96874031 Tel: 64575768 Fax: 62528459

Reg. No: 201719251W GST No: 201719251W

Email: yeeautopteltd@gmail.com

QUOTATION

Annt: First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Date: 12/02/2018

Page 1

Vehicle No.: SKZ9336E

Model: Volkswagen Polo

No.	Descriptions	Qty	Amount
1	Front bumper	1	\$ 820.00 <i>Rx</i>
2	Front bumper clip	8	\$ 50.00 <i>X</i>
3	Front bumper side retainer L/H	1	\$ 87.60 <i>X</i> <i>an</i>
4	Front bumper side retainer R/H	1	\$ 87.60 <i>X</i>
5	Front fender L/H	1	\$ 580.00 <i>dd</i> <i>✓</i>
6	Front fender splash shield clip	10	\$ 60.00 <i>X</i>
7	Front fender splash shield L/H	1	\$ 235.00 <i>X</i> <i>an</i>
8	Front lower arm L/H	1	\$ 480.00 <i>X</i>
9	Front shock absorber L/H	1	\$ 560.50 <i>X</i>
10	Fog lamp cover L/H	1	\$ 188.50 <i>X</i>
11	Headlamp L/H	1	\$ 928.60 <i>X</i>
12	Steering rack	1	\$ 2,680.50 <i>X</i>
13	Front door side mirror	1	\$ 460.50 <i>cut</i> <i>✓</i>
14	Rear door L/H	1	\$ 1,160.00 <i>dd</i> <i>✓</i>
15	Rear door outer mounting L/H	1	\$ 198.00 <i>X</i> <i>an</i>
16	Front knuckle arm L/H	1	\$ 680.00 <i>X</i>
17	Front knuckle arm bearing L/H	1	\$ 488.50 <i>X</i>
18	Front driveshaft L/H	1	\$ 1,560.00 <i>X</i>
<u>S/NETT ITEMS</u>			
19	Front wheel rim R/H	1	\$ 880.00 <i>cut</i> <i>✓</i>
20	Front tyre R/H	1	\$ 350.00 <i>X</i> <i>an</i>

Yee Auto Pte Ltd

160 Sin Ming Dr, #02-17 Sin Ming Autocity Singapore 575722.
Mobile: 96874031 Tel: 64575768 Fax: 62528459
Reg. No: 201719251W GST No: 201719251W
Email: yeeautopteltd@gmail.com

QUOTATION

Annt: First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Date: 12/02/2018

Page 2

Vehicle No.: SKZ9336E

Model: Volkswagen Polo

No	Descriptions	Amount
	Labour Charges & Misc	
21	To dismantle & replaced damaged parts and panel beat where necessary.	\$ 1,400.00
22	To putty, apply primer & spray-paint on the affected portion.	\$ 1,600.00
23	To apply rust-primer on repaired, replaced panel.	\$ 150.00
24	To wheel alignment.	\$ 120.00
25	To remove/renew front undercarriage.	\$ 400.00
26	To check wiring functions.	\$ 180.00
SUB TOTAL		\$ 16,385.30
GST 7%		\$ 1,146.97
Total Amount		\$ 17,532.27

Yours faithfully,

Chan Kai Yee
Yee Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfer 97495749
WP
6 days
Lump sum
Resurvey after repair
26/2/18
sur@lkkauto.com

Note : All cheques must be crossed and made payable to YEE AUTO PTE LTD

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002125/T1qbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 05-06-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7428L	Veh. Inspected	SKZ 9336E
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18000909MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN POLO 1.2	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WVWZZZ6RZGU028464	Colour	RED
Odometer	22867	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	CONTINENTAL	6 mm
L/H Front Tyre	185/60 R15	CONTINENTAL	6 mm
R/H Rear Tyre	185/60 R15	CONTINENTAL	6 mm
L/H Rear Tyre	185/60 R15	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/01/2018	Inspection Date	06/02/2018
Survey held at	247 ALEXANDRA ROAD SINGAPORE 159934		
Repairer	YEE AUTO SERVICE		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 9336E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	820.00	-
8	FRONT BUMPER CLIP	NOT NECESSARY	50.00	-
1	FRONT BUMPER SIDE RETAINER L/H	NOT NECESSARY	87.60	-
1	FRONT BUMPER SIDE RETAINER R/H	NOT NECESSARY	87.60	-
1	FRONT FENDER L/H	DENTED	580.00	580.00
10	FRONT FENDER SPLASH SHIELD CLIP	NOT NECESSARY	60.00	-
1	FRONT FENDER SPLASH SHIELD L/H	NOT NECESSARY	235.00	-
1	FRONT LOWER ARM L/H	NOT NECESSARY	480.00	-
1	FRONT SHOCK ABSORBER L/H	NOT NECESSARY	560.50	-
1	FOG LAMP COVER L/H	NOT NECESSARY	188.50	-
1	HEADLAMP L/H	NOT NECESSARY	928.60	-
1	STEERING RACK	NOT NECESSARY	2,680.50	-
1	FRONT DOOR SIDE MIRROR	CUT	460.50	460.50
1	REAR DOOR L/H	DENTED	1,160.00	1,160.00
1	REAR DOOR OUTER MOUNTING L/H	NOT NECESSARY	198.00	-
1	FRONT KNUCKLE ARM L/H	NOT NECESSARY	680.00	-
1	FRONT KNUCKLE ARM BEARING L/H	NOT NECESSARY	488.50	-
1	FRONT DRIVESHAFT L/H	NOT NECESSARY	1,560.00	-
			11,305.30	2,200.50
SPECIAL NETT ITEMS				
1	FRONT WHEEL RIM R/H (SN)	CUT	880.00	880.00
1	FRONT TYRE R/H (SN)	NOT NECESSARY	350.00	-
			1,230.00	880.00
LABOUR				
TO DISMANTLE & REPLACED DAMAGED PARTS AND PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.			1,400.00	700.00
TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.			1,600.00	800.00
TO APPLY RUST-PRIMER ON REPAIRED, REPLACED PANEL.			150.00	40.00

Report Ref No. CS/FCI18002125/T1qbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WHEEL ALIGNMENT.	NOT NECESSARY	120.00	80.00
	TO REMOVE/RENEW FRONT UNDERCARRIAGE.		400.00	-
	TO CHECK WIRING FUNCTIONS.		180.00	30.00
			3,850.00	1,650.00
GRAND TOTAL			16,385.30	4,730.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,750.00

Report Ref No. CS/FCI18002125/T1qbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.