

INS CASE OWNER:

Clara

CC 4 / FWD 18002129

1 MKB3

LKK:

IDAC:

Surveyor:

MA CHEN Fook

DOI:

ASSIGNMENT

02/02/18

Date / Time:

01/02/18

Registered in Merimen:

02/02/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKO 765M

Name of Insured:

ZHOU YE NAN

Insured Tel No.:

HP: 9003 5791

Excess Sec II : S\$

D.O.A: 30/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

1201800001870

Policy No.:

PNPU 2017 - 00005472

Make / Model:

TOYOTA VIOS - 1.5 (A)

Place of Accident:

FARRER FLYOVER TWDS NORTH ROAD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SKO 4473R



INSRS:

WSP: VEMOGAN ALE

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

22/02/18 (Asst)

23/2/18

Email WSP Liability Clear.

23/3/18

FINE FROM TO TYPES TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RELIMINARY ADVICE Date/Time:

06/02/18

Sent By:

Shirley Hwee

FINALIZATION

Date/Time: 19/3/18

Confirm with: PUA

Confirm by: MCF

Repair Cost:

43

S\$3,450

(3 days) Reduction:

83 %

Email

Call

FINAL SETTLEMENT

Date/Time: 19/4/18

Confirm with: PUA

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

8/101

S\$3,156.50

OI: REPAIR ENDED TP.

Cost of Rental (LOR):

S\$ -

(days)

Cost of Use (LOU):

S\$300.00

(\$50 x 5 days)

Cost of Income (LOI):

S\$ -

(\$ x days)

OR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

ALTA Search

S\$200

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Total Cost

S\$ -

Total:

S\$3,458.50

Global Sum S\$:

FINAL PAYMENT

Date/Time: 19/4/18

Confirm with: PUA

Email

Call

Fee 1:

S\$3,458.50

Name 1:

VEMOGAN ALE PTE LTD

Fee 2: (Strike if N.A.)

S\$

Name 2:

Fee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

S\$500

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle / No

at Workshop / no

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

	
NS	OS
	

Sal. or Market Value: _____

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum. Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

SLD445R JUN 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Track / Trailer or

Name: HONOR VEZE 1496

Colour: Black R/O Insured: Std / Nil / NA

Se Reading: T/Folio Insured: Std / Nil / NA

Eng No

C No: R41112123.

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / G/Rim / STD A/Rim or

Tyre Size: F: 25/60 R16
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or DUN

Front: R/Rail mm L/Rail mm

Back: R/Rail mm L/Rail mm

D.O.A: 2/2/2018 2/2/2018

Survey held at

Des. of Damages: Frt (Rear) / O/S / NS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
-------------	----------------------

NOTE: NO KEY UPON SURVEY

45: +2,950 (RED: +13,711.76 82%)

☐ : Prelim. Report
☐ : Final Report

Days Of Repair

Resurvey No. of Trio

2000

Add Fee: ☐ \$

Table 1

Result Format

Lump Sum / 1.8 / 2

1. The first step in the process of developing a new product is to identify a market need. This involves conducting market research to determine what consumers want and need. Once a market need is identified, the next step is to develop a concept for a product that meets this need. 2. The second step is to develop a business plan for the new product. This plan should outline the company's goals, the target market, the competitive landscape, and the financial projections for the product. The business plan is a critical document that helps to secure funding and guide the development of the product. 3. The third step is to develop a prototype of the product. This involves creating a physical model of the product that can be used to test the concept and gather feedback from potential customers. The prototype is an important tool for refining the product and ensuring that it meets the needs of the market. 4. The fourth step is to conduct a pilot test of the product. This involves selling the product to a small group of customers and gathering feedback on their experience. The pilot test is a valuable tool for identifying any issues with the product and making improvements before a full-scale launch. 5. The final step is to launch the product into the market. This involves developing a marketing strategy to promote the product and reaching out to potential customers. The launch is a critical moment for the product, and it is important to ensure that it is well-received by the market.	1. The first step in the process of developing a new product is to identify a market need. This involves conducting market research to determine what consumers want and need. Once a market need is identified, the next step is to develop a concept for a product that meets this need. 2. The second step is to develop a business plan for the new product. This plan should outline the company's goals, the target market, the competitive landscape, and the financial projections for the product. The business plan is a critical document that helps to secure funding and guide the development of the product. 3. The third step is to develop a prototype of the product. This involves creating a physical model of the product that can be used to test the concept and gather feedback from potential customers. The prototype is an important tool for refining the product and ensuring that it meets the needs of the market. 4. The fourth step is to conduct a pilot test of the product. This involves selling the product to a small group of customers and gathering feedback on their experience. The pilot test is a valuable tool for identifying any issues with the product and making improvements before a full-scale launch. 5. The final step is to launch the product into the market. This involves developing a marketing strategy to promote the product and reaching out to potential customers. The launch is a critical moment for the product, and it is important to ensure that it is well-received by the market.
---	---



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CC4/FWD18002129/M1es3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986			Date : 02-02-2018	
			Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKD 7655M	Veh. Inspected	SLD 4478R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/01/2018	Inspection Date	02/02/2018	
Survey held at	VERMOGEN ACE PTE LTD 6 BENOI SECTOR S 629904			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 06 Feb 2018

Preliminary Advice

Insured Vehicle No	: SKD7655M	Accident Date	: 30/01/2018
TP Vehicle No	: SLD4478R	Assignment Date	: 02/02/2018
Make	: HONDA VEZEL	Est. Duration of Repair	: 3 days
Date of Inspection	: 02/02/2018		
Inspection At	: Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector Singapore 629904		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,661.76
Revised Amount	:S\$	3,763.68
Check Items (Estimated)	:S\$	116.00
Total	:S\$	3,879.68

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

SLD4478R

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : FWD

Vehicle Reg. No. : SLD4478R

OWN INSURER : AIG

Vehicle Reg. Date: 17-Jun-2016

CLAIM TYPE: TP

Make / Model : VEZEL 1.5X CVT ABS D/All

Date of Accident : 30/1/2018

Engine No. : L15B4032128

Chassis No. : RU11112123

COST OF CLAIMS

Parts Cost / List Items :	\$	14,389.70
---------------------------	----	-----------

Plus/Less	20%	\$	2,877.94
-----------	-----	----	----------

Total Cost / List : \$ 11,511.76

Special Nett Items :	\$	1,080.00
----------------------	----	----------

Total Parts Amount : \$ 12,591.76

Total Labour Amount :	\$	4,070.00
------------------------------	----	----------

Gross Total :	\$	16,661.76
----------------------	----	-----------

GST % :	7%	\$	1,166.32
---------	----	----	----------

Nett Amount : \$ 17,828.08

Surveyor Name and Company :

Date of survey :

Part by Part / Lump Sum : days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email :

Fax No :

HP No : _____

This claim is handled by : EDMOND

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD4478R**

Vehicle Reg. Date: **17/6/2016**

Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR**

Engine No. : **L15B4032128**

Chassis No. : **RU11112123**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	✓	\$1,860.00	MA	1100.905
2	1	Tailgate outer garnish	X	\$ 285.00	SWC	
3	1 set	Tailgate outer garnish clips	✓	\$ 40.00	REIT	
4	1	Tailgate logo	✓	\$ 52.00	ALAC	
5	1	Tailgate emblem "VEZEL"	✓	\$ 56.20	SWC	
6	2	Tailgate lamp LH/RH	✓	\$ 980.00	SWC	
7	2set	Tailgate lamp clips	✓	\$ 50.00	REIT	
8	1	Tailgate outer handle switch	✓	\$ 180.00	SWC	
9	2	Tailgate damper LH/RH	✓	\$ 424.00	REIT	
10	1	Tailgate wiper motor	✓	\$ 250.00	SWC	
11	1	Tailgate wiper blade	✓	\$ 75.00	SWC	
12	1	Tailgate buzzer	✓	\$ 150.00	REIT	
13	1	Tailgate inner handle	✓	\$ 74.00	SWC	
14	1	Tailgate inner lock	✓	\$ 245.00	REIT	
15	1	Tailgate lock sensor	X	\$ 220.00	SWC	
16	1	Tailgate striker	✓	\$ 32.00	SWC	
17	1	Tailgate trimboard	✓	\$ 295.00	SWC	
18	1 set	Tailgate trimboard clips	✓	\$ 45.00	REIT	
19	1	Tailgate weatherstrip	✓	\$ 145.00	SWC	
20	1 set	Tailgate windscreen moulding	✓	\$ 164.00	SWC	
21	2	Tail lamp LH/RH	✓	\$ 978.00	SWC	
22	1set	Tail lamp clips	✓	\$ 36.00	REIT	
23	1	Rear bumper	✓	\$ 950.00	REIT	885
24	1set	Rear bumper clips	✓	\$ 50.00	REIT	
25	2	Rear bumper retainer LH/RH	✓	\$ 144.00	REIT	
26	2	Rear bumper bracket LH/RH	✓	\$ 232.00	REIT	
27	2	Rear bumper reflector LH/RH	✓	\$ 334.00	NS SWC	05.00
28	2	Rear bumper cover LH/RH	✓	\$ 420.00	SWC	
29	1set	Rear bumper cover clips	✓	\$ 50.00	SWC	
30	2	Rear bumper cover retainer LH/RH	✓	\$ 84.00	SWC	
31	1	Rear end panel outer	✓	\$ 585.00	REIT	
32	1	Rear end panel inner	✓	\$ 396.00	REIT	
33	1	Rear end panel top garnish	✓	\$ 184.00	SWC	
34	1set	Rear end panel top garnish clips	✓	\$ 25.00	SWC	
35	1	Spare tyre panel	✓	\$ 1,230.00	SWC	
36	1	Spare tyre panel insulator	✓	\$ 240.00	REIT	
37	1	Spare tyre panel top board	✓	\$ 420.00	REIT	
38	1	Spare tyre tool tray	✓	\$ 430.00	SWC	
39	2	Rear fender inner trim LH/RH	✓	\$ 480.00	SWC	
40	2	Rear fender Air duct LH/RH	✓	\$ 150.00	SWC	

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD4478R**

Vehicle Reg. Date: **17/6/2016**

Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR**

Engine No. : **L15B4032128**

Chassis No. : **RU11112123**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Exhaust muffler	X	\$ 855.00	QW	
42	1	Exhaust muffler mounting	X	\$ 79.50	QW	
43	1	Exhaust muffler heat shield	X	\$ 165.00	QW	
44	2	Rear plate lamp LH/RH	X	\$ 250.00	QW	
45	1	Rear number plate with frame	X		\$ 50.00	QW
46	1	Tailgate windscreen sealant		QW	\$ 80.00	60
47	1	Tailgate windscreen inner seal		QW	\$ 80.00	40
48	1	Rear end panel sealant		QW	\$ 80.00	60
49	1	Reverse sensor		QW	\$ 300.00	2209104
50	1	Spare tyre panel sealant			\$ 80.00	X N/H
51	1	Spare tyre panel padding			\$ 350.00	X N/H
52	1	Sundries		QW	\$ 60.00	X
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To straighten and panel beating accident area. Rear Portion.	\$ 1,400.00	400
2	To putty,respray painting and polish accident area. Rear Portion.	\$ 1,600.00	400
3	To remove and transfer tailgate components.	\$ 150.00	60
4	To remove and refit tailgate windscreen.	\$ 150.00	120
5	To remove and refit reverse sensor.	\$ 120.00	60
6	To rust proof affected areas.	\$ 250.00	70
7	To check and rectify wiring after disconnect and connect.	\$ 100.00	20
8	To remove and refit interior parts to give way the repair.	\$ 150.00	X
9	To remove and aligned exhaust pipe.	\$ 150.00	X
	Vlat Aultken U/S Repair After part place wkb Bengamun 22/2018. 3 wday 1		

Vlat Aulken
45 Regner
After put place
web design
27/2018
3 wday

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance



SLD4478R

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : FWD
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 30/1/2018

Vehicle Reg. No. : SLD4478R
Vehicle Reg. Date: 17-Jun-2016
Make / Model : VEZEL 1.5X CVT ABS D/All
Engine No. : L15B4032128
Chassis No. : RU11112123

COST OF CLAIMS

Parts Cost / List Items : \$ 14,389.70
Plus/Less 20% \$ 2,877.94
Total Cost / List : \$ 11,511.76
Special Nett Items : \$ 1,080.00
Total Parts Amount : \$ 12,591.76
Total Labour Amount : \$ 4,070.00
Gross Total : \$ 16,661.76
GST % : 7% \$ 1,166.32
Nett Amount : \$ 17,828.08

Surveyor Name and Company :

Date of survey : _____

Part by Part / Lump Sum : _____ days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : _____

Fax No : _____

HP No : _____

This claim is handled by : EDMOND

P = 3519.20
- 20%
2815.36
SL = 380
L = 1090
4285.36
- 20%
3428.29
L/S = 3400

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD4478R**

Vehicle Reg. Date: **17/6/2016**

Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR**

Engine No. : **L15B4032128**

Chassis No. : **RU11112123**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	✓	\$ 1,860.00	OK	
2	1	Tailgate outer garnish	X	\$ 285.00	OK	
3	1 set	Tailgate outer garnish clips	X	\$ 40.00	OK	
4	1	Tailgate logo	X	\$ 52.00	OK	
5	1	Tailgate emblem "VEZEL"	✓	\$ 56.20	OK	
6	2	Tailgate lamp LH/RH	✓	\$ 980.00	OK	
7	2set	Tailgate lamp clips	X	\$ 50.00	OK	
8	1	Tailgate outer handle switch	X	\$ 180.00	OK	
9	2	Tailgate damper LH/RH	X	\$ 424.00	OK	
10	1	Tailgate wiper motor	X	\$ 250.00	OK	
11	1	Tailgate wiper blade	X	\$ 75.00	OK	
12	1	Tailgate buzzer	✓	\$ 150.00	OK	
13	1	Tailgate inner handle	X	\$ 74.00	OK	
14	1	Tailgate inner lock	✓	\$ 245.00	OK	
15	1	Tailgate lock sensor	X	\$ 220.00	OK	
16	1	Tailgate striker	X	\$ 32.00	OK	
17	1	Tailgate trimboard	X	\$ 295.00	OK	
18	1 set	Tailgate trimboard clips	X	\$ 45.00	OK	
19	1	Tailgate weatherstrip	✓	\$ 145.00	OK	
20	1 set	Tailgate windscreen moulding	✓	\$ 164.00	OK	
21	2	Tail lamp LH/RH	X	\$ 978.00	OK	
22	1set	Tail lamp clips	X	\$ 36.00	OK	
23	1	Rear bumper	✓	\$ 950.00	OK	
24	1set	Rear bumper clips	✓	\$ 50.00	OK	
25	2	Rear bumper retainer LH/RH	X	\$ 144.00	OK	
26	2	Rear bumper bracket LH/RH	X	\$ 232.00	OK	
27	2	Rear bumper reflector LH/RH	X	\$ 334.00	OK	
28	2	Rear bumper cover LH/RH	X	\$ 420.00	OK	
29	1set	Rear bumper cover clips	X	\$ 50.00	OK	
30	2	Rear bumper cover retainer LH/RH	X	\$ 84.00	OK	
31	1	Rear end panel outer	X	\$ 585.00	OK	
32	1	Rear end panel inner	X	\$ 396.00	OK	
33	1	Rear end panel top garnish	X	\$ 184.00	OK	
34	1set	Rear end panel top garnish clips	X	\$ 25.00	OK	
35	1	Spare tyre panel	X	\$ 1,230.00	OK	
36	1	Spare tyre panel insulator	X	\$ 240.00	OK	
37	1	Spare tyre panel top board	X	\$ 420.00	OK	
38	1	Spare tyre tool tray	X	\$ 430.00	OK	
39	2	Rear fender inner trim LH/RH	X	\$ 480.00	OK	
40	2	Rear fender Air duct LH/RH	X	\$ 150.00	OK	

P= 3519.20

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD4478R**

Vehicle Reg. Date: **17/6/2016**

Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD SDR**

Engine No. : **L15B4032128**

Chassis No. : **RU11112123**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Exhaust muffler	X	\$ 855.00	SM	
42	1	Exhaust muffler mounting	X	\$ 79.50	SM	
43	1	Exhaust muffler heat shield	X	\$ 165.00	SM	
44	2	Rear plate lamp LH/RH	X	\$ 250.00	SM	
45	1	Rear number plate with frame	X		\$ 50.00	SM
46	1	Tailgate windscreen sealant		SM	\$ 80.00	60
47	1	Tailgate windscreen inner seal		SM	\$ 80.00	60
48	1	Rear end panel sealant			\$ 80.00	60
49	1	Reverse sensor			\$ 300.00	2209124
50	1	Spare tyre panel sealant			\$ 80.00	X 2211F
51	1	Spare tyre panel padding			\$ 350.00	X 2211F
52	1	Sundries			\$ 60.00	X
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

SN = 380

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]
$$L = 1090$$



Vermogen ACE Pte Ltd

1 Bukit Batok Crescent
#05-23 Wega Plaza
Singapore 658064
Co. Reg No.: 201606023C GST Reg No.: 201606023C
Tel: 6694 4919 Fax: 6694 4929
Email: vermogenace@gmail.com

Yr Ref : SKD7655M

Our Ref : SLD4478R

19 MARCH 2018

Without Prejudice

Attn: Motor Claim Dept

FWD SINGAPORE PTE LTD

6 Temasek Boulevard,
#18-01 Suntec Tower 4
Singapore 038986

Dear Sir/Mdm,

Accident involving SLD4478R & SKD7655M on 30/01/2018 19:45 hrs at FARRER FLYOVER

We refer to the above said accident.

As instructed, we are claiming the following as stated below:-

1. Cost of repair	\$	3,156.50
2. Loss of use (\$100 x 8 days)	\$	800.00
3. GIA search fee	\$	2.00
Total	\$	3,958.50

We enclosed herewith relevant document as stated below:-

1. Accident report
2. Final Repair Bill
3. Letter of authority
4. GIA search receipt

- We do not have the survey report and photographs as our client's motor vehicle was surveyed by your appointed surveyor.

Please kindly let us know whether you are prepared to settle our client's claim & we look forward to hear from you soonest.

Thank you.

Best Regards,



Pila (Claim Dept)

Vermogen ACE PTE LTD

Tel: 6358 3031 | Fax: 6694 4929

Email: pila.vermogenace@gmail.com



Vermogen ACE Pte Ltd
1 BUKIT BATOK CRESCENT #05-23 WCEGA PLAZA 5(658064)
TEL : 6594 4919 FAX : 6594 4929
Email : vermogenace@gmail.com
REG No : 201606023C

LETTER OF AUTHORITY & INDEMNITY

**ACCIDENT INVOLVING VEHICLE NO. SLD4478R &
SKD7655M ON 31 JAN 2018/1945HRS
AT FARRER FLYOVER.**

I/We **LCRF PTE LTD** UEN/NRIC NO. **201624597K** owner of Vehicle No. **SLD4478R**, hereby authorise M/S Vermogen ACE Pte Ltd to commence repairs to my vehicle and to forward the claim for damages sustained in the above accident to the third party driver and /or his employer and /or the vehicle owner and /or the insurer concerned. I/We agree that in consideration of you giving up your repairer's lien, I/We agree to assign the whole proceeds of my/our third party claim to you and if applicable, our solicitors (to be appointed by you on my / our behalf) shall accept this as my /our irrevocable authority to pay the amount compensated direct to you after deduction of their costs on a solicitor & client basis. I/We undertake to co-operate fully with you and our solicitors to see the claim to a successful conclusion.

If third party driver and and/or his employer and/or the vehicle owner and/or insurer reject liability, I/We will fully be responsible for the repair costs and other incidentals.

I/We also authorise you to sign all discharge vouchers/indemnity forms and all necessary paper in connection with the above claim in my/our absence.

I/We authorise you to appoint such a firm of solicitors on my/our behalf as you shall deem fit for the purpose of the third party/own insurer's claim.

I/We undertake to inform you and/or the solicitors appointed by you on my/our behalf in the event of the third party's insurance company communicate with me/us directly by telephone or in writing and I/We further undertake not to accept any monies or offer of settlement from the third party's insurers without first communicating with you.

My/our vehicle is repaired by the repairer on my/our will without any inducement, threat and/or promise.

In the event that the repairer is compelled to enforce this undertaking, I/We agree that I/shall pay for the legal costs incurred by the repairer on a solicitor and client's full indemnity basis.

Owner Signature
(Company Stamp if applicable)

RELEASE

Claim Reference:	1201800001870
Surveyor's Reference:	CC4/FWD18002129/M1eb3
TP Reference:	SLD 4478R

We, **VERMOGEN ACE PTE LTD** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **SLD 4478R** ("Vehicle") to accept the sum of **\$3,458.50**, being the amount claimed for **\$3,156.50** (repair costs), **\$300.00** (loss of rental/ use), **\$ -** (loss of income), **\$2.00** (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **30/01/2018** (date of accident) at / along **FARRER FLYOVER** (location) involving vehicle no/s. **SLD 4478R** and **SKD 7655M**.

This is pursuant to the inspection conducted on **02/02/2018** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SKD 7655M** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 19 day of April 2018

CLAIMANT

VERMOGEN ACE

Vermogen ACE Pte Ltd
[Signed by the "Workshop" with Co. Stamp]
Singapore 653354 Tel: 66944919 Fax: 66944929
For and on behalf of the "Claimant"



MCF

[FWD's appointed surveyor with Co. Stamp]
For and on behalf of FWD Singapore Pte. Ltd.



Vermogen ACE Pte Ltd
1 BUKIT BATOK CRESCENT #05-23
WCEGA PLAZA S(658064)
TEL : 6694 4919 FAX : 6694 4929
CO. & GST REG NO : 201606023C

Tax Invoice: 18994

FWD Singapore Pte Ltd.

6 Temasek Boulevard #18-01 Suntec Tower 4
Singapore 038986

Tel: +65 6727 5700 Fax: +65 6727 5799

Attn: Motor Claims Dept

Bill Date: 19/03/2018

Vehicle No: SLD4478R

Vehicle Model: HONDA VEZEL

Date of Accident: 30/01/2018

Claim No:

S/N	QTY	Descriptions	Unit Price	Amount S\$
1		Lumpsum repair		2950.00

E. & O.E.

Total	S\$	2950.00
GST 7%	S\$	206.50
Amount Due	S\$	3156.50


for Vermogen ACE Pte Ltd


**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-017018

Date of Request: 31/01/2018

Your Ref No:

Online Purchase

Vermogen Ace Pte Ltd
1 Bukit Batok Crescent, #04-54/55 WCEGA Plaza
Singapore 658064

Dear Sir/Madam,

Enquiry Date 31/01/2018
Enquiry By Nur Asyira Binte AB Rahman
TP Vehicle No. SKD7655M
Accident Date 30/01/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Feb 2018 Edit Reg		02 Feb 2018 00:00 Edit Adj Rpt	S\$2,950.00 Edit Estimates	S\$2,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Zhuo Yi'Nan , ID: S8136863E								
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLD4478R	Date of Loss:	30/01/2018 00:00 - :59 [19 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800001870	Policy/Cover Note No.:	PNPV2017-00005472 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKD7655M	Policy No. (Claimant):	999995065						
		Excess:	S\$500.00						
Repairer:	Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector, 629904 Jurong West - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 13/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (09/04/2018): Alert - Adj Mandate Approved (S\$3458.50) - SLD4478R - Claim Handler: Clara Li Zi...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD4478R (1201800001870)
[SKD7655M]
TP
LCRF PTE LTD
Jan 30 2018 12:00AM
[Zhuo Yi'Nan]
Vermogen Ace Pte Ltd (benoi)

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Assessment Reports			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/02/18 11:51	Adjuster Immediate Advice	Load HTML	
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/03/18 11:21	General View	Load JPG	☒
2	19/03/18 11:21	General View	Load JPG	☒
3	19/03/18 11:21	General View	Load JPG	☒
4	19/03/18 11:21	General View	Load JPG	☒
5	19/03/18 11:21	General View	Load JPG	☒
6	19/03/18 11:21	General View	Load JPG	☒
7	19/03/18 11:21	General View	Load JPG	☒
8	19/03/18 11:21	General View	Load JPG	☒
9	19/03/18 11:21	General View	Load JPG	☒
10	19/03/18 11:21	General View	Load JPG	☒
11	19/03/18 11:21	General View	Load JPG	☒
12	19/03/18 11:21	General View	Load JPG	☒
13	19/03/18 11:21	General View	Load JPG	☒
14	19/03/18 11:21	General View	Load JPG	☒
15	19/03/18 11:21	General View	Load JPG	☒
16	19/03/18 11:21	General View	Load JPG	☒
17	19/03/18 11:21	Reinspection Photo	Load JPG	☒
18	19/03/18 11:21	Reinspection Photo	Load JPG	☒
19	19/03/18 11:21	Reinspection Photo	Load JPG	☒
20	19/03/18 11:21	Reinspection Photo	Load JPG	☒
Documentation			1 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 16:52	EMAIL FROM FWD DD 01.02.2018	Load PDF	
2	02/02/18 16:52	ACKNOWLEDGEMENT EMAIL TO FWD DD 01.02.2018	Load PDF	
3	02/02/18 16:52	TP GIA REPORT	Load PDF	
4	06/02/18 11:56	TP ESTIMATE- MARKED	Load PDF	
5	02/04/18 11:16	WORKSHOP INVOICE	Load PDF	
6	02/04/18 11:16	GIA SEARCH	Load PDF	
7	02/04/18 11:16	LOD	Load PDF	
8	07/05/18 14:24	Release Voucher	Load PDF	
9	07/05/18 14:24	AUTHORISATION TO ACT FORM	Load PDF	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	21/02/18 17:13	OI GIA Report		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKD7655M (Insd veh)	Model:	HONDA VEZEL 1.5 CVT ABS
	SLD4478R (TP veh)		D/AIRBAG 2WD 5DR (A)
Date of Accident:	30/01/2018		

Global Sum Settlement	: [] Yes	[X] No	
Repair Estimate	: \$		17,828.08
Final Repair Cost	: \$		3,156.50
Loss of Use	: \$		600.00
			6.00 days at \$100.00 per day
Rental (if any)	: \$		0.00
			days
LTA / GIA Search Fee	: \$		2.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		3,758.50

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Vermogen Ace Pte Ltd	: \$	3,758.50
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

07 May
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18002129/M1EB3Q2

Date: 07/05/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00005472

Claimant Vehicle No: SLD4478R Insured Vehicle No: SKD7655M

Date of Loss: 30/01/2018 Nature of Claim: TP Claim No: 1201800001870

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD4478R**

Make & Model: HONDA VEZEL, 1.5 CVT ABS D/AIRBAG 2WD 5DR (A) Engine No: L15B4032128

Reg. Date: 17/06/2016 (Man. Year: 2015) Chassis No: RU11112123

Colour: Black Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,591.76	2,621.68	9,970.08	79.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	1,090.00	2,980.00	73.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,661.76	3,711.68	12,950.08	77.72
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	16,661.76	2,950.00	13,711.76	82.29
+ GST 7.00/7.00% (S\$)	1,166.32	206.50	959.82	82.29
Nett Amount (S\$)	17,828.08	3,156.50	14,671.58	82.29
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,758.50		

INSPECTION

Date of Assignment: 02/02/2018

Date Inspected: 02/02/2018 Inspected At:

Vermogen Ace Pte Ltd (benoi) (HQ)
6 Benoi Sector
Singapore 629904

Estimated Period of Repair: 3.0 days

Adjuster: MA CHIN FOOK

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2018)	
Parts: 144	HONDA VEZEL 1.5 CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLD4478R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,860.00 FL	*1,100.90 FL
2	1		*TAILGATE OUTER GARNISH	Serviceable	285.00 FL	*- FL
3	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
4	1		*TAILGATE LOGO	Not Necessary	52.00 FL	*- FL
5	1		*TAILGATE EMBLEM VEZEL	Necessary	56.20 FL	*56.20 FL
6	2		*TAILGATE LAMP LH/RH	Serviceable	980.00 FL	*- FL
7	2		*SET TAILGATE LAMP CLIPS	Not Necessary	50.00 FL	*- FL
8	1		*TAILGATE OUTER HANDLE SWITCH	Serviceable	180.00 FL	*- FL
9	2		*TAILGATE DAMPER LH/RH	Serviceable	424.00 FL	*- FL
10	1		*TAILGATE WIPER MOTOR	Serviceable	250.00 FL	*- FL
11	1		*TAILGATE WIPER BLADE	Serviceable	75.00 FL	*- FL
12	1		*TAILGATE BUZZER	No such part	150.00 FL	*- FL
13	1		*TAILGATE INNER HANDLE	Serviceable	74.00 FL	*- FL
14	1		*TAILGATE INNER LOCK	Bent	245.00 FL	*245.00 FL
15	1		*TAILGATE LOCK SENSOR	Serviceable	220.00 FL	*- FL
16	1		*TAILGATE STRIKER	Serviceable	32.00 FL	*- FL
17	1		*TAILGATE TRIMBOARD	Serviceable	295.00 FL	*- FL
18	1		*SET TAILGATE TRIMBOARD CLIPS	Not Necessary	45.00 FL	*- FL
19	1		*TAILGATE WEATHERSTRIPE	Serviceable	145.00 FL	*- FL
20	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	164.00 FL	*164.00 FL
21	2		*TAIL LAMP LH/RH	Serviceable	978.00 FL	*- FL
22	1		*SET TAIL LAMP CLIPS	Not Necessary	36.00 FL	*- FL
23	1		*REAR BUMPER	Deformed	950.00 FL	*885.00 FL
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*40.00 FL
25	2		*REAR BUMPER RETAINER LH/RH	Distorted /Necessary	144.00 FL	*144.00 FL
26	2		*REAR BUMPER BRACKET LH/RH	Repair	232.00 FL	*- FL
27	1		*REAR BUMPER REFLECTOR LH/RH	N/S Serviceable / O/S Cracked	334.00 FL	*167.00 FL
28	2		*REAR BUMPER COVER LH/RH	Serviceable	420.00 FL	*- FL
29	1		*SET REAR BUMPER COVER CLIPS	Serviceable	50.00 FL	*- FL
30	2		*REAR BUMPER COVER RETAINER LH/RH	Serviceable	84.00 FL	*- FL
31	1		*REAR END PANEL OUTER	Repair	585.00 FL	*- FL
32	1		*REAR END PANEL INNER	Repair	396.00 FL	*- FL
33	1		*REAR END PANEL TOP GARNISH	Serviceable	184.00 FL	*- FL
34	1		*SET REAR END PANEL TOP GARNISH CLIPS	Serviceable	25.00 FL	*- FL
35	1		*SPARE TYRE PANEL	Serviceable	1,230.00 FL	*- FL
36	1		*SPARE TYRE PANEL INSULATOR	Not Necessary	240.00 FL	*- FL
37	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	420.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*SPARE TYRE TOOL TRAY	Serviceable	430.00 FL	*- FL
39	2		*REAR FENDER INNER TRIM LH/RH	Serviceable	480.00 FL	*- FL
40	2		*REAR FENDER AIR DUCT LH/RH	Serviceable	150.00 FL	*- FL
41	1		*EXHAUST MUFFLER	Serviceable	855.00 FL	*- FL
42	1		*EXHAUST MUFFLER MOUNTING	Serviceable	79.50 FL	*- FL
43	1		*EXHAUST MUFFLER HEAT SHIELD	Serviceable	165.00 FL	*- FL
44	2		*REAR PLATE LAMP LH/RH	Serviceable	250.00 FL	*- FL
45	1		*REAR NUMBER PLATE WITH FRAME	Serviceable	50.00 FS	*- FS
46	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
47	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
48	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
49	1		*REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
50	1		*SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
51	1		*SPARE TYRE PANEL PADDING	Not Necessary	350.00 FS	*- FS
52	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$) 15,469.70 3,182.10
 - List Item Discount on L Items 20.00/20.00% (\$\$) 2,877.94 560.42

Total Parts (\$\$) 12,591.76 2,621.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA,REAR PORTION	New	1,400.00	400.00
2	TO PUTTY ,RESPRAY PAINTING AND POLISH ACCIDENT AREA .REAR PORTION	New	1,600.00	400.00
3	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
4	TO REMOVE AND REFIT TAILGATE WINDSCREEN	New	150.00	120.00
5	TO REMOVE AND REFIT REVERSE SENSOR	New	120.00	60.00
6	TO RUST PROOF AFFECTED AREAS	New	250.00	20.00
7	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	30.00
8	TO REMOVE AND REFIT INTERIOR PARTS TO GIVE WAY THE REPAIR	New	150.00	0.00
9	TO REMOVE AND ALIGNED EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			4,070.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >