



SLD4478R

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : FWD

OWN INSURER : AIG

CLAIM TYPE : TP

Date of Accident : 30/1/2018

Vehicle Reg. No. : SLD4478R

Vehicle Reg. Date: 17-Jun-2016

Make / Model : VEZEL 1.5X CVT ABS D/AH

Engine No. : L15B4032128

Chassis No. : RU11112123

COST OF CLAIMS

Parts Cost / List Items : \$ 14,389.70

Plus/Less 20% \$ 2,877.94

Total Cost / List : \$ 11,511.76

Special Nett Items : \$ 1,080.00

Total Parts Amount : \$ 12,591.76

Total Labour Amount : \$ 4,070.00

Gross Total : \$ 16,661.76

GST % : 7% \$ 1,166.32

Nett Amount : \$ 17,828.08

Surveyor Name and Company :

Date of survey : _____

Part by Part / Lump Sum : _____ days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : _____

Fax No : _____

HP No : _____

This claim is handled by : EDMOND

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD4478R**

Vehicle Reg. Date: **17/6/2016**

Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR**

Engine No. : **L15B4032128**

Chassis No. : **RU11112123**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	✓	\$1,860.00	dt	1100.90
2	1	Tailgate outer garnish	x	\$ 285.00	src	
3	1 set	Tailgate outer garnish clips	x	\$ 40.00	relnd	
4	1	Tailgate logo	x	\$ 52.00	relnd	
5	1	Tailgate emblem "VEZEL"	✓	\$ 56.20	new	
6	2	Tailgate lamp LH/RH	x	\$ 980.00	src	
7	2set	Tailgate lamp clips	x	\$ 50.00	relnd	
8	1	Tailgate outer handle switch	x	\$ 180.00	src	
9	2	Tailgate damper LH/RH	x	\$ 424.00	src	
10	1	Tailgate wiper motor	x	\$ 250.00	src	
11	1	Tailgate wiper blade	x	\$ 75.00	src	
12	1	Tailgate buzzer	x	\$ 150.00	new	
13	1	Tailgate inner handle	x	\$ 74.00	src	
14	1	Tailgate inner lock	✓	\$ 245.00	relnd	
15	1	Tailgate lock sensor	x	\$ 220.00	src	
16	1	Tailgate striker	x	\$ 32.00	src	
17	1	Tailgate trimboard	x	\$ 295.00	src	
18	1 set	Tailgate trimboard clips	x	\$ 45.00	relnd	
19	1	Tailgate weatherstrip	✓	\$ 145.00		
20	1 set	Tailgate windscreen moulding	✓	\$ 164.00	new	
21	2	Tail lamp LH/RH	x	\$ 978.00	src	
22	1set	Tail lamp clips	x	\$ 36.00	relnd	
23	1	Rear bumper	✓	\$ 950.00	det	
24	1set	Rear bumper clips	✓	\$ 50.00	relnd	
25	2	Rear bumper retainer LH/RH	✓	\$ 144.00	src/relnd	
26	2	Rear bumper bracket LH/RH	x	\$ 232.00	src	
27	2	Rear bumper reflector LH/RH	✓	\$ 334.00	NS src	09 org
28	2	Rear bumper cover LH/RH	x	\$ 420.00	src	
29	1set	Rear bumper cover clips	x	\$ 50.00	src	
30	2	Rear bumper cover retainer LH/RH	x	\$ 84.00	src	
31	1	Rear end panel outer	x	\$ 585.00	relnd	
32	1	Rear end panel inner	x	\$ 396.00	relnd	
33	1	Rear end panel top garnish	x	\$ 184.00	src	
34	1set	Rear end panel top garnish clips	x	\$ 25.00	src	
35	1	Spare tyre panel	x	\$ 1,230.00	src	
36	1	Spare tyre panel insulator	x	\$ 240.00	relnd	
37	1	Spare tyre panel top board	x	\$ 420.00	relnd	
38	1	Spare tyre tool tray	x	\$ 430.00	src	
39	2	Rear fender inner trim LH/RH	x	\$ 480.00	src	
40	2	Rear fender Air duct LH/RH	x	\$ 150.00	src	

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD4478R**

Vehicle Reg. Date: **17/6/2016**

Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD SDR**

Engine No. : **L15B4032128**

Chassis No. : **RU11112123**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Exhaust muffler	X	\$ 855.00	SM	
42	1	Exhaust muffler mounting	X	\$ 79.50	SM	
43	1	Exhaust muffler heat shield	X	\$ 165.00	SM	
44	2	Rear plate lamp LH/RH	X	\$ 250.00	SM	
45	1	Rear number plate with frame	X		\$ 50.00	SM
46	1	Tailgate windscreen sealant		SM	\$ 80.00	60
47	1	Tailgate windscreen inner seal		SM	\$ 80.00	60
48	1	Rear end panel sealant			\$ 80.00	60
49	1	Reverse sensor			\$ 300.00	2209104
50	1	Spare tyre panel sealant			\$ 80.00	X N/H
51	1	Spare tyre panel padding			\$ 350.00	X N/H
52	1	Sundries			\$ 60.00	X
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledgments: _____
Signature: _____
Date: _____