

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Li Zi Rong

Date: 13 Feb 2018

## **Preliminary Advice**

Insured Vehicle No : SGR4701G

TP Vehicle No : SLL3208T

Make : MAZDA 6

Date of Inspection : 08/02/2018

Inspection At : Trans Eurokars Pte Ltd  
No. 5 Ubi Close, Singapore  
Singapore 408605

Accident Date : 01/02/2018

Assignment Date : 02/02/2018

Est. Duration of Repair : 3 days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....O/S.... portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 3,988.84 |
| Revised Amount              | :S\$ | 2,542.88 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 2,542.88 |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.