



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



FWD Singapore Pte Ltd 6 Temasek Boulevard, #18-01 Suntec Tower 4, Singapore 038986		NAME : Mr Wong Chok (Tee)		WIP : 60629	
ATTN : MOTOR CLAIMS		ADDRESS : 851 Jurong West Street 81 #13-287 Singapore 640851		EXCESS : 2-Feb-18	
FAX :		TEL : 81274541		DATE :	
VEH NO :	SLL3208T	DATE IN :		Signature :	RONALD 6395 7875
CHASSIS NO :	JM6GL1071H0108526	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6 2L EXECUTIVE	DATE REG.:	21-Feb-17	POLICY NO.:	

Let Auto Consultants hence notify the insurer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	RHS SIDE MIRROR ASSY / <i>Cut</i> 1	MGS89-69-121A	\$ 453.20
3	LAMP(RHS), SIDE TURN / <i>Cut</i> 1	MB63B-69-122A	\$ 81.70
4	SEAL(RHS), SIDE MIRROR / <i>M6L</i> 1	MGHP9-69-115	\$ 12.60
5	GARNISH(RHS), SIDE MIRROR X <i>Yuan</i> 1	MGHP9-69-15YB	\$ 43.00
6	CHROME(RHS), FRONT DOOR X 1	MGHP9-50-640E	\$ 91.40
7	COVER(RHS), SIDE MIRROR / <i>Cut</i> 1	MB63B-69-1N1 53	\$ 105.70
TOTAL PARTS			\$ 787.60
LESS 10%			\$ 78.76
TOTAL PARTS COST			\$ 708.84

Labour Description

1	TO REPLACE RHS SIDE MIRROR ASSY. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	<i>660</i>	\$ 1,320.00
2	TO RESPRAY RHS SIDE MIRROR AND RHS FRONT FENDER.	<i>945</i>	\$ 1,260.00
4	MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>150</i>	\$ 250.00
5	MZ-BR-REPROG TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	<i>180</i>	\$ 350.00
6	MZ-BR-SUNDRI SUNDRIES.	<i>20</i>	NETT \$ 100.00

*3 Days .
 before paint photos .
 Gue Qing
 08/2/18*

TOTAL LABOUR	\$ -	\$ 3,280.00
TOTAL PARTS	\$ -	\$ 708.84
TOTAL	\$ -	\$ 3,988.84
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -

GRAND TOTAL	\$	-	\$	-
-------------	----	---	----	---

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature