

ASS. REC. BY:

REF: CS/AIG18002134/Ktd3et

Special Instruction:

Surveyor:
Mehmen

Kenneth

ASSIGNMENT (Office)

From (Person): chan kian-chuen

of

AIG

Date/Time:

2/2/18 @ 1:45 pm

Estimated Cost:

Bill to:

① OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLQ 3210J

Insured:

at Workshop m/s

Tong Luck Auto

Tel:

6250 088

of

160 Sin Ming Drive #07-01/06

Policy No.:

999995730

Claim No.:

3515546991SG

Sum Insured:

Excess:

TBA \$1000/-

Make of Veh:

(Client's Record)

D.O.A.

22/01/2018

CA / (REV)

REP. / REV 24 HRS

05/2/18 @ Morning

H.O.D. Endorsement:

Date/Time:

2/2/18 @ 1:45 pm

Person Contacted:

Candy

Vehicle: IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SLQ 3210J - CS/AIG17014232/M11bs?

D.O.A. 2/2/17

Part by Part \$6227.05.

(Red: 2200.35 : 26%)

Date: 5/2/18
 Estimated Cost:
 CD: TRWS TRRES CDRES EVA INTV M
 To: recipient vehicle SLQ 3210J
 at: location of the Tong Luek Auto
 or: 160 Sin Ming Drive #07-01/06
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess: TBA
 Claims Record: Moming
 Make of VEH:
 Policy Condition:
 Remarks: The veh had commenced its repair at the time of inspection.
 Bailor's Market Value: \$196K
 DAD Accident Report: Consistent? Yes or No
 G/A Rep Seen: Consistent? Yes or No
 Est Repairs: 04 days Rep: Yes or No
 Last Sum: 1.2/ Rep: 3 Val: Yes or No
 CA: (REV) REP: 24 HRS
 Date: Person Contacted: Vehicle IN/OUT:

SLQ 3210J 0717
 The Vehicle is to be Evaluated by To: Police Officer
 Truck Trailer:
 Make: Mr E200 1991
 Colour: M. Brown Insured: Std N/A
 Seating: 8P54 Insured: Std N/A
 Eng No:
 Ch No: W00 2130422A 212860
 Gen Cond: Good Fair Poor Burnt
 Steering: Incl Jammed Leaked Burnt or
 Brake: Incl Jammed Leaked Burnt or
 Mod: N/A S/Rom: STD N/A
 Tyre Size: F: 245/45R18
 R: 275/40R18
 BS/DUN EXNOVA G+ FS UZA MC OHTSU RIR SUN
 TOYO/YOKO or
 Front: Rear:
 R/Ba: 9 --- R/Ba: 9 ---
 L/Ba: 9 --- L/Ba: 9 ---
 D/OA: 22/1/18 D/O: 5/2/18
 Survey noted:
 Des. of Damages: Fr. Rear: O/S N/S U/O Roof: or
 015 Rm
 The U/O Chassis frame Body Structure affected due to collision

Date	Time	Action	Remarks
6/2		File pass to Catherine	

05-02-18: Informed Candy can authorize repair.

RECEIVED 10/10/2000

23/3 Typist ☐ Prel. Report
☒ Final Report

Days Of Repair: _____
Resurvey No. of Trs: _____

Adm. Fee: ☐ \$100 ☐ \$200 ☐ \$300 ☐ \$400 ☐ \$500 ☐ \$600 ☐ \$700 ☐ \$800 ☐ \$900 ☐ \$1000

OD
6227.05

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jan 2018		02 Feb 2018 13:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z, Tel: +6590000000		
Vehicle Reg. No.:	SLQ3210J	Date of Loss:	22/01/2018 10:00 - :59
Claim Type:	OD / 3515546991SG	Policy/Cover Note No.:	999995730 (Comprehensive)
		Excess:	
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Chuan] Kian-Chuan.Chan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/02/2018]		
Driver/Custodian:	KU CHEE YNG (40 / Male), NRIC: S7707488J, Tel: +6596918787		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your password will expire in 9 days. [Click here to change it.](#)

- OD - SLQ3210J

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 2/2/2018 1:47:50 PM
Attachments:  [SLQ3210J-Estimate.pdf](#)

Hi LKK,

Kindly assist to survey, vehicle in.
Case assigned to you in Merimen.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18002134/Ktd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 02-02-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLQ 3210J
Policy No.	999995730	Coverage (\$)	0.00
Claim No.	3515546991SG	Excess (\$)	0.00
Assign From	MERIMEN (CHAN KIAN CHUAN)	Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/01/2018	Inspection Date	
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.Z.400

COMPREHENSIVE MOTOR

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$1000.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

CERTIFICATE NO. 999994844/100828555-00000

SUM INSURED S\$1.00

INSURING WITH COE/PAF Yes

SLQ3210J

Daimler Fleet Management Singapore Pte Ltd

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

01 Jan 2018

4) DATE OF EXPIRY OF INSURANCE

31 Dec 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person who is driving on the Insured's order or with their permission.

Please refer to policy terms and conditions.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use for the carriage of passengers or goods in connection with the Insured's business. Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.

The Policy does not cover: 1) Use for tuition, driving test, racing, pace-making, reliability trial or speed-testing. 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle. 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired. 4) Use for any purpose in connection with the Motor Trade.

SOLE AGENT'S WORKSHOP: For new vehicles less than 3 years from initial registration, you have the option for claims-related repairs to be done at Sole Agent's workshop.

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

1. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118)
2. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
3. Ethoz - 30 Bukit Batok Cres (Tel: 66547777)
4. DPS Body & Paint (Subsidiary of C&C) - 209 Pandan Gardens (Tel: 65684501)
5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)
6. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)
7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)
8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)
9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Not Included

* NAMED DRIVER NA

HIRE PURCHASE COMPANY NA

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 24 Jan 2018


AIG Asia Pacific Insurance Pte. Ltd.

030023-000
JARDINE LLOYD THOMPSON PTE LTD
138 MARKET STREET
#07-01 CAPITAGREEN
SINGAPORE 048946

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPIUS



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2018 19:55
Date Of Accident	22/01/2018 10:00
Exact Location Of Accident	114 LAVENDER STREET CITY HUB 2 MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ3210J
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96918787

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 EXCLUSIVE (R18 LED)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995730
Cover Note Number	N.A.

Driver

Name of Driver	KU CHEE YNG
NRIC No	S7707488J
Date Of Birth	17/03/1977
Occupation	INDOOR
Date Of Driving Pass	16/04/1998
Driving Experience	19 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96918787
Fax Number	
Contact Number	
Email Address	NOEMAIL

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The filing and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the QIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

 - (a) My insurer, my solicitor and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may also be disclosed by any of the insurers, and/or GIA, to their third party service providers or agents (including their lawyers/law firms) which may be based outside of Singapore, for one or more of the above Purposes.

VERIFIED BY ALAX MARS
REPORTING OFFICER

AIZAM BIN ATAN

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Officer
Personal

Stamp & Print

Mr. Launder S. P.
(GIA) (M. D. M. C.)



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2018

ESTIMATE

NO : QUOT201801-000111(00)

DATE : 01/02/2018

POLICY NO : 999995730

VEH REG NO : SLQ3210J

MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)

CHASSIS NO : WDD2130422A212860

ENGINE NO : 27492030929145

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLQ3210J

86227.05

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy - RH	1	1,950.00	1,950.00 ✓
2 Headlamp lower bracket - RH	1	45.00	45.00 7✓
3 Front bumper	1	780.00	780.00 ✓
4 Front bumper side retainer - RH	1	48.00	48.00 X
5 Front bumper inside parts - RH	1	49.00	49.00 7
6 Front bumper sensor	1	135.00	135.00 ✓
7 Front bumper sensor seals necessary	6	8.00	48.00 7✓
8 Front bumper clips	15	6.50	97.50 ✓
9 Front bumper fog lamp cover - RH	1	72.00	72.00 X
10 Front bumper fog lamp cover chrome - RH	1	63.00	63.00 X
11 Front fender - RH	1	680.00	680.00 ✓
12 Front fender inner shield - RH	1	115.00	115.00 X
13 Front fender inner shield clips - RH	15	6.50	97.50 X
14 Front sport rim - RH	1	680.00	680.00 ✓
			4,769.00
		Add 10%	577.00
			5,346.00
LABOUR			
15 To remove and refit front bumper sensor	1	100.00	100.00 601
16 To panel beat and repair front bumper RH bracket, RH front fender inner panel, including replacement of parts and align where necessary, to refit and adjust the same	1	900.00	900.00 5001
17 To spray same on affected areas	1	1,000.00	1,000.00 5001
18 To re-programme headlamp faulty code	1	350.00	350.00 250
			2,350.00
			1310
		TOTAL	S\$ 7,696.00
		ADD GST @ 7%	538.72
		GRAND TOTAL	S\$ 8,234.72

SINGAPORE DOLLAR EIGHT THOUSAND TWO HUNDRED THIRTY-FOUR AND CENTS SEVENTY-TWO ONLY

2022.02



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2018

ESTIMATE

NO : QUOT201801-000111(00)

DATE : 01/02/2018

POLICY NO : 999995730

VEH REG NO : SLQ3210J

MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)

CHASSIS NO : WDD2130422A212860

ENGINE NO : 27492030929145

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLQ3210J

Description	Quantity	Unit Price	Amount
		S\$	S\$

~~$$\begin{array}{r} \$ 6,898.45 \\ \times 5 \\ \hline \$ 5,898.45 \\ 7\% \\ 412.89 \\ \hline \$ 6,311.34 \end{array}$$~~

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2018

ESTIMATE

NO : QUOT201801-000111(00)

DATE : 01/02/2018

POLICY NO : 999995730

VEH REG NO : SLQ3210J

MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)

CHASSIS NO : WDD2130422A212860

ENGINE NO : 27492030929145

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLQ3210J

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Bonnet hinges - RH / LH	2 <i>MC</i>	145.00 <i>dit</i>	290.00 <i>X</i>
2 Bonnet actuator - RH / LH	2 <i>MC</i>	142.00 <i>tu</i>	284.00 <i>X</i>
			574.00
		Add 10%	57.40
			631.40
LABOUR			
3 To computerised check wheel alignment	1	100.00	100.00 <i>60%</i>
			100.00
TOTAL			S\$ 731.40
ADD GST @ 7%			51.20
GRAND TOTAL			<u>S\$ 782.60</u>

SINGAPORE DOLLAR SEVEN HUNDRED EIGHTY-TWO AND CENTS SIXTY ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2018

ESTIMATE

NO : QUOT201801-000111(00)

DATE : 01/02/2018

POLICY NO : 999995730

VEH REG NO : SLQ3210J

MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)

CHASSIS NO : WDD2130422A212860

ENGINE NO : 27492030929145

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLQ3210J

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy - RH	1	1,950.00	1,950.00
2 Headlamp lower bracket - RH	1	45.00	45.00
3 Front bumper	1	780.00	780.00
4 Front bumper side retainer - RH	1	48.00	48.00
5 Front bumper inside parts - RH	1	49.00	49.00
6 Front bumper sensor	1	135.00	135.00
7 Front bumper sensor seals	6	8.00	48.00
8 Front bumper clips	15	6.50	97.50
9 Front bumper fog lamp cover- RH	1	72.00	72.00
10 Front bumper fog lamp cover chrome - RH	1	63.00	63.00
11 Front fender - RH	1	680.00	680.00
12 Front fender inner shield - RH	1	115.00	115.00
13 Front fender inner shield clips - RH	15	6.50	97.50
14 Front sport rim - RH	1	680.00	680.00
			4,769.00
		Add 10%	577.00
			5,346.00
LABOUR			
15 To remove and refit front bumper sensor	1	100.00	100.00
16 To panel beat and repair front bumper RH bracket, RH front fender inner panel, including replacement of parts and align where necessary, to refit and adjust the same	1	900.00	900.00
17 To spray same on affected areas	1	1,000.00	1,000.00
18 To re-programme headlamp faulty code	1	350.00	350.00
			2,350.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey must be conducted and
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

at

TOTAL S\$ 7,696.00

ADD GST @ 7% 538.72

GRAND TOTAL S\$ 8,234.72

SINGAPORE DOLLAR EIGHT THOUSAND TWO HUNDRED THIRTY-FOUR AND CENTS SEVENTY-TWO ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/01/2018

ESTIMATE

NO : QUOT201801-000111(00)

DATE : 01/02/2018

POLICY NO : 999995730

VEH REG NO : SLQ3210J

MAKE/MODEL : MERCEDES BENZ E200
EXCLUSIVE (R18 LED)

CHASSIS NO : WDD2130422A212860

ENGINE NO : 27492030929145

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLQ3210J

Description	Quantity	Unit Price	Amount
		S\$	S\$

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lambah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6297 8886 Fax: 6297 0883 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8097072

DATE	06/02/2018	PAGE	1
TERMS	30 Days Net	SALESMAN	Jason Ooi
CUSTOMER REF	SLQ3210J	OUR REF	22064

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: TONGLUK1 TIME: 10:57
TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722
Telephone No : 62500088

DELIVER TO:

TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
60			1	65.00	65.00
28			1	15.00	15.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.


*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor



DATE

ALL CHECKS MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lambah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8097135

DATE	06/02/2018	PAGE	1
TERM	30 Days Net	SALESMAN	Jason Ong
CUSTOMER REF.	SLQ3210J	OUR REF.	A0482

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: TONGLUK1 TIME: 08:55
TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722
Telephone No : 62500088

DELIVER TO:
TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1. 809713 906 22 01		6G	2 PCS	142.00	284.00
2. 809713 880 01 28		A-/E	1 PC	145.00	145.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor
HDK
C.V. JOINT
MADE IN JAPAN
Stockists

TOTAL SIN
ADD GST /%
AMOUNT DUE SIN

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

SIGN & COMPANY'S STAMP

MOTOROLA, Mercedes-Benz, BMW, HONDA, TOYOTA, KIA, HYUNDAI, FUCHS, KANAE, bisAFE₃

For MIN GHEE AUTO PTE. LTD.



明教汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building
Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8096595

DATE	02/02/2018	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choo
CUSTOMER REF.	SLQ3210J	COURIER	20298

GST REG. NO.: M2-090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER:

TONGLUK1 TIME: 09:10

TONG LUCK AUTO PTE LTD

160, SIN MING DRIVE #07-01

SIN MING AUTOCITY

SINGAPORE 575722

Telephone No : 62500088

DELIVER TO:

TONG LUCK AUTO PTE LTD

160, SIN MING DRIVE #07-01

SIN MING AUTOCITY

SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QJANTITY	UNIT PRICE	AMOUNT
----------	-------------	-----	----------	------------	--------

8096595				950.00	950.00
---------	--	--	--	--------	--------

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT JOB'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 15 DAYS FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor



MADE IN CHINA

Stockists



BMW



For MIN GHEE AUTO PTE. LTD.

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

MERCEDES & BMW: Tel: 6298 3888 Fax: 6294 1450

Mitsubishi, Hyundai, Kia, Proton: Tel: 6298 3888 Fax: 6264 1450

Toyota & Honda: Tel: 6298 3888 Fax: 6291 2172



明義汽車私人有限公司
MING GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8096658

DATE	02/02/2018	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	SLQ3210J	OUR REF.	40469

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: TONGLUO1 TIME: 08:54

TONG LUCK AUTO PTE LTD

160, SIN MING DRIVE #07-01

SIN MING AUTOCITY

SINGAPORE 575722

Telephone No : 62500088

DELIVER TO:

TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
800 00 18	FRONT BUMPER	1A	1 PC	680.00	680.00
620 07 00	DISC COVER	4C	1 PC	45.00	45.00
885 01 38 9999	BLIND ALLEV		1 PC	780.00	780.00
6 47 0016	DISTANCE SENSOR		1 PC	680.00	680.00
990 94 97 64	WHEEL RING	3B	15 PCS	6.50	97.50
905 55 04 9999		9C	1 PC	135.00	135.00
542 12 51		01F	6 PCS	8.00	48.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

OVERDUE ACCOUNTS SHALL

BEAR INTEREST AT UOB'S PREVAILING

LENDING RATE

*CASH INVOICE MUST BE

PAID WITHIN 7 DAYS

FROM DATE OF INVOICE


Exclusive Distributor

HDK

C.V. JOINT
MADE IN JAPAN

Stockists

SIGN & COMPANY'S STAMP



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.

AUTOSOON PTE LTD

Blk 176 Sin Ming Drive #01-19 Sin Ming Autocare, S 575721.

Head Office : 176 Sin Ming Drive #01-10 Sin Ming Autocare S(575721)

Cheques and payments are to be directed to Head Office.

Tel No. : 6452 6657 Fax No. : 6451 4618

Tax Reg. No. : 200709808N Buss. Reg. No. : 200709808N

TONG LUCK AUTO PTE LTD

160 Sin Ming Drive #07-01

Sin Ming AutoCity

Singapore 575722

Contact : 6250 0088

TAX Invoice : DL711952

Invoice Date : 08/02/2018

Vehicle Num. : SLQ3210J

Make/Model : Mercedes Benz E200

Mileage(Km) :

PO/VO/RO# :

Ref./Remark :

S/N	Quantity	Particular	Unit Price	Amount S\$
1	1	To re-program / coding headlamp faulty code (online)	250.00	250.00




E. & O.E.

Total S\$: 250.00
GST @ 7% S\$: 17.50
Amount Due S\$: 267.50
=====

Terms : Cash

Customer's Signature/Co. Stamp

for AUTOSOON PTE LTD



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jan 2018		02 Feb 2018 13:45 Edit Adj Rpt	S\$6,227.05 Edit Estimates	S\$6,227.05 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS **[Created by Insurer]**

Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z, Tel: +6590000000		
Vehicle Reg. No.:	SLQ3210J	Date of Loss:	22/01/2018 10:00 - :59
Claim Type:	OD / 3515546991SG	Policy/Cover Note No.:	999995730 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/02/2018]		
Driver/Custodian:	KU CHEE YNG (40 / Male), NRIC: S7707488J, Tel: +6596918787		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ3210J (3515546991SG)

OD

Jan 22 2018 10:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Tong Luck Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Assessment Reports												1 per page					
No	Finalized On		AJAX MARS PTE LTD (Bukit Merah)									Thumbnail		Print			
1	22/01/18 20:00		Accident Statement										Load HTM				
Photos/Images												3 per page					
No	Finalized On		AJAX MARS PTE LTD (Bukit Merah)									Thumbnail		Print			
1	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
2	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
3	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
4	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
5	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
6	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
7	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
8	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
9	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
10	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
11	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
12	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
13	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
14	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
15	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
16	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
17	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
18	22/01/18 19:58		Accident Photo [Linked Accident Report Documents]										Load JPG				
19	22/01/18 19:58		Driving License [Linked Accident Report Documents]										Load JPG				
20	22/01/18 19:58		Driving License [Linked Accident Report Documents]										Load JPG				
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)									Thumbnail		Print			
1	23/03/18 09:55		General View										Load JPG				
2	23/03/18 09:55		General View										Load JPG				
3	23/03/18 09:55		General View										Load JPG				
4	23/03/18 09:55		General View										Load JPG				
5	23/03/18 09:55		General View										Load JPG				
6	23/03/18 09:55		General View										Load JPG				

			1		☒
7	23/03/18 09:55	General View	1	Load JPG	☒
8	23/03/18 09:55	General View	1	Load JPG	☒
9	23/03/18 09:55	General View	1	Load JPG	☒
10	23/03/18 09:55	General View	1	Load JPG	☒
11	23/03/18 09:55	General View	1	Load JPG	☒
12	23/03/18 09:55	General View	1	Load JPG	☒
13	23/03/18 09:55	General View	1	Load JPG	☒
14	23/03/18 09:55	General View	1	Load JPG	☒
15	23/03/18 09:56	Reinspection Photo	1	Load JPG	☒
16	23/03/18 09:56	Reinspection Photo	1	Load JPG	☒
17	23/03/18 09:56	Reinspection Photo	1	Load JPG	☒
18	23/03/18 09:56	Reinspection Photo	1	Load JPG	☒
Documentation					
			1 per page	☒	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	02/02/18 11:31	Repair Estimate	1	Load PDF	
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	22/01/18 19:58	Sketch Plan [Linked Accident Report Documents]	1	Load JPG	☒
2	22/01/18 19:58	Sketch Plan #2 [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/03/18 10:24	Supplementary	1	Load PDF	
2	23/03/18 10:25	Parts Invoice	1	Load PDF	

Linked Accident Report Documents

			View	View in Browser	☒
Assessment Reports			1 per page	☒	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	22/01/18 20:00	Accident Statement	1	Load HTM	
Photos/Images					
			3 per page	☒	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	22/01/18 19:58	Accident Photo	1	Load JPG	☒
2	22/01/18 19:58	Accident Photo	1	Load JPG	☒
3	22/01/18 19:58	Accident Photo	1	Load JPG	☒
4	22/01/18 19:58	Accident Photo	1	Load JPG	☒
5	22/01/18 19:58	Accident Photo	1	Load JPG	☒
6	22/01/18 19:58	Accident Photo	1	Load JPG	☒
7	22/01/18 19:58	Accident Photo	1	Load JPG	☒
8	22/01/18 19:58	Accident Photo	1	Load JPG	☒
9	22/01/18 19:58	Accident Photo	1	Load JPG	☒
10	22/01/18 19:58	Accident Photo	1	Load JPG	☒
11	22/01/18 19:58	Accident Photo	1	Load JPG	☒
12	22/01/18 19:58	Accident Photo	1	Load JPG	☒
13	22/01/18 19:58	Accident Photo	1	Load JPG	☒
14	22/01/18 19:58	Accident Photo	1	Load JPG	☒
15	22/01/18 19:58	Accident Photo	1	Load JPG	☒
16	22/01/18 19:58	Accident Photo	1	Load JPG	☒
17	22/01/18 19:58	Accident Photo	1	Load JPG	☒
18	22/01/18 19:58	Accident Photo	1	Load JPG	☒

19	22/01/18 19:58	Driving License	1	Load JPG	☒
20	22/01/18 19:58	Driving License	1	Load JPG	☒
Documentation			1 per page	☒	
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)		Thumbnail	Print
1	22/01/18 19:58	Sketch Plan	1	Load JPG	☒
2	22/01/18 19:58	Sketch Plan #2	1	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
^ v
Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG18002134/KTD3E2

Date: 23/03/2018

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

Policy No: 999995730

Date of Loss: 22/01/2018

Nature of Claim:

OD

Claim No:

3515546991SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ3210J

Make & Model: MERCEDES-BENZ E200, 2.0 EXCLUSIVE (R18 LED) (A) Engine No: 27492030929145

Reg. Date: 05/07/2017 (Man. Year: 2017)

Chassis No: WDD2130422A212860

Colour: Metallic Brown

Odometer: 8954 km

Engine Capacity: 1991 cc

Market Value/New Car Price: S\$196,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 275/40 R18

Front Left Side: Michelin 9 mm

Rear Left Side: Michelin 9 mm

Front Right Side: Michelin 9 mm

Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,977.40	4,857.05	1,120.35	18.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,370.00	1,080.00	44.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,427.40	6,227.05	2,200.35	26.11
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	7,427.40	5,227.05	2,200.35	29.62
+ GST 7.00/7.00% (S\$)	519.92	365.89	154.03	29.63
Nett Amount (S\$)	7,947.32	5,592.94	2,354.38	29.62

INSPECTION

Date of Assignment: 02/02/2018

Date Inspected: 05/02/2018 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 SIN MING DRIVE #07-01/06
SIN MING AUTOCITY
SINGAPORE 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY - RH (WCP)	MTG Cracked	1,950.00 F	*1,950.00 F
2	1		*HEADLAMP LOWER BRACKET - RH (WCP)	Distorted	45.00 F	*45.00 F
3	1		*FRONT BUMPER (WCP)	Buckled	780.00 F	*780.00 F
4	1		*FRONT BUMPER SIDE RETAINER - RH (WCP)	Serviceable	48.00 F	*- F
5	1		*FRONT BUMPER INSIDE PARTS - RH (WCP)	Serviceable	49.00 F	*- F
6	1		*FRONT BUMPER SENSOR (WCP)	Scratched	135.00 F	*135.00 F
7	6		*FRONT BUMPER SENSOR SEALS (WCP)	Necessary	48.00 F	*48.00 F
8	15		*FRONT BUMPER CLIPS (WCP)	Necessary	97.50 F	*97.50 F
9	1		*FRONT BUMPER FOG LAMP COVER - RH (WCP)	Serviceable	72.00 F	*- F
10	1		*FRONT BUMPER FOG LAMP COVER CHROME - RH (WCP)	Serviceable	63.00 F	*- F
11	1		*FRONT FENDER - RH (WCP)	Buckled	680.00 F	*680.00 F
12	1		*FRONT FENDER INNER SHIELD - RH (WCP)	Serviceable	115.00 F	*- F
13	15		*FRONT FENDER INNER SHIELD CLIPS - RH (WCP)	Not Necessary	97.50 F	*- F
14	1		*FRONT SPORT RIM - RH (WCP)	Dented	680.00 F	*680.00 F
15	2		*BONNET HINGES - RH / LH (DISTORTED) (WCP)	Not Consistent With The Impact	290.00 F	*- F
16	2		*BONNET ACTUATOR - RH / LH (Jammed) (WCP)	Not Consistent With The Impact	284.00 F	*- F

F=Franchise part.

Sub Total (S\$)	5,434.00	4,415.50
+ Margin on L,N Items 10.00/10.00% (S\$)	543.40	441.55
Total Parts (S\$)	5,977.40	4,857.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	-
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	100.00	60.00
2	TO PANEL BEAT AND REPAIR FRONT BUMPER RH BRACKET, RH FRONT FENDER INNER PANEL, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	900.00	500.00
3	TO SPRAY SAME ON AFFECTED AREAS	New	1,000.00	500.00
4	TO RE-PROGRAMME HEADLAMP FAULTY CODE	New	350.00	250.00
5	TO COMPUTERISED CHECK WHEEL ALIGNMENT	New	100.00	60.00
Gross Labour Cost (\$\$)			2,450.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >